




CVE-2002-1797

Published on: 12/31/2002 05:00:00 AM UTC

Last Modified on: 06/15/2021 08:10:51 PM UTC

CVE-2002-1797

[Source: Mitre](#)[Source: NIST](#)[CVE.ORG](#)[Print: PDF](#) 

Certain versions of [ChaiVm](#) from [Hp](#) contain the following vulnerability:
ChaiVM for HP color LaserJet 4500 and 4550 or HP LaserJet 4100 and 8150 does not properly enforce access control restrictions, which could allow local users to add, delete, or modify any services hosted by the ChaiServer.

CVE-2002-1797 has been assigned by [M](#) cve@mitre.org to track the vulnerability

CVSS2 Score: **4.6 - MEDIUM**

Access
Vector

LOCAL

Access
Complexity

LOW

Authentication

NONE

Confidentiality
Impact

PARTIAL

Integrity
Impact

PARTIAL

Availability
Impact

PARTIAL

CVE References

Description

Tags

Link

PHENOELIT

[Vendor Advisory](#)
www.phenoelit.de
[text/plain](#)

[MISC](#)
www.phenoelit.de/stuff/HP_Chai.txt

HP ChaiVM ChaiServer Arbitrary Service Modification Vulnerability

[cve.report \(archive\)](#)
[text/html](#)

[BUGTRAQ](#) BID 5332

SecurityFocus HOME Mailing List: BugTraq

[web.archive.org](#)
[text/html](#)
[Inactive Link](#) [Not Archived](#)

[BUGTRAQ](#) 20020727 Phenoelit
Advisory #0815 +--

ISS X-Force Database: hp-chaivm-unauth-access (9694): HP ChaiVM could allow unauthorized access to services

[web.archive.org](#)
[text/html](#)
[Inactive Link](#) [Not Archived](#)

[XF](#) hp-chaivm-unauth-access(9694)

By selecting these links, you may be leaving CVEreport webspace. We have provided these links to other websites because they may have information that would be of interest to you. No inferences should be drawn on account of other sites being referenced, or not, from this page. There may be other websites that

CVEReport does not necessarily endorse the views expressed, or concur with the facts presented on these sites. Further, CVEReport does not endorse any commercial products that may be mentioned on these sites. Please address comments about any linked pages to comment@cve.report.

There are currently no QIDs associated with this CVE

Known Affected Configurations (CPE V2.3)

Type	Vendor	Product	Version	Update	Edition	Language
Application	Hp	Chaivm	All	All	All	All
Application	Hp	Chaivm	All	All	All	All
cpe:2.3:a:hp:chaivm:*.~.*.*.*.*.*.*.*.						
cpe:2.3:a:hp:chaivm:*.~.*.*.*.*.*.*.*.						

No vendor comments have been submitted for this CVE

[← Previous ID](#)

Next ID→

© CVE.report 2023   |

Use of this information constitutes acceptance for use in an AS IS condition. There are NO warranties, implied or otherwise, with regard to this information or its use. Any use of this information is at the user's risk. It is the responsibility of user to evaluate the accuracy, completeness or usefulness of any information, opinion, advice or other content. EACH USER WILL BE SOLELY RESPONSIBLE FOR ANY consequences of his or her direct or indirect use of this web site. ALL WARRANTIES OF ANY KIND ARE EXPRESSLY DISCLAIMED. This site will NOT BE LIABLE FOR ANY DIRECT, INDIRECT or any other kind of loss.

CVE, CWE, and OVAL are registered trademarks of [The MITRE Corporation](#) and the authoritative source of CVE content is [MITRE's CVE web site](#). This site includes MITRE data granted under the following [license](#).

CVE.report and Source URL Uptime Status status.cve.report