




CVE-2003-1115

Published on: 12/31/2003 05:00:00 AM UTC

Last Modified on: 03/23/2021 11:28:43 PM UTC

CVE-2003-1115

[Source: Mitre](#)[Source: NIST](#)[CVE.ORG](#)[Print: PDF](#) 

Certain versions of [Succession Communication Server 2000](#) from [Nortel](#) contain the following vulnerability:

The Session Initiation Protocol (SIP) implementation in Nortel Networks Succession Communication Server 2000, when using SIP-T, allows remote attackers to cause a denial of service and possibly execute arbitrary code via crafted INVITE messages, as demonstrated by the OUSPG PROTOS c07-sip test suite.

CVE-2003-1115 has been assigned by [M](#) cve@mitre.org to track the vulnerability

CVSS2 Score: **7.5 - HIGH**

Access
Vector

NETWORK

Access
Complexity

LOW

Authentication

NONE

Confidentiality
Impact

PARTIAL

Integrity
Impact

PARTIAL

Availability
Impact

PARTIAL

CVE References

Description

Tags

Link

No Description Provided

[Exploit](#)
[web.archive.org](#)
[text/html](#)
[Inactive Link](#) [Not Archived](#)

[MISC](#)
www.ee.oulu.fi/research/ouspg/protos/testing/c07/sip/

CERT/CC Vulnerability Note VU#528719

[Third Party Advisory](#)
[US Government Resource](#)
www.kb.cert.org
[text/html](#)

[CERT-VN VU#528719](#)

Multiple Vendor Session Initiation Protocol
Vulnerabilities

[Patch](#)
[cve.report \(archive\)](#)
[text/html](#)

[BID 6904](#)

2003 CERT Advisories

[Third Party Advisory](#)

[CERT CA-2003-06](#)

US Government Resource

www.cert.org

text/html

IBM X-Force Exchange

exchange.xforce.ibmcloud.com

XF sip-invite(11379)

text/html

By selecting these links, you may be leaving CVEreport webspace. We have provided these links to other websites because they may have information that would be of interest to you. No inferences should be drawn on account of other sites being referenced, or not, from this page. There may be other websites that are more appropriate for your purpose. CVEreport does not necessarily endorse the views expressed, or concur with the facts presented on these sites. Further, CVEreport does not endorse any commercial products that may be mentioned on these sites. Please address comments about any linked pages to comment@cve.report.

There are currently no QIDs associated with this CVE

Known Affected Configurations (CPE V2.3)

Type	Vendor	Product	Version	Update	Edition	Language
Hardware 	Nortel	Succession Communication Server 2000	All	All	All	All
Hardware 	Nortel	Succession Communication Server 2000	All	All	compact	All
Hardware 	Nortel	Succession Communication Server 2000	All	All	All	All
Hardware 	Nortel	Succession Communication Server 2000	All	All	compact	All

cpe:2.3:h:nortel:succession_communication_server_2000:*.***.***.***:

cpe:2.3:h:nortel:succession_communication_server_2000:*.***.compact:***.***.***:

cpe:2.3:h:nortel:succession_communication_server_2000:*.***.***.***:

cpe:2.3:h:nortel:succession_communication_server_2000:*.***.compact:***.***.***:

No vendor comments have been submitted for this CVE

← Previous ID

Next ID →

© CVE.report 2023   |

Use of this information constitutes acceptance for use in an AS IS condition. There are NO warranties, implied or otherwise, with regard to this information or its use. Any use of this information is at the user's risk. It is the responsibility of user to evaluate the accuracy, completeness or usefulness of any information, opinion, advice or other content. EACH USER WILL BE SOLELY RESPONSIBLE FOR ANY consequences of his or her direct or indirect use of this web site. ALL WARRANTIES OF ANY KIND ARE EXPRESSLY DISCLAIMED. This site will NOT BE LIABLE FOR ANY DIRECT, INDIRECT or any other kind of loss.

CVE, CWE, and OVAL are registered trademarks of [The MITRE Corporation](#) and the authoritative source of CVE content is [MITRE's CVE web site](#). This site includes MITRE data granted under the following [license](#).

CVE.report and Source URL Uptime Status status.cve.report