




CVE-2003-1464

Published on: 12/31/2003 05:00:00 AM UTC

Last Modified on: 03/23/2021 11:28:43 PM UTC

CVE-2003-1464

[Source: Mitre](#)[Source: NIST](#)[CVE.ORG](#)[Print: PDF](#) 

Certain versions of [M45](#) from [Siemens](#) contain the following vulnerability:

Buffer overflow in Siemens 45 series mobile phones allows remote attackers to cause a denial of service (disconnect and unavailable inbox) via a Short Message Service (SMS) message with a long image name.

CVE-2003-1464 has been assigned by [M](#) cve@mitre.org to track the vulnerability

CVSS2 Score: **7.8 - HIGH**

Access
Vector

Access
Complexity

Authentication

NETWORK

LOW

NONE

Confidentiality
Impact

Integrity
Impact

Availability
Impact

NONE

NONE

COMPLETE

CVE References

Description

Tags

Link

IBM X-Force Exchange

[exchange.xforce.ibmcloud.com](https://exchange.xforce.ibmcloud.com/text/html)
text/html

[XF siemens-sms-image-bo\(11950\)](#)

SecurityFocus HOME Mailing List: BugTraQ

[www.securityfocus.com](https://www.securityfocus.com/text/html)
text/html

[BUGTRAQ 20030506 Siemens Mobile Phone - Buffer Overflow](#)

CXSecurity - IDS

[securityreason.com](https://securityreason.com/text/html)
text/html

[SREASON 3287](#)

Siemens Mobile Phones %IMG_NAME Denial Of Service Vulnerability

[cve.report \(archive\)](#)
text/html

[BID 7507](#)

By selecting these links, you may be leaving CVEreport webspace. We have provided these links to other websites because they may have information that would be of interest to you. No inferences should be drawn on account of other sites being referenced, or not, from this page. There may be other websites that are more appropriate for your purpose. CVEreport does not necessarily endorse the views expressed, or concur with the facts presented on these sites. Further, CVEreport does not endorse any commercial products that may be mentioned on these sites. Please address comments about any linked pages to comment@cve.report.

Summary of CVE-2023-28867

There are currently no QIDs associated with this CVE

Known Affected Configurations (CPE V2.3)

Type	Vendor	Product	Version	Update	Edition	Language
Hardware 	Siemens	M45	All	All	All	All
Hardware 	Siemens	M45	All	All	All	All
Hardware 	Siemens	S45	All	All	All	All
Hardware 	Siemens	S45	All	All	All	All

cpe:2.3:h:siemens:m45:*.***.***.***.

cpe:2.3:h:siemens:m45:*.***.***.***.

cpe:2.3:h:siemens:s45:*.***.***.***.

cpe:2.3:h:siemens:s45:*.***.***.***.

No vendor comments have been submitted for this CVE

← Previous ID

Next ID→