




CVE-2004-0099

Published on: 03/03/2004 05:00:00 AM UTC

Last Modified on: 03/23/2021 11:28:12 PM UTC

CVE-2004-0099

[Source: Mitre](#)[Source: NIST](#)[CVE.ORG](#)[Print: PDF](#) 

Certain versions of [Freebsd](#) from [Freebsd](#) contain the following vulnerability:

mksnap_ffs in FreeBSD 5.1 and 5.2 only sets the snapshot flag when creating a snapshot for a file system, which causes default values for other flags to be used, possibly disabling security-critical settings and allowing a local user to bypass intended access restrictions.

CVE-2004-0099 has been assigned by [M](#) cve@mitre.org to track the vulnerability

CVSS2 Score: **4.6 - MEDIUM**

Access
Vector

LOCAL

Access
Complexity

LOW

Authentication

NONE

Confidentiality
Impact

PARTIAL

Integrity
Impact

PARTIAL

Availability
Impact

PARTIAL

CVE References

Description

Tags

Link

FreeBSD mksnap_ffs File System Option Reset Vulnerability

[Patch](#)
[Vendor Advisory](#)
[cve.report \(archive\)](#)
[text/html](#)

[BID 9533](#)

No Description Provided

[www.osvdb.org](#)

[OSVDB 3790](#)

[Inactive Link](#) [Not Archived](#)

[Patch](#)
[Vendor Advisory](#)
[ftp.freebsd.org](#)
[text/plain](#)

[FREEBSD FreeBSD-SA-04:01](#)

[Inactive Link](#) [Not Archived](#)

IBM X-Force Exchange

[exchange.xforce.ibmcloud.com](#)
[text/html](#)

[XF freebsd-mksnapffs-bypass-security\(15005\)](#)

By selecting these links, you may be leaving CVEreport webspace. We have provided these links to other websites because they may have information that would be of interest to you. No inferences should be drawn on account of other sites being referenced, or not, from this page. There may be other websites that are more appropriate for your purpose. CVEreport does not necessarily endorse the views expressed, or concur with the facts presented on these sites. Further, CVEreport does not endorse any commercial products that may be mentioned on these sites. Please address comments about any linked pages to comment@cve.report.

There are currently no QIDs associated with this CVE

Known Affected Configurations (CPE V2.3)

Type	Vendor	Product	Version	Update	Edition	Language
Operating System	Freebsd	Freebsd	5.1	release	All	All
Operating System	Freebsd	Freebsd	5.2.1	release	All	All
Operating System	Freebsd	Freebsd	5.1	release	All	All
Operating System	Freebsd	Freebsd	5.2.1	release	All	All
cpe:2.3:o:freebsd:freebsd:5.1:release:****.*.*:						
cpe:2.3:o:freebsd:freebsd:5.2.1:release:****.*.*:						
cpe:2.3:o:freebsd:freebsd:5.1:release:****.*.*:						
cpe:2.3:o:freebsd:freebsd:5.2.1:release:****.*.*:						

No vendor comments have been submitted for this CVE

[← Previous ID](#)

Next ID→

© CVE.report 2023   |

Use of this information constitutes acceptance for use in an AS IS condition. There are NO warranties, implied or otherwise, with regard to this information or its use. Any use of this information is at the user's risk. It is the responsibility of user to evaluate the accuracy, completeness or usefulness of any information, opinion, advice or other content. EACH USER WILL BE SOLELY RESPONSIBLE FOR ANY consequences of his or her direct or indirect use of this web site. ALL WARRANTIES OF ANY KIND ARE EXPRESSLY DISCLAIMED. This site will NOT BE LIABLE FOR ANY DIRECT, INDIRECT or any other kind of loss.

CVE, CWE, and OVAL are registered trademarks of [The MITRE Corporation](#) and the authoritative source of CVE content is [MITRE's CVE web site](#). This site includes MITRE data granted under the following [license](#).

CVE.report and Source URL Uptime Status status.cve.report