



CVE-2009-4292

[MITRE](#)[NVD](#)[CVE.ORG](#)[JSON API](#)[Print: PDF](#)

Summary

CVE	CVE-2009-4292
State	PUBLIC
Assigner	cve@mitre.org
Source Priority	CVE Program / NVD first with legacy fallback
Published	2009-12-10 23:30:00 UTC
Updated	2017-08-17 01:31:00 UTC
Description	Buffer overflow in the URL filtering function in Internet Initiative Japan SEIL/X1, SEIL/X2, and SEIL/B1 firmware 2.40 through

Risk And Classification

Problem Types: CWE-119

NVD Known Affected Configurations (CPE 2.3)

Type	Vendor	Product	Version	Update	Edition	Language
Hardware	lij	Seil/b1	All	All	All	All
Application	lij	Seil/b1 Firmware	2.40	All	All	All
Application	lij	Seil/b1 Firmware	2.41	All	All	All
Application	lij	Seil/b1 Firmware	2.42	All	All	All
Application	lij	Seil/b1 Firmware	2.50	All	All	All
Application	lij	Seil/b1 Firmware	2.51	All	All	All
Hardware	lij	Seil/x1	All	All	All	All
Application	lij	Seil/x1 Firmware	2.40	All	All	All
Application	lij	Seil/x1 Firmware	2.41	All	All	All
Application	lij	Seil/x1 Firmware	2.42	All	All	All
Application	lij	Seil/x1 Firmware	2.50	All	All	All
Application	lij	Seil/x1 Firmware	2.51	All	All	All
Hardware	lij	Seil/x2	All	All	All	All
Application	lij	Seil/x2 Firmware	2.40	All	All	All
Application	lij	Seil/x2 Firmware	2.41	All	All	All
Application	lij	Seil/x2 Firmware	2.42	All	All	All
Application	lij	Seil/x2 Firmware	2.50	All	All	All

Application	lij	Seil/x2 Firmware	2.51	All	All	All
Hardware	lij	Seil/b1	All	All	All	All
Hardware	lij	Seil/b1	All	All	All	All
Application	lij	Seil/b1 Firmware	2.40	All	All	All
Application	lij	Seil/b1 Firmware	2.41	All	All	All
Application	lij	Seil/b1 Firmware	2.42	All	All	All
Application	lij	Seil/b1 Firmware	2.50	All	All	All
Application	lij	Seil/b1 Firmware	2.51	All	All	All
Application	lij	Seil/b1 Firmware	2.40	All	All	All
Application	lij	Seil/b1 Firmware	2.41	All	All	All
Application	lij	Seil/b1 Firmware	2.42	All	All	All
Application	lij	Seil/b1 Firmware	2.50	All	All	All
Application	lij	Seil/b1 Firmware	2.51	All	All	All
Hardware	lij	Seil/x1	All	All	All	All
Hardware	lij	Seil/x1	All	All	All	All
Application	lij	Seil/x1 Firmware	2.40	All	All	All
Application	lij	Seil/x1 Firmware	2.41	All	All	All
Application	lij	Seil/x1 Firmware	2.42	All	All	All
Application	lij	Seil/x1 Firmware	2.50	All	All	All
Application	lij	Seil/x1 Firmware	2.51	All	All	All
Application	lij	Seil/x1 Firmware	2.40	All	All	All
Application	lij	Seil/x1 Firmware	2.41	All	All	All
Application	lij	Seil/x1 Firmware	2.42	All	All	All
Application	lij	Seil/x1 Firmware	2.50	All	All	All
Application	lij	Seil/x1 Firmware	2.51	All	All	All
Hardware	lij	Seil/x2	All	All	All	All
Hardware	lij	Seil/x2	All	All	All	All
Application	lij	Seil/x2 Firmware	2.40	All	All	All
Application	lij	Seil/x2 Firmware	2.41	All	All	All
Application	lij	Seil/x2 Firmware	2.42	All	All	All
Application	lij	Seil/x2 Firmware	2.50	All	All	All
Application	lij	Seil/x2 Firmware	2.51	All	All	All
Application	lij	Seil/x2 Firmware	2.40	All	All	All
Application	lij	Seil/x2 Firmware	2.41	All	All	All
Application	lij	Seil/x2 Firmware	2.42	All	All	All

Application	Iij	Seil/x2 Firmware	2.50	All	All	All
Application	Iij	Seil/x2 Firmware	2.51	All	All	All

References

Reference	Source
Webmail : Solution de messagerie professionnelle - OVHcloud- OVH	VUPEN
JVN#06362164 SEIL/X Series and SEIL/B1 buffer overflow vulnerability	JVN
IBM X-Force Exchange	XF
JVNDB-2009-000069 - JVN iPedia	JVNDB
IIJ SEIL Series [脆弱性情報]	CONFIRM
59362	OSVDB
SEIL Routers Denial of Service and Buffer Overflow Vulnerabilities - Secunia Advisories - Vulnerability Information - Secunia.com	SECUNIA
CVE Program record	CVE.ORG
NVD vulnerability detail	NVD

No vendor comments have been submitted for this CVE.

There are currently no legacy QID mappings associated with this CVE.