




CVE-2009-4510

Published on: 04/13/2010 12:00:00 AM UTC

Last Modified on: 03/23/2021 11:25:23 PM UTC

CVE-2009-4510

[Source: Mitre](#)[Source: NIST](#)[CVE.ORG](#)[Print: PDF](#) 

Certain versions of [Tandberg Video Communication Server](#) from [Vsecurity](#) contain the following vulnerability:

The SSH service on the TANDBERG Video Communication Server (VCS) before X5.1 uses a fixed DSA key, which makes it easier for remote attackers to conduct man-in-the-middle attacks and spoof arbitrary servers via crafted SSH packets.

CVE-2009-4510 has been assigned by [M](#) cve@mitre.org to track the vulnerability

CVSS2 Score: **8.5 - HIGH**

Access
Vector

Access
Complexity

Authentication

NETWORK

MEDIUM

SINGLE

Confidentiality
Impact

Integrity
Impact

Availability
Impact

COMPLETE

COMPLETE

COMPLETE

CVE References

Description

Tags

Link

VSR Security
Advisories

[Patch](#)

[Vendor Advisory](#)

[web.archive.org](#)

[text/html](#)

[Inactive Link](#)

[Not Archived](#)

[MISC](#) [www.vsecurity.com/resources/advisory/20100409-2](#)

TANDBERG
Video
Communication
Server Multiple
Vulnerabilities -
Advisories -
Community

[Vendor Advisory](#)

[web.archive.org](#)

[text/html](#)

[X](#) [SECUNIA 39275](#)

TelePresence -
Cisco Systems

[ftp.tandberg.com](#)

[text/html](#)

[CONFIRM](#)

[ftp.tandberg.com/pub/software/vcs/TANDBERG%20Video%20Communication%20Server%20S](#)

◀ ▶

There are currently no QIDs associated with this CVE

Known Affected Configurations (CPE V2.3)

Type	Vendor	Product	Version	Update	Edition	Language
Application	Vsecurity	Tandberg Video Communication Server	x1.0.0	All	All	All
Application	Vsecurity	Tandberg Video Communication Server	x1.1.0	All	All	All
Application	Vsecurity	Tandberg Video Communication Server	x1.2.0	All	All	All
Application	Vsecurity	Tandberg Video Communication Server	x2.0.0	All	All	All
Application	Vsecurity	Tandberg Video Communication Server	x2.1.0	All	All	All
Application	Vsecurity	Tandberg Video Communication Server	x3.0.0	All	All	All
Application	Vsecurity	Tandberg Video Communication Server	x3.1.0	All	All	All
Application	Vsecurity	Tandberg Video Communication Server	x4.1.0	All	All	All
Application	Vsecurity	Tandberg Video Communication Server	x4.2.0	All	All	All
Application	Vsecurity	Tandberg Video Communication Server	x4.2.1	All	All	All
Application	Vsecurity	Tandberg Video Communication Server	x4.3.0	All	All	All
Application	Vsecurity	Tandberg Video Communication Server	x1.0.0	All	All	All
Application	Vsecurity	Tandberg Video Communication Server	x1.1.0	All	All	All
Application	Vsecurity	Tandberg Video Communication Server	x1.2.0	All	All	All
Application	Vsecurity	Tandberg Video Communication Server	x2.0.0	All	All	All
Application	Vsecurity	Tandberg Video Communication Server	x2.1.0	All	All	All
Application	Vsecurity	Tandberg Video Communication Server	x3.0.0	All	All	All
Application	Vsecurity	Tandberg Video Communication Server	x3.1.0	All	All	All
Application	Vsecurity	Tandberg Video Communication Server	x4.1.0	All	All	All
Application	Vsecurity	Tandberg Video Communication Server	x4.2.0	All	All	All
Application	Vsecurity	Tandberg Video Communication Server	x4.2.1	All	All	All
Application	Vsecurity	Tandberg Video Communication Server	x4.3.0	All	All	All
Application	Vsecurity	Tandberg Video Communication Server	All	All	All	All

```
cpe:2.3:a:vsecurity:tandberg_video_communication_server:x1.0.0:*:*:*:*:*:
```

```
cpe:2.3:a:vsecurity:tandberg_video_communication_server:x1.1.0:*:*:*:*:*:
```

```
cpe:2.3:a:vsecurity:tandberg_video_communication_server:x1.2.0:*:*:*:*:*:
```

cpe:2.3:a:vsecurity:tandberg_video_communication_server:x2.0.0:*****:
cpe:2.3:a:vsecurity:tandberg_video_communication_server:x2.1.0:*****:
cpe:2.3:a:vsecurity:tandberg_video_communication_server:x3.0.0:*****:
cpe:2.3:a:vsecurity:tandberg_video_communication_server:x3.1.0:*****:
cpe:2.3:a:vsecurity:tandberg_video_communication_server:x4.1.0:*****:
cpe:2.3:a:vsecurity:tandberg_video_communication_server:x4.2.0:*****:
cpe:2.3:a:vsecurity:tandberg_video_communication_server:x4.2.1:*****:
cpe:2.3:a:vsecurity:tandberg_video_communication_server:x4.3.0:*****:
cpe:2.3:a:vsecurity:tandberg_video_communication_server:x1.0.0:*****:
cpe:2.3:a:vsecurity:tandberg_video_communication_server:x1.1.0:*****:
cpe:2.3:a:vsecurity:tandberg_video_communication_server:x1.2.0:*****:
cpe:2.3:a:vsecurity:tandberg_video_communication_server:x2.0.0:*****:
cpe:2.3:a:vsecurity:tandberg_video_communication_server:x2.1.0:*****:
cpe:2.3:a:vsecurity:tandberg_video_communication_server:x3.0.0:*****:
cpe:2.3:a:vsecurity:tandberg_video_communication_server:x3.1.0:*****:
cpe:2.3:a:vsecurity:tandberg_video_communication_server:x4.1.0:*****:
cpe:2.3:a:vsecurity:tandberg_video_communication_server:x4.2.0:*****:
cpe:2.3:a:vsecurity:tandberg_video_communication_server:x4.2.1:*****:
cpe:2.3:a:vsecurity:tandberg_video_communication_server:x4.3.0:*****:
cpe:2.3:a:vsecurity:tandberg_video_communication_server:*****:

No vendor comments have been submitted for this CVE

[← Previous ID](#)

[Next ID →](#)