



CVE-2012-3020

Published on: 08/06/2012 12:00:00 AM UTC

Last Modified on: 03/23/2021 11:28:16 PM UTC

CVE-2012-3020

[Source: Mitre](#)

[Source: NIST](#)

[CVE.ORG](#)

[Print: PDF](#)



Certain versions of [Synco Ozw Web Server](#) from [Siemens](#) contain the following vulnerability:

The Siemens Synco OZW Web Server devices OZW672.*, OZW772.*, and OZW775 with firmware before 4 have an unspecified default password, which makes it easier for remote attackers to obtain administrative access via a network session.

CVE-2012-3020 has been assigned by [ics-cert@hq.dhs.gov](#) to track the vulnerability

CVSS2 Score: **7.5 - HIGH**

Access Vector

NETWORK

Access Complexity

LOW

Authentication

NONE

Confidentiality Impact

PARTIAL

Integrity Impact

PARTIAL

Availability Impact

PARTIAL

CVE References

Description

Tags

Link

404 - File Not Found | CISA

[US Government Resource](#)
[www.us-cert.gov](#)
[application/pdf](#)
Inactive Link **Not Archived**

[MISC](#) [www.us-cert.gov/control_systems/pdf/ICSA-12-214-01.pdf](#)

Siemens Industry Online Support - Automation Service, Automation Support, Simatic Service, Simatic Support, Technical Support, Technical Consulting

[web.archive.org](#)
[text/html](#)
Inactive Link **Not Archived**

[MISC](#) [support.automation.siemens.com/WW/view/en/41929231/130000](#)

By selecting these links, you may be leaving CVEreport webspace. We have provided these links to other websites because they may have information that would be of interest to you. No inferences should be drawn on account of other sites being referenced, or not, from this page. There may be other websites that are more appropriate for your purpose. CVEreport does not necessarily endorse the views expressed, or concur with the facts presented on these sites. Further, CVEreport does not endorse any commercial products that may be mentioned on these sites. Please address comments about any linked pages to [comment@cve.report](#).

cpe:2.3:h:siemens:synco_ozw_web_server:ozw672.04:*****:
cpe:2.3:h:siemens:synco_ozw_web_server:ozw672.16:*****:
cpe:2.3:h:siemens:synco_ozw_web_server:ozw772.01:*****:
cpe:2.3:h:siemens:synco_ozw_web_server:ozw772.04:*****:
cpe:2.3:h:siemens:synco_ozw_web_server:ozw772.16:*****:
cpe:2.3:h:siemens:synco_ozw_web_server:ozw772.250:*****:
cpe:2.3:h:siemens:synco_ozw_web_server:ozw775:*****:
cpe:2.3:o:siemens:synco_ozw_web_server_firmware:*****:

No vendor comments have been submitted for this CVE

[← Previous ID](#)

[Next ID →](#)