



# CVE-2013-3582

[MITRE](#)[NVD](#)[CVE.ORG](#)[Print: PDF !\[\]\(e3f8612927870f2e0f9f5989e6dd3064\_img.jpg\)](#)

## Summary

<b>CVE</b>	CVE-2013-3582
<b>State</b>	PUBLIC
<b>Assigner</b>	cert@cert.org
<b>Source Priority</b>	CVE Program / NVD first with legacy fallback
<b>Published</b>	2013-08-28 13:13:00 UTC
<b>Updated</b>	2013-10-07 18:04:00 UTC
<b>Description</b>	Buffer overflow in Dell BIOS on Dell Latitude D###, E####, XT2, and Z600 devices, and Dell Precision M#### devices, allo

## Risk And Classification

**Problem Types:** CWE-119

## NVD Known Affected Configurations (CPE 2.3)

Type	Vendor	Product	Version	Update	Edition	Language
Hardware	Dell	Latitude D530	-	All	All	All
Hardware	Dell	Latitude D530	-	All	All	All
Hardware	Dell	Latitude D531	-	All	All	All
Hardware	Dell	Latitude D531	-	All	All	All
Hardware	Dell	Latitude D630	-	All	All	All
Hardware	Dell	Latitude D630	-	All	All	All
Hardware	Dell	Latitude D631	-	All	All	All
Hardware	Dell	Latitude D631	-	All	All	All
Hardware	Dell	Latitude D830	-	All	All	All
Hardware	Dell	Latitude D830	-	All	All	All
Hardware	Dell	Latitude E4200	-	All	All	All
Hardware	Dell	Latitude E4200	-	All	All	All
Hardware	Dell	Latitude E4300	-	All	All	All
Hardware	Dell	Latitude E4300	-	All	All	All
Hardware	Dell	Latitude E5400	-	All	All	All
Hardware	Dell	Latitude E5400	-	All	All	All
Hardware	Dell	Latitude E5500	-	All	All	All

Hardware	Dell	Latitude E5500	-	All	All	All
Hardware	Dell	Latitude E6400	-	All	All	All
Hardware	Dell	Latitude E6400	-	All	All	All
Hardware	Dell	Latitude E6400 Atg	-	All	All	All
Hardware	Dell	Latitude E6400 Atg	-	All	All	All
Hardware	Dell	Latitude E6400 Atg Xfr	-	All	All	All
Hardware	Dell	Latitude E6400 Atg Xfr	-	All	All	All
Hardware	Dell	Latitude E6500	-	All	All	All
Hardware	Dell	Latitude E6500	-	All	All	All
Hardware	Dell	Latitude Xt2	-	All	All	All
Hardware	Dell	Latitude Xt2	-	All	All	All
Hardware	Dell	Latitude Z600	-	All	All	All
Hardware	Dell	Latitude Z600	-	All	All	All
Hardware	Dell	Precision M2300	-	All	All	All
Hardware	Dell	Precision M2300	-	All	All	All
Hardware	Dell	Precision M2400	-	All	All	All
Hardware	Dell	Precision M2400	-	All	All	All
Hardware	Dell	Precision M4300	-	All	All	All
Hardware	Dell	Precision M4300	-	All	All	All
Hardware	Dell	Precision M4400	-	All	All	All
Hardware	Dell	Precision M4400	-	All	All	All
Hardware	Dell	Precision M6300	-	All	All	All
Hardware	Dell	Precision M6300	-	All	All	All
Hardware	Dell	Precision M6400	-	All	All	All
Hardware	Dell	Precision M6400	-	All	All	All
Hardware	Dell	Precision M6500	-	All	All	All
Hardware	Dell	Precision M6500	-	All	All	All

## References

Reference	Source
Vulnerability Note VU#912156 - Dell BIOS in some Latitude laptops and Precision Mobile Workstations vulnerable to buffer overflow	CERT-
Black Hat USA 2013   Archives	MISC
media.blackhat.com   522: Connection timed out	MISC
Dell Computer Corporation, Inc. Information for VU#912156	CONFIDENTIAL
media.blackhat.com   522: Connection timed out	MISC

No vendor comments have been submitted for this CVE.

There are currently no legacy QID mappings associated with this CVE.

© [CVE.report](#) 2026 |

Use of this information constitutes acceptance for use in an AS IS condition. There are NO warranties, implied or otherwise, with regard to this information or its use. Any use of this information is at the user's risk. It is the responsibility of user to evaluate the accuracy, completeness or usefulness of any information, opinion, advice or other content. EACH USER WILL BE SOLELY RESPONSIBLE FOR ANY consequences of his or her direct or indirect use of this web site. ALL WARRANTIES OF ANY KIND ARE EXPRESSLY DISCLAIMED. This site will NOT BE LIABLE FOR ANY DIRECT, INDIRECT or any other kind of loss.

CVE, CWE, and OVAL are registered trademarks of [The MITRE Corporation](#) and the authoritative source of CVE content is [MITRE's CVE web site](#). This site includes MITRE data granted under the following [license](#).

**CVE.report and Source URL Uptime Status [status.cve.report](#)**