



# CVE-2013-6470

Published on: 06/02/2014 12:00:00 AM UTC

Last Modified on: 02/13/2023 04:13:25 AM UTC

## CVE-2013-6470

[Source: Mitre](#)[Source: NIST](#)[CVE.ORG](#)[Print: PDF](#) 

Certain versions of [Openstack](#) from [Redhat](#) contain the following vulnerability:

The default configuration in the standalone controller quickstack manifest in openstack-foreman-installer, as used in Red Hat Enterprise Linux OpenStack Platform 4.0, disables authentication for Qpid, which allows remote attackers to gain access by connecting to Qpid.

CVE-2013-6470 has been assigned by [secalert@redhat.com](mailto:secalert@redhat.com) to track the vulnerability

CVSS2 Score: **5 - MEDIUM**

Access  
Vector

Access  
Complexity

Authentication

**NETWORK**

**LOW**

**NONE**

Confidentiality  
Impact

Integrity  
Impact

Availability  
Impact

**PARTIAL**

**NONE**

**NONE**

## CVE References

Description

Tags

Link

1051994 – (CVE-2013-6470) CVE-2013-6470 openstack foreman-installer: insecure defaults

[bugzilla.redhat.com](#)  
[text/html](#)

**CONFIRM**  
[bugzilla.redhat.com/show\\_bug.cgi?id=1051994](https://bugzilla.redhat.com/show_bug.cgi?id=1051994)

Red Hat Customer Portal

[Vendor Advisory](#)  
[web.archive.org](#)  
[text/html](#)  
**Inactive Link** **Not Archived**

**REDHAT RHSA-2014:0517**

By selecting these links, you may be leaving CVEreport webspace. We have provided these links to other websites because they may have information that would be of interest to you. No inferences should be drawn on account of other sites being referenced, or not, from this page. There may be other websites that are more appropriate for your purpose. CVEreport does not necessarily endorse the views expressed, or concur with the facts presented on these sites. Further, CVEreport does not endorse any commercial products that may be mentioned on these sites. Please address comments about any linked pages to [comment@cve.report](mailto:comment@cve.report).

There are currently no QIDs associated with this CVE

#### Known Affected Configurations (CPE V2.3)

| Type                                      | Vendor                 | Product                   | Version | Update | Edition | Language |
|-------------------------------------------|------------------------|---------------------------|---------|--------|---------|----------|
| Application                               | <a href="#">Redhat</a> | <a href="#">Openstack</a> | 4.0     | All    | All     | All      |
| Application                               | <a href="#">Redhat</a> | <a href="#">Openstack</a> | 4.0     | All    | All     | All      |
| cpe:2.3:a:redhat:openstack:4.0:*:*:*:*:*: |                        |                           |         |        |         |          |
| cpe:2.3:a:redhat:openstack:4.0:*:*:*:*:*: |                        |                           |         |        |         |          |

No vendor comments have been submitted for this CVE

[← Previous ID](#)

[Next ID→](#)

© [CVE.report](#) 2023   |

Use of this information constitutes acceptance for use in an AS IS condition. There are NO warranties, implied or otherwise, with regard to this information or its use. Any use of this information is at the user's risk. It is the responsibility of user to evaluate the accuracy, completeness or usefulness of any information, opinion, advice or other content. EACH USER WILL BE SOLELY RESPONSIBLE FOR ANY consequences of his or her direct or indirect use of this web site. ALL WARRANTIES OF ANY KIND ARE EXPRESSLY DISCLAIMED. This site will NOT BE LIABLE FOR ANY DIRECT, INDIRECT or any other kind of loss.

CVE, CWE, and OVAL are registered trademarks of [The MITRE Corporation](#) and the authoritative source of CVE content is [MITRE's CVE web site](#). This site includes MITRE data granted under the following [license](#).

**CVE.report and Source URL Uptime Status** [status.cve.report](#)