



CVE-2014-8511

[MITRE](#)[NVD](#)[CVE.ORG](#)[JSON API](#)[Print: PDF](#)

Summary

CVE	CVE-2014-8511
State	PUBLISHED
Assigner	mitre
Source Priority	CVE Program / NVD first with legacy fallback
Published	2014-12-27 15:59:00 UTC
Updated	2026-05-06 22:30:45 UTC
Description	Buffer overflow in an ActiveX control in Atx45.ocx in Schneider Electric ProClima before 6.1.7 allows remote attackers to ex

Risk And Classification

Primary CVSS: v2.0 10 from nvd@nist.gov

AV:N/AC:L/Au:N/C:C/I:C/A:C

Problem Types: CWE-119 | n/a

CVSS v2.0 Breakdown

Access Vector

Network

Access Complexity

Low

Authentication

None

Confidentiality

Complete

Integrity

Complete

Availability

Complete

AV:N/AC:L/Au:N/C:C/I:C/A:C

NVD Known Affected Configurations (CPE 2.3)

Type	Vendor	Product	Version	Update	Edition	Language
Application	Schneider-electric	Proclima	All	All	All	All

Vendor Declared Affected Products				
Source	Vendor	Product	Version	Platforms
CNA	Na	N/a	affected n/a	Not specified
References				
Reference			Source	Link
download.schneider-electric.com/files			af854a3a-2127-422b-91ae-364da2661108	download.schneid
Schneider Electric ProClima Command Injection Vulnerabilities ICS-CERT			af854a3a-2127-422b-91ae-364da2661108	ics-cert.us-cert.gov
CVE Program record			CVE.ORG	www.cve.org
NVD vulnerability detail			NVD	nvd.nist.gov
No vendor comments have been submitted for this CVE.				
There are currently no legacy QID mappings associated with this CVE.				