



CVE-2015-6374

Published on: 11/18/2015 12:00:00 AM UTC

Last Modified on: 03/23/2021 11:26:17 PM UTC


CVE-2015-6374

Source: Mitre

Source: NIST

CVE.ORG

Print: PDF



Certain versions of [Firepower Extensible Operating System](#) from [Cisco](#) contain the following vulnerability:

The web interface in Cisco Firepower Extensible Operating System 1.1(1.160) on Firepower 9000 devices does not properly restrict use of IFRAME elements, which makes it easier for remote attackers to conduct clickjacking attacks and unspecified other attacks via a crafted web site, aka Bug ID CSCux10604.

CVE-2015-6374 has been assigned by [Cisco](#) psirt@cisco.com to track the vulnerability

CVSS2 Score: **4.3 - MEDIUM**

Access
Vector

Access
Complexity

Authentication

NETWORK

MEDIUM

NONE

Confidentiality
Impact

Integrity
Impact

Availability
Impact

NONE

PARTIAL

NONE

CVE References

Description

Tags

Link

Cisco Firepower 9000 Series Switch Clickjacking Vulnerability

[Vendor Advisory](#)
[tools.cisco.com](#)
[text/html](#)

[CISCO 20151117 Cisco Firepower 9000 Series Switch Clickjacking Vulnerability](#)

By selecting these links, you may be leaving CVEreport webspace. We have provided these links to other websites because they may have information that would be of interest to you. No inferences should be drawn on account of other sites being referenced, or not, from this page. There may be other websites that are more appropriate for your purpose. CVEreport does not necessarily endorse the views expressed, or concur with the facts presented on these sites. Further, CVEreport does not endorse any commercial products that may be mentioned on these sites. Please address comments about any linked pages to comment@cve.report.

There are currently no QIDs associated with this CVE

Known Affected Configurations (CPE V2.3)						
Type	Vendor	Product	Version	Update	Edition	Language
Operating System	Cisco	Firepower Extensible Operating System	1.1(1.160)	All	All	All
Operating System	Cisco	Firepower Extensible Operating System	1.1\1.160\	All	All	All
Operating System	Cisco	Firepower Extensible Operating System	1.1\1.160\	All	All	All
cpe:2.3:o:cisco:firepower_extensible_operating_system:1.1(1.160):*:~::~:						
cpe:2.3:o:cisco:firepower_extensible_operating_system:1.1\1.160\):*:~::~:						
cpe:2.3:o:cisco:firepower_extensible_operating_system:1.1\1.160\):*:~::~:						
No vendor comments have been submitted for this CVE						
← Previous ID			Next ID →			