



CVE-2015-7287

Published on: 11/24/2015 12:00:00 AM UTC

Last Modified on: 03/23/2021 11:26:11 PM UTC

CVE-2015-7287

Source: Mitre

Source: NIST

CVE.ORG

Print: PDF



Certain versions of [Gprs](#) from [Csl Dualcom](#) contain the following vulnerability:

CSL DualCom GPRS CS2300-R devices with firmware 1.25 through 3.53 use the same 001984 default PIN across different customers' installations, which allows remote attackers to execute commands by leveraging knowledge of this PIN and including it in an SMS message.

CVE-2015-7287 has been assigned by cert@cert.org to track the vulnerability

CVSS2 Score: **7.5 - HIGH**

Access
Vector

NETWORK

Access
Complexity

LOW

Authentication

NONE

Confidentiality
Impact

PARTIAL

Integrity
Impact

PARTIAL

Availability
Impact

PARTIAL

CVE References

Description

Tags

Link

Vulnerability Note VU#428280 - CSL DualCom GPRS CS2300-R alarm signalling boards contain multiple vulnerabilities

[Third Party Advisory](#)
[US Government Resource](#)
www.kb.cert.org
[text/html](#)

[CERT-VN VU#428280](#)

» CSL Dualcom CS2300-R signalling unit vulnerabilities

[Exploit](#)
cybergibbons.com
[text/html](#)

[MISC cybergibbons.com/?p=2844](http://MISC.cybergibbons.com/?p=2844)

VU#428280 - CSL DualCom GPRS CS2300-R alarm signalling boards contain multiple vulnerabilities

[Third Party Advisory](#)
[US Government Resource](#)
www.kb.cert.org
[text/html](#)

[CONFIRM](#)
www.kb.cert.org/vuls/id/BLUU-A3NQAL

By selecting these links, you may be leaving CVEreport webspace. We have provided these links to other websites because they may have information that would be of interest to you. No inferences should be drawn on account of other sites being referenced, or not, from this page. There may be other websites that are more appropriate for your purpose. CVEreport does not necessarily endorse the views expressed, or concur with the facts presented on these sites. Further

are more appropriate for your purpose. CVEreport does not necessarily endorse the views expressed, or concur with the facts presented on these sites. Further, CVEreport does not endorse any commercial products that may be mentioned on these sites. Please address comments about any linked pages to comment@cve.report.

There are currently no QIDs associated with this CVE

Known Affected Configurations (CPE V2.3)

Type	Vendor	Product	Version	Update	Edition	Language
Hardware 	Csl Dualcom	Gprs	cs2300-r	All	All	All
Hardware 	Csl Dualcom	Gprs	cs2300-r	All	All	All
Operating System	Csl Dualcom	Gprs Cs2300-r Firmware	1.25	All	All	All
Operating System	Csl Dualcom	Gprs Cs2300-r Firmware	3.53	All	All	All
Operating System	Csl Dualcom	Gprs Cs2300-r Firmware	1.25	All	All	All
Operating System	Csl Dualcom	Gprs Cs2300-r Firmware	3.53	All	All	All
cpe:2.3:h:csl_dualcom:gprs:cs2300-r:*:*:*:*:*:						
cpe:2.3:h:csl_dualcom:gprs:cs2300-r:*:*:*:*:*:						
cpe:2.3:o:csl_dualcom:gprs_cs2300-r_firmware:1.25:*:*:*:*:*:						
cpe:2.3:o:csl_dualcom:gprs_cs2300-r_firmware:3.53:*:*:*:*:*:						
cpe:2.3:o:csl_dualcom:gprs_cs2300-r_firmware:1.25:*:*:*:*:*:						
cpe:2.3:o:csl_dualcom:gprs_cs2300-r_firmware:3.53:*:*:*:*:*:						

No vendor comments have been submitted for this CVE

[← Previous ID](#)

[Next ID →](#)