



# CVE-2017-12260

[MITRE](#)[NVD](#)[CVE.ORG](#)[Print: PDF !\[\]\(e3f8612927870f2e0f9f5989e6dd3064\_img.jpg\)](#)

## Summary

<b>CVE</b>	CVE-2017-12260
<b>State</b>	PUBLIC
<b>Assigner</b>	psirt@cisco.com
<b>Source Priority</b>	CVE Program / NVD first with legacy fallback
<b>Published</b>	2017-10-19 08:29:00 UTC
<b>Updated</b>	2019-10-09 23:22:00 UTC
<b>Description</b>	A vulnerability in the implementation of Session Initiation Protocol (SIP) functionality in Cisco Small Business SPA50x, SPA

## Risk And Classification

**Problem Types: CWE-119**

## NVD Known Affected Configurations (CPE 2.3)

Type	Vendor	Product	Version	Update	Edition	Language
Hardware	Cisco	Spa 501g	-	All	All	All
Hardware	Cisco	Spa 501g	-	All	All	All
Operating System	Cisco	Spa 501g Firmware	All	sr1	All	All
Hardware	Cisco	Spa 502g	-	All	All	All
Hardware	Cisco	Spa 502g	-	All	All	All
Operating System	Cisco	Spa 502g Firmware	All	sr1	All	All
Hardware	Cisco	Spa 504g	-	All	All	All
Hardware	Cisco	Spa 504g	-	All	All	All
Operating System	Cisco	Spa 504g Firmware	All	sr1	All	All
Hardware	Cisco	Spa 508g	-	All	All	All
Hardware	Cisco	Spa 508g	-	All	All	All
Operating System	Cisco	Spa 508g Firmware	All	sr1	All	All
Hardware	Cisco	Spa 509g	-	All	All	All
Hardware	Cisco	Spa 509g	-	All	All	All
Operating System	Cisco	Spa 509g Firmware	All	sr1	All	All
Hardware	Cisco	Spa 512g	-	All	All	All
Hardware	Cisco	Spa 512g	-	All	All	All

Operating System	<a href="#">Cisco</a>	<a href="#">Spa 512g Firmware</a>	All	sr1	All	All
Hardware	<a href="#">Cisco</a>	<a href="#">Spa 514g</a>	-	All	All	All
Hardware	<a href="#">Cisco</a>	<a href="#">Spa 514g</a>	-	All	All	All
Operating System	<a href="#">Cisco</a>	<a href="#">Spa 514g Firmware</a>	All	sr1	All	All
Hardware	<a href="#">Cisco</a>	<a href="#">Spa 525g</a>	-	All	All	All
Hardware	<a href="#">Cisco</a>	<a href="#">Spa 525g</a>	-	All	All	All
Operating System	<a href="#">Cisco</a>	<a href="#">Spa 525g Firmware</a>	All	sr1	All	All

## References

### Reference

[Cisco Small Business SPA50x, SPA51x, and SPA52x Series IP Phones SIP Denial of Service Vulnerability](#)

[Cisco Small Business SPA50x/SPA51x/SPA52x Series IP Phones SIP Processing Flaw Lets Remote Users Deny Service - SecurityTracker](#)

[Cisco Small Business SPA50x, SPA51x, and SPA52x Series IP Phones Denial of Service Vulnerability](#)

[CVE Program record](#)

[NVD vulnerability detail](#)



No vendor comments have been submitted for this CVE.

There are currently no legacy QID mappings associated with this CVE.

© [CVE.report](#) 2026 |

Use of this information constitutes acceptance for use in an AS IS condition. There are NO warranties, implied or otherwise, with regard to this information or its use. Any use of this information is at the user's risk. It is the responsibility of user to evaluate the accuracy, completeness or usefulness of any information, opinion, advice or other content. EACH USER WILL BE SOLELY RESPONSIBLE FOR ANY consequences of his or her direct or indirect use of this web site. ALL WARRANTIES OF ANY KIND ARE EXPRESSLY DISCLAIMED. This site will NOT BE LIABLE FOR ANY DIRECT, INDIRECT or any other kind of loss.

CVE, CWE, and OVAL are registered trademarks of [The MITRE Corporation](#) and the authoritative source of CVE content is [MITRE's CVE web site](#). This site includes MITRE data granted under the following [license](#).

**CVE.report and Source URL Uptime Status** [status.cve.report](#)