




CVE-2017-14335

Published on: 09/12/2017 12:00:00 AM UTC

Last Modified on: 03/23/2021 11:26:44 PM UTC

CVE-2017-14335

[Source: Mitre](#)[Source: NIST](#)[CVE.ORG](#)[Print: PDF](#) 

Certain versions of **7204xr** from **Hbgk** contain the following vulnerability:

On Beijing Hanbang Hanbanggaoke devices, because user-controlled input is not sufficiently sanitized, sending a PUT request to /ISAPI/Security/users/1 allows an admin password change.

CVE-2017-14335 has been assigned by [M](#) cve@mitre.org to track the vulnerability - currently rated as **HIGH** severity.

CVSS3 Score: **7.5 - HIGH**

Attack Vector	Attack Complexity	Privileges Required	User Interaction
NETWORK	LOW	NONE	NONE
Scope	Confidentiality Impact	Integrity Impact	Availability Impact
UNCHANGED	NONE	HIGH	NONE

CVSS2 Score: **5 - MEDIUM**

Access Vector	Access Complexity	Authentication
NETWORK	LOW	NONE
Confidentiality Impact	Integrity Impact	Availability Impact
NONE	PARTIAL	NONE

CVE References

Description	Tags	Link
401 Authorization Required	Exploit Third Party Advisory blogs.securiteam.com text/html Inactive Link Not Archived	MISC blogs.securiteam.com/index.php/archives/3420

By selecting these links, you may be leaving CVEreport webspace. We have provided these links to other websites because they may have information that would be of interest to you. No inferences should be drawn on account of other sites being referenced, or not, from this page. There may be other websites that are more appropriate for your purpose. CVEreport does not necessarily endorse the views expressed, or concur with the facts presented on these sites. Further, CVEreport does not endorse any commercial products that may be mentioned on these sites. Please address comments about any linked pages to comment@cve.report.

There are currently no QIDs associated with this CVE

Known Affected Configurations (CPE V2.3)

Type	Vendor	Product	Version	Update	Edition	Language
Hardware  	Hbgk	7204xr	-	All	All	All
Hardware  	Hbgk	7204xr	-	All	All	All
Operating System	Hbgk	7204xr Firmware	-	All	All	All
Operating System	Hbgk	7204xr Firmware	-	All	All	All
Hardware  	Hbgk	7208xr	-	All	All	All
Hardware  	Hbgk	7208xr	-	All	All	All
Operating System	Hbgk	7208xr Firmware	-	All	All	All
Operating System	Hbgk	7208xr Firmware	-	All	All	All
Hardware  	Hbgk	7216xr	-	All	All	All
Hardware  	Hbgk	7216xr	-	All	All	All
Operating System	Hbgk	7216xr Firmware	-	All	All	All
Operating System	Hbgk	7216xr Firmware	-	All	All	All
Hardware  	Hbgk	Hb7004k	-	All	All	All
Hardware  	Hbgk	Hb7004k	-	All	All	All
Hardware  	Hbgk	Hb7004kh	-	All	All	All
Hardware  	Hbgk	Hb7004kh	-	All	All	All
Operating System	Hbgk	Hb7004kh Firmware	-	All	All	All
Operating System	Hbgk	Hb7004kh Firmware	-	All	All	All
Operating System	Hbgk	Hb7004k Firmware	-	All	All	All
Operating System	Hbgk	Hb7004k Firmware	-	All	All	All
Hardware  	Hbgk	Hb7008k	-	All	All	All

Hardware 	Hbgk	Hb7008kc	-	All	All	All
Hardware 	Hbgk	Hb7008kc	-	All	All	All
Hardware 	Hbgk	Hb7008kce	-	All	All	All
Hardware 	Hbgk	Hb7008kce	-	All	All	All
Operating System	Hbgk	Hb7008kce Firmware	-	All	All	All
Operating System	Hbgk	Hb7008kce Firmware	-	All	All	All
Operating System	Hbgk	Hb7008kc Firmware	-	All	All	All
Operating System	Hbgk	Hb7008kc Firmware	-	All	All	All
Hardware 	Hbgk	Hb7008kh	-	All	All	All
Hardware 	Hbgk	Hb7008kh	-	All	All	All
Hardware 	Hbgk	Hb7008khe	-	All	All	All
Hardware 	Hbgk	Hb7008khe	-	All	All	All
Operating System	Hbgk	Hb7008khe Firmware	-	All	All	All
Operating System	Hbgk	Hb7008khe Firmware	-	All	All	All
Operating System	Hbgk	Hb7008kh Firmware	-	All	All	All
Operating System	Hbgk	Hb7008kh Firmware	-	All	All	All
Hardware 	Hbgk	Hb7008t2	-	All	All	All
Hardware 	Hbgk	Hb7008t2	-	All	All	All
Operating System	Hbgk	Hb7008t2 Firmware	-	All	All	All
Operating System	Hbgk	Hb7008t2 Firmware	-	All	All	All
Hardware 	Hbgk	Hb7016lc	-	All	All	All
Hardware 	Hbgk	Hb7016lc	-	All	All	All
Operating System	Hbgk	Hb7016lc Firmware	-	All	All	All
Operating System	Hbgk	Hb7016lc Firmware	-	All	All	All
Hardware 	Hbgk	Hb7016lh	-	All	All	All
Hardware 	Hbgk	Hb7016lh	-	All	All	All
Operating System	Hbgk	Hb7016lh Firmware	-	All	All	All

Operating System	Hbgk	Hb7016lh Firmware	-	All	All	All
Hardware  	Hbgk	Hb7016t2	-	All	All	All
Hardware  	Hbgk	Hb7016t2	-	All	All	All
Operating System	Hbgk	Hb7016t2 Firmware	-	All	All	All
Operating System	Hbgk	Hb7016t2 Firmware	-	All	All	All
Hardware  	Hbgk	Hb7024xt	-	All	All	All
Hardware  	Hbgk	Hb7024xt	-	All	All	All
Operating System	Hbgk	Hb7024xt Firmware	-	All	All	All
Operating System	Hbgk	Hb7024xt Firmware	-	All	All	All
Hardware  	Hbgk	Hb7032xt	-	All	All	All
Hardware  	Hbgk	Hb7032xt	-	All	All	All
Operating System	Hbgk	Hb7032xt Firmware	-	All	All	All
Operating System	Hbgk	Hb7032xt Firmware	-	All	All	All
Hardware  	Hbgk	Hb7108x3	-	All	All	All
Hardware  	Hbgk	Hb7108x3	-	All	All	All
Operating System	Hbgk	Hb7108x3 Firmware	-	All	All	All
Operating System	Hbgk	Hb7108x3 Firmware	-	All	All	All
Hardware  	Hbgk	Hb7116x3	-	All	All	All
Hardware  	Hbgk	Hb7116x3	-	All	All	All
Operating System	Hbgk	Hb7116x3 Firmware	-	All	All	All
Operating System	Hbgk	Hb7116x3 Firmware	-	All	All	All
Hardware  	Hbgk	Hb7204kk	-	All	All	All
Hardware  	Hbgk	Hb7204kk	-	All	All	All
Operating System	Hbgk	Hb7204kk Firmware	-	All	All	All
Operating System	Hbgk	Hb7204kk Firmware	-	All	All	All
Hardware  	Hbgk	Hb7204kl	-	All	All	All
Hardware  	Hbgk	Hb7204kl	-	All	All	All

Hardware 	Hbgk	Hb7204M	-	All	All	All
Operating System	Hbgk	Hb7204kl Firmware	-	All	All	All
Operating System	Hbgk	Hb7204kl Firmware	-	All	All	All
Hardware 	Hbgk	Hb7204x	-	All	All	All
Hardware 	Hbgk	Hb7204x	-	All	All	All
Hardware 	Hbgk	Hb7204xt	-	All	All	All
Hardware 	Hbgk	Hb7204xt	-	All	All	All
Operating System	Hbgk	Hb7204xt Firmware	-	All	All	All
Operating System	Hbgk	Hb7204xt Firmware	-	All	All	All
Operating System	Hbgk	Hb7204x Firmware	-	All	All	All
Operating System	Hbgk	Hb7204x Firmware	-	All	All	All
Hardware 	Hbgk	Hb7208x	-	All	All	All
Hardware 	Hbgk	Hb7208x	-	All	All	All
Hardware 	Hbgk	Hb7208x3	-	All	All	All
Hardware 	Hbgk	Hb7208x3	-	All	All	All
Operating System	Hbgk	Hb7208x3 Firmware	-	All	All	All
Operating System	Hbgk	Hb7208x3 Firmware	-	All	All	All
Hardware 	Hbgk	Hb7208xt	-	All	All	All
Hardware 	Hbgk	Hb7208xt	-	All	All	All
Operating System	Hbgk	Hb7208xt Firmware	-	All	All	All
Operating System	Hbgk	Hb7208xt Firmware	-	All	All	All
Operating System	Hbgk	Hb7208x Firmware	-	All	All	All
Operating System	Hbgk	Hb7208x Firmware	-	All	All	All
Hardware 	Hbgk	Hb7216x	-	All	All	All
Hardware 	Hbgk	Hb7216x	-	All	All	All
Hardware 	Hbgk	Hb7216x3	-	All	All	All
Hardware 	Hbgk	Hb7216x3	-	All	All	All

Operating System	Hbgk	Hb7216x3 Firmware	-	All	All	All
Operating System	Hbgk	Hb7216x3 Firmware	-	All	All	All
Hardware 	Hbgk	Hb7216xt	-	All	All	All
Hardware 	Hbgk	Hb7216xt	-	All	All	All
Operating System	Hbgk	Hb7216xt Firmware	-	All	All	All
Operating System	Hbgk	Hb7216xt Firmware	-	All	All	All
Operating System	Hbgk	Hb7216x Firmware	-	All	All	All
Operating System	Hbgk	Hb7216x Firmware	-	All	All	All
Hardware 	Hbgk	Hb7904	-	All	All	All
Hardware 	Hbgk	Hb7904	-	All	All	All
Hardware 	Hbgk	Hb7904x	-	All	All	All
Hardware 	Hbgk	Hb7904x	-	All	All	All
Operating System	Hbgk	Hb7904x Firmware	-	All	All	All
Operating System	Hbgk	Hb7904x Firmware	-	All	All	All
Operating System	Hbgk	Hb7904 Firmware	-	All	All	All
Operating System	Hbgk	Hb7904 Firmware	-	All	All	All
Hardware 	Hbgk	Hb7908	-	All	All	All
Hardware 	Hbgk	Hb7908	-	All	All	All
Hardware 	Hbgk	Hb7908x	-	All	All	All
Hardware 	Hbgk	Hb7908x	-	All	All	All
Operating System	Hbgk	Hb7908x Firmware	-	All	All	All
Operating System	Hbgk	Hb7908x Firmware	-	All	All	All
Operating System	Hbgk	Hb7908 Firmware	-	All	All	All
Operating System	Hbgk	Hb7908 Firmware	-	All	All	All
Hardware 	Hbgk	Hb7916s	-	All	All	All
Hardware 	Hbgk	Hb7916s	-	All	All	All
Hardware 	Hbgk	Hb7916rev	-	All	All	All

Hardware  	Hbgk	Hb7916sx	-	All	All	All
Hardware  	Hbgk	Hb7916sx	-	All	All	All
Operating System	Hbgk	Hb7916sx Firmware	-	All	All	All
Operating System	Hbgk	Hb7916sx Firmware	-	All	All	All
Operating System	Hbgk	Hb7916s Firmware	-	All	All	All
Operating System	Hbgk	Hb7916s Firmware	-	All	All	All
Hardware  	Hbgk	Hb8004	-	All	All	All
Hardware  	Hbgk	Hb8004	-	All	All	All
Hardware  	Hbgk	Hb8004r	-	All	All	All
Hardware  	Hbgk	Hb8004r	-	All	All	All
Operating System	Hbgk	Hb8004r Firmware	-	All	All	All
Operating System	Hbgk	Hb8004r Firmware	-	All	All	All
Operating System	Hbgk	Hb8004 Firmware	-	All	All	All
Operating System	Hbgk	Hb8004 Firmware	-	All	All	All
Hardware  	Hbgk	Hb8008	-	All	All	All
Hardware  	Hbgk	Hb8008	-	All	All	All
Hardware  	Hbgk	Hb8008r	-	All	All	All
Hardware  	Hbgk	Hb8008r	-	All	All	All
Operating System	Hbgk	Hb8008r Firmware	-	All	All	All
Operating System	Hbgk	Hb8008r Firmware	-	All	All	All
Operating System	Hbgk	Hb8008 Firmware	-	All	All	All
Operating System	Hbgk	Hb8008 Firmware	-	All	All	All
Hardware  	Hbgk	Hb8016	-	All	All	All
Hardware  	Hbgk	Hb8016	-	All	All	All
Hardware  	Hbgk	Hb8016r	-	All	All	All
Hardware  	Hbgk	Hb8016r	-	All	All	All
Operating System	Hbgk	Hb8016r Firmware	-	All	All	All

Operating System	Hbgk	Hb8016r Firmware	-	All	All	All
Operating System	Hbgk	Hb8016 Firmware	-	All	All	All
Operating System	Hbgk	Hb8016 Firmware	-	All	All	All
Hardware 	Hbgk	Hb8204h	-	All	All	All
Hardware 	Hbgk	Hb8204h	-	All	All	All
Hardware 	Hbgk	Hb8204hr	-	All	All	All
Hardware 	Hbgk	Hb8204hr	-	All	All	All
Operating System	Hbgk	Hb8204hr Firmware	-	All	All	All
Operating System	Hbgk	Hb8204hr Firmware	-	All	All	All
Operating System	Hbgk	Hb8204h Firmware	-	All	All	All
Operating System	Hbgk	Hb8204h Firmware	-	All	All	All
Hardware 	Hbgk	Hb8208h	-	All	All	All
Hardware 	Hbgk	Hb8208h	-	All	All	All
Hardware 	Hbgk	Hb8208hr	-	All	All	All
Hardware 	Hbgk	Hb8208hr	-	All	All	All
Operating System	Hbgk	Hb8208hr Firmware	-	All	All	All
Operating System	Hbgk	Hb8208hr Firmware	-	All	All	All
Operating System	Hbgk	Hb8208h Firmware	-	All	All	All
Operating System	Hbgk	Hb8208h Firmware	-	All	All	All
Hardware 	Hbgk	Hb8208x3	-	All	All	All
Hardware 	Hbgk	Hb8208x3	-	All	All	All
Operating System	Hbgk	Hb8208x3 Firmware	-	All	All	All
Operating System	Hbgk	Hb8208x3 Firmware	-	All	All	All
Hardware 	Hbgk	Hb8216h	-	All	All	All
Hardware 	Hbgk	Hb8216h	-	All	All	All
Hardware 	Hbgk	Hb8216hr	-	All	All	All
Hardware 	Hbgk	Hb8216hr	-	All	All	All

Hardware  	Hbgk	Hb8216hr	-	All	All	All
Operating System	Hbgk	Hb8216hr Firmware	-	All	All	All
Operating System	Hbgk	Hb8216hr Firmware	-	All	All	All
Operating System	Hbgk	Hb8216h Firmware	-	All	All	All
Operating System	Hbgk	Hb8216h Firmware	-	All	All	All
Hardware  	Hbgk	Hb8216x3	-	All	All	All
Hardware  	Hbgk	Hb8216x3	-	All	All	All
Operating System	Hbgk	Hb8216x3 Firmware	-	All	All	All
Operating System	Hbgk	Hb8216x3 Firmware	-	All	All	All
Hardware  	Hbgk	Hb8608x3	-	All	All	All
Hardware  	Hbgk	Hb8608x3	-	All	All	All
Operating System	Hbgk	Hb8608x3 Firmware	-	All	All	All
Operating System	Hbgk	Hb8608x3 Firmware	-	All	All	All
Hardware  	Hbgk	Hb8616x3	-	All	All	All
Hardware  	Hbgk	Hb8616x3	-	All	All	All
Operating System	Hbgk	Hb8616x3 Firmware	-	All	All	All
Operating System	Hbgk	Hb8616x3 Firmware	-	All	All	All
Hardware  	Hbgk	Hb8808x3	-	All	All	All
Hardware  	Hbgk	Hb8808x3	-	All	All	All
Operating System	Hbgk	Hb8808x3 Firmware	-	All	All	All
Operating System	Hbgk	Hb8808x3 Firmware	-	All	All	All
Hardware  	Hbgk	Hb8816x3	-	All	All	All
Hardware  	Hbgk	Hb8816x3	-	All	All	All
Operating System	Hbgk	Hb8816x3 Firmware	-	All	All	All
Operating System	Hbgk	Hb8816x3 Firmware	-	All	All	All
Hardware  	Hbgk	Hb9012x3	-	All	All	All
Hardware  	Hbgk	Hb9012x3	-	All	All	All

Operating System	Hbgk	Hb9012x3 Firmware	-	All	All	All
Operating System	Hbgk	Hb9012x3 Firmware	-	All	All	All
Hardware 	Hbgk	Hb9020x3	-	All	All	All
Hardware 	Hbgk	Hb9020x3	-	All	All	All
Operating System	Hbgk	Hb9020x3 Firmware	-	All	All	All
Operating System	Hbgk	Hb9020x3 Firmware	-	All	All	All
Hardware 	Hbgk	Hb9212x3	-	All	All	All
Hardware 	Hbgk	Hb9212x3	-	All	All	All
Operating System	Hbgk	Hb9212x3 Firmware	-	All	All	All
Operating System	Hbgk	Hb9212x3 Firmware	-	All	All	All
Hardware 	Hbgk	Hb9220x3	-	All	All	All
Hardware 	Hbgk	Hb9220x3	-	All	All	All
Operating System	Hbgk	Hb9220x3 Firmware	-	All	All	All
Operating System	Hbgk	Hb9220x3 Firmware	-	All	All	All
Hardware 	Hbgk	Hb9404x3	-	All	All	All
Hardware 	Hbgk	Hb9404x3	-	All	All	All
Operating System	Hbgk	Hb9404x3 Firmware	-	All	All	All
Operating System	Hbgk	Hb9404x3 Firmware	-	All	All	All
Hardware 	Hbgk	Hb9408x3	-	All	All	All
Hardware 	Hbgk	Hb9408x3	-	All	All	All
Operating System	Hbgk	Hb9408x3 Firmware	-	All	All	All
Operating System	Hbgk	Hb9408x3 Firmware	-	All	All	All
Hardware 	Hbgk	Hb9604x3	-	All	All	All
Hardware 	Hbgk	Hb9604x3	-	All	All	All
Operating System	Hbgk	Hb9604x3 Firmware	-	All	All	All
Operating System	Hbgk	Hb9604x3 Firmware	-	All	All	All

Hardware  	Hbgk	Hb9608x3	-	All	All	All
Hardware  	Hbgk	Hb9608x3	-	All	All	All
Operating System	Hbgk	Hb9608x3 Firmware	-	All	All	All
Operating System	Hbgk	Hb9608x3 Firmware	-	All	All	All
Hardware  	Hbgk	Hb9808n04	-	All	All	All
Hardware  	Hbgk	Hb9808n04	-	All	All	All
Operating System	Hbgk	Hb9808n04 Firmware	-	All	All	All
Operating System	Hbgk	Hb9808n04 Firmware	-	All	All	All
Hardware  	Hbgk	Hb9816n08	-	All	All	All
Hardware  	Hbgk	Hb9816n08	-	All	All	All
Operating System	Hbgk	Hb9816n08 Firmware	-	All	All	All
Operating System	Hbgk	Hb9816n08 Firmware	-	All	All	All
Hardware  	Hbgk	Hb9824n16	-	All	All	All
Hardware  	Hbgk	Hb9824n16	-	All	All	All
Operating System	Hbgk	Hb9824n16 Firmware	-	All	All	All
Operating System	Hbgk	Hb9824n16 Firmware	-	All	All	All
Hardware  	Hbgk	Hb9832n16	-	All	All	All
Hardware  	Hbgk	Hb9832n16	-	All	All	All
Operating System	Hbgk	Hb9832n16 Firmware	-	All	All	All
Operating System	Hbgk	Hb9832n16 Firmware	-	All	All	All
Hardware  	Hbgk	Hb9904	-	All	All	All
Hardware  	Hbgk	Hb9904	-	All	All	All
Operating System	Hbgk	Hb9904 Firmware	-	All	All	All
Operating System	Hbgk	Hb9904 Firmware	-	All	All	All
Hardware  	Hbgk	Hb9908	-	All	All	All
Hardware  	Hbgk	Hb9908	-	All	All	All
Operating	Hbgk	Hb9908 Firmware	-	All	All	All

System						
Operating System	Hbgk	Hb9908 Firmware	-	All	All	All
Hardware 🇵🇪 ↗️	Hbgk	Hb9912	-	All	All	All
Hardware 🇵🇪 ↗️	Hbgk	Hb9912	-	All	All	All
Operating System	Hbgk	Hb9912 Firmware	-	All	All	All
Operating System	Hbgk	Hb9912 Firmware	-	All	All	All
Hardware 🇵🇪 ↗️	Hbgk	Hb9916	-	All	All	All
Hardware 🇵🇪 ↗️	Hbgk	Hb9916	-	All	All	All
Operating System	Hbgk	Hb9916 Firmware	-	All	All	All
Operating System	Hbgk	Hb9916 Firmware	-	All	All	All
Hardware 🇵🇪 ↗️	Hbgk	Hb9924	-	All	All	All
Hardware 🇵🇪 ↗️	Hbgk	Hb9924	-	All	All	All
Operating System	Hbgk	Hb9924 Firmware	-	All	All	All
Operating System	Hbgk	Hb9924 Firmware	-	All	All	All
Hardware 🇵🇪 ↗️	Hbgk	Hb9932	-	All	All	All
Hardware 🇵🇪 ↗️	Hbgk	Hb9932	-	All	All	All
Operating System	Hbgk	Hb9932 Firmware	-	All	All	All
Operating System	Hbgk	Hb9932 Firmware	-	All	All	All
<code>cpe:2.3:h:hbgk:7204xr:-:*:*:*:*:*:</code>						
<code>cpe:2.3:h:hbgk:7204xr:-:*:*:*:*:*:</code>						
<code>cpe:2.3:o:hbgk:7204xr_firmware:-:*:*:*:*:*:</code>						
<code>cpe:2.3:o:hbgk:7204xr_firmware:-:*:*:*:*:*:</code>						
<code>cpe:2.3:h:hbgk:7208xr:-:*:*:*:*:*:</code>						
<code>cpe:2.3:h:hbgk:7208xr:-:*:*:*:*:*:</code>						
<code>cpe:2.3:o:hbgk:7208xr_firmware:-:*:*:*:*:*:</code>						
<code>cpe:2.3:o:hbgk:7208xr_firmware:-:*:*:*:*:*:</code>						
<code>cpe:2.3:h:hbgk:7216xr:-:*:*:*:*:*:</code>						

cpe:2.3:h:hbgek:7216xr:-:~::~:
cpe:2.3:o:hbgek:7216xr_firmware:-:~::~:
cpe:2.3:o:hbgek:7216xr_firmware:-:~::~:
cpe:2.3:h:hbgek:hb7004k:-:~::~:
cpe:2.3:h:hbgek:hb7004k:-:~::~:
cpe:2.3:h:hbgek:hb7004kh:-:~::~:
cpe:2.3:h:hbgek:hb7004kh:-:~::~:
cpe:2.3:o:hbgek:hb7004kh_firmware:-:~::~:
cpe:2.3:o:hbgek:hb7004kh_firmware:-:~::~:
cpe:2.3:o:hbgek:hb7004k_firmware:-:~::~:
cpe:2.3:o:hbgek:hb7004k_firmware:-:~::~:
cpe:2.3:h:hbgek:hb7008kc:-:~::~:
cpe:2.3:h:hbgek:hb7008kc:-:~::~:
cpe:2.3:h:hbgek:hb7008kce:-:~::~:
cpe:2.3:h:hbgek:hb7008kce:-:~::~:
cpe:2.3:o:hbgek:hb7008kce_firmware:-:~::~:
cpe:2.3:o:hbgek:hb7008kce_firmware:-:~::~:
cpe:2.3:o:hbgek:hb7008kc_firmware:-:~::~:
cpe:2.3:o:hbgek:hb7008kc_firmware:-:~::~:
cpe:2.3:h:hbgek:hb7008kh:-:~::~:
cpe:2.3:h:hbgek:hb7008kh:-:~::~:
cpe:2.3:h:hbgek:hb7008khe:-:~::~:
cpe:2.3:h:hbgek:hb7008khe:-:~::~:
cpe:2.3:o:hbgek:hb7008khe_firmware:-:~::~:
cpe:2.3:o:hbgek:hb7008khe_firmware:-:~::~:
cpe:2.3:o:hbgek:hb7008kh_firmware:-:~::~:
cpe:2.3:o:hbgek:hb7008kh_firmware:-:~::~:
cpe:2.3:h:hbgek:hb7008t2:-:~::~:
cpe:2.3:h:hbgek:hb7008t2:-:~::~:

```
cpe:2.3:o:hbgk:hb7008t2_firmware:-:*:*:*:*:*.*
```

```
cpe:2.3:o:hbgek:hb7008t2_firmware:-:*:*:*:*:*:*
```

cpe:2.3:h:hbgbk:hb7016lc:-:*:*:*:*:*:*:

cpe:2.3:h:hbgbk:hb7016lc:-:*:*:*:*:*:

```
cpe:2.3:o:hbgek:hb7016lc_firmware:-:*:*:*:*:*:
```

cpe:2.3:o:hbgek:hb7016lc_firmware:-:*:*:*:*:*:

cpe:2.3:h:hbgek:hb7016lh:-:*:*:*:*:*:*:

cpe:2.3:h:hbgbk:hb7016lh:-:*:*:*:*:*:*:

```
cpe:2.3:o:hbqk:hb7016lh firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:hbqk:hb7016lh firmware:-:*:*:*:*:*:
```

cpe:2.3:h:hbgek:hb7016t2:-:*:*:*:*:*:*:

cpe:2.3:h:hbgek:hb7016t2:-:*:*:*:*:*:

cpe:2.3:o:hbgek:hb7016t2_firmware:-:*:*:*:*:*:

cpe:2.3:o:hbgek:hb7016t2_firmware:-:*:*:*:*:*:

cpe:2.3:h:hbgek:hb7024xt:-:*:*:*:*:*:

cpe:2.3:h:hbgbk:hb7024xt:-:*:*:*:*:*:*:

cpe:2.3:o:hbgek:hb7024xt_firmware:-:*:*:*:*:*:

cpe:2.3:o:hbgek:hb7024xt_firmware:-:*:*:*:*:*:

cpe:2.3:h:hbgek:hb7032xt:-:*:*:*:*:*:*:

cpe:2.3:h:hbgek:hb7032xt:-:*:*:*:*:*:*:

cpe:2.3:o:hbgek:hb7032xt_firmware:-:*:*:*:*:*:

cpe:2.3:o:hbgbk:hb7032xt_firmware:-:*:*:*:*:*:*:

cpe:2.3:h:hbgek:hb7108x3:-:*:*:*:*:*:*:

cpe:2.3:h:hbqk:hb7108x3:-:*:*:*:*:*:

```
cpe:2.3:o:hbgek:hb7108x3_firmware:-:*:*:*:*:*:*:
```

```
cpe:2.3:o:hbgk:hb7108x3_firmware:-:*:*:*:*.*
```

cpe:2.3:h:hbgek:hb7116x3:-:*:*:*:*:*:*:

cpe:2.3:h:hbqk:hb7116x3:-:*:*:*:*:*:*:

cpe:2.3:o:hbgek:hb7116x3_firmware:-:*:*:*:*:*:

cpe:2.3:o:hbgek:hb7116x3_firmware:-:*:*:*:*:*:

cpe:2.3:h:hbgek:hb7204kk:-:*:*:*:*:*:*:

cpe:2.3:h:hbgek:hb7204kk:-:*:*:*:*:*:*:

cpe:2.3:o:hbgek:hb7204kk_firmware:-:*:*:*:*:*:*:

cpe:2.3:o:hbgk:hb7204kk_firmware:-:*:*:*:*:*:

cpe:2.3:h:hbgek:hb7204kl:-:*:*:*:*:*:*:

cpe:2.3:h:hbqk:hb7204kl:-:*:*:*:*:*:*:

```
cpe:2.3:o:hbqk:hb7204kl_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:hbqk:hb7204kl_firmware:-:*:*:*:*:*:
```

cpe:2.3:h:hbgek:hb7204x:-:*:*:*:*:*:*:

cpe:2.3:h:hbgek:hb7204x:-:*:*:*:*:*:*:

cpe:2.3:h:hbqk:hb7204xt:-:*:*:*:*:*:

cpe:2.3:h:hbgek:hb7204xt:-:*:*:*:*:*:

```
cpe:2.3:o:hbgek:hb7204xt_firmware:-:~::~~::~~::~~::~~::~~::~::
```

cpe:2.3:o:hbgek:hb7204xt_firmware:-:*:*:*:*:*:

```
cpe:2.3:o:hbqk:hb7204x_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:hbqk:hb7204x_firmware:-:*:*:*:*:*:
```

cpe:2.3:h:hbgek:hb7208x:-:*:*:*:*:*:*:

cpe:2.3:h:hbgek:hb7208x:-:*:*:*:*:*:*:

cpe:2.3:h:hbgek:hb7208x3:-:*:*:*:*:*:*:

cpe:2.3:h:hbqk:hb7208x3:-:*:*:*:*:*:*:

```
cpe:2.3:o:hbqk:hb7208x3 firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:hbqk:hb7208x3_firmware:-:*:*:*:*:*:
```

cpe:2.3:h:hbgek:hb7208xt:-:*:*:*:*:*:*:

cpe:2.3:h:hbgek:hb7208xt:-:*:*:*:*:*:*:

```
cpe:2.3:o:hbqk:hb7208xt firmware:-:~::~::~:
```

```
cpe:2.3:o:hbqk:hb7208xt_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:bbk:bb7208x_firmware:*.*.*.*.*.*.*
```

[illegible]

```
cpe:2.3:o:hbqk:hb7208x firmware:-:*:*:*:*:*:
```

cpe:2.3:h:hbgk:hb7216x:-:*:*:*:*:*:*:

cpe:2.3:h:hbgek:hb7216x:-:*:*:*:*:*:*:

cpe:2.3:h:hbqk:hb7216x3:-:*:*:*:*:*:*:

cpe:2.3:h:hbqk:hb7216x3:-:*:*:*:*:*:*:

```
cpe:2.3:o:hbqk:hb7216x3_firmware:-:*:*:*:*:*:
```

cpe:2.3:o:hbgek:hb7216x3_firmware:-:*:*:*:*:*:*:

cpe:2.3:h:hbgbk:hb7216xt:-:*:*:*:*:*:*:

cpe:2.3:h:hbgek:hb7216xt:-:*:*:*:*:*:*:

```
cpe:2.3:o:hbqk:hb7216xt firmware:-:*:*:*:*:*:*:
```

```
cpe:2.3:o:hbqk:hb7216xt firmware:-:*:*:*:*:*:*:
```

```
cpe:2.3:o:hbgek:hb7216x_firmware:-:*:*:*:*:*:
```

cpe:2.3:o:hbgek:hb7216x_firmware:-:*:*:*:*:*:*:

cpe:2.3:h:hbgek:hb7904:-:*:*:*:*:*:*:

cpe:2.3:h:hbqk:hb7904:-:*:*:*:*:*:*:

cpe:2.3:h:hbqk:hb7904x:-:*:*:*:*:*:*:

cpe:2.3:h:hbqk:hb7904x:-:*:*:*:*:*:*:

cpe:2.3:o:hbgek:hb7904x_firmware:-:*:*:*:*:*:*:

```
cpe:2.3:o:hbqk:hb7904x firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:hbqk:hb7904 firmware:-:*:*:*:*:*:*
```

cpe:2.3:o:hbgek:hb7904_firmware:-:*:*:*:*:*:*:

cpe:2.3:h:hbgek:hb7908:-:*:*:*:*:*:*:

cpe:2.3:h:hbgek:hb7908:-:*:*:*:*:*:*:

cpe:2.3:h:hbqk:hb7908x:-:*:*:*:*:*:*:

cpe:2.3:h:hbqk:hb7908x:-:*:*:*:*:*:*:

```
cpe:2.3:o:hbqk:hb7908x firmware:-:*:*:*:*:*:
```

cpe:2.3:o:hbgek:hb7908x_firmware:-:*:*:*:*:*:*:

cpe:2.3:o:hbgek:hb7908_firmware:-:*:*:*:*:*:*:

cpe:2.3:o:hbgbk:hb7908_firmware:-:*:*:*:*:*:*:

cpe:2.3:h:hbgek:hb7916s:-:*:*:*:*:*:*:

cpe:2.3:h:hbgek:hb7916s:-:*:*:*:*:*:*:

cpe:2.3:h:hbgbk:hb7916sx:-:*:*:*:*:*:*:

cpe:2.3:h:hbgbk:hb7916sx:-:*:*:*:*:*:*:

cpe:2.3:o:hbkg:hb7916sx_firmware:-:*:*:*:*:*:

cpe:2.3:o:hbkg:hb7916sx_firmware:-:*:*:*:*:*:

cpe:2.3:o:hbgek:hb7916s_firmware:-:*:*:*:*:*:

cpe:2.3:o:hbgek:hb7916s_firmware:-:*:*:*:*:*:

cpe:2.3:h:hbgek:hb8004:-:*:*:*:*:*:*:

cpe:2.3:h:hbgek:hb8004:-:*:*:*:*:*:*:

cpe:2.3:h:hbgek:hb8004r:-:*:*:*:*:*:*:

cpe:2.3:h:hbgek:hb8004r:-:*:*:*:*:*:*:

cpe:2.3:o:hbgbk:hb8004r_firmware:-:*:*:*:*:*:

cpe:2.3:o:hbgek:hb8004r_firmware:-:*:*:*:*:*:*:

cpe:2.3:o:hbgek:hb8004_firmware:-:*:*:*:*:*:*:

cpe:2.3:o:hbgek:hb8004_firmware:-:*:*:*:*:*:

cpe:2.3:h:hbgek:hb8008:-:*:*:*:*:*:*:

cpe:2.3:h:hbgek:hb8008:-:*:*:*:*:*:*:

cpe:2.3:h:hbgbk:hb8008r:-:*:*:*:*:*:*:

cpe:2.3:h:hbgek:hb8008r:-:*:*:*:*:*:*:

```
cpe:2.3:o:hbgek:hb8008r_firmware:-:*:*:*:*:*:
```

cpe:2.3:o:hbgek:hb8008r_firmware:-:*:*:*:*:*:

cpe:2.3:o:hbgbk:hb8008_firmware:-:*:*:*:*:*:*:

cpe:2.3:o:hbgek:hb8008_firmware:-:*:*:*:*:*:

```
cpe:2.3:h:hbgek:hb8016:-:*:*:*:*:*:*:
```

cpe:2.3:h:hbgek:hb8016:-:*:*:*:*:*:*:

cpe:2.3:h:hbgek:hb8016r:-:*:*:*:*:*:*:

[illegible]

cpe:2.3:h:hbgk:hb8016r:-:::~::~:

cpe:2.3:o:hbgek:hb8016r_firmware:-:*:*:*:*:*:*:

cpe:2.3:o:hbgek:hb8016r_firmware:-:*:*:*:*:*:*:

cpe:2.3:o:hbgbk:hb8016_firmware:-:*:*:*:*:*:*:

cpe:2.3:o:hbgbk:hb8016_firmware:-:*:*:*:*:*:*:

cpe:2.3:h:hbgek:hb8204h:-:*:*:*:*:*:*:

cpe:2.3:h:hbgek:hb8204h:-:*:*:*:*:*:*:

cpe:2.3:h:hbgbk:hb8204hr:-:*:*:*:*:*:*:

cpe:2.3:h:hbgek:hb8204hr:-:*:*:*:*:*:*:

```
cpe:2.3:o:hbgk:hb8204hr_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:hbgk:hb8204hr_firmware:-:*:*:*:*:*:
```

cpe:2.3:o:hbgek:hb8204h_firmware:-:*:*:*:*:*:*:

cpe:2.3:o:hbgek:hb8204h_firmware:-:*:*:*:*:*:*:

cpe:2.3:h:hb9k:hb8208h:-:*:*:*:*:*:*:

cpe:2.3:h:hb9k:hb8208h:-:*:*:*:*:*:

cpe:2.3:h:hbgek:hb8208hr:-:*:*:*:*:*:*:

cpe:2.3:h:hbgek:hb8208hr:-:*:*:*:*:*:*:

```
cpe:2.3:o:hbqk:hb8208hr_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:hbgk:hb8208hr_firmware:-:*:*:*:*:
```

```
cpe:2.3:o:hbqk:hb8208h_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:hbqk:hb8208h firmware:-:*:*:*:*:*:
```

cpe:2.3:h:hbqk:hb8208x3:-:*:*:*:*:*:*:

cpe:2.3:h:hbgek:hb8208x3:-:*:*:*:*:*:*:

cpe:2.3:o:hbgek:hb8208x3_firmware:-:*:*:*:*:*:

```
cpe:2.3:o:hbqk:hb8208x3_firmware:-:*:*:*:*:*:
```

cpe:2.3:h:hbqk:hb8216h:-:*:*:*:*:*:*:

cpe:2.3:h:hbqk:hb8216h:-:*:*:*:*:*:*:

cpe:2.3:h:hbqk:hb8216hr:-:*:*:*:*:*:*:

cpe:2.3:h:hbgek:hb8216hr:-:*:*:*:*:*:*:

```
cpe:2.3:o:hbgek:hb8216hr_firmware:-:*:*:*:*:*:*:
```

cpe:2.3:o:hbgek:hb8216hr_firmware:-:*:*:*:*:*:*:

cpe:2.3:o:hbgek:hb8216h_firmware:-:*:*:*:*:*:

cpe:2.3:o:hbgek:hb8216h_firmware:-:*:*:*:*:*:

cpe:2.3:h:hbgek:hb8216x3:-:*:*:*:*:*:*:

cpe:2.3:h:hbgbk:hb8216x3:-:*:*:*:*:*:*:

```
cpe:2.3:o:hbqk:hb8216x3_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:hbgek:hb8216x3_firmware:-:*:*:*:*:*:
```

cpe:2.3:h:hbgek:hb8608x3:-:*:*:*:*:*:*:

cpe:2.3:h:hbgek:hb8608x3:-:*:*:*:*:*:*:

```
cpe:2.3:o:hbgek:hb8608x3_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:hbgek:hb8608x3_firmware:-:*:*:*:*:*:
```

cpe:2.3:h:hbqk:hb8616x3:-:*:*:*:*:*:*:

cpe:2.3:h:hbgek:hb8616x3:-:*:*:*:*:*:*:

cpe:2.3:o:hbgek:hb8616x3_firmware:-:*:*:*:*:*:

cpe:2.3:o:hbgek:hb8616x3_firmware:-:*:*:*:*:*:

cpe:2.3:h:hbgek:hb8808x3:-:*:*:*:*:*:*:

cpe:2.3:h:hbgek:hb8808x3:-:*:*:*:*:*:*:

```
cpe:2.3:o:hbgek:hb8808x3_firmware:-:*:*:*:*:*:
```

cpe:2.3:o:hbgek:hb8808x3_firmware:-:*:*:*:*:*:

cpe:2.3:h:hbgek:hb8816x3:-:*:*:*:*:*:*:

cpe:2.3:h:hbgek:hb8816x3:-:*:*:*:*:*:

cpe:2.3:o:hbgek:hb8816x3_firmware:-:*:*:*:*:*:

cpe:2.3:o:hbgek:hb8816x3_firmware:-:*:*:*:*:*:

cpe:2.3:h:hb9012x3:-:*:*:*:*:*:

cpe:2.3:h:hb9012x3:-:*:*:*:*:*:*:

cpe:2.3:o:hbgek:hb9012x3_firmware:-:*:*:*:*:*:

cpe:2.3:o:hbgek:hb9012x3_firmware:-:*:*:*:*:*:

cpe:2.3:h:hb9020x3:-:*:*:*:*:*:*:

cpe:2.3:h:hb9020x3:-:*:*:*:*:*:*:

```
cpe:2.3:o:hbgbk:hb9020x3_firmware:-:*:*:*:*:*:*:
```

```
cpe:2.3:o:hbgbk:hb9020x3_firmware:-:*:*:*:*:*:*:
```

cpe:2.3:h:hb9212x3:-:*:*:*:*:*:

cpe:2.3:h:hb9212x3:-:*:*:*:*:*:*:

cpe:2.3:o:hbgek:hb9212x3_firmware:-:*:*:*:*:*:

```
cpe:2.3:o:hbgek:hb9212x3_firmware:-:*:*:*:*:*:
```

cpe:2.3:h:hb9220x3:-:*:*:*:*:*:*:

cpe:2.3:h:hb9220x3:-:*:*:*:*:*:*:

cpe:2.3:o:hb9220x3_firmware:-:*:*:*:*:*:

```
cpe:2.3:o:hbgek:hb9220x3_firmware:-:*:*:*:*:*:*:
```

cpe:2.3:h:hb9404x3:-:*:*:*:*:*:*:

cpe:2.3:h:hb9404x3:-:*:*:*:*:*:*:

cpe:2.3:o:hb9404x3_firmware:-:*:*:*:*:*:

```
cpe:2.3:o:hb9404x3_firmware:-:*:*:*:*:*:
```

cpe:2.3:h:hb9408x3:-:*:*:*:*:*:*:

cpe:2.3:h:hb9408x3:-:*:*:*:*:*:*:

```
cpe:2.3:o:hbgek:hb9408x3_firmware:-:*:*:*:*:*:
```

cpe:2.3:o:hbgek:hb9408x3_firmware:-:*:*:*:*:*:*:

cpe:2.3:h:hb9604x3:-:*:*:*:*:*:

cpe:2.3:h:hb9604x3:-:*:*:*:*:*:*:

```
cpe:2.3:o:hbkg:hb9604x3_firmware:-:*:*:*:*:*:*:
```

cpe:2.3:o:hb9604x3_firmware:-:*:*:*:*:*:

cpe:2.3:h:hb9608x3:-:*:*:*:*:*:*:

cpe:2.3:h:hbgek:hb9608x3:-:*:*:*:*:*:*:

```
cpe:2.3:o:hbgek:hb9608x3_firmware:-:*:*:*:*:*:*:
```

```
cpe:2.3:o:hbgek:hb9608x3_firmware:-:*:*:*:*:*:*:
```

cpe:2.3:h:hbgtk:hb9808n04:-:*:*:*:*:*:*:

cpe:2.3:h:hbgek:hb9808n04:-:*:*:*:*:*:*:

```
cpe:2.3:o:hbqk:hb9808n04_firmware:-:*:*:*:*:*:*
```

```
cpe:2.3:o:hbqk:hb9808n04_firmware:-:*:*:*:*:*:*
```

cpe:2.3:h:hb9816n08:-:*:*:*:*:*:

cpe:2.3:h:hbgek:hb9816n08:-:*:*:*:*:*:*:

```
cpe:2.3:o:hbgek:hb9816n08_firmware:-:*:*:*:*:*:*:
```

```
cpe:2.3:o:hbgbk:hb9816n08_firmware:-:*:*:*:*:*:*:
```

cpe:2.3:h:hb9824n16:-:*:*:*:*:*:

cpe:2.3:h:hbgek:hb9824n16:-:*:*:*:*:*:

```
cpe:2.3:o:hbgbk:hb9824n16_firmware:-:*:*:*:*:*:*:
```

```
cpe:2.3:o:hbgbk:hb9824n16_firmware:-:*:*:*:*:*:*:
```

cpe:2.3:h:hbgek:hb9832n16:-:*:*:*:*:*:*:

cpe:2.3:h:hb9832n16:-:*:*:*:*:*:

```
cpe:2.3:o:hbqk:hb9832n16_firmware:-:*:*:*:*:*:*
```

```
cpe:2.3:o:hbqk:hb9832n16_firmware:-:*:*:*:*:*:*
```

cpe:2.3:h:hbgek:hb9904:-:*:*:*:*:*:*:

cpe:2.3:h:hbgek:hb9904:-:*:*:*:*:*:*:

cpe:2.3:o:hbgek:hb9904_firmware:-:*:*:*:*:*:*:

cpe:2.3:o:hb9904_firmware:-:*:*:*:*:*:

cpe:2.3:h:hbgek:hb9908:-:*:*:*:*:*:*:

cpe:2.3:h:hbgek:hb9908:-:*:*:*:*:*:*:

cpe:2.3:o:hbgek:hb9908_firmware:-:*:*:*:*:*:*:

```
cpe:2.3:o:hbqk:hb9908 firmware:-:*:*:*:*:*:
```

cpe:2.3:h:hb9912:-:*:*:*:*:*:

cpe:2.3:h:hb9912:-:*:*:*:*:*:

cpe:2.3:o:hbgek:hb9912_firmware:-:*:*:*:*:*:

cpe:2.3:o:hb9912_firmware:-:*:*:*:*:*:

cpe:2.3:h:hb9916:-:*:*:*:*:*:

cpe:2.3:h:hb9916:-:*****:
cpe:2.3:o:hb9916_firmware:-:*****:
cpe:2.3:o:hb9916_firmware:-:*****:
cpe:2.3:h:hb9924:-:*****:
cpe:2.3:h:hb9924:-:*****:
cpe:2.3:o:hb9924_firmware:-:*****:
cpe:2.3:o:hb9924_firmware:-:*****:
cpe:2.3:h:hb9932:-:*****:
cpe:2.3:h:hb9932:-:*****:
cpe:2.3:o:hb9932_firmware:-:*****:
cpe:2.3:o:hb9932_firmware:-:*****:

No vendor comments have been submitted for this CVE

[← Previous ID](#)

[Next ID→](#)