



CVE-2017-15043

[MITRE](#)[NVD](#)[CVE.ORG](#)[Print: PDF !\[\]\(e3f8612927870f2e0f9f5989e6dd3064_img.jpg\)](#)

Summary

CVE	CVE-2017-15043
State	PUBLIC
Assigner	cve@mitre.org
Source Priority	CVE Program / NVD first with legacy fallback
Published	2018-05-04 20:29:00 UTC
Updated	2018-06-13 15:07:00 UTC
Description	A vulnerability in Sierra Wireless AirLink GX400, GX440, ES440, and LS300 routers with firmware before 4.4.5 and GX450,

Risk And Classification

Problem Types: CWE-20

NVD Known Affected Configurations (CPE 2.3)

Type	Vendor	Product	Version	Update	Edition	Language
Hardware	Sierrawireless	Es440	-	All	All	All
Hardware	Sierrawireless	Es440	-	All	All	All
Operating System	Sierrawireless	Es440 Firmware	All	All	All	All
Operating System	Sierrawireless	Es440 Firmware	All	All	All	All
Hardware	Sierrawireless	Es450	-	All	All	All
Hardware	Sierrawireless	Es450	-	All	All	All
Operating System	Sierrawireless	Es450 Firmware	All	All	All	All
Operating System	Sierrawireless	Es450 Firmware	All	All	All	All
Hardware	Sierrawireless	Gx400	-	All	All	All
Hardware	Sierrawireless	Gx400	-	All	All	All
Operating System	Sierrawireless	Gx400 Firmware	All	All	All	All
Operating System	Sierrawireless	Gx400 Firmware	All	All	All	All
Hardware	Sierrawireless	Gx440	-	All	All	All
Hardware	Sierrawireless	Gx440	-	All	All	All
Operating System	Sierrawireless	Gx440 Firmware	All	All	All	All
Operating System	Sierrawireless	Gx440 Firmware	All	All	All	All
Hardware	Sierrawireless	Gx450	-	All	All	All

Hardware	Sierrawireless	Gx450	-	All	All	All
Operating System	Sierrawireless	Gx450 Firmware	All	All	All	All
Operating System	Sierrawireless	Gx450 Firmware	All	All	All	All
Hardware	Sierrawireless	Ls300	-	All	All	All
Hardware	Sierrawireless	Ls300	-	All	All	All
Operating System	Sierrawireless	Ls300 Firmware	All	All	All	All
Operating System	Sierrawireless	Ls300 Firmware	All	All	All	All
Hardware	Sierrawireless	Mp70	-	All	All	All
Hardware	Sierrawireless	Mp70	-	All	All	All
Hardware	Sierrawireless	Mp70e	-	All	All	All
Hardware	Sierrawireless	Mp70e	-	All	All	All
Operating System	Sierrawireless	Mp70e Firmware	All	All	All	All
Operating System	Sierrawireless	Mp70e Firmware	All	All	All	All
Operating System	Sierrawireless	Mp70 Firmware	All	All	All	All
Operating System	Sierrawireless	Mp70 Firmware	All	All	All	All
Hardware	Sierrawireless	Rv50	-	All	All	All
Hardware	Sierrawireless	Rv50	-	All	All	All
Hardware	Sierrawireless	Rv50x	-	All	All	All
Hardware	Sierrawireless	Rv50x	-	All	All	All
Operating System	Sierrawireless	Rv50x Firmware	All	All	All	All
Operating System	Sierrawireless	Rv50x Firmware	All	All	All	All
Operating System	Sierrawireless	Rv50 Firmware	All	All	All	All
Operating System	Sierrawireless	Rv50 Firmware	All	All	All	All

References

Reference	Source	Link	Tags
SWI-PSA-2018-003: Technical Bulletin - Reaper	CONFIRM	source.sierrawireless.com	Mitigation, Vendor Advisory
CVE Program record	CVE.ORG	www.cve.org	canonical
NVD vulnerability detail	NVD	nvd.nist.gov	canonical, analysis

No vendor comments have been submitted for this CVE.

There are currently no legacy QID mappings associated with this CVE.

this information or its use. Any use of this information is at the user's risk. It is the responsibility of user to evaluate the accuracy, completeness or usefulness of any information, opinion, advice or other content. EACH USER WILL BE SOLELY RESPONSIBLE FOR ANY consequences of his or her direct or indirect use of this web site. ALL WARRANTIES OF ANY KIND ARE EXPRESSLY DISCLAIMED. This site will NOT BE LIABLE FOR ANY DIRECT, INDIRECT or any other kind of loss.

CVE, CWE, and OVAL are registered trademarks of [The MITRE Corporation](#) and the authoritative source of CVE content is [MITRE's CVE web site](#). This site includes MITRE data granted under the following [license](#).

CVE.report and Source URL Uptime Status [status.cve.report](#)