




# CVE-2017-15620

Published on: 01/11/2018 12:00:00 AM UTC

Last Modified on: 03/23/2021 11:26:34 PM UTC

## CVE-2017-15620

[Source: Mitre](#)[Source: NIST](#)[CVE.ORG](#)[Print: PDF](#) 

Certain versions of [Er5110g](#) from [Tp-link](#) contain the following vulnerability:

TP-Link WVR, WAR and ER devices allow remote authenticated administrators to execute arbitrary commands via command injection in the new-zone variable in the ipmac\_import.lua file.

CVE-2017-15620 has been assigned by [M](#) cve@mitre.org to track the vulnerability - currently rated as **HIGH** severity.

CVSS3 Score: **7.2 - HIGH**

| Attack Vector    | Attack Complexity      | Privileges Required | User Interaction    |
|------------------|------------------------|---------------------|---------------------|
| <b>NETWORK</b>   | <b>LOW</b>             | <b>HIGH</b>         | <b>NONE</b>         |
| Scope            | Confidentiality Impact | Integrity Impact    | Availability Impact |
| <b>UNCHANGED</b> | <b>HIGH</b>            | <b>HIGH</b>         | <b>HIGH</b>         |

CVSS2 Score: **9 - HIGH**

| Access Vector          | Access Complexity | Authentication      |
|------------------------|-------------------|---------------------|
| <b>NETWORK</b>         | <b>LOW</b>        | <b>SINGLE</b>       |
| Confidentiality Impact | Integrity Impact  | Availability Impact |
| <b>COMPLETE</b>        | <b>COMPLETE</b>   | <b>COMPLETE</b>     |

## CVE References

| Description                                                                                      | Tags                                                                                                                       | Link                                                                                                                         |
|--------------------------------------------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------------------|
| Vulnerability/CVE-2017-15613_to_CVE-2017-15637.txt at master · chunibalon/Vulnerability · GitHub | <a href="#">Exploit</a><br><a href="#">Third Party Advisory</a><br><a href="#">github.com</a><br><a href="#">text/html</a> | <a href="#">MISC</a><br><a href="#">github.com/chunibalon/Vulnerability/blob/master/CVE-2017-15613_to_CVE-2017-15637.txt</a> |

By selecting these links, you may be leaving CVEreport webspace. We have provided these links to other websites because they may have information that would be of interest to you. No inferences should be drawn on account of other sites being referenced, or not, from this page. There may be other websites that are more appropriate for your purpose. CVEreport does not necessarily endorse the views expressed, or concur with the facts presented on these sites. Further, CVEreport does not endorse any commercial products that may be mentioned on these sites. Please address comments about any linked pages to [comment@cve.report](mailto:comment@cve.report).

There are currently no QIDs associated with this CVE

#### Known Affected Configurations (CPE V2.3)

| Type                                                                                         | Vendor                  | Product                          | Version | Update | Edition | Language |
|----------------------------------------------------------------------------------------------|-------------------------|----------------------------------|---------|--------|---------|----------|
| Hardware    | <a href="#">Tp-link</a> | <a href="#">Er5110g</a>          | -       | All    | All     | All      |
| Hardware    | <a href="#">Tp-link</a> | <a href="#">Er5110g</a>          | -       | All    | All     | All      |
| Operating System                                                                             | <a href="#">Tp-link</a> | <a href="#">Er5110g Firmware</a> | -       | All    | All     | All      |
| Operating System                                                                             | <a href="#">Tp-link</a> | <a href="#">Er5110g Firmware</a> | -       | All    | All     | All      |
| Hardware  | <a href="#">Tp-link</a> | <a href="#">Er5120g</a>          | -       | All    | All     | All      |
| Hardware  | <a href="#">Tp-link</a> | <a href="#">Er5120g</a>          | -       | All    | All     | All      |
| Operating System                                                                             | <a href="#">Tp-link</a> | <a href="#">Er5120g Firmware</a> | -       | All    | All     | All      |
| Operating System                                                                             | <a href="#">Tp-link</a> | <a href="#">Er5120g Firmware</a> | -       | All    | All     | All      |
| Hardware  | <a href="#">Tp-link</a> | <a href="#">Er5510g</a>          | -       | All    | All     | All      |
| Hardware  | <a href="#">Tp-link</a> | <a href="#">Er5510g</a>          | -       | All    | All     | All      |
| Operating System                                                                             | <a href="#">Tp-link</a> | <a href="#">Er5510g Firmware</a> | -       | All    | All     | All      |
| Operating System                                                                             | <a href="#">Tp-link</a> | <a href="#">Er5510g Firmware</a> | -       | All    | All     | All      |
| Hardware  | <a href="#">Tp-link</a> | <a href="#">Er5520g</a>          | -       | All    | All     | All      |
| Hardware  | <a href="#">Tp-link</a> | <a href="#">Er5520g</a>          | -       | All    | All     | All      |
| Operating System                                                                             | <a href="#">Tp-link</a> | <a href="#">Er5520g Firmware</a> | -       | All    | All     | All      |
| Operating System                                                                             | <a href="#">Tp-link</a> | <a href="#">Er5520g Firmware</a> | -       | All    | All     | All      |
| Hardware  | <a href="#">Tp-link</a> | <a href="#">R4149g</a>           | -       | All    | All     | All      |
| Hardware  | <a href="#">Tp-link</a> | <a href="#">R4149g</a>           | -       | All    | All     | All      |
| Operating System                                                                             | <a href="#">Tp-link</a> | <a href="#">R4149g Firmware</a>  | -       | All    | All     | All      |

|                                                                                                                                                                                  |         |                    |   |     |     |     |
|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------|--------------------|---|-----|-----|-----|
| System                                                                                                                                                                           |         |                    |   |     |     |     |
| Operating System                                                                                                                                                                 | Tp-link | R4149g Firmware    | - | All | All | All |
| Hardware       | Tp-link | R4239g             | - | All | All | All |
| Hardware       | Tp-link | R4239g             | - | All | All | All |
| Operating System                                                                                                                                                                 | Tp-link | R4239g Firmware    | - | All | All | All |
| Operating System                                                                                                                                                                 | Tp-link | R4239g Firmware    | - | All | All | All |
| Hardware       | Tp-link | R4299g             | - | All | All | All |
| Hardware       | Tp-link | R4299g             | - | All | All | All |
| Operating System                                                                                                                                                                 | Tp-link | R4299g Firmware    | - | All | All | All |
| Operating System                                                                                                                                                                 | Tp-link | R4299g Firmware    | - | All | All | All |
| Hardware       | Tp-link | R473               | - | All | All | All |
| Hardware       | Tp-link | R473               | - | All | All | All |
| Hardware     | Tp-link | R473g              | - | All | All | All |
| Hardware   | Tp-link | R473g              | - | All | All | All |
| Hardware   | Tp-link | R473gp-ac          | - | All | All | All |
| Hardware   | Tp-link | R473gp-ac          | - | All | All | All |
| Operating System                                                                                                                                                                 | Tp-link | R473gp-ac Firmware | - | All | All | All |
| Operating System                                                                                                                                                                 | Tp-link | R473gp-ac Firmware | - | All | All | All |
| Operating System                                                                                                                                                                 | Tp-link | R473g Firmware     | - | All | All | All |
| Operating System                                                                                                                                                                 | Tp-link | R473g Firmware     | - | All | All | All |
| Hardware   | Tp-link | R473p-ac           | - | All | All | All |
| Hardware   | Tp-link | R473p-ac           | - | All | All | All |
| Operating System                                                                                                                                                                 | Tp-link | R473p-ac Firmware  | - | All | All | All |
| Operating System                                                                                                                                                                 | Tp-link | R473p-ac Firmware  | - | All | All | All |
| Operating System                                                                                                                                                                 | Tp-link | R473 Firmware      | - | All | All | All |
| Operating System                                                                                                                                                                 | Tp-link | R473 Firmware      | - | All | All | All |
| Hardware   | Tp-link | R478               | - | All | All | All |

|                                                                                              |                         |                                |   |     |     |     |
|----------------------------------------------------------------------------------------------|-------------------------|--------------------------------|---|-----|-----|-----|
| Hardware     | <a href="#">Tp-link</a> | <a href="#">R478</a>           | - | All | All | All |
| Hardware    | <a href="#">Tp-link</a> | <a href="#">R478</a>           | - | All | All | All |
| Operating System                                                                             | <a href="#">Tp-link</a> | <a href="#">R478 Firmware</a>  | - | All | All | All |
| Hardware    | <a href="#">Tp-link</a> | <a href="#">R478g</a>          | - | All | All | All |
| Operating System                                                                             | <a href="#">Tp-link</a> | <a href="#">R478g Firmware</a> | - | All | All | All |
| Hardware    | <a href="#">Tp-link</a> | <a href="#">R478g</a>          | - | All | All | All |
| Hardware    | <a href="#">Tp-link</a> | <a href="#">R478g</a>          | - | All | All | All |
| Operating System                                                                             | <a href="#">Tp-link</a> | <a href="#">R478g Firmware</a> | - | All | All | All |
| Operating System                                                                             | <a href="#">Tp-link</a> | <a href="#">R478g Firmware</a> | - | All | All | All |
| Hardware    | <a href="#">Tp-link</a> | <a href="#">R478</a>           | - | All | All | All |
| Hardware    | <a href="#">Tp-link</a> | <a href="#">R478</a>           | - | All | All | All |
| Operating System                                                                             | <a href="#">Tp-link</a> | <a href="#">R478 Firmware</a>  | - | All | All | All |
| Operating System                                                                             | <a href="#">Tp-link</a> | <a href="#">R478 Firmware</a>  | - | All | All | All |
| Operating System                                                                             | <a href="#">Tp-link</a> | <a href="#">R478 Firmware</a>  | - | All | All | All |
| Operating System                                                                             | <a href="#">Tp-link</a> | <a href="#">R478 Firmware</a>  | - | All | All | All |
| Hardware  | <a href="#">Tp-link</a> | <a href="#">R483</a>           | - | All | All | All |
| Hardware  | <a href="#">Tp-link</a> | <a href="#">R483</a>           | - | All | All | All |
| Hardware  | <a href="#">Tp-link</a> | <a href="#">R483g</a>          | - | All | All | All |
| Hardware  | <a href="#">Tp-link</a> | <a href="#">R483g</a>          | - | All | All | All |
| Operating System                                                                             | <a href="#">Tp-link</a> | <a href="#">R483g Firmware</a> | - | All | All | All |
| Operating System                                                                             | <a href="#">Tp-link</a> | <a href="#">R483g Firmware</a> | - | All | All | All |
| Operating System                                                                             | <a href="#">Tp-link</a> | <a href="#">R483 Firmware</a>  | - | All | All | All |
| Operating System                                                                             | <a href="#">Tp-link</a> | <a href="#">R483 Firmware</a>  | - | All | All | All |
| Hardware  | <a href="#">Tp-link</a> | <a href="#">R488</a>           | - | All | All | All |
| Hardware  | <a href="#">Tp-link</a> | <a href="#">R488</a>           | - | All | All | All |
| Operating System                                                                             | <a href="#">Tp-link</a> | <a href="#">R488 Firmware</a>  | - | All | All | All |
| Operating                                                                                    | <a href="#">Tp-link</a> | <a href="#">R488 Firmware</a>  | - | All | All | All |

| Operating System                                                                                                                                                                 | Operating System        | Firmware                          | Operating System | Operating System | Operating System | Operating System |
|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------|-----------------------------------|------------------|------------------|------------------|------------------|
| Hardware       | <a href="#">Tp-link</a> | <a href="#">War1300l</a>          | -                | All              | All              | All              |
| Hardware       | <a href="#">Tp-link</a> | <a href="#">War1300l</a>          | -                | All              | All              | All              |
| Operating System                                                                                                                                                                 | <a href="#">Tp-link</a> | <a href="#">War1300l Firmware</a> | -                | All              | All              | All              |
| Operating System                                                                                                                                                                 | <a href="#">Tp-link</a> | <a href="#">War1300l Firmware</a> | -                | All              | All              | All              |
| Hardware       | <a href="#">Tp-link</a> | <a href="#">War1750l</a>          | -                | All              | All              | All              |
| Hardware       | <a href="#">Tp-link</a> | <a href="#">War1750l</a>          | -                | All              | All              | All              |
| Operating System                                                                                                                                                                 | <a href="#">Tp-link</a> | <a href="#">War1750l Firmware</a> | -                | All              | All              | All              |
| Operating System                                                                                                                                                                 | <a href="#">Tp-link</a> | <a href="#">War1750l Firmware</a> | -                | All              | All              | All              |
| Hardware       | <a href="#">Tp-link</a> | <a href="#">War2600l</a>          | -                | All              | All              | All              |
| Hardware       | <a href="#">Tp-link</a> | <a href="#">War2600l</a>          | -                | All              | All              | All              |
| Operating System                                                                                                                                                                 | <a href="#">Tp-link</a> | <a href="#">War2600l Firmware</a> | -                | All              | All              | All              |
| Operating System                                                                                                                                                                 | <a href="#">Tp-link</a> | <a href="#">War2600l Firmware</a> | -                | All              | All              | All              |
| Hardware   | <a href="#">Tp-link</a> | <a href="#">War302</a>            | -                | All              | All              | All              |
| Hardware   | <a href="#">Tp-link</a> | <a href="#">War302</a>            | -                | All              | All              | All              |
| Operating System                                                                                                                                                                 | <a href="#">Tp-link</a> | <a href="#">War302 Firmware</a>   | -                | All              | All              | All              |
| Operating System                                                                                                                                                                 | <a href="#">Tp-link</a> | <a href="#">War302 Firmware</a>   | -                | All              | All              | All              |
| Hardware   | <a href="#">Tp-link</a> | <a href="#">War450</a>            | -                | All              | All              | All              |
| Hardware   | <a href="#">Tp-link</a> | <a href="#">War450</a>            | -                | All              | All              | All              |
| Hardware   | <a href="#">Tp-link</a> | <a href="#">War450l</a>           | -                | All              | All              | All              |
| Hardware   | <a href="#">Tp-link</a> | <a href="#">War450l</a>           | -                | All              | All              | All              |
| Operating System                                                                                                                                                                 | <a href="#">Tp-link</a> | <a href="#">War450l Firmware</a>  | -                | All              | All              | All              |
| Operating System                                                                                                                                                                 | <a href="#">Tp-link</a> | <a href="#">War450l Firmware</a>  | -                | All              | All              | All              |
| Operating System                                                                                                                                                                 | <a href="#">Tp-link</a> | <a href="#">War450 Firmware</a>   | -                | All              | All              | All              |
| Operating System                                                                                                                                                                 | <a href="#">Tp-link</a> | <a href="#">War450 Firmware</a>   | -                | All              | All              | All              |
| Hardware   | <a href="#">Tp-link</a> | <a href="#">War458</a>            | -                | All              | All              | All              |
| Hardware   | <a href="#">Tp-link</a> | <a href="#">War458</a>            | -                | All              | All              | All              |

|                                                                                                                                                                                  |                         |                                   |   |     |     |     |
|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------|-----------------------------------|---|-----|-----|-----|
| Hardware         | <a href="#">Tp-link</a> | <a href="#">War458l</a>           | - | All | All | All |
| Hardware       | <a href="#">Tp-link</a> | <a href="#">War458l</a>           | - | All | All | All |
| Operating System                                                                                                                                                                 | <a href="#">Tp-link</a> | <a href="#">War458l Firmware</a>  | - | All | All | All |
| Operating System                                                                                                                                                                 | <a href="#">Tp-link</a> | <a href="#">War458l Firmware</a>  | - | All | All | All |
| Operating System                                                                                                                                                                 | <a href="#">Tp-link</a> | <a href="#">War458 Firmware</a>   | - | All | All | All |
| Operating System                                                                                                                                                                 | <a href="#">Tp-link</a> | <a href="#">War458 Firmware</a>   | - | All | All | All |
| Hardware       | <a href="#">Tp-link</a> | <a href="#">War900l</a>           | - | All | All | All |
| Hardware       | <a href="#">Tp-link</a> | <a href="#">War900l</a>           | - | All | All | All |
| Operating System                                                                                                                                                                 | <a href="#">Tp-link</a> | <a href="#">War900l Firmware</a>  | - | All | All | All |
| Operating System                                                                                                                                                                 | <a href="#">Tp-link</a> | <a href="#">War900l Firmware</a>  | - | All | All | All |
| Hardware       | <a href="#">Tp-link</a> | <a href="#">Wvr1300g</a>          | - | All | All | All |
| Hardware     | <a href="#">Tp-link</a> | <a href="#">Wvr1300g</a>          | - | All | All | All |
| Operating System                                                                                                                                                                 | <a href="#">Tp-link</a> | <a href="#">Wvr1300g Firmware</a> | - | All | All | All |
| Operating System                                                                                                                                                                 | <a href="#">Tp-link</a> | <a href="#">Wvr1300g Firmware</a> | - | All | All | All |
| Hardware   | <a href="#">Tp-link</a> | <a href="#">Wvr1300l</a>          | - | All | All | All |
| Hardware   | <a href="#">Tp-link</a> | <a href="#">Wvr1300l</a>          | - | All | All | All |
| Operating System                                                                                                                                                                 | <a href="#">Tp-link</a> | <a href="#">Wvr1300l Firmware</a> | - | All | All | All |
| Operating System                                                                                                                                                                 | <a href="#">Tp-link</a> | <a href="#">Wvr1300l Firmware</a> | - | All | All | All |
| Hardware   | <a href="#">Tp-link</a> | <a href="#">Wvr1750l</a>          | - | All | All | All |
| Hardware   | <a href="#">Tp-link</a> | <a href="#">Wvr1750l</a>          | - | All | All | All |
| Operating System                                                                                                                                                                 | <a href="#">Tp-link</a> | <a href="#">Wvr1750l Firmware</a> | - | All | All | All |
| Operating System                                                                                                                                                                 | <a href="#">Tp-link</a> | <a href="#">Wvr1750l Firmware</a> | - | All | All | All |
| Hardware   | <a href="#">Tp-link</a> | <a href="#">Wvr2600l</a>          | - | All | All | All |
| Hardware   | <a href="#">Tp-link</a> | <a href="#">Wvr2600l</a>          | - | All | All | All |
| Operating System                                                                                                                                                                 | <a href="#">Tp-link</a> | <a href="#">Wvr2600l Firmware</a> | - | All | All | All |
| Operating System                                                                                                                                                                 | <a href="#">Tp-link</a> | <a href="#">Wvr2600l Firmware</a> | - | All | All | All |

|                                                                                                                                                                                  |                         |                                   |            |     |     |     |
|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------|-----------------------------------|------------|-----|-----|-----|
| Hardware         | <a href="#">Tp-link</a> | <a href="#">Wvr300</a>            | -          | All | All | All |
| Hardware       | <a href="#">Tp-link</a> | <a href="#">Wvr300</a>            | -          | All | All | All |
| Operating System                                                                                                                                                                 | <a href="#">Tp-link</a> | <a href="#">Wvr300 Firmware</a>   | -          | All | All | All |
| Operating System                                                                                                                                                                 | <a href="#">Tp-link</a> | <a href="#">Wvr300 Firmware</a>   | -          | All | All | All |
| Hardware       | <a href="#">Tp-link</a> | <a href="#">Wvr302</a>            | -          | All | All | All |
| Hardware       | <a href="#">Tp-link</a> | <a href="#">Wvr302</a>            | -          | All | All | All |
| Operating System                                                                                                                                                                 | <a href="#">Tp-link</a> | <a href="#">Wvr302 Firmware</a>   | -          | All | All | All |
| Operating System                                                                                                                                                                 | <a href="#">Tp-link</a> | <a href="#">Wvr302 Firmware</a>   | -          | All | All | All |
| Hardware       | <a href="#">Tp-link</a> | <a href="#">Wvr4300l</a>          | -          | All | All | All |
| Hardware       | <a href="#">Tp-link</a> | <a href="#">Wvr4300l</a>          | -          | All | All | All |
| Operating System                                                                                                                                                                 | <a href="#">Tp-link</a> | <a href="#">Wvr4300l Firmware</a> | -          | All | All | All |
| Operating System                                                                                                                                                                 | <a href="#">Tp-link</a> | <a href="#">Wvr4300l Firmware</a> | -          | All | All | All |
| Hardware   | <a href="#">Tp-link</a> | <a href="#">Wvr450</a>            | -          | All | All | All |
| Hardware   | <a href="#">Tp-link</a> | <a href="#">Wvr450</a>            | -          | All | All | All |
| Hardware   | <a href="#">Tp-link</a> | <a href="#">Wvr450l</a>           | -          | All | All | All |
| Hardware   | <a href="#">Tp-link</a> | <a href="#">Wvr450l</a>           | -          | All | All | All |
| Operating System                                                                                                                                                                 | <a href="#">Tp-link</a> | <a href="#">Wvr450l Firmware</a>  | 1.0161125  | All | All | All |
| Operating System                                                                                                                                                                 | <a href="#">Tp-link</a> | <a href="#">Wvr450l Firmware</a>  | 1.0161125  | All | All | All |
| Operating System                                                                                                                                                                 | <a href="#">Tp-link</a> | <a href="#">Wvr450 Firmware</a>   | -          | All | All | All |
| Operating System                                                                                                                                                                 | <a href="#">Tp-link</a> | <a href="#">Wvr450 Firmware</a>   | -          | All | All | All |
| Hardware   | <a href="#">Tp-link</a> | <a href="#">Wvr458l</a>           | -          | All | All | All |
| Hardware   | <a href="#">Tp-link</a> | <a href="#">Wvr458l</a>           | -          | All | All | All |
| Operating System                                                                                                                                                                 | <a href="#">Tp-link</a> | <a href="#">Wvr458l Firmware</a>  | -          | All | All | All |
| Operating System                                                                                                                                                                 | <a href="#">Tp-link</a> | <a href="#">Wvr458l Firmware</a>  | -          | All | All | All |
| Hardware   | <a href="#">Tp-link</a> | <a href="#">Wvr900g</a>           | -          | All | All | All |
| Hardware   | <a href="#">Tp-link</a> | <a href="#">Wvr900g</a>           | -          | All | All | All |
| Operating System                                                                                                                                                                 | <a href="#">Tp-link</a> | <a href="#">Wvr900g Firmware</a>  | 3.0_170306 | All | All | All |

|                                                  |         |                  |            |     |     |     |
|--------------------------------------------------|---------|------------------|------------|-----|-----|-----|
| Operating System                                 | Tp-link | Wvr900g Firmware | 3.0_170306 | All | All | All |
| Hardware                                         | Tp-link | Wvr900l          | -          | All | All | All |
| Hardware                                         | Tp-link | Wvr900l          | -          | All | All | All |
| Operating System                                 | Tp-link | Wvr900l Firmware | -          | All | All | All |
| Operating System                                 | Tp-link | Wvr900l Firmware | -          | All | All | All |
| cpe:2.3:h:tp-link:er5110g:-:*:*:*:*:*:           |         |                  |            |     |     |     |
| cpe:2.3:h:tp-link:er5110g:-:*:*:*:*:*:           |         |                  |            |     |     |     |
| cpe:2.3:o:tp-link:er5110g_firmware:-:*:*:*:*:*:  |         |                  |            |     |     |     |
| cpe:2.3:o:tp-link:er5110g_firmware:-:*:*:*:*:*:  |         |                  |            |     |     |     |
| cpe:2.3:h:tp-link:er5120g:-:*:*:*:*:*:           |         |                  |            |     |     |     |
| cpe:2.3:h:tp-link:er5120g:-:*:*:*:*::~:          |         |                  |            |     |     |     |
| cpe:2.3:o:tp-link:er5120g_firmware:-:*:*:*:*::~: |         |                  |            |     |     |     |
| cpe:2.3:o:tp-link:er5120g_firmware:-:*:*:*:*::~: |         |                  |            |     |     |     |
| cpe:2.3:h:tp-link:er5510g:-:*:*:*:*::~:          |         |                  |            |     |     |     |
| cpe:2.3:h:tp-link:er5510g:-:*:*:*:*::~:          |         |                  |            |     |     |     |
| cpe:2.3:o:tp-link:er5510g_firmware:-:*:*:*:*::~: |         |                  |            |     |     |     |
| cpe:2.3:o:tp-link:er5510g_firmware:-:*:*:*:*::~: |         |                  |            |     |     |     |
| cpe:2.3:h:tp-link:er5520g:-:*:*:*:*::~:          |         |                  |            |     |     |     |
| cpe:2.3:h:tp-link:er5520g:-:*:*:*:*::~:          |         |                  |            |     |     |     |
| cpe:2.3:o:tp-link:er5520g_firmware:-:*:*:*:*::~: |         |                  |            |     |     |     |
| cpe:2.3:o:tp-link:er5520g_firmware:-:*:*:*:*::~: |         |                  |            |     |     |     |
| cpe:2.3:h:tp-link:r4149g:-:*:*:*:*::~:           |         |                  |            |     |     |     |
| cpe:2.3:h:tp-link:r4149g:-:*:*:*:*::~:           |         |                  |            |     |     |     |
| cpe:2.3:o:tp-link:r4149g_firmware:-:*:*:*:*::~:  |         |                  |            |     |     |     |
| cpe:2.3:o:tp-link:r4149g_firmware:-:*:*:*:*::~:  |         |                  |            |     |     |     |
| cpe:2.3:h:tp-link:r4239g:-:*:*:*:*::~:           |         |                  |            |     |     |     |
| cpe:2.3:h:tp-link:r4239g:-:*:*:*:*::~:           |         |                  |            |     |     |     |
| cpe:2.3:o:tp-link:r4239g_firmware:-:*:*:*:*::~:  |         |                  |            |     |     |     |

```
cpio.2.0.0.tar-mk.tgz_mfware.7 . . . . .
```

```
cpe:2.3:o:tp-link:r4239g_firmware:-:*:*:*:*:*:*:
```

cpe:2.3:h:tp-link:r4299g:-:\*:\*:\*:\*:\*:\*:

cpe:2.3:h:tp-link:r4299g:-:\*:\*:\*:\*:\*:\*:\*:

```
cpe:2.3:o:tp-link:r4299g_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:tp-link:r4299g_firmware:-:*:*:*:*:*:
```

cpe:2.3:h:tp-link:r473:-:\*:\*:\*:\*:\*:\*:

cpe:2.3:h:tp-link:r473:-:\*:\*:\*:\*:\*:\*:

cpe:2.3:h:tp-link:r473g:-:\*:\*:\*:\*:\*:\*:

```
cpe:2.3:h:tp-link:r473g:-:*:*:*:*:*:*:
```

```
cpe:2.3:h:tp-link:r473gp-ac:-:*:*:*:*:*:*:
```

```
cpe:2.3:h:tp-link:r473gp-ac:-:*:*:*:*:*:*:
```

```
cpe:2.3:o:tp-link:r473gp-ac_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:tp-link:r473gp-ac_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:tp-link:r473g_firmware:-:*:*:*:*:*:*:
```

cpe:2.3:o:tp-link:r473g\_firmware:-:\*:\*:\*:\*:\*:

cpe:2.3:h:tp-link:r473p-ac:-:\*:\*:\*:\*:\*:\*:

cpe:2.3:h:tp-link:r473p-ac:-:\*:\*:\*:\*:\*:\*:

```
cpe:2.3:o:tp-link:r473p-ac_firmware:-:*:*:*:*:*:*:
```

```
cpe:2.3:o:tp-link:r473p-ac_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:tp-link:r473_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:tp-link:r473_firmware:-:*:*:*:*:*:
```

cpe:2.3:h:tp-link:r478:-:\*:\*:\*:\*:\*:\*:

```
cpe:2.3:h:tp-link:r478:-:*:*:*:*:*:*:
```

cpe:2.3:h:tp-link:r478+:-:\*:\*:\*:\*:\*:\*:

```
cpe:2.3:o:tp-link:r478+_firmware:-:*:*:*:*:*:
```

cpe:2.3:h:tp-link:r478g+:-:\*:\*:\*:\*:\*:

```
cpe:2.3:o:tp-link:r478g+_firmware:-:*:*:*:*:*:
```

cpe:2.3:h:tp-link:r478g\+:-:\*:\*:\*:\*:\*:\*:

```
cpe:2.3:h:tp-link:r478g\+:-:*:*:*:*:*:*:
```

```
cpe:2.3:o:tp-link:r478g\+_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:tp-link:r478g\+_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:h:tp-link:r478\+:-:*:*:*:*:*:*:
```

```
cpe:2.3:h:tp-link:r478\+:-:*:*:*:*:*:*:
```

```
cpe:2.3:o:tp-link:r478\+_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:tp-link:r478\+_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:tp-link:r478 firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:tp-link:r478_firmware:-:*:*:*:*:*:
```

cpe:2.3:http-link:r483:-:\*:\*:\*:\*:\*:

```
cpe:2.3:h:tp-link:r483:-:*:*:*:*:*:*:
```

```
cpe:2.3:h:tp-link:r483g:-:*:*:*:*:*:
```

cpe:2.3:h:tp-link:r483g:-:\*:\*:\*:\*:\*:\*:

```
cpe:2.3:o:tp-link:r483g_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:tp-link:r483g_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:tp-link:r483_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:tp-link:r483_firmware:-:*:*:*:*:*:
```

cpe:2.3:htp-link:r488:-:\*:\*:\*:\*:\*:

cpe:2.3:h:tp-link:r488:-:\*:\*:\*:\*:\*:

```
cpe:2.3:o:tp-link:r488_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:tp-link:r488_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:h:tp-link:war1300l:-:*:*:*:*:*:*:
```

cpe:2.3:h:tp-link:war1300l:-:\*:\*:\*:\*:\*:\*:

```
cpe:2.3:o:tp-link:war1300l_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:tp-link:war1300l_firmware:-:*:*:*:*:*:
```

cpe:2.3:h:tp-link:war1750l:-:\*:\*:\*:\*:\*:\*:

```
cpe:2.3:h:tp-link:war1750l:-:*:*:*:*:*:
```

```
cpe:2.3:o:tp-link:war1750l_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:tp-link:war1750l_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:h:tp-link:war2600l:-:*:*:*:*:*:*:
```

```
cpe:2.3:h:tp-link:war2600l:-:*:*:*:*:*:
```

```
cpe:2.3:o:tp-link:war2600l_firmware:-:*:*:*:*:*:*
```

```
cpe:2.3:o:tp-link:war2600l_firmware:-:*:*:*:*:*:*
```

```
cpe:2.3:h:tp-link:war302:-:*:*:*:*:*:*:
```

```
cpe:2.3:h:tp-link:war302:-:*:*:*:*:*:
```

```
cpe:2.3:o:tp-link:war302_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:tp-link:war302_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:h:tp-link:war450:-:*:*:*:*:*:*:
```

cpe:2.3:h:tp-link:war450:-:\*:\*:\*:\*:\*:\*:

```
cpe:2.3:h:tp-link:war450l:-:*:*:*:*:*:
```

```
cpe:2.3:h:tp-link:war450l:-:*:*:*:*:*:*:
```

```
cpe:2.3:o:tp-link:war450l_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:tp-link:war450l_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:tp-link:war450_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:tp-link:war450_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:h:tp-link:war458:-:*:*:*:*:*:*:
```

```
cpe:2.3:h:tp-link:war458:-:*:*:*:*:*:*:
```

```
cpe:2.3:h:tp-link:war458l:-:*:*:*:*:*:*:
```

```
cpe:2.3:h:tp-link:war458l:-:*:*:*:*:*:
```

```
cpe:2.3:o:tp-link:war458l_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:tp-link:war458l_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:tp-link:war458_firmware:-:*:*:*:*:*:*:
```

```
cpe:2.3:o:tp-link:war458_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:h:tp-link:war900l:-:*:*:*:*:*:*:
```

```
cpe:2.3:h:tp-link:war900l:-:*:*:*:*:*:*:
```

```
cpe:2.3:o:tp-link:war900l_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:tp-link:war900l_firmware:-:*:*:*:*:*:
```

cpe:2.3:h:tp-link:wvr1300g:-:\*:\*:\*:\*:\*:

cpe:2.3:h:tp-link:wvr1300g:-:\*:\*:\*:\*:\*:\*:

```
cpe:2.3:o:tp-link:wvr1300g_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:tp-link:wvr1300g_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:h:tp-link:wvr1300l:-:*:*:*:*:*:
```

cpe:2.3:h:tp-link:wvr1300l:-:\*:\*:\*:\*:\*:

```
cpe:2.3:o:tp-link:wvr1300l_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:tp-link:wvr1300l firmware:-:*:*:*:*:*:
```

cpe:2.3:h:tp-link:wvr1750l:-:\*:\*:\*:\*:\*:

```
cpe:2.3:h:tp-link:wvr1750l:-:*:*:*:*:*:
```

```
cpe:2.3:o:tp-link:wvr1750l_firmware:-:*:*:*:*:*:*:
```

```
cpe:2.3:o:tp-link:wvr1750l_firmware:-:*:*:*:*:*:
```

cpe:2.3:h:tp-link:wvr2600l:-\*:~::~:\*~:::

```
cpe:2.3:h:tp-link:wvr2600l:-:*:*:*:*:*:
```

```
cpe:2.3:o:tp-link:wvr2600l firmware:-:*:*:*:*:*:*:
```

```
cpe:2.3:o:tp-link:wvr2600l_firmware:-:*:*:*:*:*:*
```

```
cpe:2.3:h:tp-link:wvr300:-:*:*:*:*:*:
```

```
cpe:2.3:h:tp-link:wvr300:-:*:*:*:*:*:
```

```
cpe:2.3:o:tp-link:wvr300_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:tp-link:wvr300_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:h:tp-link:wvr302:-:*:*:*:*:*:
```

```
cpe:2.3:h:tp-link:wvr302:-:*:*:*:*:*:*:
```

```
cpe:2.3:o:tp-link:wvr302 firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:tp-link:wvr302 firmware:-:*:*:*:*:*:
```

```
cpe:2.3:h:tp-link:wvr4300l:-:*:*:*:*:*:
```

cpe:2.3:h:tp-link:wvr4300l:-:\*:\*:\*:\*:\*:\*:

```
cpe:2.3:o:tp-link:wvr4300l_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:tp-link:wvr4300l_firmware:-:*:*:*:*:*:
```

|                                                          |
|----------------------------------------------------------|
| cpe:2.3:h:tp-link:wvr450:-:*:*:*:*:*:                    |
| cpe:2.3:h:tp-link:wvr450:-:*:*:*:*:*:                    |
| cpe:2.3:h:tp-link:wvr450l:-:*:*:*:*:*:                   |
| cpe:2.3:h:tp-link:wvr450l:-:*:*:*:*:*:                   |
| cpe:2.3:o:tp-link:wvr450l_firmware:1.0161125:*:*:*:*:*:  |
| cpe:2.3:o:tp-link:wvr450l_firmware:1.0161125:*:*:*:*:*:  |
| cpe:2.3:o:tp-link:wvr450_firmware:-:*:*:*:*:*:           |
| cpe:2.3:o:tp-link:wvr450_firmware:-:*:*:*:*:*:           |
| cpe:2.3:h:tp-link:wvr458l:-:*:*:*:*:*:                   |
| cpe:2.3:h:tp-link:wvr458l:-:*:*:*:*:*:                   |
| cpe:2.3:o:tp-link:wvr458l_firmware:-:*:*:*:*:*:          |
| cpe:2.3:o:tp-link:wvr458l_firmware:-:*:*:*:*:*:          |
| cpe:2.3:h:tp-link:wvr900g:-:*:*:*:*:*:                   |
| cpe:2.3:h:tp-link:wvr900g:-:*:*:*:*:*:                   |
| cpe:2.3:o:tp-link:wvr900g_firmware:3.0_170306:*:*:*:*:*: |
| cpe:2.3:o:tp-link:wvr900g_firmware:3.0_170306:*:*:*:*:*: |
| cpe:2.3:h:tp-link:wvr900l:-:*:*:*:*:*:                   |
| cpe:2.3:h:tp-link:wvr900l:-:*:*:*:*:*:                   |
| cpe:2.3:o:tp-link:wvr900l_firmware:-:*:*:*:*:*:          |
| cpe:2.3:o:tp-link:wvr900l_firmware:-:*:*:*:*:*:          |

No vendor comments have been submitted for this CVE

[← Previous ID](#)

Next ID→