



CVE-2017-18765


Published on: 04/22/2020 12:00:00 AM UTC

Last Modified on: 03/23/2021 11:26:54 PM UTC

CVE-2017-18765

[Source: Mitre](#)[Source: NIST](#)[CVE.ORG](#)[Print: PDF](#)

CVSS:30/AC:L/AV:A/A:H/C:N/I:N/PR:N/S:U/UI:N



Certain versions of **R6300** from **Netgear** contain the following vulnerability:

Certain NETGEAR devices are affected by denial of service. This affects R6300v2 before 1.0.4.8, R6400 before 1.0.1.22, R6400v2 before 1.0.2.32, R6700 before 1.0.1.20, R6900 before 1.0.1.20, WNR3500Lv2 before 1.2.0.44, and WNR2000v2 before 1.2.0.8.

CVE-2017-18765 has been assigned by [M](#) cve@mitre.org to track the vulnerability - currently rated as **MEDIUM** severity.

CVSS3 Score: **6.5 - MEDIUM**

Attack Vector	Attack Complexity	Privileges Required	User Interaction
ADJACENT_NETWORK	LOW	NONE	NONE
Scope	Confidentiality Impact	Integrity Impact	Availability Impact
UNCHANGED	NONE	NONE	HIGH

CVSS2 Score: **3.3 - LOW**

Access Vector	Access Complexity	Authentication
ADJACENT_NETWORK	LOW	NONE
Confidentiality Impact	Integrity Impact	Availability Impact
NONE	NONE	PARTIAL

CVE References

Description	Tags	Link
Security Advisory for Denial of Service on Some Routers, PSV-2017-0648 Answer NETGEAR Support	Vendor Advisory kb.netgear.com text/html	N CONFIRM kb.netgear.com/000051480/Security-Advisory-for-Denial-of-Service-on-Some-Routers-PSV-2017-0648

By selecting these links, you may be leaving CVEreport webspace. We have provided these links to other websites because they may have information that

would be of interest to you. No inferences should be drawn on account of other sites being referenced, or not, from this page. There may be other websites that are more appropriate for your purpose. CVEreport does not necessarily endorse the views expressed, or concur with the facts presented on these sites. Further, CVEreport does not endorse any commercial products that may be mentioned on these sites. Please address comments about any linked pages to comment@cve.report.

There are currently no QIDs associated with this CVE

Known Affected Configurations (CPE V2.3)

Type	Vendor	Product	Version	Update	Edition	Language
Hardware 	Netgear	R6300	v2	All	All	All
Hardware 	Netgear	R6300	v2	All	All	All
Operating System	Netgear	R6300 Firmware	All	All	All	All
Operating System	Netgear	R6300 Firmware	All	All	All	All
Hardware 	Netgear	R6400	-	All	All	All
Hardware 	Netgear	R6400	v2	All	All	All
Hardware 	Netgear	R6400	-	All	All	All
Hardware 	Netgear	R6400	v2	All	All	All
Operating System	Netgear	R6400 Firmware	All	All	All	All
Operating System	Netgear	R6400 Firmware	All	All	All	All
Hardware 	Netgear	R6700	-	All	All	All
Hardware 	Netgear	R6700	-	All	All	All
Operating System	Netgear	R6700 Firmware	All	All	All	All
Operating System	Netgear	R6700 Firmware	All	All	All	All
Hardware 	Netgear	R6900	-	All	All	All
Hardware 	Netgear	R6900	-	All	All	All
Operating System	Netgear	R6900 Firmware	All	All	All	All
Operating System	Netgear	R6900 Firmware	All	All	All	All
Hardware 	Netgear	Wnr2000	v2	All	All	All
Hardware 	Netgear	Wnr2000	v2	All	All	All
Operating System	Netgear	Wnr2000 Firmware	All	All	All	All
Operating	Netgear	Wnr2000 Firmware	All	All	All	All

cpe:2.3:o:netgear:wnr3500l_firmware:*****:

cpe:2.3:o:netgear:wnr3500l_firmware:*****:

No vendor comments have been submitted for this CVE

← Previous ID

Next ID→