



CVE-2017-18768


Published on: 04/22/2020 12:00:00 AM UTC

Last Modified on: 03/23/2021 11:26:54 PM UTC

CVE-2017-18768

[Source: Mitre](#)[Source: NIST](#)[CVE.ORG](#)[Print: PDF](#)

CVSS:30/AC:L/AV:N/A:H/C:H/I:H/PR:N/S:U/UI:R



Certain versions of [Ex6100](#) from [Netgear](#) contain the following vulnerability:

Certain NETGEAR devices are affected by CSRF. This affects EX6100 before 1.0.2.16_1.1.130, EX6100v2 before 1.0.1.70, EX6150v2 before 1.0.1.54, EX6200v2 before 1.0.1.50, EX6400 before 1.0.1.60, EX7300 before 1.0.1.60, and WN3000RPv3 before 1.0.2.44.

CVE-2017-18768 has been assigned by [M](#) cve@mitre.org to track the vulnerability - currently rated as **HIGH** severity.

CVSS3 Score: **8.8 - HIGH**

Attack Vector	Attack Complexity	Privileges Required	User Interaction
NETWORK	LOW	NONE	REQUIRED
Scope	Confidentiality Impact	Integrity Impact	Availability Impact
UNCHANGED	HIGH	HIGH	HIGH

CVSS2 Score: **6.8 - MEDIUM**

Access Vector	Access Complexity	Authentication
NETWORK	MEDIUM	NONE
Confidentiality Impact	Integrity Impact	Availability Impact
PARTIAL	PARTIAL	PARTIAL

CVE References

Description	Tags	Link
Security Advisory for Cross Site Request Forgery on Some Extenders, PSV-2016-0130 Answer NETGEAR Support	Vendor Advisory kb.netgear.com text/html	CONFIRM kb.netgear.com/000051475/Security-Advisory-for-Cross-Site-Request-Forgery-on-Some-Extenders-PSV-2016-0130

By selecting these links, you may be leaving CVEreport webspace. We have provided these links to other websites because they may have information that

would be of interest to you. No inferences should be drawn on account of other sites being referenced, or not, from this page. There may be other websites that are more appropriate for your purpose. CVEreport does not necessarily endorse the views expressed, or concur with the facts presented on these sites. Further, CVEreport does not endorse any commercial products that may be mentioned on these sites. Please address comments about any linked pages to comment@cve.report.

There are currently no QIDs associated with this CVE

Known Affected Configurations (CPE V2.3)

Type	Vendor	Product	Version	Update	Edition	Language
Hardware 	Netgear	Ex6100	-	All	All	All
Hardware 	Netgear	Ex6100	v2	All	All	All
Hardware 	Netgear	Ex6100	-	All	All	All
Hardware 	Netgear	Ex6100	v2	All	All	All
Operating System	Netgear	Ex6100 Firmware	All	All	All	All
Operating System	Netgear	Ex6100 Firmware	All	All	All	All
Hardware 	Netgear	Ex6150	v2	All	All	All
Hardware 	Netgear	Ex6150	v2	All	All	All
Operating System	Netgear	Ex6150 Firmware	All	All	All	All
Operating System	Netgear	Ex6150 Firmware	All	All	All	All
Hardware 	Netgear	Ex6200	v2	All	All	All
Hardware 	Netgear	Ex6200	v2	All	All	All
Operating System	Netgear	Ex6200 Firmware	All	All	All	All
Operating System	Netgear	Ex6200 Firmware	All	All	All	All
Hardware 	Netgear	Ex6400	-	All	All	All
Hardware 	Netgear	Ex6400	-	All	All	All
Operating System	Netgear	Ex6400 Firmware	All	All	All	All
Operating System	Netgear	Ex6400 Firmware	All	All	All	All
Hardware 	Netgear	Ex7300	-	All	All	All
Hardware 	Netgear	Ex7300	-	All	All	All
Operating System	Netgear	Ex7300 Firmware	All	All	All	All
Operating	Netgear	Ex7300 Firmware	All	All	All	All

System						
Hardware		Netgear	Wn3000rp	v3	All	All
Hardware		Netgear	Wn3000rp	v3	All	All
Operating System		Netgear	Wn3000rp Firmware	All	All	All
Operating System		Netgear	Wn3000rp Firmware	All	All	All
cpe:2.3:h:netgear:ex6100:-:*~::~:						
cpe:2.3:h:netgear:ex6100:v2:*~::~:						
cpe:2.3:h:netgear:ex6100:-:*~::~:						
cpe:2.3:h:netgear:ex6100:v2:*~::~:						
cpe:2.3:o:netgear:ex6100_firmware:*~::~:						
cpe:2.3:o:netgear:ex6100_firmware:*~::~:						
cpe:2.3:h:netgear:ex6150:v2:*~::~:						
cpe:2.3:h:netgear:ex6150:v2:*~::~:						
cpe:2.3:o:netgear:ex6150_firmware:*~::~:						
cpe:2.3:o:netgear:ex6150_firmware:*~::~:						
cpe:2.3:h:netgear:ex6200:v2:*~::~:						
cpe:2.3:h:netgear:ex6200:v2:*~::~:						
cpe:2.3:o:netgear:ex6200_firmware:*~::~:						
cpe:2.3:o:netgear:ex6200_firmware:*~::~:						
cpe:2.3:h:netgear:ex6400:-:*~::~:						
cpe:2.3:h:netgear:ex6400:-:*~::~:						
cpe:2.3:o:netgear:ex6400_firmware:*~::~:						
cpe:2.3:o:netgear:ex6400_firmware:*~::~:						
cpe:2.3:h:netgear:ex7300:-:*~::~:						
cpe:2.3:h:netgear:ex7300:-:*~::~:						
cpe:2.3:o:netgear:ex7300_firmware:*~::~:						
cpe:2.3:o:netgear:ex7300_firmware:*~::~:						
cpe:2.3:h:netgear:wn3000rp:v3:*~::~:						
cpe:2.3:h:netgear:wn3000rp:v3:*~::~:						

cpe:2.3:o:netgear:wn3000rp_vo:

cpe:2.3:o:netgear:wn3000rp_firmware:*****:

cpe:2.3:o:netgear:wn3000rp_firmware:*****:

No vendor comments have been submitted for this CVE

← Previous ID

Next ID →