



CVE-2017-2873

Published on: 09/19/2018 12:00:00 AM UTC

Last Modified on: 06/07/2022 05:21:00 PM UTC


CVE-2017-2873

[Source: Mitre](#)

[Source: NIST](#)

[CVE.ORG](#)

[Print: PDF](#)



Certain versions of **C1** from **Foscam** contain the following vulnerability:

An exploitable command injection vulnerability exists in the web management interface used by the Foscam C1 Indoor HD Camera running application firmware 2.52.2.43. A specially crafted HTTP request can allow for a user to inject arbitrary shell characters during the SoftAP configuration resulting in command injection. An attacker can simply send an HTTP request to the device to trigger this

vulnerability.

CVE-2017-2873 has been assigned by [cisco](#) talos-cna@cisco.com to track the vulnerability - currently rated as **HIGH** severity.

Affected Vendor/Software: [cisco](#) **Foscam** - **Foscam C1 Indoor HD Camera** version **Foscam Indoor IP Camera C1 Series**

CVSS3 Score: **7.2 - HIGH**

Attack Vector	Attack Complexity	Privileges Required	User Interaction
NETWORK	LOW	HIGH	NONE
Scope	Confidentiality Impact	Integrity Impact	Availability Impact
UNCHANGED	HIGH	HIGH	HIGH

CVSS2 Score: **6.5 - MEDIUM**

Access Vector	Access Complexity	Authentication
NETWORK	LOW	SINGLE
Confidentiality Impact	Integrity Impact	Availability Impact
PARTIAL	PARTIAL	PARTIAL

CVE References

Description	Tags	Link
-------------	------	------

By selecting these links, you may be leaving CVEreport webspace. We have provided these links to other websites because they may have information that would be of interest to you. No inferences should be drawn on account of other sites being referenced, or not, from this page. There may be other websites that are more appropriate for your purpose. CVEreport does not necessarily endorse the views expressed, or concur with the facts presented on these sites. Further, CVEreport does not endorse any commercial products that may be mentioned on these sites. Please address comments about any linked pages to comment@cve.report.

There are currently no QIDs associated with this CVE

Known Affected Configurations (CPE V2.3)

Type	Vendor	Product	Version	Update	Edition	Language
Hardware	Foscam	C1	-	All	All	All
Hardware	Foscam	C1	-	All	All	All
Operating System	Foscam	C1 Firmware	2.52.2.43	All	All	All
Operating System	Foscam	C1 Firmware	2.52.2.43	All	All	All
cpe:2.3:h:foscam:c1:-:~::~~::~~::~~::~~::~~::~~:::						
cpe:2.3:h:foscam:c1:-:~::~~::~~::~~::~~::~~::~~:::						
cpe:2.3:o:foscam:c1_firmware:2.52.2.43:~::~~::~~::~~::~~::~~::~~:::						
cpe:2.3:o:foscam:c1_firmware:2.52.2.43:~::~~::~~::~~::~~::~~::~~:::						

No vendor comments have been submitted for this CVE