




CVE-2017-8771

Published on: 09/20/2017 12:00:00 AM UTC

Last Modified on: 03/23/2021 11:26:43 PM UTC

CVE-2017-8771

[Source: Mitre](#)[Source: NIST](#)[CVE.ORG](#)[Print: PDF](#) 

Certain versions of [Wifi Repeater](#) from [Twsz](#) contain the following vulnerability:

On BE126 WIFI repeater 1.0 devices, an attacker can log into telnet (which is open by default) with default credentials as root (username:"root" password:"root"). The attacker can make a user that is connected to the repeater click on a malicious link that will log into the telnet and will infect the device with malicious code.

CVE-2017-8771 has been assigned by [M](#) cve@mitre.org to track the vulnerability - currently rated as **CRITICAL** severity.

CVSS3 Score: **9.8 - CRITICAL**

Attack Vector	Attack Complexity	Privileges Required	User Interaction
NETWORK	LOW	NONE	NONE
Scope	Confidentiality Impact	Integrity Impact	Availability Impact
UNCHANGED	HIGH	HIGH	HIGH

CVSS2 Score: **10 - HIGH**

Access Vector	Access Complexity	Authentication
NETWORK	LOW	NONE
Confidentiality Impact	Integrity Impact	Availability Impact
COMPLETE	COMPLETE	COMPLETE

CVE References

Description	Tags	Link
	Technical Description	MISC www.digitalwhisper.co.il/files/Zines/0x56/DW86-1-RepeaterHack.pdf
	Third Party Advisory	
	www.digitalwhisper.co.il	

By selecting these links, you may be leaving CVEreport webspace. We have provided these links to other websites because they may have information that would be of interest to you. No inferences should be drawn on account of other sites being referenced, or not, from this page. There may be other websites that are more appropriate for your purpose. CVEreport does not necessarily endorse the views expressed, or concur with the facts presented on these sites. Further, CVEreport does not endorse any commercial products that may be mentioned on these sites. Please address comments about any linked pages to comment@cve.report.

There are currently no QIDs associated with this CVE

Known Affected Configurations (CPE V2.3)

Type	Vendor	Product	Version	Update	Edition	Language
Hardware 	Twsz	Wifi Repeater	-	All	All	All
Hardware 	Twsz	Wifi Repeater	-	All	All	All
Operating System	Twsz	Wifi Repeater Firmware	-	All	All	All
Operating System	Twsz	Wifi Repeater Firmware	-	All	All	All
cpe:2.3:h:twsz:wifi_repeater:-:*:*:*:*:*:						
cpe:2.3:h:twsz:wifi_repeater:-:*:*:*:*:*:						
cpe:2.3:o:twsz:wifi_repeater_firmware:-:*:*:*:*:*:						
cpe:2.3:o:twsz:wifi_repeater_firmware:-:*:*:*:*:*:						

No vendor comments have been submitted for this CVE

[← Previous ID](#)

Next ID→