



CVE-2018-11899

Published on: 02/11/2019 12:00:00 AM UTC

Last Modified on: 03/23/2021 11:24:17 PM UTC

CVE-2018-11899

[Source: Mitre](#)[Source: NIST](#)[CVE.ORG](#)[Print: PDF](#) 

Certain versions of [Mdm9206](#) from [Qualcomm](#) contain the following vulnerability:

While processing radio connection status change events, Radio index is not properly validated in Snapdragon Auto, Snapdragon Connectivity, Snapdragon Consumer IOT, Snapdragon Industrial IOT, Snapdragon Mobile and Snapdragon Voice & Music in versions MDM9206, MDM9607, MDM9640, MDM9650, MSM8996AU, SD

210/SD 212/SD 205, SD 425, SD 427, SD 430, SD 435, SD 439 / SD 429, SD 450, SD 625, SD 636, SD 650/52, SD 675, SD 712 / SD 710 / SD 670, SD 820, SD 820A, SD 835, SD 845 / SD 850, SD 855, SDA660, SDM439, SDM630, SDM660, SDX20, SDX24.

CVE-2018-11899 has been assigned by [Q](#) product-security@qualcomm.com to track the vulnerability - currently rated as **HIGH** severity.

Affected Vendor/Software: [Q](#) Qualcomm, Inc. - Snapdragon Auto, Snapdragon Connectivity, Snapdragon Consumer IOT, Snapdragon Industrial IOT, Snapdragon Mobile, Snapdragon Voice & Music version MDM9206, MDM9607, MDM9640, MDM9650, MSM8996AU, SD 210/SD 212/SD 205, SD 425, SD 427, SD 430, SD 435, SD 439 / SD 429, SD 450, SD 625, SD 636, SD 650/52, SD 675, SD 712 / SD 710 / SD 670, SD 820, SD 820A, SD 835, SD 845 / SD 850, SD 855, SDA660, SDM439, SDM630, SDM660, SDX20, SDX24

CVSS3 Score: **7.8 - HIGH**

Attack Vector	Attack Complexity	Privileges Required	User Interaction
LOCAL	LOW	LOW	NONE
Scope	Confidentiality Impact	Integrity Impact	Availability Impact
UNCHANGED	HIGH	HIGH	HIGH

CVSS2 Score: **4.6 - MEDIUM**

Access Vector	Access Complexity	Authentication
LOCAL	LOW	NONE
Confidentiality	Integrity	Availability

Impact	Impact	Impact
PARTIAL	PARTIAL	PARTIAL

CVE References

Description	Tags	Link
Bulletins Qualcomm	Vendor Advisory www.qualcomm.com text/html	Q CONFIRM www.qualcomm.com/company/product-security/bulletins
By selecting these links, you may be leaving CVEreport webspace. We have provided these links to other websites because they may have information that would be of interest to you. No inferences should be drawn on account of other sites being referenced, or not, from this page. There may be other websites that are more appropriate for your purpose. CVEreport does not necessarily endorse the views expressed, or concur with the facts presented on these sites. Further, CVEreport does not endorse any commercial products that may be mentioned on these sites. Please address comments about any linked pages to comment@cve.report.		

There are currently no QIDs associated with this CVE

Known Affected Configurations (CPE V2.3)

Type	Vendor	Product	Version	Update	Edition	Language
Hardware 	Qualcomm	Mdm9206	-	All	All	All
Hardware 	Qualcomm	Mdm9206	-	All	All	All
Operating System	Qualcomm	Mdm9206 Firmware	-	All	All	All
Operating System	Qualcomm	Mdm9206 Firmware	-	All	All	All
Hardware 	Qualcomm	Mdm9607	-	All	All	All
Hardware 	Qualcomm	Mdm9607	-	All	All	All
Operating System	Qualcomm	Mdm9607 Firmware	-	All	All	All
Operating System	Qualcomm	Mdm9607 Firmware	-	All	All	All
Hardware 	Qualcomm	Mdm9640	-	All	All	All
Hardware 	Qualcomm	Mdm9640	-	All	All	All
Operating System	Qualcomm	Mdm9640 Firmware	-	All	All	All
Operating System	Qualcomm	Mdm9640 Firmware	-	All	All	All
Hardware 	Qualcomm	Mdm9650	-	All	All	All
Hardware 	Qualcomm	Mdm9650	-	All	All	All
Operating System	Qualcomm	Mdm9650 Firmware	-	All	All	All
Operating System	Qualcomm	Mdm9650 Firmware	-	All	All	All

Hardware  	Qualcomm	Msm8996au	-	All	All	All
Hardware  	Qualcomm	Msm8996au	-	All	All	All
Operating System	Qualcomm	Msm8996au Firmware	-	All	All	All
Operating System	Qualcomm	Msm8996au Firmware	-	All	All	All
Hardware  	Qualcomm	Sda660	-	All	All	All
Hardware  	Qualcomm	Sda660	-	All	All	All
Operating System	Qualcomm	Sda660 Firmware	-	All	All	All
Operating System	Qualcomm	Sda660 Firmware	-	All	All	All
Hardware  	Qualcomm	Sdm439	-	All	All	All
Hardware  	Qualcomm	Sdm439	-	All	All	All
Operating System	Qualcomm	Sdm439 Firmware	-	All	All	All
Operating System	Qualcomm	Sdm439 Firmware	-	All	All	All
Hardware  	Qualcomm	Sdm630	-	All	All	All
Hardware  	Qualcomm	Sdm630	-	All	All	All
Operating System	Qualcomm	Sdm630 Firmware	-	All	All	All
Operating System	Qualcomm	Sdm630 Firmware	-	All	All	All
Hardware  	Qualcomm	Sdm660	-	All	All	All
Hardware  	Qualcomm	Sdm660	-	All	All	All
Operating System	Qualcomm	Sdm660 Firmware	-	All	All	All
Operating System	Qualcomm	Sdm660 Firmware	-	All	All	All
Hardware  	Qualcomm	Sdx20	-	All	All	All
Hardware  	Qualcomm	Sdx20	-	All	All	All
Operating System	Qualcomm	Sdx20 Firmware	-	All	All	All
Operating System	Qualcomm	Sdx20 Firmware	-	All	All	All
Hardware  	Qualcomm	Sdx24	-	All	All	All
Hardware  	Qualcomm	Sdx24	-	All	All	All
Operating	Qualcomm	Sdx24 Firmware	-	All	All	All

System						
Operating System	Qualcomm	Sdx24 Firmware	-	All	All	All
Hardware  	Qualcomm	Sd 205	-	All	All	All
Hardware  	Qualcomm	Sd 205	-	All	All	All
Operating System	Qualcomm	Sd 205 Firmware	-	All	All	All
Operating System	Qualcomm	Sd 205 Firmware	-	All	All	All
Hardware  	Qualcomm	Sd 210	-	All	All	All
Hardware  	Qualcomm	Sd 210	-	All	All	All
Operating System	Qualcomm	Sd 210 Firmware	-	All	All	All
Operating System	Qualcomm	Sd 210 Firmware	-	All	All	All
Hardware  	Qualcomm	Sd 212	-	All	All	All
Hardware  	Qualcomm	Sd 212	-	All	All	All
Operating System	Qualcomm	Sd 212 Firmware	-	All	All	All
Operating System	Qualcomm	Sd 212 Firmware	-	All	All	All
Hardware  	Qualcomm	Sd 425	-	All	All	All
Hardware  	Qualcomm	Sd 425	-	All	All	All
Operating System	Qualcomm	Sd 425 Firmware	-	All	All	All
Operating System	Qualcomm	Sd 425 Firmware	-	All	All	All
Hardware  	Qualcomm	Sd 427	-	All	All	All
Hardware  	Qualcomm	Sd 427	-	All	All	All
Operating System	Qualcomm	Sd 427 Firmware	-	All	All	All
Operating System	Qualcomm	Sd 427 Firmware	-	All	All	All
Hardware  	Qualcomm	Sd 429	-	All	All	All
Hardware  	Qualcomm	Sd 429	-	All	All	All
Operating System	Qualcomm	Sd 429 Firmware	-	All	All	All
Operating System	Qualcomm	Sd 429 Firmware	-	All	All	All
Hardware  	Qualcomm	Sd 430	-	All	All	All

Hardware  	Qualcomm	Sd 430	-	All	All	All
Operating System	Qualcomm	Sd 430 Firmware	-	All	All	All
Operating System	Qualcomm	Sd 430 Firmware	-	All	All	All
Hardware  	Qualcomm	Sd 435	-	All	All	All
Hardware  	Qualcomm	Sd 435	-	All	All	All
Operating System	Qualcomm	Sd 435 Firmware	-	All	All	All
Operating System	Qualcomm	Sd 435 Firmware	-	All	All	All
Hardware  	Qualcomm	Sd 439	-	All	All	All
Hardware  	Qualcomm	Sd 439	-	All	All	All
Operating System	Qualcomm	Sd 439 Firmware	-	All	All	All
Operating System	Qualcomm	Sd 439 Firmware	-	All	All	All
Hardware  	Qualcomm	Sd 450	-	All	All	All
Hardware  	Qualcomm	Sd 450	-	All	All	All
Operating System	Qualcomm	Sd 450 Firmware	-	All	All	All
Operating System	Qualcomm	Sd 450 Firmware	-	All	All	All
Hardware  	Qualcomm	Sd 625	-	All	All	All
Hardware  	Qualcomm	Sd 625	-	All	All	All
Operating System	Qualcomm	Sd 625 Firmware	-	All	All	All
Operating System	Qualcomm	Sd 625 Firmware	-	All	All	All
Hardware  	Qualcomm	Sd 636	-	All	All	All
Hardware  	Qualcomm	Sd 636	-	All	All	All
Operating System	Qualcomm	Sd 636 Firmware	-	All	All	All
Operating System	Qualcomm	Sd 636 Firmware	-	All	All	All
Hardware  	Qualcomm	Sd 650	-	All	All	All
Hardware  	Qualcomm	Sd 650	-	All	All	All
Operating System	Qualcomm	Sd 650 Firmware	-	All	All	All

Operating System	Qualcomm	Sd 650 Firmware	-	All	All	All
Hardware  	Qualcomm	Sd 652	-	All	All	All
Hardware  	Qualcomm	Sd 652	-	All	All	All
Operating System	Qualcomm	Sd 652 Firmware	-	All	All	All
Operating System	Qualcomm	Sd 652 Firmware	-	All	All	All
Hardware  	Qualcomm	Sd 670	-	All	All	All
Hardware  	Qualcomm	Sd 670	-	All	All	All
Operating System	Qualcomm	Sd 670 Firmware	-	All	All	All
Operating System	Qualcomm	Sd 670 Firmware	-	All	All	All
Hardware  	Qualcomm	Sd 675	-	All	All	All
Hardware  	Qualcomm	Sd 675	-	All	All	All
Operating System	Qualcomm	Sd 675 Firmware	-	All	All	All
Operating System	Qualcomm	Sd 675 Firmware	-	All	All	All
Hardware  	Qualcomm	Sd 710	-	All	All	All
Hardware  	Qualcomm	Sd 710	-	All	All	All
Operating System	Qualcomm	Sd 710 Firmware	-	All	All	All
Operating System	Qualcomm	Sd 710 Firmware	-	All	All	All
Hardware  	Qualcomm	Sd 712	-	All	All	All
Hardware  	Qualcomm	Sd 712	-	All	All	All
Operating System	Qualcomm	Sd 712 Firmware	-	All	All	All
Operating System	Qualcomm	Sd 712 Firmware	-	All	All	All
Hardware  	Qualcomm	Sd 820	-	All	All	All
Hardware  	Qualcomm	Sd 820	-	All	All	All
Hardware  	Qualcomm	Sd 820a	-	All	All	All
Hardware  	Qualcomm	Sd 820a	-	All	All	All
Operating System	Qualcomm	Sd 820a Firmware	-	All	All	All
Operating System	Qualcomm	Sd 820a Firmware	-	All	All	All

Operating System	Qualcomm	Sd 820 Firmware	-	All	All	All
Operating System	Qualcomm	Sd 820 Firmware	-	All	All	All
Hardware  	Qualcomm	Sd 835	-	All	All	All
Hardware  	Qualcomm	Sd 835	-	All	All	All
Operating System	Qualcomm	Sd 835 Firmware	-	All	All	All
Operating System	Qualcomm	Sd 835 Firmware	-	All	All	All
Hardware  	Qualcomm	Sd 845	-	All	All	All
Hardware  	Qualcomm	Sd 845	-	All	All	All
Operating System	Qualcomm	Sd 845 Firmware	-	All	All	All
Operating System	Qualcomm	Sd 845 Firmware	-	All	All	All
Hardware  	Qualcomm	Sd 850	-	All	All	All
Hardware  	Qualcomm	Sd 850	-	All	All	All
Operating System	Qualcomm	Sd 850 Firmware	-	All	All	All
Operating System	Qualcomm	Sd 850 Firmware	-	All	All	All
Hardware  	Qualcomm	Sd 855	-	All	All	All
Hardware  	Qualcomm	Sd 855	-	All	All	All
Operating System	Qualcomm	Sd 855 Firmware	-	All	All	All
Operating System	Qualcomm	Sd 855 Firmware	-	All	All	All
cpe:2.3:h:qualcomm:mdm9206:-:~::~:						
cpe:2.3:h:qualcomm:mdm9206:-:~::~:						
cpe:2.3:o:qualcomm:mdm9206_firmware:-:~::~:						
cpe:2.3:o:qualcomm:mdm9206_firmware:-:~::~:						
cpe:2.3:h:qualcomm:mdm9607:-:~::~:						
cpe:2.3:h:qualcomm:mdm9607:-:~::~:						
cpe:2.3:o:qualcomm:mdm9607_firmware:-:~::~:						
cpe:2.3:o:qualcomm:mdm9607_firmware:-:~::~:						
cpe:2.3:h:qualcomm:mdm9640:-:~::~:						

```

cpe:2.3.11.qualcomm.msm8940-. . . . .

```

cpe:2.3:h:qualcomm:mdm9640:-:*:*:*:*:*:*:

```
cpe:2.3:o:qualcomm:mdm9640_firmware:-:*:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:mdm9640_firmware:-:*:*:*:*:*:*:
```

cpe:2.3:h:qualcomm:mdm9650:-:*:*:*:*:*:*:

cpe:2.3:h:qualcomm:mdm9650:-:*:*:*:*:*:*:

```
cpe:2.3:o:qualcomm:mdm9650_firmware:-:*:*:*:*:*:*
```

```
cpe:2.3:o:qualcomm:mdm9650_firmware:-:*:*:*:*:*:*:
```

cpe:2.3:h:qualcomm:msm8996au:-:*:*:*:*:*:*:

```
cpe:2.3:h:qualcomm:msm8996au:-:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:msm8996au_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:msm8996au_firmware:-:*:*:*:*:*:
```

cpe:2.3:h:qualcomm:sda660:-:*:*:*:*:*:*:

cpe:2.3:h:qualcomm:sda660:-:*:*:*:*:*:*:

```
cpe:2.3:o:qualcomm:sda660_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:sda660_firmware:-:*:*:*:*:*:*
```

cpe:2.3:h:qualcomm:sdm439:-:*:*:*:*:*:*:

cpe:2.3:h:qualcomm:sdm439:-:*:*:*:*:*:*:

```
cpe:2.3:o:qualcomm:sdm439_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:sdm439_firmware:-:*:*:*:*:*:*
```

```
cpe:2.3:h:qualcomm:sdm630:-:*:*:*:*:*:*:
```

```
cpe:2.3:h:qualcomm:sdm630:-:*:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:sdm630_firmware:-:*:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:sdm630_firmware:-:*:*:*:*:*:
```

cpe:2.3:h:qualcomm:sdm660:-:*:*:*:*:*:*:

cpe:2.3:h:qualcomm:sdm660:-:*:*:*:*:*:*:

```
cpe:2.3:o:qualcomm:sdm660_firmware:-:*:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:sdm660_firmware:-:*:*:*:*:*:
```

cpe:2.3:h:qualcomm:sdx20:-:*:*:*:*:*:*:

cpe:2.3:h:qualcomm:sd_x20:-:*:*:*:*:*:
cpe:2.3:o:qualcomm:sd_x20_firmware:-:*:*:*:*:*:
cpe:2.3:o:qualcomm:sd_x20_firmware:-:*:*:*:*:*:
cpe:2.3:h:qualcomm:sd_x24:-:*:*:*:*:*:
cpe:2.3:h:qualcomm:sd_x24:-:*:*:*:*:*:
cpe:2.3:o:qualcomm:sd_x24_firmware:-:*:*:*:*:*:
cpe:2.3:o:qualcomm:sd_x24_firmware:-:*:*:*:*:*:
cpe:2.3:h:qualcomm:sd_205:-:*:*:*:*:*:
cpe:2.3:h:qualcomm:sd_205:-:*:*:*:*:*:
cpe:2.3:o:qualcomm:sd_205_firmware:-:*:*:*:*:*:
cpe:2.3:o:qualcomm:sd_205_firmware:-:*:*:*:*:*:
cpe:2.3:h:qualcomm:sd_210:-:*:*:*:*:*:
cpe:2.3:h:qualcomm:sd_210:-:*:*:*:*:*:
cpe:2.3:o:qualcomm:sd_210_firmware:-:*:*:*:*:*:
cpe:2.3:o:qualcomm:sd_210_firmware:-:*:*:*:*:*:
cpe:2.3:h:qualcomm:sd_212:-:*:*:*:*:*:
cpe:2.3:h:qualcomm:sd_212:-:*:*:*:*:*:
cpe:2.3:o:qualcomm:sd_212_firmware:-:*:*:*:*:*:
cpe:2.3:o:qualcomm:sd_212_firmware:-:*:*:*:*:*:
cpe:2.3:h:qualcomm:sd_425:-:*:*:*:*:*:
cpe:2.3:h:qualcomm:sd_425:-:*:*:*:*:*:
cpe:2.3:o:qualcomm:sd_425_firmware:-:*:*:*:*:*:
cpe:2.3:o:qualcomm:sd_425_firmware:-:*:*:*:*:*:
cpe:2.3:h:qualcomm:sd_427:-:*:*:*:*:*:
cpe:2.3:h:qualcomm:sd_427:-:*:*:*:*:*:
cpe:2.3:o:qualcomm:sd_427_firmware:-:*:*:*:*:*:
cpe:2.3:o:qualcomm:sd_427_firmware:-:*:*:*:*:*:
cpe:2.3:h:qualcomm:sd_429:-:*:*:*:*:*:

cpe:2.3:h:qualcomm:sd_429:-:~::~~::~~::~~::~~::~~::~~:::
cpe:2.3:o:qualcomm:sd_429_firmware:-:~::~~::~~::~~::~~::~~::~~:::
cpe:2.3:o:qualcomm:sd_429_firmware:-:~::~~::~~::~~::~~::~~::~~:::
cpe:2.3:h:qualcomm:sd_430:-:~::~~::~~::~~::~~::~~::~~:::
cpe:2.3:h:qualcomm:sd_430:-:~::~~::~~::~~::~~::~~::~~:::
cpe:2.3:o:qualcomm:sd_430_firmware:-:~::~~::~~::~~::~~::~~::~~:::
cpe:2.3:o:qualcomm:sd_430_firmware:-:~::~~::~~::~~::~~::~~::~~:::
cpe:2.3:h:qualcomm:sd_435:-:~::~~::~~::~~::~~::~~::~~:::
cpe:2.3:h:qualcomm:sd_435:-:~::~~::~~::~~::~~::~~::~~:::
cpe:2.3:o:qualcomm:sd_435_firmware:-:~::~~::~~::~~::~~::~~::~~:::
cpe:2.3:o:qualcomm:sd_435_firmware:-:~::~~::~~::~~::~~::~~::~~:::
cpe:2.3:h:qualcomm:sd_439:-:~::~~::~~::~~::~~::~~::~~:::
cpe:2.3:h:qualcomm:sd_439:-:~::~~::~~::~~::~~::~~::~~:::
cpe:2.3:o:qualcomm:sd_439_firmware:-:~::~~::~~::~~::~~::~~::~~:::
cpe:2.3:o:qualcomm:sd_439_firmware:-:~::~~::~~::~~::~~::~~::~~:::
cpe:2.3:h:qualcomm:sd_450:-:~::~~::~~::~~::~~::~~::~~:::
cpe:2.3:h:qualcomm:sd_450:-:~::~~::~~::~~::~~::~~::~~:::
cpe:2.3:o:qualcomm:sd_450_firmware:-:~::~~::~~::~~::~~::~~::~~:::
cpe:2.3:o:qualcomm:sd_450_firmware:-:~::~~::~~::~~::~~::~~::~~:::
cpe:2.3:h:qualcomm:sd_625:-:~::~~::~~::~~::~~::~~::~~:::
cpe:2.3:h:qualcomm:sd_625:-:~::~~::~~::~~::~~::~~::~~:::
cpe:2.3:o:qualcomm:sd_625_firmware:-:~::~~::~~::~~::~~::~~::~~:::
cpe:2.3:o:qualcomm:sd_625_firmware:-:~::~~::~~::~~::~~::~~::~~:::
cpe:2.3:h:qualcomm:sd_636:-:~::~~::~~::~~::~~::~~::~~:::
cpe:2.3:h:qualcomm:sd_636:-:~::~~::~~::~~::~~::~~::~~:::
cpe:2.3:o:qualcomm:sd_636_firmware:-:~::~~::~~::~~::~~::~~::~~:::
cpe:2.3:o:qualcomm:sd_636_firmware:-:~::~~::~~::~~::~~::~~::~~:::
cpe:2.3:h:qualcomm:sd_650:-:~::~~::~~::~~::~~::~~::~~:::
cpe:2.3:h:qualcomm:sd_650:-:~::~~::~~::~~::~~::~~::~~:::

cpe:2.3:o:qualcomm:sd_650_firmware:-:~::~~::~~::~~::~~::~~::~~:::
cpe:2.3:o:qualcomm:sd_650_firmware:-:~::~~::~~::~~::~~::~~::~~:::
cpe:2.3:h:qualcomm:sd_652:-:~::~~::~~::~~::~~::~~::~~:::
cpe:2.3:h:qualcomm:sd_652:-:~::~~::~~::~~::~~::~~::~~:::
cpe:2.3:o:qualcomm:sd_652_firmware:-:~::~~::~~::~~::~~::~~::~~:::
cpe:2.3:o:qualcomm:sd_652_firmware:-:~::~~::~~::~~::~~::~~::~~:::
cpe:2.3:h:qualcomm:sd_670:-:~::~~::~~::~~::~~::~~::~~:::
cpe:2.3:h:qualcomm:sd_670:-:~::~~::~~::~~::~~::~~::~~:::
cpe:2.3:o:qualcomm:sd_670_firmware:-:~::~~::~~::~~::~~::~~::~~:::
cpe:2.3:o:qualcomm:sd_670_firmware:-:~::~~::~~::~~::~~::~~::~~:::
cpe:2.3:h:qualcomm:sd_675:-:~::~~::~~::~~::~~::~~::~~:::
cpe:2.3:h:qualcomm:sd_675:-:~::~~::~~::~~::~~::~~::~~:::
cpe:2.3:o:qualcomm:sd_675_firmware:-:~::~~::~~::~~::~~::~~::~~:::
cpe:2.3:o:qualcomm:sd_675_firmware:-:~::~~::~~::~~::~~::~~::~~:::
cpe:2.3:h:qualcomm:sd_710:-:~::~~::~~::~~::~~::~~::~~:::
cpe:2.3:h:qualcomm:sd_710:-:~::~~::~~::~~::~~::~~::~~:::
cpe:2.3:o:qualcomm:sd_710_firmware:-:~::~~::~~::~~::~~::~~::~~:::
cpe:2.3:o:qualcomm:sd_710_firmware:-:~::~~::~~::~~::~~::~~::~~:::
cpe:2.3:h:qualcomm:sd_712:-:~::~~::~~::~~::~~::~~::~~:::
cpe:2.3:h:qualcomm:sd_712:-:~::~~::~~::~~::~~::~~::~~:::
cpe:2.3:o:qualcomm:sd_712_firmware:-:~::~~::~~::~~::~~::~~::~~:::
cpe:2.3:o:qualcomm:sd_712_firmware:-:~::~~::~~::~~::~~::~~::~~:::
cpe:2.3:h:qualcomm:sd_820:-:~::~~::~~::~~::~~::~~::~~:::
cpe:2.3:h:qualcomm:sd_820:-:~::~~::~~::~~::~~::~~::~~:::
cpe:2.3:h:qualcomm:sd_820a:-:~::~~::~~::~~::~~::~~::~~:::
cpe:2.3:h:qualcomm:sd_820a:-:~::~~::~~::~~::~~::~~::~~:::
cpe:2.3:o:qualcomm:sd_820a_firmware:-:~::~~::~~::~~::~~::~~::~~:::
cpe:2.3:o:qualcomm:sd_820a_firmware:-:~::~~::~~::~~::~~::~~::~~:::

cpe:2.3:o:qualcomm:sd_820_firmware:-:~::~:
cpe:2.3:o:qualcomm:sd_820_firmware:-:~::~:
cpe:2.3:h:qualcomm:sd_835:-:~::~:
cpe:2.3:h:qualcomm:sd_835:-:~::~:
cpe:2.3:o:qualcomm:sd_835_firmware:-:~::~:
cpe:2.3:o:qualcomm:sd_835_firmware:-:~::~:
cpe:2.3:h:qualcomm:sd_845:-:~::~:
cpe:2.3:h:qualcomm:sd_845:-:~::~:
cpe:2.3:o:qualcomm:sd_845_firmware:-:~::~:
cpe:2.3:o:qualcomm:sd_845_firmware:-:~::~:
cpe:2.3:h:qualcomm:sd_850:-:~::~:
cpe:2.3:h:qualcomm:sd_850:-:~::~:
cpe:2.3:o:qualcomm:sd_850_firmware:-:~::~:
cpe:2.3:o:qualcomm:sd_850_firmware:-:~::~:
cpe:2.3:h:qualcomm:sd_855:-:~::~:
cpe:2.3:h:qualcomm:sd_855:-:~::~:
cpe:2.3:o:qualcomm:sd_855_firmware:-:~::~:
cpe:2.3:o:qualcomm:sd_855_firmware:-:~::~:

No vendor comments have been submitted for this CVE

[← Previous ID](#)

[Next ID →](#)