



CVE-2018-11925

Published on: 05/24/2019 12:00:00 AM UTC

Last Modified on: 03/23/2021 11:24:18 PM UTC

CVE-2018-11925

[Source: Mitre](#)[Source: NIST](#)[CVE.ORG](#)[Print: PDF](#) 

Certain versions of [lpq4019](#) from [Qualcomm](#) contain the following vulnerability:

Data length received from firmware is not validated against the max allowed size which can result in buffer overflow. in Snapdragon Auto, Snapdragon Compute, Snapdragon Consumer IOT, Snapdragon Industrial IOT, Snapdragon Mobile, Snapdragon Wired Infrastructure and Networking in IPQ4019, IPQ8064, IPQ8074, MDM9150,

MDM9206, MDM9607, MDM9640, MDM9650, QCS605, SD 425, SD 427, SD 430, SD 435, SD 450, SD 625, SD 636, SD 712 / SD 710 / SD 670, SD 835, SD 845 / SD 850, SD 855, SDA660, SDM630, SDM660, SDX20, SDX24

CVE-2018-11925 has been assigned by [Q](#) product-security@qualcomm.com to track the vulnerability - currently rated as **HIGH** severity.

Affected Vendor/Software: [Q](#) Qualcomm, Inc. - Snapdragon Auto, Snapdragon Compute, Snapdragon Consumer IOT, Snapdragon Industrial IOT, Snapdragon Mobile, Snapdragon Wired Infrastructure and Networking version IPQ4019, IPQ8064, IPQ8074, MDM9150, MDM9206, MDM9607, MDM9640, MDM9650, QCS605, SD 425, SD 427, SD 430, SD 435, SD 450, SD 625, SD 636, SD 712 / SD 710 / SD 670, SD 835, SD 845 / SD 850, SD 855, SDA660, SDM630, SDM660, SDX20, SDX24

CVSS3 Score: **7.8 - HIGH**

Attack Vector	Attack Complexity	Privileges Required	User Interaction
LOCAL	LOW	LOW	NONE
Scope	Confidentiality Impact	Integrity Impact	Availability Impact
UNCHANGED	HIGH	HIGH	HIGH

CVSS2 Score: **7.2 - HIGH**

Access Vector	Access Complexity	Authentication
LOCAL	LOW	NONE
Confidentiality Impact	Integrity Impact	Availability Impact

COMPLETE

COMPLETE

COMPLETE

CVE References

Description	Tags	Link
April 2019 Code Aurora Security Bulletin - Code Aurora	Patch Third Party Advisory www.codeaurora.org text/html	 CONFIRM www.codeaurora.org/security-bulletin/2019/04/01/april-2019-code-aurora-security-bulletin

By selecting these links, you may be leaving CVEreport webspace. We have provided these links to other websites because they may have information that would be of interest to you. No inferences should be drawn on account of other sites being referenced, or not, from this page. There may be other websites that are more appropriate for your purpose. CVEreport does not necessarily endorse the views expressed, or concur with the facts presented on these sites. Further, CVEreport does not endorse any commercial products that may be mentioned on these sites. Please address comments about any linked pages to comment@cve.report.

There are currently no QIDs associated with this CVE

Known Affected Configurations (CPE V2.3)

Type	Vendor	Product	Version	Update	Edition	Language
Hardware 	Qualcomm	Ipq4019	-	All	All	All
Hardware 	Qualcomm	Ipq4019	-	All	All	All
Operating System	Qualcomm	Ipq4019 Firmware	-	All	All	All
Operating System	Qualcomm	Ipq4019 Firmware	-	All	All	All
Hardware 	Qualcomm	Ipq8064	-	All	All	All
Hardware 	Qualcomm	Ipq8064	-	All	All	All
Operating System	Qualcomm	Ipq8064 Firmware	-	All	All	All
Operating System	Qualcomm	Ipq8064 Firmware	-	All	All	All
Hardware 	Qualcomm	Ipq8074	-	All	All	All
Hardware 	Qualcomm	Ipq8074	-	All	All	All
Operating System	Qualcomm	Ipq8074 Firmware	-	All	All	All
Operating System	Qualcomm	Ipq8074 Firmware	-	All	All	All
Hardware 	Qualcomm	Mdm9150	-	All	All	All
Hardware 	Qualcomm	Mdm9150	-	All	All	All
Operating System	Qualcomm	Mdm9150 Firmware	-	All	All	All
Operating System	Qualcomm	Mdm9150 Firmware	-	All	All	All

Hardware  	Qualcomm	Mdm9206	-	All	All	All
Hardware  	Qualcomm	Mdm9206	-	All	All	All
Operating System	Qualcomm	Mdm9206 Firmware	-	All	All	All
Operating System	Qualcomm	Mdm9206 Firmware	-	All	All	All
Hardware  	Qualcomm	Mdm9607	-	All	All	All
Hardware  	Qualcomm	Mdm9607	-	All	All	All
Operating System	Qualcomm	Mdm9607 Firmware	-	All	All	All
Operating System	Qualcomm	Mdm9607 Firmware	-	All	All	All
Hardware  	Qualcomm	Mdm9640	-	All	All	All
Hardware  	Qualcomm	Mdm9640	-	All	All	All
Operating System	Qualcomm	Mdm9640 Firmware	-	All	All	All
Operating System	Qualcomm	Mdm9640 Firmware	-	All	All	All
Hardware  	Qualcomm	Mdm9650	-	All	All	All
Hardware  	Qualcomm	Mdm9650	-	All	All	All
Operating System	Qualcomm	Mdm9650 Firmware	-	All	All	All
Operating System	Qualcomm	Mdm9650 Firmware	-	All	All	All
Hardware  	Qualcomm	Qcs605	-	All	All	All
Hardware  	Qualcomm	Qcs605	-	All	All	All
Operating System	Qualcomm	Qcs605 Firmware	-	All	All	All
Operating System	Qualcomm	Qcs605 Firmware	-	All	All	All
Hardware  	Qualcomm	Sda660	-	All	All	All
Hardware  	Qualcomm	Sda660	-	All	All	All
Operating System	Qualcomm	Sda660 Firmware	-	All	All	All
Operating System	Qualcomm	Sda660 Firmware	-	All	All	All
Hardware  	Qualcomm	Sdm630	-	All	All	All
Hardware  	Qualcomm	Sdm630	-	All	All	All
Operating	Qualcomm	Sdm630 Firmware	-	All	All	All

System						
Operating System	Qualcomm	Sdm630 Firmware	-	All	All	All
Hardware  	Qualcomm	Sdm660	-	All	All	All
Hardware  	Qualcomm	Sdm660	-	All	All	All
Operating System	Qualcomm	Sdm660 Firmware	-	All	All	All
Operating System	Qualcomm	Sdm660 Firmware	-	All	All	All
Hardware  	Qualcomm	Sdx20	-	All	All	All
Hardware  	Qualcomm	Sdx20	-	All	All	All
Operating System	Qualcomm	Sdx20 Firmware	-	All	All	All
Operating System	Qualcomm	Sdx20 Firmware	-	All	All	All
Hardware  	Qualcomm	Sdx24	-	All	All	All
Hardware  	Qualcomm	Sdx24	-	All	All	All
Operating System	Qualcomm	Sdx24 Firmware	-	All	All	All
Operating System	Qualcomm	Sdx24 Firmware	-	All	All	All
Hardware  	Qualcomm	Sd 425	-	All	All	All
Hardware  	Qualcomm	Sd 425	-	All	All	All
Operating System	Qualcomm	Sd 425 Firmware	-	All	All	All
Operating System	Qualcomm	Sd 425 Firmware	-	All	All	All
Hardware  	Qualcomm	Sd 427	-	All	All	All
Hardware  	Qualcomm	Sd 427	-	All	All	All
Operating System	Qualcomm	Sd 427 Firmware	-	All	All	All
Operating System	Qualcomm	Sd 427 Firmware	-	All	All	All
Hardware  	Qualcomm	Sd 430	-	All	All	All
Hardware  	Qualcomm	Sd 430	-	All	All	All
Operating System	Qualcomm	Sd 430 Firmware	-	All	All	All
Operating System	Qualcomm	Sd 430 Firmware	-	All	All	All
Hardware  	Qualcomm	Sd 435	-	All	All	All

Hardware  	Qualcomm	Sd 435	-	All	All	All
Operating System	Qualcomm	Sd 435 Firmware	-	All	All	All
Operating System	Qualcomm	Sd 435 Firmware	-	All	All	All
Hardware  	Qualcomm	Sd 450	-	All	All	All
Hardware  	Qualcomm	Sd 450	-	All	All	All
Operating System	Qualcomm	Sd 450 Firmware	-	All	All	All
Operating System	Qualcomm	Sd 450 Firmware	-	All	All	All
Hardware  	Qualcomm	Sd 625	-	All	All	All
Hardware  	Qualcomm	Sd 625	-	All	All	All
Operating System	Qualcomm	Sd 625 Firmware	-	All	All	All
Operating System	Qualcomm	Sd 625 Firmware	-	All	All	All
Hardware  	Qualcomm	Sd 636	-	All	All	All
Hardware  	Qualcomm	Sd 636	-	All	All	All
Operating System	Qualcomm	Sd 636 Firmware	-	All	All	All
Operating System	Qualcomm	Sd 636 Firmware	-	All	All	All
Hardware  	Qualcomm	Sd 670	-	All	All	All
Hardware  	Qualcomm	Sd 670	-	All	All	All
Operating System	Qualcomm	Sd 670 Firmware	-	All	All	All
Operating System	Qualcomm	Sd 670 Firmware	-	All	All	All
Hardware  	Qualcomm	Sd 710	-	All	All	All
Hardware  	Qualcomm	Sd 710	-	All	All	All
Operating System	Qualcomm	Sd 710 Firmware	-	All	All	All
Operating System	Qualcomm	Sd 710 Firmware	-	All	All	All
Hardware  	Qualcomm	Sd 712	-	All	All	All
Hardware  	Qualcomm	Sd 712	-	All	All	All
Operating System	Qualcomm	Sd 712 Firmware	-	All	All	All

Operating System	Qualcomm	Sd 712 Firmware	-	All	All	All
Hardware	Qualcomm	Sd 835	-	All	All	All
Hardware	Qualcomm	Sd 835	-	All	All	All
Operating System	Qualcomm	Sd 835 Firmware	-	All	All	All
Operating System	Qualcomm	Sd 835 Firmware	-	All	All	All
Hardware	Qualcomm	Sd 845	-	All	All	All
Hardware	Qualcomm	Sd 845	-	All	All	All
Operating System	Qualcomm	Sd 845 Firmware	-	All	All	All
Operating System	Qualcomm	Sd 845 Firmware	-	All	All	All
Hardware	Qualcomm	Sd 850	-	All	All	All
Hardware	Qualcomm	Sd 850	-	All	All	All
Operating System	Qualcomm	Sd 850 Firmware	-	All	All	All
Operating System	Qualcomm	Sd 850 Firmware	-	All	All	All
Hardware	Qualcomm	Sd 855	-	All	All	All
Hardware	Qualcomm	Sd 855	-	All	All	All
Operating System	Qualcomm	Sd 855 Firmware	-	All	All	All
Operating System	Qualcomm	Sd 855 Firmware	-	All	All	All
cpe:2.3:h:qualcomm:ipq4019:-:*:*:*:*:*:						
cpe:2.3:h:qualcomm:ipq4019:-:*:*:*:*:*:						
cpe:2.3:o:qualcomm:ipq4019_firmware:-:*:*:*:*:*:						
cpe:2.3:o:qualcomm:ipq4019_firmware:-:*:*:*:*:*:						
cpe:2.3:h:qualcomm:ipq8064:-:*:*:*:*:*:						
cpe:2.3:h:qualcomm:ipq8064:-:*:*:*:*::~:						
cpe:2.3:o:qualcomm:ipq8064_firmware:-:*:*:*:*:*:						
cpe:2.3:o:qualcomm:ipq8064_firmware:-:*:*:*:*::~:						
cpe:2.3:h:qualcomm:ipq8074:-:*:*:*:*::~:						
cpe:2.3:h:qualcomm:ipq8074:-:*:*:*:*::~:						

```
cpe:2.3:o:qualcomm:ipq8074_firmware:-:*:*:*:*:*:*
```

```
cpe:2.3:o:qualcomm:ipq8074_firmware:-:*:*:*:*:*:*
```

cpe:2.3:h:qualcomm:mdm9150:-:*:*:*:*:*:

cpe:2.3:h:qualcomm:mdm9150:-:*:*:*:*:*:

cpe:2.3:o:qualcomm:mdm9150_firmware:-:*:*:*:*:*:

```
cpe:2.3:o:qualcomm:mdm9150_firmware:-:*:*:*:*:*:*:
```

cpe:2.3:h:qualcomm:mdm9206:-:*:*:*:*:*:

cpe:2.3:h:qualcomm:mdm9206:-:*:*:*:*:*:

```
cpe:2.3:o:qualcomm:mdm9206_firmware:-:*:*:*:*:*:*
```

```
cpe:2.3:o:qualcomm:mdm9206_firmware:-:*:*:*:*:*.*
```

cpe:2.3:h:qualcomm:mdm9607:-:*:*:*:*:*:

cpe:2.3:h:qualcomm:mdm9607:-:*:*:*:*:*:

```
cpe:2.3:o:qualcomm:mdm9607_firmware:-:*:*:*:*:*
```

```
cpe:2.3:o:qualcomm:mdm9607_firmware:-:*:*:*:*:*:*
```

```
cpe:2.3:h:qualcomm:mdm9640:-:*:*:*:*:*:
```

```
cpe:2.3:h:qualcomm:mdm9640:-:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:mdm9640_firmware:-:*:*:*:*:*.*
```

```
cpe:2.3:o:qualcomm:mdm9640_firmware:-:*:*:*:*:*:*:
```

cpe:2.3:h:qualcomm:mdm9650:-:*:*:*:*:*:*:

cpe:2.3:h:qualcomm:mdm9650:-:*:*:*:*:*:*:

```
cpe:2.3:o:qualcomm:mdm9650_firmware:-:*:*:*:*:*.*
```

```
cpe:2.3:o:qualcomm:mdm9650_firmware:-:*:*:*:*:*:*
```

cpe:2.3:h:qualcomm:qcs605:-:*:*:*:*:*:*:

cpe:2.3:h:qualcomm:qcs605:-:*:*:*:*:*:*:

```
cpe:2.3:o:qualcomm:qcs605_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:qcs605_firmware:-:*:*:*:*:*:
```

cpe:2.3:h:qualcomm:sda660:-:*:*:*:*:*:*:

```
cpe:2.3:h:qualcomm:sda660:-:*:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:sda660_firmware:-:.*:.*:.*:.*:.*:.*:.*
```

cpe:2.3:o:qualcomm:sda660_firmware:-:*****:
cpe:2.3:h:qualcomm:sdm630:-:*****:
cpe:2.3:h:qualcomm:sdm630:-:*****:
cpe:2.3:o:qualcomm:sdm630_firmware:-:*****:
cpe:2.3:o:qualcomm:sdm630_firmware:-:*****:
cpe:2.3:h:qualcomm:sdm660:-:*****:
cpe:2.3:h:qualcomm:sdm660:-:*****:
cpe:2.3:o:qualcomm:sdm660_firmware:-:*****:
cpe:2.3:o:qualcomm:sdm660_firmware:-:*****:
cpe:2.3:h:qualcomm:sdx20:-:*****:
cpe:2.3:h:qualcomm:sdx20:-:*****:
cpe:2.3:o:qualcomm:sdx20_firmware:-:*****:
cpe:2.3:o:qualcomm:sdx20_firmware:-:*****:
cpe:2.3:h:qualcomm:sdx24:-:*****:
cpe:2.3:h:qualcomm:sdx24:-:*****:
cpe:2.3:o:qualcomm:sdx24_firmware:-:*****:
cpe:2.3:o:qualcomm:sdx24_firmware:-:*****:
cpe:2.3:h:qualcomm:sd_425:-:*****:
cpe:2.3:h:qualcomm:sd_425:-:*****:
cpe:2.3:o:qualcomm:sd_425_firmware:-:*****:
cpe:2.3:o:qualcomm:sd_425_firmware:-:*****:
cpe:2.3:h:qualcomm:sd_427:-:*****:
cpe:2.3:h:qualcomm:sd_427:-:*****:
cpe:2.3:o:qualcomm:sd_427_firmware:-:*****:
cpe:2.3:o:qualcomm:sd_427_firmware:-:*****:
cpe:2.3:h:qualcomm:sd_430:-:*****:
cpe:2.3:h:qualcomm:sd_430:-:*****:
cpe:2.3:o:qualcomm:sd_430_firmware:-:*****:

cpe:2.3:o:qualcomm:sd_430_firmware:-:*****:
cpe:2.3:h:qualcomm:sd_435:-:*****:
cpe:2.3:h:qualcomm:sd_435:-:*****:
cpe:2.3:o:qualcomm:sd_435_firmware:-:*****:
cpe:2.3:o:qualcomm:sd_435_firmware:-:*****:
cpe:2.3:h:qualcomm:sd_450:-:*****:
cpe:2.3:h:qualcomm:sd_450:-:*****:
cpe:2.3:o:qualcomm:sd_450_firmware:-:*****:
cpe:2.3:o:qualcomm:sd_450_firmware:-:*****:
cpe:2.3:h:qualcomm:sd_625:-:*****:
cpe:2.3:h:qualcomm:sd_625:-:*****:
cpe:2.3:o:qualcomm:sd_625_firmware:-:*****:
cpe:2.3:o:qualcomm:sd_625_firmware:-:*****:
cpe:2.3:h:qualcomm:sd_636:-:*****:
cpe:2.3:h:qualcomm:sd_636:-:*****:
cpe:2.3:o:qualcomm:sd_636_firmware:-:*****:
cpe:2.3:o:qualcomm:sd_636_firmware:-:*****:
cpe:2.3:h:qualcomm:sd_670:-:*****:
cpe:2.3:h:qualcomm:sd_670:-:*****:
cpe:2.3:o:qualcomm:sd_670_firmware:-:*****:
cpe:2.3:o:qualcomm:sd_670_firmware:-:*****:
cpe:2.3:h:qualcomm:sd_710:-:*****:
cpe:2.3:h:qualcomm:sd_710:-:*****:
cpe:2.3:o:qualcomm:sd_710_firmware:-:*****:
cpe:2.3:o:qualcomm:sd_710_firmware:-:*****:
cpe:2.3:h:qualcomm:sd_712:-:*****:
cpe:2.3:h:qualcomm:sd_712:-:*****:
cpe:2.3:o:qualcomm:sd_712_firmware:-:*****:
cpe:2.3:o:qualcomm:sd_712_firmware:-:*****:

cpe:2.3:o:qualcomm:sd_712_firmware:-:*****:*
cpe:2.3:h:qualcomm:sd_835:-:*****:*
cpe:2.3:h:qualcomm:sd_835:-:*****:*
cpe:2.3:o:qualcomm:sd_835_firmware:-:*****:*
cpe:2.3:o:qualcomm:sd_835_firmware:-:*****:*
cpe:2.3:h:qualcomm:sd_845:-:*****:*
cpe:2.3:h:qualcomm:sd_845:-:*****:*
cpe:2.3:o:qualcomm:sd_845_firmware:-:*****:*
cpe:2.3:o:qualcomm:sd_845_firmware:-:*****:*
cpe:2.3:h:qualcomm:sd_850:-:*****:*
cpe:2.3:h:qualcomm:sd_850:-:*****:*
cpe:2.3:o:qualcomm:sd_850_firmware:-:*****:*
cpe:2.3:o:qualcomm:sd_850_firmware:-:*****:*
cpe:2.3:h:qualcomm:sd_855:-:*****:*
cpe:2.3:h:qualcomm:sd_855:-:*****:*
cpe:2.3:o:qualcomm:sd_855_firmware:-:*****:*
cpe:2.3:o:qualcomm:sd_855_firmware:-:*****:*

No vendor comments have been submitted for this CVE

[← Previous ID](#)

[Next ID →](#)