



# CVE-2018-11937


Published on: 05/24/2019 12:00:00 AM UTC

Last Modified on: 03/23/2021 11:24:17 PM UTC

## CVE-2018-11937

[Source: Mitre](#)[Source: NIST](#)[CVE.ORG](#)[Print: PDF](#)

CVSS:30/AV:N/AC:L/PR:N/UI:N/S:U/C:H/I:H/A:H



Certain versions of [Mdm9150](#) from [Qualcomm](#) contain the following vulnerability:

Lack of input validation before copying can lead to a buffer over read in WLAN function in Snapdragon Auto, Snapdragon Compute, Snapdragon Consumer IOT, Snapdragon Industrial IOT, Snapdragon Mobile in MDM9150, MDM9206, MDM9607, MDM9640, MDM9650, MSM8996AU, QCA6574AU, QCS605, SD 425, SD 427, SD 430, SD 435, SD 450, SD 625, SD 636, SD 675, SD 712 / SD 710 / SD 670, SD 820A, SD 835, SD 845 / SD 850, SD 855, SDA660, SDM630, SDM660, SDX20, SDX24, SM7150

CVE-2018-11937 has been assigned by [Q](#) product-security@qualcomm.com to track the vulnerability - currently rated as **CRITICAL** severity.

Affected Vendor/Software: [Q](#) Qualcomm, Inc. - Snapdragon Auto, Snapdragon Compute, Snapdragon Consumer IOT, Snapdragon Industrial IOT, Snapdragon Mobile version MDM9150, MDM9206, MDM9607, MDM9640, MDM9650, MSM8996AU, QCA6574AU, QCS605, SD 425, SD 427, SD 430, SD 435, SD 450, SD 625, SD 636, SD 675, SD 712 / SD 710 / SD 670, SD 820A, SD 835, SD 845 / SD 850, SD 855, SDA660, SDM630, SDM660, SDX20, SDX24, SM7150

CVSS3 Score: **9.8 - CRITICAL**

| Attack Vector    | Attack Complexity      | Privileges Required | User Interaction    |
|------------------|------------------------|---------------------|---------------------|
| <b>NETWORK</b>   | <b>LOW</b>             | <b>NONE</b>         | <b>NONE</b>         |
| Scope            | Confidentiality Impact | Integrity Impact    | Availability Impact |
| <b>UNCHANGED</b> | <b>HIGH</b>            | <b>HIGH</b>         | <b>HIGH</b>         |

CVSS2 Score: **10 - HIGH**

| Access Vector          | Access Complexity | Authentication      |
|------------------------|-------------------|---------------------|
| <b>NETWORK</b>         | <b>LOW</b>        | <b>NONE</b>         |
| Confidentiality Impact | Integrity Impact  | Availability Impact |
| <b>COMPLETE</b>        | <b>COMPLETE</b>   | <b>COMPLETE</b>     |

## CVE References

| Description                                            | Tags                                                                                                                             | Link                                                                                                                                                                                                                                                                                             |
|--------------------------------------------------------|----------------------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| April 2019 Code Aurora Security Bulletin - Code Aurora | <a href="#">Patch</a><br><a href="#">Third Party Advisory</a><br><a href="#">www.codeaurora.org</a><br><a href="#">text/html</a> |  CONFIRM <a href="http://www.codeaurora.org/security-bulletin/2019/04/01/april-2019-code-aurora-security-bulletin">www.codeaurora.org/security-bulletin/2019/04/01/april-2019-code-aurora-security-bulletin</a> |

By selecting these links, you may be leaving CVEreport webspace. We have provided these links to other websites because they may have information that would be of interest to you. No inferences should be drawn on account of other sites being referenced, or not, from this page. There may be other websites that are more appropriate for your purpose. CVEreport does not necessarily endorse the views expressed, or concur with the facts presented on these sites. Further, CVEreport does not endorse any commercial products that may be mentioned on these sites. Please address comments about any linked pages to [comment@cve.report](mailto:comment@cve.report).

There are currently no QIDs associated with this CVE

## Known Affected Configurations (CPE V2.3)

| Type                                                                                         | Vendor                   | Product                          | Version | Update | Edition | Language |
|----------------------------------------------------------------------------------------------|--------------------------|----------------------------------|---------|--------|---------|----------|
| Hardware    | <a href="#">Qualcomm</a> | <a href="#">Mdm9150</a>          | -       | All    | All     | All      |
| Hardware    | <a href="#">Qualcomm</a> | <a href="#">Mdm9150</a>          | -       | All    | All     | All      |
| Operating System                                                                             | <a href="#">Qualcomm</a> | <a href="#">Mdm9150 Firmware</a> | -       | All    | All     | All      |
| Operating System                                                                             | <a href="#">Qualcomm</a> | <a href="#">Mdm9150 Firmware</a> | -       | All    | All     | All      |
| Hardware  | <a href="#">Qualcomm</a> | <a href="#">Mdm9206</a>          | -       | All    | All     | All      |
| Hardware  | <a href="#">Qualcomm</a> | <a href="#">Mdm9206</a>          | -       | All    | All     | All      |
| Operating System                                                                             | <a href="#">Qualcomm</a> | <a href="#">Mdm9206 Firmware</a> | -       | All    | All     | All      |
| Operating System                                                                             | <a href="#">Qualcomm</a> | <a href="#">Mdm9206 Firmware</a> | -       | All    | All     | All      |
| Hardware  | <a href="#">Qualcomm</a> | <a href="#">Mdm9607</a>          | -       | All    | All     | All      |
| Hardware  | <a href="#">Qualcomm</a> | <a href="#">Mdm9607</a>          | -       | All    | All     | All      |
| Operating System                                                                             | <a href="#">Qualcomm</a> | <a href="#">Mdm9607 Firmware</a> | -       | All    | All     | All      |
| Operating System                                                                             | <a href="#">Qualcomm</a> | <a href="#">Mdm9607 Firmware</a> | -       | All    | All     | All      |
| Hardware  | <a href="#">Qualcomm</a> | <a href="#">Mdm9640</a>          | -       | All    | All     | All      |
| Hardware  | <a href="#">Qualcomm</a> | <a href="#">Mdm9640</a>          | -       | All    | All     | All      |
| Operating System                                                                             | <a href="#">Qualcomm</a> | <a href="#">Mdm9640 Firmware</a> | -       | All    | All     | All      |
| Operating System                                                                             | <a href="#">Qualcomm</a> | <a href="#">Mdm9640 Firmware</a> | -       | All    | All     | All      |
| Hardware  | <a href="#">Qualcomm</a> | <a href="#">Mdm9650</a>          | -       | All    | All     | All      |

| Hardware                                                                                         | Qualcomm | Memory             |   | RAM | RAM | RAM |
|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------|--------------------|---|-----|-----|-----|
| Hardware       | Qualcomm | Mdm9650            | - | All | All | All |
| Operating System                                                                                                                                                                 | Qualcomm | Mdm9650 Firmware   | - | All | All | All |
| Operating System                                                                                                                                                                 | Qualcomm | Mdm9650 Firmware   | - | All | All | All |
| Hardware       | Qualcomm | Msm8996au          | - | All | All | All |
| Hardware       | Qualcomm | Msm8996au          | - | All | All | All |
| Operating System                                                                                                                                                                 | Qualcomm | Msm8996au Firmware | - | All | All | All |
| Operating System                                                                                                                                                                 | Qualcomm | Msm8996au Firmware | - | All | All | All |
| Hardware       | Qualcomm | Qca6574au          | - | All | All | All |
| Hardware       | Qualcomm | Qca6574au          | - | All | All | All |
| Operating System                                                                                                                                                                 | Qualcomm | Qca6574au Firmware | - | All | All | All |
| Operating System                                                                                                                                                                 | Qualcomm | Qca6574au Firmware | - | All | All | All |
| Hardware   | Qualcomm | Qcs605             | - | All | All | All |
| Hardware   | Qualcomm | Qcs605             | - | All | All | All |
| Operating System                                                                                                                                                                 | Qualcomm | Qcs605 Firmware    | - | All | All | All |
| Operating System                                                                                                                                                                 | Qualcomm | Qcs605 Firmware    | - | All | All | All |
| Hardware   | Qualcomm | Sda660             | - | All | All | All |
| Hardware   | Qualcomm | Sda660             | - | All | All | All |
| Operating System                                                                                                                                                                 | Qualcomm | Sda660 Firmware    | - | All | All | All |
| Operating System                                                                                                                                                                 | Qualcomm | Sda660 Firmware    | - | All | All | All |
| Hardware   | Qualcomm | Sdm630             | - | All | All | All |
| Hardware   | Qualcomm | Sdm630             | - | All | All | All |
| Operating System                                                                                                                                                                 | Qualcomm | Sdm630 Firmware    | - | All | All | All |
| Operating System                                                                                                                                                                 | Qualcomm | Sdm630 Firmware    | - | All | All | All |
| Hardware   | Qualcomm | Sdm660             | - | All | All | All |
| Hardware   | Qualcomm | Sdm660             | - | All | All | All |
| Operating System                                                                                                                                                                 | Qualcomm | Sdm660 Firmware    | - | All | All | All |

|                                                                                                                                                                                  |          |                 |   |     |     |     |
|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------|-----------------|---|-----|-----|-----|
| Operating System                                                                                                                                                                 | Qualcomm | Sdm660 Firmware | - | All | All | All |
| Hardware       | Qualcomm | Sdx20           | - | All | All | All |
| Hardware       | Qualcomm | Sdx20           | - | All | All | All |
| Operating System                                                                                                                                                                 | Qualcomm | Sdx20 Firmware  | - | All | All | All |
| Operating System                                                                                                                                                                 | Qualcomm | Sdx20 Firmware  | - | All | All | All |
| Hardware       | Qualcomm | Sdx24           | - | All | All | All |
| Hardware       | Qualcomm | Sdx24           | - | All | All | All |
| Operating System                                                                                                                                                                 | Qualcomm | Sdx24 Firmware  | - | All | All | All |
| Operating System                                                                                                                                                                 | Qualcomm | Sdx24 Firmware  | - | All | All | All |
| Hardware       | Qualcomm | Sd 425          | - | All | All | All |
| Hardware       | Qualcomm | Sd 425          | - | All | All | All |
| Operating System                                                                                                                                                                 | Qualcomm | Sd 425 Firmware | - | All | All | All |
| Operating System                                                                                                                                                                 | Qualcomm | Sd 425 Firmware | - | All | All | All |
| Hardware   | Qualcomm | Sd 427          | - | All | All | All |
| Hardware   | Qualcomm | Sd 427          | - | All | All | All |
| Operating System                                                                                                                                                                 | Qualcomm | Sd 427 Firmware | - | All | All | All |
| Operating System                                                                                                                                                                 | Qualcomm | Sd 427 Firmware | - | All | All | All |
| Hardware   | Qualcomm | Sd 430          | - | All | All | All |
| Hardware   | Qualcomm | Sd 430          | - | All | All | All |
| Operating System                                                                                                                                                                 | Qualcomm | Sd 430 Firmware | - | All | All | All |
| Operating System                                                                                                                                                                 | Qualcomm | Sd 430 Firmware | - | All | All | All |
| Hardware   | Qualcomm | Sd 435          | - | All | All | All |
| Hardware   | Qualcomm | Sd 435          | - | All | All | All |
| Operating System                                                                                                                                                                 | Qualcomm | Sd 435 Firmware | - | All | All | All |
| Operating System                                                                                                                                                                 | Qualcomm | Sd 435 Firmware | - | All | All | All |
| Hardware   | Qualcomm | Sd 450          | - | All | All | All |
| Hardware   | Qualcomm | Sd 450          | - | All | All | All |

| Hardware      | Qualcomm | Sd 100          | - | All | All | All |
|----------------------------------------------------------------------------------------------|----------|-----------------|---|-----|-----|-----|
| Operating System                                                                             | Qualcomm | Sd 450 Firmware | - | All | All | All |
| Operating System                                                                             | Qualcomm | Sd 450 Firmware | - | All | All | All |
| Hardware    | Qualcomm | Sd 625          | - | All | All | All |
| Hardware    | Qualcomm | Sd 625          | - | All | All | All |
| Operating System                                                                             | Qualcomm | Sd 625 Firmware | - | All | All | All |
| Operating System                                                                             | Qualcomm | Sd 625 Firmware | - | All | All | All |
| Hardware    | Qualcomm | Sd 636          | - | All | All | All |
| Hardware    | Qualcomm | Sd 636          | - | All | All | All |
| Operating System                                                                             | Qualcomm | Sd 636 Firmware | - | All | All | All |
| Operating System                                                                             | Qualcomm | Sd 636 Firmware | - | All | All | All |
| Hardware    | Qualcomm | Sd 670          | - | All | All | All |
| Hardware   | Qualcomm | Sd 670          | - | All | All | All |
| Operating System                                                                             | Qualcomm | Sd 670 Firmware | - | All | All | All |
| Operating System                                                                             | Qualcomm | Sd 670 Firmware | - | All | All | All |
| Hardware  | Qualcomm | Sd 675          | - | All | All | All |
| Hardware  | Qualcomm | Sd 675          | - | All | All | All |
| Operating System                                                                             | Qualcomm | Sd 675 Firmware | - | All | All | All |
| Operating System                                                                             | Qualcomm | Sd 675 Firmware | - | All | All | All |
| Hardware  | Qualcomm | Sd 710          | - | All | All | All |
| Hardware  | Qualcomm | Sd 710          | - | All | All | All |
| Operating System                                                                             | Qualcomm | Sd 710 Firmware | - | All | All | All |
| Operating System                                                                             | Qualcomm | Sd 710 Firmware | - | All | All | All |
| Hardware  | Qualcomm | Sd 712          | - | All | All | All |
| Hardware  | Qualcomm | Sd 712          | - | All | All | All |
| Operating System                                                                             | Qualcomm | Sd 712 Firmware | - | All | All | All |
| Operating System                                                                             | Qualcomm | Sd 712 Firmware | - | All | All | All |



```
cpe:2.3:o:qualcomm:mdm9150_firmware:-:*:*:*:*:*.*
```

```
cpe:2.3:o:qualcomm:mdm9150_firmware:-:*:*:*:*:*:*
```

cpe:2.3:h:qualcomm:mdm9206:-:\*:\*:\*:\*:\*:\*:

cpe:2.3:h:qualcomm:mdm9206:-:\*:\*:\*:\*:\*:

```
cpe:2.3:o:qualcomm:mdm9206_firmware:-:*:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:mdm9206_firmware:-:*:*:*:*:*:*
```

cpe:2.3:h:qualcomm:mdm9607:-:\*:\*:\*:\*:\*:

cpe:2.3:h:qualcomm:mdm9607:-:\*:\*:\*:\*:\*:

```
cpe:2.3:o:qualcomm:mdm9607_firmware:-:*:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:mdm9607_firmware:-:*:*:*:*:*.*
```

cpe:2.3:h:qualcomm:mdm9640:-:\*:\*:\*:\*:\*:

```
cpe:2.3:h:qualcomm:mdm9640:-:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:mdm9640_firmware:-:*:*:*:*:*
```

```
cpe:2.3:o:qualcomm:mdm9640_firmware:-:*:*:*:*:*.*
```

cpe:2.3:h:qualcomm:mdm9650:-:\*:\*:\*:\*:\*:

cpe:2.3:h:qualcomm:mdm9650:-:\*:\*:\*:\*:\*:

```
cpe:2.3:o:qualcomm:mdm9650_firmware:-:*:*:*:*:*
```

```
cpe:2.3:o:qualcomm:mdm9650_firmware:-:*:*:*:*:*:*:
```

cpe:2.3:h:qualcomm:msm8996au:-:\*:\*:\*:\*:\*:\*:

```
cpe:2.3:h:qualcomm:msm8996au:-:*:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:msm8996au firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:msm8996au firmware:-.*:.*:.*:.*:.*:.*
```

cpe:2.3:h:qualcomm:qca6574au:-:\*:\*:\*:\*:\*:

cpe:2.3:h:qualcomm:qca6574au:-:\*:\*:\*:\*:\*:\*:

```
cpe:2.3:o:qualcomm:qca6574au_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:qca6574au_firmware:-:*:*:*:*:*.*
```

cpe:2.3:h:qualcomm:gcs605:-:\*:\*:\*:\*:\*:\*:

cpe:2.3:h:qualcomm:gcs605:-:\*:\*:\*:\*:\*:\*:

```
cpe:2.3:o:qualcomm:qcs605_firmware:-:*:*:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:qcs605_firmware:-:*:*:*:*:*:*
```

cpe:2.3:h:qualcomm:sda660:-:\*:\*:\*:\*:\*:\*:

cpe:2.3:h:qualcomm:sda660:-:\*:\*:\*:\*:\*:\*:

```
cpe:2.3:o:qualcomm:sda660_firmware:-:*:*:*:*:*:*
```

```
cpe:2.3:o:qualcomm:sda660_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:h:qualcomm:sdm630:-:*:*:*:*:*:*:
```

```
cpe:2.3:h:qualcomm:sdm630:-:*:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:sdm630 firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:sdm630 firmware:-:*:*:*:*:*:
```

```
cpe:2.3:h:qualcomm:sdm660:-:*:*:*:*:*:*:
```

cpe:2.3:h:qualcomm:sdm660:-:\*:\*:\*:\*:\*:\*:

```
cpe:2.3:o:qualcomm:sdm660_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:sdm660_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:h:qualcomm:sdx20:-:*:*:*:*:*:
```

```
cpe:2.3:h:qualcomm:sdx20:-:*:*:*:*:*:*:
```

cpe:2.3:o:qualcomm:sdx20\_firmware:-:\*:\*:\*:\*:\*

```
cpe:2.3:o:qualcomm:sdx20_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:h:qualcomm:sdx24:-:*:*:*:*:*:*:
```

cpe:2.3:h:qualcomm:sdx24:-:\*:\*:\*:\*:\*:

```
cpe:2.3:o:qualcomm:sdx24_firmware:-:*:*:*:*:*:
```

cpe:2.3:o:qualcomm:sdx24\_firmware:-:\*:\*:\*:\*:\*

```
cpe:2.3:h:qualcomm:sd_425:-:*:*:*:*:*:*:
```

```
cpe:2.3:h:qualcomm:sd 425:-:*:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:sd 425 firmware:-:*:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:sd 425 firmware:-:*:*:*:*:*:
```

```
cpe:2.3:h:qualcomm:sd_427:-:*:*:*:*:*:*:
```

```
cpe:2.3:h:qualcomm:sd_427:-:*:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:sd_427_firmware:-:*:*:*:*:*:
```



```
cpe:2.3:o:qualcomm:sd_427_firmware:-:*:*:*:*:*:*:
```

```
cpe:2.3:h:qualcomm:sd_430:-:*:*:*:*:*:*:
```

cpe:2.3:h:qualcomm:sd\_430:-:\*:\*:\*:\*:\*:\*:

```
cpe:2.3:o:qualcomm:sd_430_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:sd_430_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:h:qualcomm:sd_435:-:*:*:*:*:*:
```

```
cpe:2.3:h:qualcomm:sd_435:-:*:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:sd 435 firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:sd_435_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:h:qualcomm:sd_450:-:*:*:*:*:*:*:
```

```
cpe:2.3:h:qualcomm:sd_450:-:*:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:sd_450_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:sd 450 firmware:-:*:*:*:*:*:
```

cpe:2.3:h:qualcomm:sd\_625:-:\*:\*:\*:\*:\*:

cpe:2.3:h:qualcomm:sd\_625:-:\*:\*:\*:\*:\*:

```
cpe:2.3:o:qualcomm:sd_625_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:sd 625 firmware:-:*:*:*:*:*:
```

```
cpe:2.3:h:qualcomm:sd_636:-:*:*:*:*:*:*:
```

```
cpe:2.3:h:qualcomm:sd_636:-:*:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:sd_636_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:sd_636_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:h:qualcomm:sd 670:-:*:*:*:*:*:*:
```

```
cpe:2.3:h:qualcomm:sd 670:-:*:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:sd 670 firmware:-:~::~~::~~::~~::~~::~::
```

```
cpe:2.3:o:qualcomm:sd_670_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:h:qualcomm:sd_675:-:*:*:*:*:*:*:
```

```
cpe:2.3:h:qualcomm:sd_675:-:*:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:sd 675 firmware:-:*.***.***.***
```

```
cne:2.3.0:qualcomm:sd 675 firmware:~*~*~*~*~*~*
```

```
cpu.2.0.0.qualcomm.com_070_minivare . . . . .
```

```
cpe:2.3:h:qualcomm:sd_710:-:*:*:*:*:*:
```

```
cpe:2.3:h:qualcomm:sd_710:-:*:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:sd_710_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:sd_710_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:h:qualcomm:sd_712:-:*:*:*:*:*:*:
```

```
cpe:2.3:h:qualcomm:sd_712:-:*:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:sd_712_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:sd_712_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:h:qualcomm:sd_820a:-:*:*:*:*:*:
```

```
cpe:2.3:h:qualcomm:sd_820a:-:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:sd_820a_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:sd_820a_firmware:-:*:*:*:*:*:*:
```

```
cpe:2.3:h:qualcomm:sd_835:-:*:*:*:*:*:*:
```

```
cpe:2.3:h:qualcomm:sd_835:-:*:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:sd_835_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:sd_835_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:h:qualcomm:sd_845:-:*:*:*:*:*:*:
```

```
cpe:2.3:h:qualcomm:sd_845:-:*:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:sd_845_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:sd_845_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:h:qualcomm:sd_850:-:*:*:*:*:*:*:
```

```
cpe:2.3:h:qualcomm:sd_850:-:*:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:sd_850_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:sd_850_firmware:-:*:*:*:*:*:
```

cpe:2.3:h:qualcomm:sd\_855:-:\*:\*:\*:\*:\*:\*:

cpe:2.3:h:qualcomm:sd\_855:-:\*:\*:\*:\*:\*:\*:

```
cpe:2.3:o:qualcomm:sd_855_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:sd_855_firmware:-:*:*:*:*:*:
```

cpe:2.3:h:qualcomm:sm7150:-:\*\*\*\*\*:

cpe:2.3:h:qualcomm:sm7150:-:\*\*\*\*\*:

cpe:2.3:o:qualcomm:sm7150\_firmware:-:\*\*\*\*\*:

cpe:2.3:o:qualcomm:sm7150\_firmware:-:\*\*\*\*\*:

No vendor comments have been submitted for this CVE

← Previous ID

Next ID →