



CVE-2018-13315

[MITRE](#)[NVD](#)[CVE.ORG](#)[JSON API](#)[Print: PDF !\[\]\(003082e50e3009141f59bd5df831749f_img.jpg\)](#)

Summary

CVE	CVE-2018-13315
State	PUBLIC
Assigner	cve@mitre.org
Source Priority	CVE Program / NVD first with legacy fallback
Published	2018-11-26 23:29:00 UTC
Updated	2018-12-20 15:54:00 UTC
Description	Incorrect access control in formPasswordSetup in TOTOLINK A3002RU version 1.0.8 allows attackers to change the admin

Risk And Classification

Problem Types: CWE-20

NVD Known Affected Configurations (CPE 2.3)

Type	Vendor	Product	Version	Update	Edition	Language
Hardware	Totolink	A3002ru	-	All	All	All
Hardware	Totolink	A3002ru	-	All	All	All
Operating System	Totolink	A3002ru Firmware	1.0.8	All	All	All
Operating System	Totolink	A3002ru Firmware	1.0.8	All	All	All

References

Reference	Source	Link	Tags
New Vulnerabilities in TOTOLINK A3002RU – Independent Security Evaluators	MISC	blog.securityevaluators.com	Exploit, Third Party
CVE Program record	CVE.ORG	www.cve.org	canonical
NVD vulnerability detail	NVD	nvd.nist.gov	canonical, analysis

No vendor comments have been submitted for this CVE.

There are currently no legacy QID mappings associated with this CVE.

this information or its use. Any use of this information is at the user's risk. It is the responsibility of user to evaluate the accuracy, completeness or usefulness of any information, opinion, advice or other content. EACH USER WILL BE SOLELY RESPONSIBLE FOR ANY consequences of his or her direct or indirect use of this web site. ALL WARRANTIES OF ANY KIND ARE EXPRESSLY DISCLAIMED. This site will NOT BE LIABLE FOR ANY DIRECT, INDIRECT or any other kind of loss.

CVE, CWE, and OVAL are registered trademarks of [The MITRE Corporation](#) and the authoritative source of CVE content is [MITRE's CVE web site](#). This site includes MITRE data granted under the following [license](#).

Free CVE JSON API [cve.report/api](#)

CVE.report and Source URL Uptime Status [status.cve.report](#)