




CVE-2018-13885

Published on: 05/24/2019 12:00:00 AM UTC

Last Modified on: 03/23/2021 11:24:29 PM UTC

CVE-2018-13885

[Source: Mitre](#)[Source: NIST](#)[CVE.ORG](#)[Print: PDF](#) 

Certain versions of [Mdm9150](#) from [Qualcomm](#) contain the following vulnerability:

Possible memory overread may be lead to access of sensitive data in Snapdragon Auto, Snapdragon Compute, Snapdragon Consumer IOT, Snapdragon Industrial IOT, Snapdragon Mobile, Snapdragon Wearables in MDM9150, MDM9206, MDM9607, MDM9615, MDM9625, MDM9635M, MDM9650, MDM9655, QCS605, Qualcomm 215, SD

210/SD 212/SD 205, SD 425, SD 427, SD 430, SD 435, SD 439 / SD 429, SD 450, SD 625, SD 632, SD 636, SD 675, SD 712 / SD 710 / SD 670, SD 835, SD 845 / SD 850, SDA660, SDM439, SDM630, SDM660, SDX20, SM7150, SXR1130

CVE-2018-13885 has been assigned by [Q](#) product-security@qualcomm.com to track the vulnerability - currently rated as **MEDIUM** severity.

Affected Vendor/Software: [Q](#) Qualcomm, Inc. - Snapdragon Auto, Snapdragon Compute, Snapdragon Consumer IOT, Snapdragon Industrial IOT, Snapdragon Mobile, Snapdragon Wearables version MDM9150, MDM9206, MDM9607, MDM9615, MDM9625, MDM9635M, MDM9650, MDM9655, QCS605, Qualcomm 215, SD 210/SD 212/SD 205, SD 425, SD 427, SD 430, SD 435, SD 439 / SD 429, SD 450, SD 625, SD 632, SD 636, SD 675, SD 712 / SD 710 / SD 670, SD 835, SD 845 / SD 850, SDA660, SDM439, SDM630, SDM660, SDX20, SM7150, SXR1130

CVSS3 Score: **5.5 - MEDIUM**

Attack Vector	Attack Complexity	Privileges Required	User Interaction
LOCAL	LOW	LOW	NONE
Scope	Confidentiality Impact	Integrity Impact	Availability Impact
UNCHANGED	HIGH	NONE	NONE

CVSS2 Score: **4.9 - MEDIUM**

Access Vector	Access Complexity	Authentication
LOCAL	LOW	NONE
Confidentiality	Integrity	Availability

Impact	Impact	Impact
COMPLETE	NONE	NONE

CVE References		
Description	Tags	Link
Bulletins Qualcomm	Vendor Advisory www.qualcomm.com text/html	Q CONFIRM www.qualcomm.com/company/product-security/bulletins#_CVE-2018-13885
By selecting these links, you may be leaving CVEreport webspace. We have provided these links to other websites because they may have information that would be of interest to you. No inferences should be drawn on account of other sites being referenced, or not, from this page. There may be other websites that are more appropriate for your purpose. CVEreport does not necessarily endorse the views expressed, or concur with the facts presented on these sites. Further, CVEreport does not endorse any commercial products that may be mentioned on these sites. Please address comments about any linked pages to comment@cve.report.		

There are currently no QIDs associated with this CVE

Known Affected Configurations (CPE V2.3)						
Type	Vendor	Product	Version	Update	Edition	Language
Hardware 	Qualcomm	Mdm9150	-	All	All	All
Hardware 	Qualcomm	Mdm9150	-	All	All	All
Operating System	Qualcomm	Mdm9150 Firmware	-	All	All	All
Operating System	Qualcomm	Mdm9150 Firmware	-	All	All	All
Hardware 	Qualcomm	Mdm9206	-	All	All	All
Hardware 	Qualcomm	Mdm9206	-	All	All	All
Operating System	Qualcomm	Mdm9206 Firmware	-	All	All	All
Operating System	Qualcomm	Mdm9206 Firmware	-	All	All	All
Hardware 	Qualcomm	Mdm9607	-	All	All	All
Hardware 	Qualcomm	Mdm9607	-	All	All	All
Operating System	Qualcomm	Mdm9607 Firmware	-	All	All	All
Operating System	Qualcomm	Mdm9607 Firmware	-	All	All	All
Hardware 	Qualcomm	Mdm9615	-	All	All	All
Hardware 	Qualcomm	Mdm9615	-	All	All	All
Operating System	Qualcomm	Mdm9615 Firmware	-	All	All	All
Operating System	Qualcomm	Mdm9615 Firmware	-	All	All	All

Hardware  	Qualcomm	Mdm9625	-	All	All	All
Hardware  	Qualcomm	Mdm9625	-	All	All	All
Operating System	Qualcomm	Mdm9625 Firmware	-	All	All	All
Operating System	Qualcomm	Mdm9625 Firmware	-	All	All	All
Hardware  	Qualcomm	Mdm9635m	-	All	All	All
Hardware  	Qualcomm	Mdm9635m	-	All	All	All
Operating System	Qualcomm	Mdm9635m Firmware	-	All	All	All
Operating System	Qualcomm	Mdm9635m Firmware	-	All	All	All
Hardware  	Qualcomm	Mdm9650	-	All	All	All
Hardware  	Qualcomm	Mdm9650	-	All	All	All
Operating System	Qualcomm	Mdm9650 Firmware	-	All	All	All
Operating System	Qualcomm	Mdm9650 Firmware	-	All	All	All
Hardware  	Qualcomm	Mdm9655	-	All	All	All
Hardware  	Qualcomm	Mdm9655	-	All	All	All
Operating System	Qualcomm	Mdm9655 Firmware	-	All	All	All
Operating System	Qualcomm	Mdm9655 Firmware	-	All	All	All
Hardware  	Qualcomm	Qcs605	-	All	All	All
Hardware  	Qualcomm	Qcs605	-	All	All	All
Operating System	Qualcomm	Qcs605 Firmware	-	All	All	All
Operating System	Qualcomm	Qcs605 Firmware	-	All	All	All
Hardware  	Qualcomm	Qm215	-	All	All	All
Hardware  	Qualcomm	Qm215	-	All	All	All
Operating System	Qualcomm	Qm215 Firmware	-	All	All	All
Operating System	Qualcomm	Qm215 Firmware	-	All	All	All
Hardware  	Qualcomm	Sda660	-	All	All	All
Hardware  	Qualcomm	Sda660	-	All	All	All
Operating	Qualcomm	Sda660 Firmware	-	All	All	All

System						
Operating System	Qualcomm	Sda660 Firmware	-	All	All	All
Hardware  	Qualcomm	Sdm439	-	All	All	All
Hardware  	Qualcomm	Sdm439	-	All	All	All
Operating System	Qualcomm	Sdm439 Firmware	-	All	All	All
Operating System	Qualcomm	Sdm439 Firmware	-	All	All	All
Hardware  	Qualcomm	Sdm630	-	All	All	All
Hardware  	Qualcomm	Sdm630	-	All	All	All
Operating System	Qualcomm	Sdm630 Firmware	-	All	All	All
Operating System	Qualcomm	Sdm630 Firmware	-	All	All	All
Hardware  	Qualcomm	Sdm660	-	All	All	All
Hardware  	Qualcomm	Sdm660	-	All	All	All
Operating System	Qualcomm	Sdm660 Firmware	-	All	All	All
Operating System	Qualcomm	Sdm660 Firmware	-	All	All	All
Hardware  	Qualcomm	Sdx20	-	All	All	All
Hardware  	Qualcomm	Sdx20	-	All	All	All
Operating System	Qualcomm	Sdx20 Firmware	-	All	All	All
Operating System	Qualcomm	Sdx20 Firmware	-	All	All	All
Hardware  	Qualcomm	Sd 205	-	All	All	All
Hardware  	Qualcomm	Sd 205	-	All	All	All
Operating System	Qualcomm	Sd 205 Firmware	-	All	All	All
Operating System	Qualcomm	Sd 205 Firmware	-	All	All	All
Hardware  	Qualcomm	Sd 210	-	All	All	All
Hardware  	Qualcomm	Sd 210	-	All	All	All
Operating System	Qualcomm	Sd 210 Firmware	-	All	All	All
Operating System	Qualcomm	Sd 210 Firmware	-	All	All	All
Hardware  	Qualcomm	Sd 212	-	All	All	All

Hardware  	Qualcomm	Sd 212	-	All	All	All
Operating System	Qualcomm	Sd 212 Firmware	-	All	All	All
Operating System	Qualcomm	Sd 212 Firmware	-	All	All	All
Hardware  	Qualcomm	Sd 425	-	All	All	All
Hardware  	Qualcomm	Sd 425	-	All	All	All
Operating System	Qualcomm	Sd 425 Firmware	-	All	All	All
Operating System	Qualcomm	Sd 425 Firmware	-	All	All	All
Hardware  	Qualcomm	Sd 427	-	All	All	All
Hardware  	Qualcomm	Sd 427	-	All	All	All
Operating System	Qualcomm	Sd 427 Firmware	-	All	All	All
Operating System	Qualcomm	Sd 427 Firmware	-	All	All	All
Hardware  	Qualcomm	Sd 429	-	All	All	All
Hardware  	Qualcomm	Sd 429	-	All	All	All
Operating System	Qualcomm	Sd 429 Firmware	-	All	All	All
Operating System	Qualcomm	Sd 429 Firmware	-	All	All	All
Hardware  	Qualcomm	Sd 430	-	All	All	All
Hardware  	Qualcomm	Sd 430	-	All	All	All
Operating System	Qualcomm	Sd 430 Firmware	-	All	All	All
Operating System	Qualcomm	Sd 430 Firmware	-	All	All	All
Hardware  	Qualcomm	Sd 435	-	All	All	All
Hardware  	Qualcomm	Sd 435	-	All	All	All
Operating System	Qualcomm	Sd 435 Firmware	-	All	All	All
Operating System	Qualcomm	Sd 435 Firmware	-	All	All	All
Hardware  	Qualcomm	Sd 439	-	All	All	All
Hardware  	Qualcomm	Sd 439	-	All	All	All
Operating System	Qualcomm	Sd 439 Firmware	-	All	All	All

Operating System	Qualcomm	Sd 439 Firmware	-	All	All	All
Hardware  	Qualcomm	Sd 450	-	All	All	All
Hardware  	Qualcomm	Sd 450	-	All	All	All
Operating System	Qualcomm	Sd 450 Firmware	-	All	All	All
Operating System	Qualcomm	Sd 450 Firmware	-	All	All	All
Hardware  	Qualcomm	Sd 625	-	All	All	All
Hardware  	Qualcomm	Sd 625	-	All	All	All
Operating System	Qualcomm	Sd 625 Firmware	-	All	All	All
Operating System	Qualcomm	Sd 625 Firmware	-	All	All	All
Hardware  	Qualcomm	Sd 632	-	All	All	All
Hardware  	Qualcomm	Sd 632	-	All	All	All
Operating System	Qualcomm	Sd 632 Firmware	-	All	All	All
Operating System	Qualcomm	Sd 632 Firmware	-	All	All	All
Hardware  	Qualcomm	Sd 636	-	All	All	All
Hardware  	Qualcomm	Sd 636	-	All	All	All
Operating System	Qualcomm	Sd 636 Firmware	-	All	All	All
Operating System	Qualcomm	Sd 636 Firmware	-	All	All	All
Hardware  	Qualcomm	Sd 670	-	All	All	All
Hardware  	Qualcomm	Sd 670	-	All	All	All
Operating System	Qualcomm	Sd 670 Firmware	-	All	All	All
Operating System	Qualcomm	Sd 670 Firmware	-	All	All	All
Hardware  	Qualcomm	Sd 675	-	All	All	All
Hardware  	Qualcomm	Sd 675	-	All	All	All
Operating System	Qualcomm	Sd 675 Firmware	-	All	All	All
Operating System	Qualcomm	Sd 675 Firmware	-	All	All	All
Hardware  	Qualcomm	Sd 710	-	All	All	All
Hardware  	Qualcomm	Sd 710	-	All	All	All

Operating System	Qualcomm	Sd 710 Firmware	-	All	All	All
Operating System	Qualcomm	Sd 710 Firmware	-	All	All	All
Hardware  	Qualcomm	Sd 712	-	All	All	All
Hardware  	Qualcomm	Sd 712	-	All	All	All
Operating System	Qualcomm	Sd 712 Firmware	-	All	All	All
Operating System	Qualcomm	Sd 712 Firmware	-	All	All	All
Hardware  	Qualcomm	Sd 835	-	All	All	All
Hardware  	Qualcomm	Sd 835	-	All	All	All
Operating System	Qualcomm	Sd 835 Firmware	-	All	All	All
Operating System	Qualcomm	Sd 835 Firmware	-	All	All	All
Hardware  	Qualcomm	Sd 845	-	All	All	All
Hardware  	Qualcomm	Sd 845	-	All	All	All
Operating System	Qualcomm	Sd 845 Firmware	-	All	All	All
Operating System	Qualcomm	Sd 845 Firmware	-	All	All	All
Hardware  	Qualcomm	Sd 850	-	All	All	All
Hardware  	Qualcomm	Sd 850	-	All	All	All
Operating System	Qualcomm	Sd 850 Firmware	-	All	All	All
Operating System	Qualcomm	Sd 850 Firmware	-	All	All	All
Hardware  	Qualcomm	Sm7150	-	All	All	All
Hardware  	Qualcomm	Sm7150	-	All	All	All
Operating System	Qualcomm	Sm7150 Firmware	-	All	All	All
Operating System	Qualcomm	Sm7150 Firmware	-	All	All	All
Hardware  	Qualcomm	Sxr1130	-	All	All	All
Hardware  	Qualcomm	Sxr1130	-	All	All	All
Operating System	Qualcomm	Sxr1130 Firmware	-	All	All	All
Operating System	Qualcomm	Sxr1130 Firmware	-	All	All	All

cpe:2.3:h:qualcomm:mdm9150:-:*:*:*:*:*:*:

cpe:2.3:h:qualcomm:mdm9150:-:*:*:*:*:*:*:

```
cpe:2.3:o:qualcomm:mdm9150_firmware:-:*:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:mdm9150_firmware:-:*:*:*:*:*:*:
```

cpe:2.3:h:qualcomm:mdm9206:-:*:*:*:*:*:*:

cpe:2.3:h:qualcomm:mdm9206:-:*:*:*:*:*:*:

```
cpe:2.3:o:qualcomm:mdm9206_firmware:-:*:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:mdm9206_firmware:-:*:*:*:*:*:*
```

```
cpe:2.3:h:qualcomm:mdm9607:-:*:*:*:*:*:
```

```
cpe:2.3:h:qualcomm:mdm9607:-:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:mdm9607_firmware:-:*:*:*:*:*:*
```

```
cpe:2.3:o:qualcomm:mdm9607_firmware:-:*:*:*:*:*.*
```

cpe:2.3:h:qualcomm:mdm9615:-:*:*:*:*:*:

```
cpe:2.3:h:qualcomm:mdm9615:-:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:mdm9615_firmware:-:*:*:*:*:*
```

```
cpe:2.3:o:qualcomm:mdm9615_firmware:-:*:*:*:*:*.*
```

cpe:2.3:h:qualcomm:mdm9625:-:*:*:*:*:*:*:

cpe:2.3:h:qualcomm:mdm9625:-:*:*:*:*:*:

```
cpe:2.3:o:qualcomm:mdm9625_firmware:-:*:*:*:*:*
```

```
cpe:2.3:o:qualcomm:mdm9625_firmware:-:*:*:*:*:*:
```

cpe:2.3:h:qualcomm:mdm9635m:-:*:*:*:*:*:

cpe:2.3:h:qualcomm:mdm9635m:-:*:*:*:*:*:*:

```
cpe:2.3:o:qualcomm:mdm9635m_firmware:-:*:*:*:*:*.*
```

```
cpe:2.3:o:qualcomm:mdm9635m_firmware:-:*:*:*:*:*.*
```

cpe:2.3:h:qualcomm:mdm9650:-:*:*:*:*:*:*:

```
cpe:2.3:h:qualcomm:mdm9650:-:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:mdm9650_firmware:-:*:*:*:*:*.*
```

```
cpe:2.3:o:qualcomm:mdm9650_firmware:-:*:*:*:*:*
```


cpe:2.3:h:qualcomm:mdm9655:-:*:*:*:*:*:*:

cpe:2.3:h:qualcomm:mdm9655:-:*:*:*:*:*:*:

```
cpe:2.3:o:qualcomm:mdm9655_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:mdm9655_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:h:qualcomm:qcs605:-:*:*:*:*:*:*:
```

cpe:2.3:h:qualcomm:qcs605:-:*:*:*:*:*:*:

```
cpe:2.3:o:qualcomm:qcs605_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:qcs605_firmware:-:*:*:*:*:*:*:
```

cpe:2.3:h:qualcomm:qm215:-:*:*:*:*:*:*:

cpe:2.3:h:qualcomm:qm215:-:*:*:*:*:*:*:

```
cpe:2.3:o:qualcomm:qm215_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:qm215_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:h:qualcomm:sda660:-:*:*:*:*:*:*:
```

```
cpe:2.3:h:qualcomm:sda660:-:*:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:sda660_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:sda660_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:h:qualcomm:sdm439:-:*:*:*:*:*:*:
```

```
cpe:2.3:h:qualcomm:sdm439:-:*:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:sdm439_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:sdm439_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:h:qualcomm:sdm630:-:*:*:*:*:*:
```

```
cpe:2.3:h:qualcomm:sdm630:-:*:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:sdm630_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:sdm630_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:h:qualcomm:sdm660:-:*:*:*:*:*:
```

```
cpe:2.3:h:qualcomm:sdm660:-:*:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:sdm660 firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:sdm660_firmware:-:*:*:*:*:*:
```

cpe:2.3:h:qualcomm:sdx20:-:*:*:*:*:*:*:

cpe:2.3:h:qualcomm:sd_x20:-:~::~~::~~::~~::~~::~~::~~:::
cpe:2.3:o:qualcomm:sd_x20_firmware:-:~::~~::~~::~~::~~::~~::~~:::
cpe:2.3:o:qualcomm:sd_x20_firmware:-:~::~~::~~::~~::~~::~~::~~:::
cpe:2.3:h:qualcomm:sd_205:-:~::~~::~~::~~::~~::~~::~~:::
cpe:2.3:h:qualcomm:sd_205:-:~::~~::~~::~~::~~::~~::~~:::
cpe:2.3:o:qualcomm:sd_205_firmware:-:~::~~::~~::~~::~~::~~::~~:::
cpe:2.3:o:qualcomm:sd_205_firmware:-:~::~~::~~::~~::~~::~~::~~:::
cpe:2.3:h:qualcomm:sd_210:-:~::~~::~~::~~::~~::~~::~~:::
cpe:2.3:h:qualcomm:sd_210:-:~::~~::~~::~~::~~::~~::~~:::
cpe:2.3:o:qualcomm:sd_210_firmware:-:~::~~::~~::~~::~~::~~::~~:::
cpe:2.3:o:qualcomm:sd_210_firmware:-:~::~~::~~::~~::~~::~~::~~:::
cpe:2.3:h:qualcomm:sd_212:-:~::~~::~~::~~::~~::~~::~~:::
cpe:2.3:h:qualcomm:sd_212:-:~::~~::~~::~~::~~::~~::~~:::
cpe:2.3:o:qualcomm:sd_212_firmware:-:~::~~::~~::~~::~~::~~::~~:::
cpe:2.3:o:qualcomm:sd_212_firmware:-:~::~~::~~::~~::~~::~~::~~:::
cpe:2.3:h:qualcomm:sd_425:-:~::~~::~~::~~::~~::~~::~~:::
cpe:2.3:h:qualcomm:sd_425:-:~::~~::~~::~~::~~::~~::~~:::
cpe:2.3:o:qualcomm:sd_425_firmware:-:~::~~::~~::~~::~~::~~::~~:::
cpe:2.3:o:qualcomm:sd_425_firmware:-:~::~~::~~::~~::~~::~~::~~:::
cpe:2.3:h:qualcomm:sd_427:-:~::~~::~~::~~::~~::~~::~~:::
cpe:2.3:h:qualcomm:sd_427:-:~::~~::~~::~~::~~::~~::~~:::
cpe:2.3:o:qualcomm:sd_427_firmware:-:~::~~::~~::~~::~~::~~::~~:::
cpe:2.3:o:qualcomm:sd_427_firmware:-:~::~~::~~::~~::~~::~~::~~:::
cpe:2.3:h:qualcomm:sd_429:-:~::~~::~~::~~::~~::~~::~~:::
cpe:2.3:h:qualcomm:sd_429:-:~::~~::~~::~~::~~::~~::~~:::
cpe:2.3:o:qualcomm:sd_429_firmware:-:~::~~::~~::~~::~~::~~::~~:::
cpe:2.3:o:qualcomm:sd_429_firmware:-:~::~~::~~::~~::~~::~~::~~:::
cpe:2.3:h:qualcomm:sd_430:-:~::~~::~~::~~::~~::~~::~~:::

cpe:2.3:h:qualcomm:sd_430:-:~::~~::~~::~~::~~::~~::~~:::
cpe:2.3:o:qualcomm:sd_430_firmware:-:~::~~::~~::~~::~~::~~::~~:::
cpe:2.3:o:qualcomm:sd_430_firmware:-:~::~~::~~::~~::~~::~~::~~:::
cpe:2.3:h:qualcomm:sd_435:-:~::~~::~~::~~::~~::~~::~~:::
cpe:2.3:h:qualcomm:sd_435:-:~::~~::~~::~~::~~::~~::~~:::
cpe:2.3:o:qualcomm:sd_435_firmware:-:~::~~::~~::~~::~~::~~::~~:::
cpe:2.3:o:qualcomm:sd_435_firmware:-:~::~~::~~::~~::~~::~~::~~:::
cpe:2.3:h:qualcomm:sd_439:-:~::~~::~~::~~::~~::~~::~~:::
cpe:2.3:h:qualcomm:sd_439:-:~::~~::~~::~~::~~::~~::~~:::
cpe:2.3:o:qualcomm:sd_439_firmware:-:~::~~::~~::~~::~~::~~::~~:::
cpe:2.3:o:qualcomm:sd_439_firmware:-:~::~~::~~::~~::~~::~~::~~:::
cpe:2.3:h:qualcomm:sd_450:-:~::~~::~~::~~::~~::~~::~~:::
cpe:2.3:h:qualcomm:sd_450:-:~::~~::~~::~~::~~::~~::~~:::
cpe:2.3:o:qualcomm:sd_450_firmware:-:~::~~::~~::~~::~~::~~::~~:::
cpe:2.3:o:qualcomm:sd_450_firmware:-:~::~~::~~::~~::~~::~~::~~:::
cpe:2.3:h:qualcomm:sd_625:-:~::~~::~~::~~::~~::~~::~~:::
cpe:2.3:h:qualcomm:sd_625:-:~::~~::~~::~~::~~::~~::~~:::
cpe:2.3:o:qualcomm:sd_625_firmware:-:~::~~::~~::~~::~~::~~::~~:::
cpe:2.3:o:qualcomm:sd_625_firmware:-:~::~~::~~::~~::~~::~~::~~:::
cpe:2.3:h:qualcomm:sd_632:-:~::~~::~~::~~::~~::~~::~~:::
cpe:2.3:h:qualcomm:sd_632:-:~::~~::~~::~~::~~::~~::~~:::
cpe:2.3:o:qualcomm:sd_632_firmware:-:~::~~::~~::~~::~~::~~::~~:::
cpe:2.3:o:qualcomm:sd_632_firmware:-:~::~~::~~::~~::~~::~~::~~:::
cpe:2.3:h:qualcomm:sd_636:-:~::~~::~~::~~::~~::~~::~~:::
cpe:2.3:h:qualcomm:sd_636:-:~::~~::~~::~~::~~::~~::~~:::
cpe:2.3:o:qualcomm:sd_636_firmware:-:~::~~::~~::~~::~~::~~::~~:::
cpe:2.3:o:qualcomm:sd_636_firmware:-:~::~~::~~::~~::~~::~~::~~:::
cpe:2.3:h:qualcomm:sd_670:-:~::~~::~~::~~::~~::~~::~~:::
cpe:2.3:h:qualcomm:sd_670:-:~::~~::~~::~~::~~::~~::~~:::

```
cpe:2.3:o:qualcomm:sd_670_firmware:-:*:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:sd_670_firmware:-:*:*:*:*:*:
```

cpe:2.3:h:qualcomm:sd_675:-:*:*:*:*:*:*:

cpe:2.3:h:qualcomm:sd_675:-:*:*:*:*:*:

```
cpe:2.3:o:qualcomm:sd_675_firmware:-:*:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:sd_675_firmware:-:*:*:*:*:*:*:
```

cpe:2.3:h:qualcomm:sd_710:-:*:*:*:*:*:*:

```
cpe:2.3:h:qualcomm:sd_710:-:*:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:sd_710_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:sd_710_firmware:-:*:*:*:*:*:
```

cpe:2.3:h:qualcomm:sd_712:-:*:*:*:*:*:

cpe:2.3:h:qualcomm:sd_712:-:*:*:*:*:*:

```
cpe:2.3:o:qualcomm:sd 712 firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:sd_712_firmware:-:*:*:*:*:*:*:
```

cpe:2.3:h:qualcomm:sd_835:-:*:*:*:*:*:*:

cpe:2.3:h:qualcomm:sd_835:-:*:*:*:*:*:*:

```
cpe:2.3:o:qualcomm:sd_835_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:sd_835_firmware:-:*:*:*:*:*:*
```

cpe:2.3:h:qualcomm:sd_845:-:*:*:*:*:*:

cpe:2.3:h:qualcomm:sd_845:-:*:*:*:*:*:*:

```
cpe:2.3:o:qualcomm:sd_845_firmware:-:*:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:sd_845_firmware:-:*:*:*:*:*:*:
```

cpe:2.3:h:qualcomm:sd_850:-:*:*:*:*:*:*:

cpe:2.3:h:qualcomm:sd_850:-:*:*:*:*:*:*:

```
cpe:2.3:o:qualcomm:sd_850_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:sd_850_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:h:qualcomm:sm7150:-:*:*:*:*:*:
```

cpe:2.3:h:qualcomm:sm7150:-:*:*:*:*:*:*:

cpe:2.3:o:qualcomm:sm7150_firmware:-:*****:	
cpe:2.3:o:qualcomm:sm7150_firmware:-:*****:	
cpe:2.3:h:qualcomm:sxr1130:-:*****:	
cpe:2.3:h:qualcomm:sxr1130:-:*****:	
cpe:2.3:o:qualcomm:sxr1130_firmware:-:*****:	
cpe:2.3:o:qualcomm:sxr1130_firmware:-:*****:	
No vendor comments have been submitted for this CVE	
← Previous ID	Next ID →