




CVE-2018-15355

Published on: 08/17/2018 12:00:00 AM UTC

Last Modified on: 03/23/2021 11:24:27 PM UTC

CVE-2018-15355

[Source: Mitre](#)[Source: NIST](#)[CVE.ORG](#)[Print: PDF](#) 

Certain versions of **24f2xg Router** from **Kraftway** contain the following vulnerability:

Usage of SSLv2 and SSLv3 leads to transmitted data decryption in Kraftway 24F2XG Router firmware 3.5.30.1118.

CVE-2018-15355 has been assigned by **k** vulnerability@kaspersky.com to track the vulnerability - currently rated as **MEDIUM** severity.

Affected Vendor/Software: **k** **Kaspersky Lab - Kraftway** version **Kraftway 24F2XG Router firmware 3.5.30.1118**

CVSS3 Score: **5.9 - MEDIUM**

Attack Vector	Attack Complexity	Privileges Required	User Interaction
NETWORK	HIGH	NONE	NONE
Scope	Confidentiality Impact	Integrity Impact	Availability Impact
UNCHANGED	HIGH	NONE	NONE

CVSS2 Score: **4.3 - MEDIUM**

Access Vector	Access Complexity	Authentication
NETWORK	MEDIUM	NONE
Confidentiality Impact	Integrity Impact	Availability Impact
PARTIAL	NONE	NONE

CVE References

Description	Tags	Link
KLCERT-18-011: Kraftway-24F2XG Router Outdated Certificate Usage Kaspersky ICS CERT	US Government Resource ics-cert.kaspersky.com/text/html	MISC ics-cert.kaspersky.com/advisories/kcert-advisories/2018/08/17/kcert-18-011-kraftway-24f2xg-router-outdated-certificate-usage/

Created 6 months ago

By selecting these links, you may be leaving CVEreport webspace. We have provided these links to other websites because they may have information that would be of interest to you. No inferences should be drawn on account of other sites being referenced, or not, from this page. There may be other websites that are more appropriate for your purpose. CVEreport does not necessarily endorse the views expressed, or concur with the facts presented on these sites. Further, CVEreport does not endorse any commercial products that may be mentioned on these sites. Please address comments about any linked pages to comment@cve.report.

There are currently no QIDs associated with this CVE

Known Affected Configurations (CPE V2.3)

Type	Vendor	Product	Version	Update	Edition	Language
Hardware 	Kraftway	24f2xg Router	-	All	All	All
Hardware 	Kraftway	24f2xg Router	-	All	All	All
Operating System	Kraftway	24f2xg Router Firmware	All	All	All	All
<code>cpe:2.3:h:kraftway:24f2xg_router:-:~::~~::~~::~~::~~::~~::~~::</code>						
<code>cpe:2.3:h:kraftway:24f2xg_router:-:~::~~::~~::~~::~~::~~::~~::</code>						
<code>cpe:2.3:o:kraftway:24f2xg_router_firmware:~::~~::~~::~~::~~::~~::~~::</code>						

No vendor comments have been submitted for this CVE

← Previous ID

Next ID →