



CVE-2018-15702

[MITRE](#)[NVD](#)[CVE.ORG](#)[JSON API](#)[Print: PDF](#)

Summary

CVE	CVE-2018-15702
State	PUBLIC
Assigner	vulnreport@tenable.com
Source Priority	CVE Program / NVD first with legacy fallback
Published	2018-10-01 20:29:00 UTC
Updated	2018-11-27 20:06:00 UTC
Description	The web interface in TP-Link TL-WRN841N 0.9.1 4.16 v0348.0 is vulnerable to CSRF due to insufficient validation of the re

Risk And Classification

Problem Types: CWE-352

NVD Known Affected Configurations (CPE 2.3)

Type	Vendor	Product	Version	Update	Edition	Language
Hardware	Tp-link	Tl-wrn841n	-	All	All	All
Hardware	Tp-link	Tl-wrn841n	-	All	All	All
Operating System	Tp-link	Tl-wrn841n Firmware	0.9.1_4.16_v0348.0	All	All	All
Operating System	Tp-link	Tl-wrn841n Firmware	0.9.1_4.16_v0348.0	All	All	All

References

Reference	Source	Link	Tags
[R1] TP-Link TL-WRN841N Multiple Vulnerabilities - Research Advisory Tenable®	MISC	www.tenable.com	Vendor Advisory
CVE Program record	CVE.ORG	www.cve.org	canonical
NVD vulnerability detail	NVD	nvd.nist.gov	canonical, analysis

No vendor comments have been submitted for this CVE.

There are currently no legacy QID mappings associated with this CVE.

completeness or usefulness of any information, opinion, advice or other content. EACH USER WILL BE SOLELY RESPONSIBLE FOR ANY consequences of his or her direct or indirect use of this web site. ALL WARRANTIES OF ANY KIND ARE EXPRESSLY DISCLAIMED. This site will NOT BE LIABLE FOR ANY DIRECT, INDIRECT or any other kind of loss.

CVE, CWE, and OVAL are registered trademarks of [The MITRE Corporation](#) and the authoritative source of CVE content is [MITRE's CVE web site](#). This site includes MITRE data granted under the following [license](#).

Free CVE JSON API cve.report/api

CVE.report and Source URL Uptime Status status.cve.report