



CVE-2018-17989

[MITRE](#)[NVD](#)[CVE.ORG](#)[JSON API](#)[Print: PDF](#)

Summary

CVE	CVE-2018-17989
State	PUBLIC
Assigner	cve@mitre.org
Source Priority	CVE Program / NVD first with legacy fallback
Published	2019-04-01 21:29:00 UTC
Updated	2019-04-02 19:24:00 UTC
Description	A stored XSS vulnerability exists in the web interface on D-Link DSL-3782 devices with firmware 1.01 that allows authenticat

Risk And Classification

Problem Types: CWE-79

NVD Known Affected Configurations (CPE 2.3)

Type	Vendor	Product	Version	Update	Edition	Language
Hardware	Dlink	Dsl-3782	-	All	All	All
Hardware	Dlink	Dsl-3782	-	All	All	All
Operating System	Dlink	Dsl-3782 Firmware	1.01	All	All	All
Operating System	Dlink	Dsl-3782 Firmware	1.01	All	All	All

References

Reference	Source	Link	Tags
D-Link DSL-3782 SecAdvisory: OS Command Injection and Stored XSS	MISC	c0mix.github.io	Exploit, Third Party Advisory
CVE Program record	CVE.ORG	www.cve.org	canonical
NVD vulnerability detail	NVD	nvd.nist.gov	canonical, analysis

No vendor comments have been submitted for this CVE.

There are currently no legacy QID mappings associated with this CVE.

completeness or usefulness of any information, opinion, advice or other content. EACH USER WILL BE SOLELY RESPONSIBLE FOR ANY consequences of his or her direct or indirect use of this web site. ALL WARRANTIES OF ANY KIND ARE EXPRESSLY DISCLAIMED. This site will NOT BE LIABLE FOR ANY DIRECT, INDIRECT or any other kind of loss.

CVE, CWE, and OVAL are registered trademarks of [The MITRE Corporation](#) and the authoritative source of CVE content is [MITRE's CVE web site](#). This site includes MITRE data granted under the following [license](#).

Free CVE JSON API cve.report/api

CVE.report and Source URL Uptime Status status.cve.report