



CVE-2018-2566

[MITRE](#)[NVD](#)[CVE.ORG](#)[Print: PDF !\[\]\(e3f8612927870f2e0f9f5989e6dd3064_img.jpg\)](#)

Summary

CVE	CVE-2018-2566
State	PUBLIC
Assigner	secalert_us@oracle.com
Source Priority	CVE Program / NVD first with legacy fallback
Published	2018-01-18 02:29:00 UTC
Updated	2019-10-03 00:03:00 UTC
Description	Vulnerability in the Integrated Lights Out Manager (ILOM) component of Oracle Sun Systems Products Suite (subcomponent

Risk And Classification

Problem Types: NVD-CWE-noinfo

NVD Known Affected Configurations (CPE 2.3)

Type	Vendor	Product	Version	Update	Edition	Language
Operating System	Oracle	Integrated Lights Out Manager Firmware	3.0.0	All	All	All
Operating System	Oracle	Integrated Lights Out Manager Firmware	3.0.10	All	All	All
Operating System	Oracle	Integrated Lights Out Manager Firmware	3.0.12	All	All	All
Operating System	Oracle	Integrated Lights Out Manager Firmware	3.0.14	All	All	All
Operating System	Oracle	Integrated Lights Out Manager Firmware	3.0.16	All	All	All
Operating System	Oracle	Integrated Lights Out Manager Firmware	3.0.3	All	All	All
Operating System	Oracle	Integrated Lights Out Manager Firmware	3.0.4	All	All	All
Operating System	Oracle	Integrated Lights Out Manager Firmware	3.0.6	All	All	All
Operating System	Oracle	Integrated Lights Out Manager Firmware	3.0.8	All	All	All
Operating System	Oracle	Integrated Lights Out Manager Firmware	3.0.9	All	All	All
Operating System	Oracle	Integrated Lights Out Manager Firmware	3.1.0	All	All	All
Operating System	Oracle	Integrated Lights Out Manager Firmware	3.1.1	All	All	All
Operating System	Oracle	Integrated Lights Out Manager Firmware	3.1.2	All	All	All
Operating System	Oracle	Integrated Lights Out Manager Firmware	3.2.0	All	All	All
Operating System	Oracle	Integrated Lights Out Manager Firmware	3.2.1	All	All	All
Operating System	Oracle	Integrated Lights Out Manager Firmware	3.2.2	All	All	All
Operating System	Oracle	Integrated Lights Out Manager Firmware	3.2.4	All	All	All

Reference


Oracle Integrated Lights Out Manager (ILOM) CVE-2018-2566 Remote Security Vulnerability

Oracle Critical Patch Update - January 2018

Sun Integrated Lights-Out Manager Bugs Let Remote Users Access and Modify Data and Cause Denial of Service Conditions - SecurityTrack

CVE Program record

NVD vulnerability detail



No vendor comments have been submitted for this CVE.

There are currently no legacy QID mappings associated with this CVE.

© [CVE.report](#) 2026 |

Use of this information constitutes acceptance for use in an AS IS condition. There are NO warranties, implied or otherwise, with regard to this information or its use. Any use of this information is at the user's risk. It is the responsibility of user to evaluate the accuracy, completeness or usefulness of any information, opinion, advice or other content. EACH USER WILL BE SOLELY RESPONSIBLE FOR ANY consequences of his or her direct or indirect use of this web site. ALL WARRANTIES OF ANY KIND ARE EXPRESSLY DISCLAIMED. This site will NOT BE LIABLE FOR ANY DIRECT, INDIRECT or any other kind of loss.

CVE, CWE, and OVAL are registered trademarks of [The MITRE Corporation](#) and the authoritative source of CVE content is [MITRE's CVE web site](#). This site includes MITRE data granted under the following [license](#).

CVE.report and Source URL Uptime Status [status.cve.report](#)