



CVE-2018-3864

[MITRE](#)[NVD](#)[CVE.ORG](#)[JSON API](#)[Print: PDF](#)

Summary

CVE	CVE-2018-3864
State	PUBLIC
Assigner	talos-cna@cisco.com
Source Priority	CVE Program / NVD first with legacy fallback
Published	2018-09-20 15:29:00 UTC
Updated	2023-05-16 11:14:00 UTC
Description	An exploitable buffer overflow vulnerability exists in the Samsung WifiScan handler of video-core's HTTP server of Samsung

Risk And Classification

Problem Types: CWE-120

NVD Known Affected Configurations (CPE 2.3)

Type	Vendor	Product	Version	Update	Edition	Language
Hardware	Samsung	Sth-eth-250	-	All	All	All
Hardware	Samsung	Sth-eth-250	-	All	All	All
Operating System	Samsung	Sth-eth-250 Firmware	0.20.17	All	All	All
Operating System	Samsung	Sth-eth-250 Firmware	0.20.17	All	All	All

References

Reference	Source	Link	Tags
TALOS-2018-0548 Cisco Talos Intelligence Group - Comprehensive Threat Intelligence	MISC	talosintelligence.com	Exploit, Third Party
CVE Program record	CVE.ORG	www.cve.org	canonical
NVD vulnerability detail	NVD	nvd.nist.gov	canonical, authoritative

No vendor comments have been submitted for this CVE.

There are currently no legacy QID mappings associated with this CVE.

this information or its use. Any use of this information is at the user's risk. It is the responsibility of user to evaluate the accuracy, completeness or usefulness of any information, opinion, advice or other content. EACH USER WILL BE SOLELY RESPONSIBLE FOR ANY consequences of his or her direct or indirect use of this web site. ALL WARRANTIES OF ANY KIND ARE EXPRESSLY DISCLAIMED. This site will NOT BE LIABLE FOR ANY DIRECT, INDIRECT or any other kind of loss.

CVE, CWE, and OVAL are registered trademarks of [The MITRE Corporation](#) and the authoritative source of CVE content is [MITRE's CVE web site](#). This site includes MITRE data granted under the following [license](#).

Free CVE JSON API cve.report/api

CVE.report and Source URL Uptime Status status.cve.report