



CVE-2019-14008

Published on: 01/21/2020 12:00:00 AM UTC

Last Modified on: 03/23/2021 11:27:57 PM UTC

CVE-2019-14008

[Source: Mitre](#)[Source: NIST](#)[CVE.ORG](#)[Print: PDF](#)

CVSS:31/AV:N/AC:L/PR:N/UI:N/S:U/C:N/I:N/A:H



Certain versions of [Mdm9150](#) from [Qualcomm](#) contain the following vulnerability:

Possible null pointer dereference issue in location assistance data processing due to missing null check on resources before using it in Snapdragon Auto, Snapdragon Consumer IOT, Snapdragon Industrial IOT, Snapdragon Mobile in MDM9150, MDM9607, MDM9650, SDM660, SDM845, SM8150, SM8250, SXR2130

CVE-2019-14008 has been assigned by [Q](#) product-security@qualcomm.com to track the vulnerability - currently rated as **HIGH** severity.

Affected Vendor/Software: [Q](#) [Qualcomm, Inc.](#) - [Snapdragon Auto](#), [Snapdragon Consumer IOT](#), [Snapdragon Industrial IOT](#), [Snapdragon Mobile](#) version [MDM9150](#), [MDM9607](#), [MDM9650](#), [SDM660](#), [SDM845](#), [SM8150](#), [SM8250](#), [SXR2130](#)

CVSS3 Score: **7.5 - HIGH**

Attack Vector	Attack Complexity	Privileges Required	User Interaction
NETWORK	LOW	NONE	NONE
Scope	Confidentiality Impact	Integrity Impact	Availability Impact
UNCHANGED	NONE	NONE	HIGH

CVSS2 Score: **7.8 - HIGH**

Access Vector	Access Complexity	Authentication
NETWORK	LOW	NONE
Confidentiality Impact	Integrity Impact	Availability Impact
NONE	NONE	COMPLETE

CVE References

Description	Tags	Link
-------------	------	------

By selecting these links, you may be leaving CVEreport webspace. We have provided these links to other websites because they may have information that would be of interest to you. No inferences should be drawn on account of other sites being referenced, or not, from this page. There may be other websites that are more appropriate for your purpose. CVEreport does not necessarily endorse the views expressed, or concur with the facts presented on these sites. Further, CVEreport does not endorse any commercial products that may be mentioned on these sites. Please address comments about any linked pages to comment@cve.report.

There are currently no QIDs associated with this CVE

Known Affected Configurations (CPE V2.3)

Type	Vendor	Product	Version	Update	Edition	Language
Hardware 	Qualcomm	Mdm9150	-	All	All	All
Hardware 	Qualcomm	Mdm9150	-	All	All	All
Operating System	Qualcomm	Mdm9150 Firmware	-	All	All	All
Operating System	Qualcomm	Mdm9150 Firmware	-	All	All	All
Hardware 	Qualcomm	Mdm9607	-	All	All	All
Hardware 	Qualcomm	Mdm9607	-	All	All	All
Operating System	Qualcomm	Mdm9607 Firmware	-	All	All	All
Operating System	Qualcomm	Mdm9607 Firmware	-	All	All	All
Hardware 	Qualcomm	Mdm9650	-	All	All	All
Hardware 	Qualcomm	Mdm9650	-	All	All	All
Operating System	Qualcomm	Mdm9650 Firmware	-	All	All	All
Operating System	Qualcomm	Mdm9650 Firmware	-	All	All	All
Hardware 	Qualcomm	Sdm660	-	All	All	All
Hardware 	Qualcomm	Sdm660	-	All	All	All
Operating System	Qualcomm	Sdm660 Firmware	-	All	All	All
Operating System	Qualcomm	Sdm660 Firmware	-	All	All	All
Hardware 	Qualcomm	Sdm845	-	All	All	All
Hardware 	Qualcomm	Sdm845	-	All	All	All
Operating System	Qualcomm	Sdm845 Firmware	-	All	All	All

Operating System	Qualcomm	Sdm845 Firmware	-	All	All	All
Hardware 🇳🇵🔗	Qualcomm	Sm8150	-	All	All	All
Hardware 🇳🇵🔗	Qualcomm	Sm8150	-	All	All	All
Operating System	Qualcomm	Sm8150 Firmware	-	All	All	All
Operating System	Qualcomm	Sm8150 Firmware	-	All	All	All
Hardware 🇳🇵🔗	Qualcomm	Sm8250	-	All	All	All
Hardware 🇳🇵🔗	Qualcomm	Sm8250	-	All	All	All
Operating System	Qualcomm	Sm8250 Firmware	-	All	All	All
Operating System	Qualcomm	Sm8250 Firmware	-	All	All	All
Hardware 🇳🇵🔗	Qualcomm	Sxr2130	-	All	All	All
Hardware 🇳🇵🔗	Qualcomm	Sxr2130	-	All	All	All
Operating System	Qualcomm	Sxr2130 Firmware	-	All	All	All
Operating System	Qualcomm	Sxr2130 Firmware	-	All	All	All
cpe:2.3:h:qualcomm:mdm9150:-:*:*:*:*:*:						
cpe:2.3:h:qualcomm:mdm9150:-:*:*:*:*:*:						
cpe:2.3:o:qualcomm:mdm9150_firmware:-:*:*:*:*:*:						
cpe:2.3:o:qualcomm:mdm9150_firmware:-:*:*:*:*:*:						
cpe:2.3:h:qualcomm:mdm9607:-:*:*:*:*:*:						
cpe:2.3:h:qualcomm:mdm9607:-:*:*:*:*:*:						
cpe:2.3:o:qualcomm:mdm9607_firmware:-:*:*:*:*:*:						
cpe:2.3:o:qualcomm:mdm9607_firmware:-:*:*:*:*::~:						
cpe:2.3:h:qualcomm:mdm9650:-:*:*:*:*:*:						
cpe:2.3:h:qualcomm:mdm9650:-:*:*:*:*::~:						
cpe:2.3:o:qualcomm:mdm9650_firmware:-:*:*:*:*::~:						
cpe:2.3:o:qualcomm:mdm9650_firmware:-:*:*:*:*::~:						
cpe:2.3:h:qualcomm:sdm660:-:*:*:*:*::~:						
cpe:2.3:h:qualcomm:sdm660:-:*:*:*:*::~:						

```
cpe:2.3:o:qualcomm:sxr2130_firmware:-:*:*:*:*:*:
```

Next ID→