



# CVE-2019-14012

Published on: 04/16/2020 12:00:00 AM UTC

Last Modified on: 03/23/2021 11:27:57 PM UTC

## CVE-2019-14012

[Source: Mitre](#)[Source: NIST](#)[CVE.ORG](#)[Print: PDF](#)

CVSS:31/AV:N/AC:L/PR:N/UI:N/S:U/C:N/I:N/A:H



Certain versions of [Msm8905](#) from [Qualcomm](#) contain the following vulnerability:

Possibility of null pointer deference as the array of video codecs from media info is referenced without null checking while processing SDP messages in Snapdragon Auto, Snapdragon Compute, Snapdragon Consumer IOT, Snapdragon Industrial IOT, Snapdragon Mobile, Snapdragon Wearables in MSM8905, MSM8909, MSM8917,

MSM8920, MSM8937, MSM8940, MSM8953, Nicobar, QCM2150, QM215, Rennell, SC7180, SC8180X, SDA845, SDM429, SDM439, SDM450, SDM632, SDM845, SDM850, SDX24, SM6150, SM7150, SM8150

CVE-2019-14012 has been assigned by [Q](#) product-security@qualcomm.com to track the vulnerability - currently rated as **HIGH** severity.

Affected Vendor/Software: [Q](#) Qualcomm, Inc. - Snapdragon Auto, Snapdragon Compute, Snapdragon Consumer IOT, Snapdragon Industrial IOT, Snapdragon Mobile, Snapdragon Wearables version MSM8905, MSM8909, MSM8917, MSM8920, MSM8937, MSM8940, MSM8953, Nicobar, QCM2150, QM215, Rennell, SC7180, SC8180X, SDA845, SDM429, SDM439, SDM450, SDM632, SDM845, SDM850, SDX24, SM6150, SM7150, SM8150

CVSS3 Score: **7.5 - HIGH**

| Attack Vector    | Attack Complexity      | Privileges Required | User Interaction    |
|------------------|------------------------|---------------------|---------------------|
| <b>NETWORK</b>   | <b>LOW</b>             | <b>NONE</b>         | <b>NONE</b>         |
| Scope            | Confidentiality Impact | Integrity Impact    | Availability Impact |
| <b>UNCHANGED</b> | <b>NONE</b>            | <b>NONE</b>         | <b>HIGH</b>         |

CVSS2 Score: **7.8 - HIGH**

| Access Vector          | Access Complexity | Authentication      |
|------------------------|-------------------|---------------------|
| <b>NETWORK</b>         | <b>LOW</b>        | <b>NONE</b>         |
| Confidentiality Impact | Integrity Impact  | Availability Impact |
|                        |                   |                     |

NONE

NONE

COMPLETE

## CVE References

## Description

## Tags

## Link

April 2020 Bulletin |  
Qualcomm

Vendor Advisory  
www.qualcomm.com  
text/html

 CONFIRM [www.qualcomm.com/company/product-security/bulletins/april-2020-bulletin](http://www.qualcomm.com/company/product-security/bulletins/april-2020-bulletin)

By selecting these links, you may be leaving CVEreport webspace. We have provided these links to other websites because they may have information that would be of interest to you. No inferences should be drawn on account of other sites being referenced, or not, from this page. There may be other websites that are more appropriate for your purpose. CVEreport does not necessarily endorse the views expressed, or concur with the facts presented on these sites. Further, CVEreport does not endorse any commercial products that may be mentioned on these sites. Please address comments about any linked pages to [comment@cve.report](mailto:comment@cve.report).

There are currently no QIDs associated with this CVE

## Known Affected Configurations (CPE V2.3)

| Type                                                                                         | Vendor                   | Product                          | Version | Update | Edition | Language |
|----------------------------------------------------------------------------------------------|--------------------------|----------------------------------|---------|--------|---------|----------|
| Hardware    | <a href="#">Qualcomm</a> | <a href="#">Msm8905</a>          | -       | All    | All     | All      |
| Hardware    | <a href="#">Qualcomm</a> | <a href="#">Msm8905</a>          | -       | All    | All     | All      |
| Operating System                                                                             | <a href="#">Qualcomm</a> | <a href="#">Msm8905 Firmware</a> | -       | All    | All     | All      |
| Operating System                                                                             | <a href="#">Qualcomm</a> | <a href="#">Msm8905 Firmware</a> | -       | All    | All     | All      |
| Hardware  | <a href="#">Qualcomm</a> | <a href="#">Msm8909</a>          | -       | All    | All     | All      |
| Hardware  | <a href="#">Qualcomm</a> | <a href="#">Msm8909</a>          | -       | All    | All     | All      |
| Operating System                                                                             | <a href="#">Qualcomm</a> | <a href="#">Msm8909 Firmware</a> | -       | All    | All     | All      |
| Operating System                                                                             | <a href="#">Qualcomm</a> | <a href="#">Msm8909 Firmware</a> | -       | All    | All     | All      |
| Hardware  | <a href="#">Qualcomm</a> | <a href="#">Msm8917</a>          | -       | All    | All     | All      |
| Hardware  | <a href="#">Qualcomm</a> | <a href="#">Msm8917</a>          | -       | All    | All     | All      |
| Operating System                                                                             | <a href="#">Qualcomm</a> | <a href="#">Msm8917 Firmware</a> | -       | All    | All     | All      |
| Operating System                                                                             | <a href="#">Qualcomm</a> | <a href="#">Msm8917 Firmware</a> | -       | All    | All     | All      |
| Hardware  | <a href="#">Qualcomm</a> | <a href="#">Msm8920</a>          | -       | All    | All     | All      |
| Hardware  | <a href="#">Qualcomm</a> | <a href="#">Msm8920</a>          | -       | All    | All     | All      |
| Operating System                                                                             | <a href="#">Qualcomm</a> | <a href="#">Msm8920 Firmware</a> | -       | All    | All     | All      |
| Operating System                                                                             | <a href="#">Qualcomm</a> | <a href="#">Msm8920 Firmware</a> | -       | All    | All     | All      |

|                                                                                                                                                                                  |          |                  |   |     |     |     |
|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------|------------------|---|-----|-----|-----|
| Hardware         | Qualcomm | Msm8937          | - | All | All | All |
| Hardware       | Qualcomm | Msm8937          | - | All | All | All |
| Operating System                                                                                                                                                                 | Qualcomm | Msm8937 Firmware | - | All | All | All |
| Operating System                                                                                                                                                                 | Qualcomm | Msm8937 Firmware | - | All | All | All |
| Hardware       | Qualcomm | Msm8940          | - | All | All | All |
| Hardware       | Qualcomm | Msm8940          | - | All | All | All |
| Operating System                                                                                                                                                                 | Qualcomm | Msm8940 Firmware | - | All | All | All |
| Operating System                                                                                                                                                                 | Qualcomm | Msm8940 Firmware | - | All | All | All |
| Hardware       | Qualcomm | Msm8953          | - | All | All | All |
| Hardware       | Qualcomm | Msm8953          | - | All | All | All |
| Operating System                                                                                                                                                                 | Qualcomm | Msm8953 Firmware | - | All | All | All |
| Operating System                                                                                                                                                                 | Qualcomm | Msm8953 Firmware | - | All | All | All |
| Hardware   | Qualcomm | Nicobar          | - | All | All | All |
| Hardware   | Qualcomm | Nicobar          | - | All | All | All |
| Operating System                                                                                                                                                                 | Qualcomm | Nicobar Firmware | - | All | All | All |
| Operating System                                                                                                                                                                 | Qualcomm | Nicobar Firmware | - | All | All | All |
| Hardware   | Qualcomm | Qcm2150          | - | All | All | All |
| Hardware   | Qualcomm | Qcm2150          | - | All | All | All |
| Operating System                                                                                                                                                                 | Qualcomm | Qcm2150 Firmware | - | All | All | All |
| Operating System                                                                                                                                                                 | Qualcomm | Qcm2150 Firmware | - | All | All | All |
| Hardware   | Qualcomm | Qm215            | - | All | All | All |
| Hardware   | Qualcomm | Qm215            | - | All | All | All |
| Operating System                                                                                                                                                                 | Qualcomm | Qm215 Firmware   | - | All | All | All |
| Operating System                                                                                                                                                                 | Qualcomm | Qm215 Firmware   | - | All | All | All |
| Hardware   | Qualcomm | Rennell          | - | All | All | All |
| Hardware   | Qualcomm | Rennell          | - | All | All | All |
| Operating System                                                                                                                                                                 | Qualcomm | Rennell Firmware | - | All | All | All |

|                                                                                                                                                                                  |          |                  |   |     |     |     |
|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------|------------------|---|-----|-----|-----|
| Operating System                                                                                                                                                                 | Qualcomm | Rennell Firmware | - | All | All | All |
| Hardware       | Qualcomm | Sc7180           | - | All | All | All |
| Hardware       | Qualcomm | Sc7180           | - | All | All | All |
| Operating System                                                                                                                                                                 | Qualcomm | Sc7180 Firmware  | - | All | All | All |
| Operating System                                                                                                                                                                 | Qualcomm | Sc7180 Firmware  | - | All | All | All |
| Hardware       | Qualcomm | Sc8180x          | - | All | All | All |
| Hardware       | Qualcomm | Sc8180x          | - | All | All | All |
| Operating System                                                                                                                                                                 | Qualcomm | Sc8180x Firmware | - | All | All | All |
| Operating System                                                                                                                                                                 | Qualcomm | Sc8180x Firmware | - | All | All | All |
| Hardware       | Qualcomm | Sda845           | - | All | All | All |
| Hardware       | Qualcomm | Sda845           | - | All | All | All |
| Operating System                                                                                                                                                                 | Qualcomm | Sda845 Firmware  | - | All | All | All |
| Operating System                                                                                                                                                                 | Qualcomm | Sda845 Firmware  | - | All | All | All |
| Hardware   | Qualcomm | Sdm429           | - | All | All | All |
| Hardware   | Qualcomm | Sdm429           | - | All | All | All |
| Operating System                                                                                                                                                                 | Qualcomm | Sdm429 Firmware  | - | All | All | All |
| Operating System                                                                                                                                                                 | Qualcomm | Sdm429 Firmware  | - | All | All | All |
| Hardware   | Qualcomm | Sdm439           | - | All | All | All |
| Hardware   | Qualcomm | Sdm439           | - | All | All | All |
| Operating System                                                                                                                                                                 | Qualcomm | Sdm439 Firmware  | - | All | All | All |
| Operating System                                                                                                                                                                 | Qualcomm | Sdm439 Firmware  | - | All | All | All |
| Hardware   | Qualcomm | Sdm450           | - | All | All | All |
| Hardware   | Qualcomm | Sdm450           | - | All | All | All |
| Operating System                                                                                                                                                                 | Qualcomm | Sdm450 Firmware  | - | All | All | All |
| Operating System                                                                                                                                                                 | Qualcomm | Sdm450 Firmware  | - | All | All | All |
| Hardware   | Qualcomm | Sdm632           | - | All | All | All |

|                                                                                                                                                                                  |          |                                 |   |     |     |     |
|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------|---------------------------------|---|-----|-----|-----|
| Hardware         | Qualcomm | Sdm632                          | - | All | All | All |
| Operating System                                                                                                                                                                 | Qualcomm | <a href="#">Sdm632 Firmware</a> | - | All | All | All |
| Operating System                                                                                                                                                                 | Qualcomm | <a href="#">Sdm632 Firmware</a> | - | All | All | All |
| Hardware       | Qualcomm | Sdm845                          | - | All | All | All |
| Hardware       | Qualcomm | Sdm845                          | - | All | All | All |
| Operating System                                                                                                                                                                 | Qualcomm | <a href="#">Sdm845 Firmware</a> | - | All | All | All |
| Operating System                                                                                                                                                                 | Qualcomm | <a href="#">Sdm845 Firmware</a> | - | All | All | All |
| Hardware       | Qualcomm | Sdm850                          | - | All | All | All |
| Hardware       | Qualcomm | Sdm850                          | - | All | All | All |
| Operating System                                                                                                                                                                 | Qualcomm | <a href="#">Sdm850 Firmware</a> | - | All | All | All |
| Operating System                                                                                                                                                                 | Qualcomm | <a href="#">Sdm850 Firmware</a> | - | All | All | All |
| Hardware       | Qualcomm | Sdx24                           | - | All | All | All |
| Hardware   | Qualcomm | Sdx24                           | - | All | All | All |
| Operating System                                                                                                                                                                 | Qualcomm | <a href="#">Sdx24 Firmware</a>  | - | All | All | All |
| Operating System                                                                                                                                                                 | Qualcomm | <a href="#">Sdx24 Firmware</a>  | - | All | All | All |
| Hardware   | Qualcomm | Sm6150                          | - | All | All | All |
| Hardware   | Qualcomm | Sm6150                          | - | All | All | All |
| Operating System                                                                                                                                                                 | Qualcomm | <a href="#">Sm6150 Firmware</a> | - | All | All | All |
| Operating System                                                                                                                                                                 | Qualcomm | <a href="#">Sm6150 Firmware</a> | - | All | All | All |
| Hardware   | Qualcomm | Sm7150                          | - | All | All | All |
| Hardware   | Qualcomm | Sm7150                          | - | All | All | All |
| Operating System                                                                                                                                                                 | Qualcomm | <a href="#">Sm7150 Firmware</a> | - | All | All | All |
| Operating System                                                                                                                                                                 | Qualcomm | <a href="#">Sm7150 Firmware</a> | - | All | All | All |
| Hardware   | Qualcomm | Sm8150                          | - | All | All | All |
| Hardware   | Qualcomm | Sm8150                          | - | All | All | All |
| Operating System                                                                                                                                                                 | Qualcomm | <a href="#">Sm8150 Firmware</a> | - | All | All | All |
| Operating                                                                                                                                                                        | Qualcomm | <a href="#">Sm8150 Firmware</a> | - | All | All | All |

## System

```
cpe:2.3:h:qualcomm:msm8905:-:*:*:*:*:*:*:
```

cpe:2.3:h:qualcomm:msm8905:-:\*:\*:\*:\*:\*:\*:

```
cpe:2.3:o:qualcomm:msm8905_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:msm8905_firmware:-:*:*:*:*:*:
```

cpe:2.3:h:qualcomm:msm8909:-:\*:\*:\*:\*:\*:\*:

```
cpe:2.3:h:qualcomm:msm8909:-:*:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:msm8909_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:msm8909_firmware:-:*:*:*:*:*:*:
```

cpe:2.3:h:qualcomm:msm8917:-:\*:\*:\*:\*:\*:\*:

```
cpe:2.3:h:qualcomm:msm8917:-:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:msm8917_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:msm8917_firmware:-:*:*:*:*:*:*
```

cpe:2.3:h:qualcomm:msm8920:-:\*:\*:\*:\*:\*:\*:

cpe:2.3:h:qualcomm:msm8920:-:\*:\*:\*:\*:\*:\*:

```
cpe:2.3:o:qualcomm:msm8920_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:msm8920_firmware:-:*:*:*:*:*:
```

cpe:2.3:h:qualcomm:msm8937:-:\*:\*:\*:\*:\*:\*:

cpe:2.3:h:qualcomm:msm8937:-:\*:\*:\*:\*:\*:\*:

```
cpe:2.3:o:qualcomm:msm8937_firmware:-:*:*:*:*:*.*
```

```
cpe:2.3:o:qualcomm:msm8937_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:h:qualcomm:msm8940:-:*:*:*:*:*:
```

cpe:2.3:h:qualcomm:msm8940:-:\*:\*:\*:\*:\*:\*:

```
cpe:2.3:o:qualcomm:msm8940_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:msm8940 firmware:-.*:.*:.*:.*:.*:.*
```

```
cpe:2.3:h:qualcomm:msm8953:-:*:*:*:*:*:
```

cpe:2.3:h:qualcomm:msm8953:-:\*:\*:\*:\*:\*:\*:

```
cpe:2.3:o:qualcomm:msm8953_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:msm8953_firmware:-:*:*:*:*:*:
```

cpe:2.3:h:qualcomm:nicobar:-:\*:\*:\*:\*:\*:\*:

cpe:2.3:h:qualcomm:nicobar:-:\*:\*:\*:\*:\*:\*:

```
cpe:2.3:o:qualcomm:nicobar_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:nicobar_firmware:-:*:*:*:*:*:*:
```

```
cpe:2.3:h:qualcomm:qcm2150:-:*:*:*:*:*:*:
```

```
cpe:2.3:h:qualcomm:qcm2150:-:*:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:qcm2150_firmware:-:*:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:qcm2150_firmware:-:*:*:*:*:*:*:
```

cpe:2.3:h:qualcomm:qm215:-:\*:\*:\*:\*:\*:\*:

cpe:2.3:h:qualcomm:qm215:-:\*:\*:\*:\*:\*:\*:

```
cpe:2.3:o:qualcomm:qm215_firmware:-:*:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:qm215_firmware:-:*:*:*:*:*:
```

cpe:2.3:h:qualcomm:rennell:-:\*:\*:\*:\*:\*:\*:

cpe:2.3:h:qualcomm:rennell:-:\*:\*:\*:\*:\*:\*:

```
cpe:2.3:o:qualcomm:rennell_firmware:-:*:*:*:*:*:*
```

```
cpe:2.3:o:qualcomm:rennell_firmware:-:*:*:*:*:*:*:
```

cpe:2.3:h:qualcomm:sc7180:-:\*:\*:\*:\*:\*:\*:

cpe:2.3:h:qualcomm:sc7180:-:\*:\*:\*:\*:\*:\*:

```
cpe:2.3:o:qualcomm:sc7180_firmware:-:*:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:sc7180_firmware:-:*:*:*:*:*:*:
```

cpe:2.3:h:qualcomm:sc8180x:-:\*:\*:\*:\*:\*:\*:

cpe:2.3:h:qualcomm:sc8180x:-:\*:\*:\*:\*:\*:\*:

```
cpe:2.3:o:qualcomm:sc8180x_firmware:-:*:*:*:*:*:*
```

```
cpe:2.3:o:qualcomm:sc8180x_firmware:-:*:*:*:*:*:*:
```

cpe:2.3:h:qualcomm:sda845:-:\*:\*:\*:\*:\*:\*:

cpe:2.3:h:qualcomm:sda845:-:\*:\*:\*:\*:\*:\*:

```
cpe:2.3:o:qualcomm:sda845_firmware:-:*:*:*:*:*:*
```

```
cpe:2.3:o:qualcomm:sda845_firmware:-:*:*:*:*:*:*:
```

|                                                                   |
|-------------------------------------------------------------------|
| cpe:2.3:h:qualcomm:sdm429:-:~::~~::~~::~~::~~::~~::~~:::          |
| cpe:2.3:h:qualcomm:sdm429:-:~::~~::~~::~~::~~::~~::~~:::          |
| cpe:2.3:o:qualcomm:sdm429_firmware:-:~::~~::~~::~~::~~::~~::~~::: |
| cpe:2.3:o:qualcomm:sdm429_firmware:-:~::~~::~~::~~::~~::~~::~~::: |
| cpe:2.3:h:qualcomm:sdm439:-:~::~~::~~::~~::~~::~~::~~:::          |
| cpe:2.3:h:qualcomm:sdm439:-:~::~~::~~::~~::~~::~~::~~:::          |
| cpe:2.3:o:qualcomm:sdm439_firmware:-:~::~~::~~::~~::~~::~~::~~::: |
| cpe:2.3:o:qualcomm:sdm439_firmware:-:~::~~::~~::~~::~~::~~::~~::: |
| cpe:2.3:h:qualcomm:sdm450:-:~::~~::~~::~~::~~::~~::~~:::          |
| cpe:2.3:h:qualcomm:sdm450:-:~::~~::~~::~~::~~::~~::~~:::          |
| cpe:2.3:o:qualcomm:sdm450_firmware:-:~::~~::~~::~~::~~::~~::~~::: |
| cpe:2.3:o:qualcomm:sdm450_firmware:-:~::~~::~~::~~::~~::~~::~~::: |
| cpe:2.3:h:qualcomm:sdm632:-:~::~~::~~::~~::~~::~~::~~:::          |
| cpe:2.3:h:qualcomm:sdm632:-:~::~~::~~::~~::~~::~~::~~:::          |
| cpe:2.3:o:qualcomm:sdm632_firmware:-:~::~~::~~::~~::~~::~~::~~::: |
| cpe:2.3:o:qualcomm:sdm632_firmware:-:~::~~::~~::~~::~~::~~::~~::: |
| cpe:2.3:h:qualcomm:sdm845:-:~::~~::~~::~~::~~::~~::~~:::          |
| cpe:2.3:h:qualcomm:sdm845:-:~::~~::~~::~~::~~::~~::~~:::          |
| cpe:2.3:o:qualcomm:sdm845_firmware:-:~::~~::~~::~~::~~::~~::~~::: |
| cpe:2.3:o:qualcomm:sdm845_firmware:-:~::~~::~~::~~::~~::~~::~~::: |
| cpe:2.3:h:qualcomm:sdm850:-:~::~~::~~::~~::~~::~~::~~:::          |
| cpe:2.3:h:qualcomm:sdm850:-:~::~~::~~::~~::~~::~~::~~:::          |
| cpe:2.3:o:qualcomm:sdm850_firmware:-:~::~~::~~::~~::~~::~~::~~::: |
| cpe:2.3:o:qualcomm:sdm850_firmware:-:~::~~::~~::~~::~~::~~::~~::: |
| cpe:2.3:h:qualcomm:sdx24:-:~::~~::~~::~~::~~::~~::~~:::           |
| cpe:2.3:h:qualcomm:sdx24:-:~::~~::~~::~~::~~::~~::~~:::           |
| cpe:2.3:o:qualcomm:sdx24_firmware:-:~::~~::~~::~~::~~::~~::~~:::  |
| cpe:2.3:o:qualcomm:sdx24_firmware:-:~::~~::~~::~~::~~::~~::~~:::  |
| cpe:2.3:h:qualcomm:sm6150:-:~::~~::~~::~~::~~::~~::~~:::          |



|                                             |
|---------------------------------------------|
| cpe:2.3:h:qualcomm:sm6150:-:*~::~:          |
| cpe:2.3:o:qualcomm:sm6150_firmware:-:*~::~: |
| cpe:2.3:o:qualcomm:sm6150_firmware:-:*~::~: |
| cpe:2.3:h:qualcomm:sm7150:-:*~::~:          |
| cpe:2.3:h:qualcomm:sm7150:-:*~::~:          |
| cpe:2.3:o:qualcomm:sm7150_firmware:-:*~::~: |
| cpe:2.3:o:qualcomm:sm7150_firmware:-:*~::~: |
| cpe:2.3:h:qualcomm:sm8150:-:*~::~:          |
| cpe:2.3:h:qualcomm:sm8150:-:*~::~:          |
| cpe:2.3:o:qualcomm:sm8150_firmware:-:*~::~: |
| cpe:2.3:o:qualcomm:sm8150_firmware:-:*~::~: |

|                                             |
|---------------------------------------------|
| cpe:2.3:h:qualcomm:sm6150:-:*~::~:          |
| cpe:2.3:o:qualcomm:sm6150_firmware:-:*~::~: |
| cpe:2.3:o:qualcomm:sm6150_firmware:-:*~::~: |
| cpe:2.3:h:qualcomm:sm7150:-:*~::~:          |
| cpe:2.3:h:qualcomm:sm7150:-:*~::~:          |
| cpe:2.3:o:qualcomm:sm7150_firmware:-:*~::~: |
| cpe:2.3:o:qualcomm:sm7150_firmware:-:*~::~: |
| cpe:2.3:h:qualcomm:sm8150:-:*~::~:          |
| cpe:2.3:h:qualcomm:sm8150:-:*~::~:          |
| cpe:2.3:o:qualcomm:sm8150_firmware:-:*~::~: |
| cpe:2.3:o:qualcomm:sm8150_firmware:-:*~::~: |

|                                             |
|---------------------------------------------|
| cpe:2.3:h:qualcomm:sm6150:-:*~::~:          |
| cpe:2.3:o:qualcomm:sm6150_firmware:-:*~::~: |
| cpe:2.3:o:qualcomm:sm6150_firmware:-:*~::~: |
| cpe:2.3:h:qualcomm:sm7150:-:*~::~:          |
| cpe:2.3:h:qualcomm:sm7150:-:*~::~:          |
| cpe:2.3:o:qualcomm:sm7150_firmware:-:*~::~: |
| cpe:2.3:o:qualcomm:sm7150_firmware:-:*~::~: |
| cpe:2.3:h:qualcomm:sm8150:-:*~::~:          |
| cpe:2.3:h:qualcomm:sm8150:-:*~::~:          |
| cpe:2.3:o:qualcomm:sm8150_firmware:-:*~::~: |
| cpe:2.3:o:qualcomm:sm8150_firmware:-:*~::~: |

|                                             |
|---------------------------------------------|
| cpe:2.3:h:qualcomm:sm6150:-:*~::~:          |
| cpe:2.3:o:qualcomm:sm6150_firmware:-:*~::~: |
| cpe:2.3:o:qualcomm:sm6150_firmware:-:*~::~: |
| cpe:2.3:h:qualcomm:sm7150:-:*~::~:          |
| cpe:2.3:h:qualcomm:sm7150:-:*~::~:          |
| cpe:2.3:o:qualcomm:sm7150_firmware:-:*~::~: |
| cpe:2.3:o:qualcomm:sm7150_firmware:-:*~::~: |
| cpe:2.3:h:qualcomm:sm8150:-:*~::~:          |
| cpe:2.3:h:qualcomm:sm8150:-:*~::~:          |
| cpe:2.3:o:qualcomm:sm8150_firmware:-:*~::~: |
| cpe:2.3:o:qualcomm:sm8150_firmware:-:*~::~: |

|                                             |
|---------------------------------------------|
| cpe:2.3:h:qualcomm:sm6150:-:*~::~:          |
| cpe:2.3:o:qualcomm:sm6150_firmware:-:*~::~: |
| cpe:2.3:o:qualcomm:sm6150_firmware:-:*~::~: |
| cpe:2.3:h:qualcomm:sm7150:-:*~::~:          |
| cpe:2.3:h:qualcomm:sm7150:-:*~::~:          |
| cpe:2.3:o:qualcomm:sm7150_firmware:-:*~::~: |
| cpe:2.3:o:qualcomm:sm7150_firmware:-:*~::~: |
| cpe:2.3:h:qualcomm:sm8150:-:*~::~:          |
| cpe:2.3:h:qualcomm:sm8150:-:*~::~:          |
| cpe:2.3:o:qualcomm:sm8150_firmware:-:*~::~: |
| cpe:2.3:o:qualcomm:sm8150_firmware:-:*~::~: |

|                                             |
|---------------------------------------------|
| cpe:2.3:h:qualcomm:sm6150:-:*~::~:          |
| cpe:2.3:o:qualcomm:sm6150_firmware:-:*~::~: |
| cpe:2.3:o:qualcomm:sm6150_firmware:-:*~::~: |
| cpe:2.3:h:qualcomm:sm7150:-:*~::~:          |
| cpe:2.3:h:qualcomm:sm7150:-:*~::~:          |
| cpe:2.3:o:qualcomm:sm7150_firmware:-:*~::~: |
| cpe:2.3:o:qualcomm:sm7150_firmware:-:*~::~: |
| cpe:2.3:h:qualcomm:sm8150:-:*~::~:          |
| cpe:2.3:h:qualcomm:sm8150:-:*~::~:          |
| cpe:2.3:o:qualcomm:sm8150_firmware:-:*~::~: |
| cpe:2.3:o:qualcomm:sm8150_firmware:-:*~::~: |

|                                             |
|---------------------------------------------|
| cpe:2.3:h:qualcomm:sm6150:-:*~::~:          |
| cpe:2.3:o:qualcomm:sm6150_firmware:-:*~::~: |
| cpe:2.3:o:qualcomm:sm6150_firmware:-:*~::~: |
| cpe:2.3:h:qualcomm:sm7150:-:*~::~:          |
| cpe:2.3:h:qualcomm:sm7150:-:*~::~:          |
| cpe:2.3:o:qualcomm:sm7150_firmware:-:*~::~: |
| cpe:2.3:o:qualcomm:sm7150_firmware:-:*~::~: |
| cpe:2.3:h:qualcomm:sm8150:-:*~::~:          |
| cpe:2.3:h:qualcomm:sm8150:-:*~::~:          |
| cpe:2.3:o:qualcomm:sm8150_firmware:-:*~::~: |
| cpe:2.3:o:qualcomm:sm8150_firmware:-:*~::~: |

|                                             |
|---------------------------------------------|
| cpe:2.3:h:qualcomm:sm6150:-:*~::~:          |
| cpe:2.3:o:qualcomm:sm6150_firmware:-:*~::~: |
| cpe:2.3:o:qualcomm:sm6150_firmware:-:*~::~: |
| cpe:2.3:h:qualcomm:sm7150:-:*~::~:          |
| cpe:2.3:h:qualcomm:sm7150:-:*~::~:          |
| cpe:2.3:o:qualcomm:sm7150_firmware:-:*~::~: |
| cpe:2.3:o:qualcomm:sm7150_firmware:-:*~::~: |
| cpe:2.3:h:qualcomm:sm8150:-:*~::~:          |
| cpe:2.3:h:qualcomm:sm8150:-:*~::~:          |
| cpe:2.3:o:qualcomm:sm8150_firmware:-:*~::~: |
| cpe:2.3:o:qualcomm:sm8150_firmware:-:*~::~: |

|                                             |
|---------------------------------------------|
| cpe:2.3:h:qualcomm:sm6150:-:*~::~:          |
| cpe:2.3:o:qualcomm:sm6150_firmware:-:*~::~: |
| cpe:2.3:o:qualcomm:sm6150_firmware:-:*~::~: |
| cpe:2.3:h:qualcomm:sm7150:-:*~::~:          |
| cpe:2.3:h:qualcomm:sm7150:-:*~::~:          |
| cpe:2.3:o:qualcomm:sm7150_firmware:-:*~::~: |
| cpe:2.3:o:qualcomm:sm7150_firmware:-:*~::~: |
| cpe:2.3:h:qualcomm:sm8150:-:*~::~:          |
| cpe:2.3:h:qualcomm:sm8150:-:*~::~:          |
| cpe:2.3:o:qualcomm:sm8150_firmware:-:*~::~: |
| cpe:2.3:o:qualcomm:sm8150_firmware:-:*~::~: |

|                                             |
|---------------------------------------------|
| cpe:2.3:h:qualcomm:sm6150:-:*~::~:          |
| cpe:2.3:o:qualcomm:sm6150_firmware:-:*~::~: |
| cpe:2.3:o:qualcomm:sm6150_firmware:-:*~::~: |
| cpe:2.3:h:qualcomm:sm7150:-:*~::~:          |
| cpe:2.3:h:qualcomm:sm7150:-:*~::~:          |
| cpe:2.3:o:qualcomm:sm7150_firmware:-:*~::~: |
| cpe:2.3:o:qualcomm:sm7150_firmware:-:*~::~: |
| cpe:2.3:h:qualcomm:sm8150:-:*~::~:          |
| cpe:2.3:h:qualcomm:sm8150:-:*~::~:          |
| cpe:2.3:o:qualcomm:sm8150_firmware:-:*~::~: |
| cpe:2.3:o:qualcomm:sm8150_firmware:-:*~::~: |

|                                             |
|---------------------------------------------|
| cpe:2.3:h:qualcomm:sm6150:-:*~::~:          |
| cpe:2.3:o:qualcomm:sm6150_firmware:-:*~::~: |
| cpe:2.3:o:qualcomm:sm6150_firmware:-:*~::~: |
| cpe:2.3:h:qualcomm:sm7150:-:*~::~:          |
| cpe:2.3:h:qualcomm:sm7150:-:*~::~:          |
| cpe:2.3:o:qualcomm:sm7150_firmware:-:*~::~: |
| cpe:2.3:o:qualcomm:sm7150_firmware:-:*~::~: |
| cpe:2.3:h:qualcomm:sm8150:-:*~::~:          |
| cpe:2.3:h:qualcomm:sm8150:-:*~::~:          |
| cpe:2.3:o:qualcomm:sm8150_firmware:-:*~::~: |
| cpe:2.3:o:qualcomm:sm8150_firmware:-:*~::~: |

No vendor comments have been submitted for this CVE

[← Previous ID](#)

Next ID→

© CVE.report 2023   |

Use of this information constitutes acceptance for use in an AS IS condition. There are NO warranties, implied or otherwise, with regard to this information or its use. Any use of this information is at the user's risk. It is the responsibility of user to evaluate the accuracy, completeness or usefulness of any information, opinion, advice or other content. EACH USER WILL BE SOLELY RESPONSIBLE FOR ANY consequences of his or her direct or indirect use of this web site. ALL WARRANTIES OF ANY KIND ARE EXPRESSLY DISCLAIMED. This site will NOT BE LIABLE FOR ANY DIRECT, INDIRECT or any other kind of loss.

CVE, CWE, and OVAL are registered trademarks of [The MITRE Corporation](#) and the authoritative source of CVE content is [MITRE's CVE web site](#). This site includes MITRE data granted under the following [license](#).

CVE.report and Source URL Uptime Status [status.cve.report](https://status.cve.report)