



CVE-2019-14053

Published on: 06/02/2020 12:00:00 AM UTC

Last Modified on: 03/23/2021 11:27:59 PM UTC


CVE-2019-14053

Source: Mitre

Source: NIST

CVE.ORG

Print: PDF



Certain versions of [Apq8009](#) from [Qualcomm](#) contain the following vulnerability:

When attempting to create a new XFRM policy, a stack out-of-bounds read will occur if the user provides a template where the mode is set to a value that does not resolve to a valid XFRM mode in Snapdragon Auto, Snapdragon Compute, Snapdragon Consumer Electronics Connectivity, Snapdragon Consumer IOT, Snapdragon Industrial IOT,

Snapdragon IoT, Snapdragon Mobile, Snapdragon Voice & Music, Snapdragon Wearables, Snapdragon Wired Infrastructure and Networking in APQ8009, APQ8053, APQ8096AU, APQ8098, IPQ4019, IPQ8074, MDM9206, MDM9207C, MDM9607, MDM9640, MDM9650, MSM8905, MSM8909W, MSM8917, MSM8953, MSM8996AU, QCA4531, QCN7605, QCS605, QM215, SA415M, SC8180X, SDA660, SDA845, SDM429, SDM429W, SDM439, SDM450, SDM630, SDM632, SDM636, SDM660, SDM845, SDX20, SDX24, SDX55, SM6150, SM7150, SM8150, SM8250, SXR2130

CVE-2019-14053 has been assigned by [Q](#) product-security@qualcomm.com to track the vulnerability - currently rated as **HIGH** severity.

Affected Vendor/Software: [Q](#) Qualcomm, Inc. - Snapdragon Auto, Snapdragon Compute, Snapdragon Consumer Electronics Connectivity, Snapdragon Consumer IOT, Snapdragon Industrial IOT, Snapdragon IoT, Snapdragon Mobile, Snapdragon Voice & Music, Snapdragon Wearables, Snapdragon Wired Infrastructure and Networking version APQ8009, APQ8053, APQ8096AU, APQ8098, IPQ4019, IPQ8074, MDM9206, MDM9207C, MDM9607, MDM9640, MDM9650, MSM8905, MSM8909W, MSM8917, MSM8953, MSM8996AU, QCA4531, QCN7605, QCS605, QM215, SA415M, SC8180X, SDA660, SDA845, SDM429, SDM429W, SDM439, SDM450, SDM630, SDM632, SDM636, SDM660, SDM845, SDX20, SDX24, SDX55, SM6150, SM7150, SM8150, SM8250, SXR2130

CVSS3 Score: **7.1 - HIGH**

Attack Vector	Attack Complexity	Privileges Required	User Interaction
LOCAL	LOW	LOW	NONE
Scope	Confidentiality Impact	Integrity Impact	Availability Impact
UNCHANGED	HIGH	NONE	HIGH

CVSS2 Score: 3.6 - LOW						
Access Vector	Access Complexity	Authentication				
LOCAL	LOW	NONE				
Confidentiality Impact	Integrity Impact	Availability Impact				
PARTIAL	NONE	PARTIAL				
CVE References						
Description	Tags	Link				
May 2020 Security Bulletin Qualcomm	Patch Vendor Advisory www.qualcomm.com text/html	Q CONFIRM www.qualcomm.com/company/product-security/bulletins/may-2020-bulletin				
By selecting these links, you may be leaving CVEreport webspace. We have provided these links to other websites because they may have information that would be of interest to you. No inferences should be drawn on account of other sites being referenced, or not, from this page. There may be other websites that are more appropriate for your purpose. CVEreport does not necessarily endorse the views expressed, or concur with the facts presented on these sites. Further, CVEreport does not endorse any commercial products that may be mentioned on these sites. Please address comments about any linked pages to comment@cve.report.						
There are currently no QIDs associated with this CVE						
Known Affected Configurations (CPE V2.3)						
Type	Vendor	Product	Version	Update	Edition	Language
Hardware	Qualcomm	Apq8009	-	All	All	All
Hardware	Qualcomm	Apq8009	-	All	All	All
Operating System	Qualcomm	Apq8009 Firmware	-	All	All	All
Operating System	Qualcomm	Apq8009 Firmware	-	All	All	All
Hardware	Qualcomm	Apq8053	-	All	All	All
Hardware	Qualcomm	Apq8053	-	All	All	All
Operating System	Qualcomm	Apq8053 Firmware	-	All	All	All
Operating System	Qualcomm	Apq8053 Firmware	-	All	All	All
Hardware	Qualcomm	Apq8096au	-	All	All	All
Hardware	Qualcomm	Apq8096au	-	All	All	All
Operating System	Qualcomm	Apq8096au Firmware	-	All	All	All
Operating System	Qualcomm	Apq8096au Firmware	-	All	All	All

Hardware  	Qualcomm	Apq8098	-	All	All	All
Hardware  	Qualcomm	Apq8098	-	All	All	All
Operating System	Qualcomm	Apq8098 Firmware	-	All	All	All
Operating System	Qualcomm	Apq8098 Firmware	-	All	All	All
Hardware  	Qualcomm	Ipq4019	-	All	All	All
Hardware  	Qualcomm	Ipq4019	-	All	All	All
Operating System	Qualcomm	Ipq4019 Firmware	-	All	All	All
Operating System	Qualcomm	Ipq4019 Firmware	-	All	All	All
Hardware  	Qualcomm	Ipq8074	-	All	All	All
Hardware  	Qualcomm	Ipq8074	-	All	All	All
Operating System	Qualcomm	Ipq8074 Firmware	-	All	All	All
Operating System	Qualcomm	Ipq8074 Firmware	-	All	All	All
Hardware  	Qualcomm	Mdm9206	-	All	All	All
Hardware  	Qualcomm	Mdm9206	-	All	All	All
Operating System	Qualcomm	Mdm9206 Firmware	-	All	All	All
Operating System	Qualcomm	Mdm9206 Firmware	-	All	All	All
Hardware  	Qualcomm	Mdm9207c	-	All	All	All
Hardware  	Qualcomm	Mdm9207c	-	All	All	All
Operating System	Qualcomm	Mdm9207c Firmware	-	All	All	All
Operating System	Qualcomm	Mdm9207c Firmware	-	All	All	All
Hardware  	Qualcomm	Mdm9607	-	All	All	All
Hardware  	Qualcomm	Mdm9607	-	All	All	All
Operating System	Qualcomm	Mdm9607 Firmware	-	All	All	All
Operating System	Qualcomm	Mdm9607 Firmware	-	All	All	All
Hardware  	Qualcomm	Mdm9640	-	All	All	All
Hardware  	Qualcomm	Mdm9640	-	All	All	All
Operating System	Qualcomm	Mdm9640 Firmware	-	All	All	All

Operating System	Qualcomm	Mdm9640 Firmware	-	All	All	All
Hardware  	Qualcomm	Mdm9650	-	All	All	All
Hardware  	Qualcomm	Mdm9650	-	All	All	All
Operating System	Qualcomm	Mdm9650 Firmware	-	All	All	All
Operating System	Qualcomm	Mdm9650 Firmware	-	All	All	All
Hardware  	Qualcomm	Msm8905	-	All	All	All
Hardware  	Qualcomm	Msm8905	-	All	All	All
Operating System	Qualcomm	Msm8905 Firmware	-	All	All	All
Operating System	Qualcomm	Msm8905 Firmware	-	All	All	All
Hardware  	Qualcomm	Msm8909w	-	All	All	All
Hardware  	Qualcomm	Msm8909w	-	All	All	All
Operating System	Qualcomm	Msm8909w Firmware	-	All	All	All
Operating System	Qualcomm	Msm8909w Firmware	-	All	All	All
Hardware  	Qualcomm	Msm8917	-	All	All	All
Hardware  	Qualcomm	Msm8917	-	All	All	All
Operating System	Qualcomm	Msm8917 Firmware	-	All	All	All
Operating System	Qualcomm	Msm8917 Firmware	-	All	All	All
Hardware  	Qualcomm	Msm8953	-	All	All	All
Hardware  	Qualcomm	Msm8953	-	All	All	All
Operating System	Qualcomm	Msm8953 Firmware	-	All	All	All
Operating System	Qualcomm	Msm8953 Firmware	-	All	All	All
Hardware  	Qualcomm	Msm8996au	-	All	All	All
Hardware  	Qualcomm	Msm8996au	-	All	All	All
Operating System	Qualcomm	Msm8996au Firmware	-	All	All	All
Operating System	Qualcomm	Msm8996au Firmware	-	All	All	All
Hardware  	Qualcomm	Qca4531	-	All	All	All

Hardware  	Qualcomm	Qca4531	-	All	All	All
Operating System	Qualcomm	Qca4531 Firmware	-	All	All	All
Operating System	Qualcomm	Qca4531 Firmware	-	All	All	All
Hardware  	Qualcomm	Qcn7605	-	All	All	All
Hardware  	Qualcomm	Qcn7605	-	All	All	All
Operating System	Qualcomm	Qcn7605 Firmware	-	All	All	All
Operating System	Qualcomm	Qcn7605 Firmware	-	All	All	All
Hardware  	Qualcomm	Qcs605	-	All	All	All
Hardware  	Qualcomm	Qcs605	-	All	All	All
Operating System	Qualcomm	Qcs605 Firmware	-	All	All	All
Operating System	Qualcomm	Qcs605 Firmware	-	All	All	All
Hardware  	Qualcomm	Qm215	-	All	All	All
Hardware  	Qualcomm	Qm215	-	All	All	All
Operating System	Qualcomm	Qm215 Firmware	-	All	All	All
Operating System	Qualcomm	Qm215 Firmware	-	All	All	All
Hardware  	Qualcomm	Sa415m	-	All	All	All
Hardware  	Qualcomm	Sa415m	-	All	All	All
Operating System	Qualcomm	Sa415m Firmware	-	All	All	All
Operating System	Qualcomm	Sa415m Firmware	-	All	All	All
Hardware  	Qualcomm	Sc8180x	-	All	All	All
Hardware  	Qualcomm	Sc8180x	-	All	All	All
Operating System	Qualcomm	Sc8180x Firmware	-	All	All	All
Operating System	Qualcomm	Sc8180x Firmware	-	All	All	All
Hardware  	Qualcomm	Sda660	-	All	All	All
Hardware  	Qualcomm	Sda660	-	All	All	All
Operating System	Qualcomm	Sda660 Firmware	-	All	All	All
Operating	Qualcomm	Sda660 Firmware	-	All	All	All

System						
Hardware  	Qualcomm	Sda845	-	All	All	All
Hardware  	Qualcomm	Sda845	-	All	All	All
Operating System	Qualcomm	Sda845 Firmware	-	All	All	All
Operating System	Qualcomm	Sda845 Firmware	-	All	All	All
Hardware  	Qualcomm	Sdm429	-	All	All	All
Hardware  	Qualcomm	Sdm429	-	All	All	All
Hardware  	Qualcomm	Sdm429w	-	All	All	All
Hardware  	Qualcomm	Sdm429w	-	All	All	All
Operating System	Qualcomm	Sdm429w Firmware	-	All	All	All
Operating System	Qualcomm	Sdm429w Firmware	-	All	All	All
Operating System	Qualcomm	Sdm429 Firmware	-	All	All	All
Operating System	Qualcomm	Sdm429 Firmware	-	All	All	All
Hardware  	Qualcomm	Sdm439	-	All	All	All
Hardware  	Qualcomm	Sdm439	-	All	All	All
Operating System	Qualcomm	Sdm439 Firmware	-	All	All	All
Operating System	Qualcomm	Sdm439 Firmware	-	All	All	All
Hardware  	Qualcomm	Sdm450	-	All	All	All
Hardware  	Qualcomm	Sdm450	-	All	All	All
Operating System	Qualcomm	Sdm450 Firmware	-	All	All	All
Operating System	Qualcomm	Sdm450 Firmware	-	All	All	All
Hardware  	Qualcomm	Sdm630	-	All	All	All
Hardware  	Qualcomm	Sdm630	-	All	All	All
Operating System	Qualcomm	Sdm630 Firmware	-	All	All	All
Operating System	Qualcomm	Sdm630 Firmware	-	All	All	All
Hardware  	Qualcomm	Sdm632	-	All	All	All
Hardware  	Qualcomm	Sdm632	-	All	All	All

Operating System	Qualcomm	Sdm632 Firmware	-	All	All	All
Operating System	Qualcomm	Sdm632 Firmware	-	All	All	All
Hardware 	Qualcomm	Sdm636	-	All	All	All
Hardware 	Qualcomm	Sdm636	-	All	All	All
Operating System	Qualcomm	Sdm636 Firmware	-	All	All	All
Operating System	Qualcomm	Sdm636 Firmware	-	All	All	All
Hardware 	Qualcomm	Sdm660	-	All	All	All
Hardware 	Qualcomm	Sdm660	-	All	All	All
Operating System	Qualcomm	Sdm660 Firmware	-	All	All	All
Operating System	Qualcomm	Sdm660 Firmware	-	All	All	All
Hardware 	Qualcomm	Sdm845	-	All	All	All
Hardware 	Qualcomm	Sdm845	-	All	All	All
Operating System	Qualcomm	Sdm845 Firmware	-	All	All	All
Operating System	Qualcomm	Sdm845 Firmware	-	All	All	All
Hardware 	Qualcomm	Sdx20	-	All	All	All
Hardware 	Qualcomm	Sdx20	-	All	All	All
Operating System	Qualcomm	Sdx20 Firmware	-	All	All	All
Operating System	Qualcomm	Sdx20 Firmware	-	All	All	All
Hardware 	Qualcomm	Sdx24	-	All	All	All
Hardware 	Qualcomm	Sdx24	-	All	All	All
Operating System	Qualcomm	Sdx24 Firmware	-	All	All	All
Operating System	Qualcomm	Sdx24 Firmware	-	All	All	All
Hardware 	Qualcomm	Sdx55	-	All	All	All
Hardware 	Qualcomm	Sdx55	-	All	All	All
Operating System	Qualcomm	Sdx55 Firmware	-	All	All	All
Operating System	Qualcomm	Sdx55 Firmware	-	All	All	All
Operating System	Qualcomm	Sdx55 Firmware	-	All	All	All

Hardware		Qualcomm	Sm6150	-	All	All	All
Hardware		Qualcomm	Sm6150	-	All	All	All
Operating System		Qualcomm	Sm6150 Firmware	-	All	All	All
Operating System		Qualcomm	Sm6150 Firmware	-	All	All	All
Hardware		Qualcomm	Sm7150	-	All	All	All
Hardware		Qualcomm	Sm7150	-	All	All	All
Operating System		Qualcomm	Sm7150 Firmware	-	All	All	All
Operating System		Qualcomm	Sm7150 Firmware	-	All	All	All
Hardware		Qualcomm	Sm8150	-	All	All	All
Hardware		Qualcomm	Sm8150	-	All	All	All
Operating System		Qualcomm	Sm8150 Firmware	-	All	All	All
Operating System		Qualcomm	Sm8150 Firmware	-	All	All	All
Hardware		Qualcomm	Sm8250	-	All	All	All
Hardware		Qualcomm	Sm8250	-	All	All	All
Operating System		Qualcomm	Sm8250 Firmware	-	All	All	All
Operating System		Qualcomm	Sm8250 Firmware	-	All	All	All
Hardware		Qualcomm	Sxr2130	-	All	All	All
Hardware		Qualcomm	Sxr2130	-	All	All	All
Operating System		Qualcomm	Sxr2130 Firmware	-	All	All	All
Operating System		Qualcomm	Sxr2130 Firmware	-	All	All	All
cpe:2.3:h:qualcomm:apq8009:-:*~::~:							
cpe:2.3:h:qualcomm:apq8009:-:*~::~:							
cpe:2.3:o:qualcomm:apq8009_firmware:-:*~::~:							
cpe:2.3:o:qualcomm:apq8009_firmware:-:*~::~:							
cpe:2.3:h:qualcomm:apq8053:-:*~::~:							
cpe:2.3:h:qualcomm:apq8053:-:*~::~:							
cpe:2.3:o:qualcomm:apq8053_firmware:-:*~::~:							


```
cpe:2.3:o:qualcomm:apq8053_firmware:-:*:*:*:*:*:
```

cpe:2.3:h:qualcomm:apq8096au:-:*:*:*:*:*:*:

cpe:2.3:h:qualcomm:apq8096au:-:*:*:*:*:*:

```
cpe:2.3:o:qualcomm:apq8096au_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:apq8096au_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:h:qualcomm:apq8098:-:*:*:*:*:*:*:
```

cpe:2.3:h:qualcomm:apq8098:-:*:*:*:*:*:*:

```
cpe:2.3:o:qualcomm:apq8098_firmware:-:*:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:apq8098_firmware:-:*:*:*:*:*:
```

cpe:2.3:h:qualcomm:ipq4019:-:*:*:*:*:*:*:

cpe:2.3:h:qualcomm:ipq4019:-:*:*:*:*:*:*:

```
cpe:2.3:o:qualcomm:ipq4019_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:ipq4019_firmware:-:*:*:*:*:*:
```

cpe:2.3:h:qualcomm:ipq8074:-:*:*:*:*:*:*:

cpe:2.3:h:qualcomm:ipq8074:-:*:*:*:*:*:*:

```
cpe:2.3:o:qualcomm:ipq8074_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:ipq8074_firmware:-:*:*:*:*:*:
```

cpe:2.3:h:qualcomm:mdm9206:-:*:*:*:*:*:

cpe:2.3:h:qualcomm:mdm9206:-:*:*:*:*:*:*:

```
cpe:2.3:o:qualcomm:mdm9206_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:mdm9206_firmware:-:*:*:*:*:*.*
```

cpe:2.3:h:qualcomm:mdm9207c:-:*:*:*:*:*:*:

cpe:2.3:h:qualcomm:mdm9207c:-:*:*:*:*:*:*:

cpe:2.3:o:qualcomm:mdm9207c_firmware:-:*:*:*:*:*:*:

```
cpe:2.3:o:qualcomm:mdm9207c_firmware:-:*:*:*:*:*:
```

cpe:2.3:h:qualcomm:mdm9607:-:*:*:*:*:*:

cpe:2.3:h:qualcomm:mdm9607:-:*:*:*:*:*:*:

```
cpe:2.3:o:qualcomm:mdm9607_firmware:-:*:*:*:*:*
```

```
cpe:2.3:o:qualcomm:mdm9607_firmware:-:*:*:*:*:*:
```

cpe:2.3:h:qualcomm:mdm9640:-:*~::~:
cpe:2.3:h:qualcomm:mdm9640:-:*~::~:
cpe:2.3:o:qualcomm:mdm9640_firmware:-:*~::~:
cpe:2.3:o:qualcomm:mdm9640_firmware:-:*~::~:
cpe:2.3:h:qualcomm:mdm9650:-:*~::~:
cpe:2.3:h:qualcomm:mdm9650:-:*~::~:
cpe:2.3:o:qualcomm:mdm9650_firmware:-:*~::~:
cpe:2.3:o:qualcomm:mdm9650_firmware:-:*~::~:
cpe:2.3:h:qualcomm:msm8905:-:*~::~:
cpe:2.3:h:qualcomm:msm8905:-:*~::~:
cpe:2.3:o:qualcomm:msm8905_firmware:-:*~::~:
cpe:2.3:o:qualcomm:msm8905_firmware:-:*~::~:
cpe:2.3:h:qualcomm:msm8909w:-:*~::~:
cpe:2.3:h:qualcomm:msm8909w:-:*~::~:
cpe:2.3:o:qualcomm:msm8909w_firmware:-:*~::~:
cpe:2.3:o:qualcomm:msm8909w_firmware:-:*~::~:
cpe:2.3:h:qualcomm:msm8917:-:*~::~:
cpe:2.3:h:qualcomm:msm8917:-:*~::~:
cpe:2.3:o:qualcomm:msm8917_firmware:-:*~::~:
cpe:2.3:o:qualcomm:msm8917_firmware:-:*~::~:
cpe:2.3:h:qualcomm:msm8953:-:*~::~:
cpe:2.3:h:qualcomm:msm8953:-:*~::~:
cpe:2.3:o:qualcomm:msm8953_firmware:-:*~::~:
cpe:2.3:o:qualcomm:msm8953_firmware:-:*~::~:
cpe:2.3:h:qualcomm:msm8996au:-:*~::~:
cpe:2.3:h:qualcomm:msm8996au:-:*~::~:
cpe:2.3:o:qualcomm:msm8996au_firmware:-:*~::~:
cpe:2.3:o:qualcomm:msm8996au_firmware:-:*~::~:

cpe:2.3:h:qualcomm:gca4531:-:*:*:*:*:*:*:

cpe:2.3:h:qualcomm:gca4531:-:*:*:*:*:*:*:

```
cpe:2.3:o:qualcomm:qca4531 firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:qca4531 firmware:-:*:*:*:*:*:
```

cpe:2.3:h:qualcomm:qcn7605:-:*:*:*:*:*:*:

cpe:2.3:h:qualcomm:gcn7605:-:*:*:*:*:*:*:

```
cpe:2.3:o:qualcomm:qcn7605_firmware:-:*:*:*:*:*.*
```

```
cpe:2.3:o:qualcomm:qcn7605 firmware:-:*:*:*:*:*:
```

cpe:2.3:h:qualcomm:qcs605:-:*:*:*:*:*:*:

cpe:2.3:h:qualcomm:qcs605:-:*:*:*:*:*:*:

```
cpe:2.3:o:qualcomm:qcs605_firmware:-:*:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:qcs605_firmware:-:*:*:*:*:*:*:
```

cpe:2.3:h:qualcomm:qm215:-:*:*:*:*:*:

cpe:2.3:h:qualcomm:qm215:-:*:*:*:*:*:

```
cpe:2.3:o:qualcomm:qm215 firmware:-:*:*:*:*:*:*
```

```
cpe:2.3:o:qualcomm:qm215 firmware:-:*:*:*:*:*:*
```

cpe:2.3:h:qualcomm:sa415m:-:*:*:*:*:*:*:

cpe:2.3:h:qualcomm:sa415m:-:*:*:*:*:*:*:

```
cpe:2.3:o:qualcomm:sa415m_firmware:-:*:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:sa415m_firmware:-:*:*:*:*:*:*
```

cpe:2.3:h:qualcomm:sc8180x:-:*:*:*:*:*:

cpe:2.3:h:qualcomm:sc8180x:-:~::~::~:

```
cpe:2.3:o:qualcomm:sc8180x firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:sc8180x_firmware:-:*:*:*:*:*:*:
```

cpe:2.3:h:qualcomm:sda660:-:*:*:*:*:*:*:

cpe:2.3:h:qualcomm:sda660:-:*:*:*:*:*:*:

```
cpe:2.3:o:qualcomm:sda660_firmware:-:*:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:sda660_firmware:-:*:*:*:*:*:*
```

000-2 2-b-auglocomm-cdc245. *. *. *. *. *. *. *. *

CPe.2.3.11.qualificazioni.Sud043.7.

```
cpe:2.3:h:qualcomm:sda845:-:*:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:sda845_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:sda845_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:h:qualcomm:sdm429:-:*:*:*:*:*:*:
```

```
cpe:2.3:h:qualcomm:sdm429:-:*:*:*:*:*:*:
```

cpe:2.3:h:qualcomm:sdm429w:-:*:*:*:*:*:*:

cpe:2.3:h:qualcomm:sdm429w:-:*:*:*:*:*:*:

```
cpe:2.3:o:qualcomm:sdm429w_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:sdm429w_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:sdm429_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:sdm429_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:h:qualcomm:sdm439:-:*:*:*:*:*:*:
```

```
cpe:2.3:h:qualcomm:sdm439:-:*:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:sdm439_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:sdm439_firmware:-:*:*:*:*:*:*:
```

```
cpe:2.3:h:qualcomm:sdm450:-:*:*:*:*:*:*:
```

```
cpe:2.3:h:qualcomm:sdm450:-:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:sdm450_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:sdm450_firmware:-:*:*:*:*:*
```

```
cpe:2.3:h:qualcomm:sdm630:-:*:*:*:*:*:*:
```

```
cpe:2.3:h:qualcomm:sdm630:-:*:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:sdm630_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:sdm630_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:h:qualcomm:sdm632:-:*:*:*:*:*:
```

```
cpe:2.3:h:qualcomm:sdm632:-:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:sdm632_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:sdm632_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:h:qualcomm:sdm636:-:*:*:*:*:*:*:
```

cpe:2.3:h:qualcomm:sdm636:-:~::~~::~~::~~::~~::~~::~~:::
cpe:2.3:o:qualcomm:sdm636_firmware:-:~::~~::~~::~~::~~::~~::~~:::
cpe:2.3:o:qualcomm:sdm636_firmware:-:~::~~::~~::~~::~~::~~::~~:::
cpe:2.3:h:qualcomm:sdm660:-:~::~~::~~::~~::~~::~~::~~:::
cpe:2.3:h:qualcomm:sdm660:-:~::~~::~~::~~::~~::~~::~~:::
cpe:2.3:o:qualcomm:sdm660_firmware:-:~::~~::~~::~~::~~::~~::~~:::
cpe:2.3:o:qualcomm:sdm660_firmware:-:~::~~::~~::~~::~~::~~::~~:::
cpe:2.3:h:qualcomm:sdm845:-:~::~~::~~::~~::~~::~~::~~:::
cpe:2.3:h:qualcomm:sdm845:-:~::~~::~~::~~::~~::~~::~~:::
cpe:2.3:o:qualcomm:sdm845_firmware:-:~::~~::~~::~~::~~::~~::~~:::
cpe:2.3:o:qualcomm:sdm845_firmware:-:~::~~::~~::~~::~~::~~::~~:::
cpe:2.3:h:qualcomm:sdx20:-:~::~~::~~::~~::~~::~~::~~:::
cpe:2.3:h:qualcomm:sdx20:-:~::~~::~~::~~::~~::~~::~~:::
cpe:2.3:o:qualcomm:sdx20_firmware:-:~::~~::~~::~~::~~::~~::~~:::
cpe:2.3:o:qualcomm:sdx20_firmware:-:~::~~::~~::~~::~~::~~::~~:::
cpe:2.3:h:qualcomm:sdx24:-:~::~~::~~::~~::~~::~~::~~:::
cpe:2.3:h:qualcomm:sdx24:-:~::~~::~~::~~::~~::~~::~~:::
cpe:2.3:o:qualcomm:sdx24_firmware:-:~::~~::~~::~~::~~::~~::~~:::
cpe:2.3:o:qualcomm:sdx24_firmware:-:~::~~::~~::~~::~~::~~::~~:::
cpe:2.3:h:qualcomm:sdx55:-:~::~~::~~::~~::~~::~~::~~:::
cpe:2.3:h:qualcomm:sdx55:-:~::~~::~~::~~::~~::~~::~~:::
cpe:2.3:o:qualcomm:sdx55_firmware:-:~::~~::~~::~~::~~::~~::~~:::
cpe:2.3:o:qualcomm:sdx55_firmware:-:~::~~::~~::~~::~~::~~::~~:::
cpe:2.3:h:qualcomm:sm6150:-:~::~~::~~::~~::~~::~~::~~:::
cpe:2.3:h:qualcomm:sm6150:-:~::~~::~~::~~::~~::~~::~~:::
cpe:2.3:o:qualcomm:sm6150_firmware:-:~::~~::~~::~~::~~::~~::~~:::
cpe:2.3:o:qualcomm:sm6150_firmware:-:~::~~::~~::~~::~~::~~::~~:::
cpe:2.3:h:qualcomm:sm7150:-:~::~~::~~::~~::~~::~~::~~:::

cpe:2.3:h:qualcomm:sm7150:-:*.*.*.*.*.*.*.*.*
cpe:2.3:o:qualcomm:sm7150_firmware:-:*.*.*.*.*.*.*.*.*
cpe:2.3:o:qualcomm:sm7150_firmware:-:*.*.*.*.*.*.*.*.*
cpe:2.3:h:qualcomm:sm8150:-:*.*.*.*.*.*.*.*.*
cpe:2.3:h:qualcomm:sm8150:-:*.*.*.*.*.*.*.*.*
cpe:2.3:o:qualcomm:sm8150_firmware:-:*.*.*.*.*.*.*.*.*
cpe:2.3:o:qualcomm:sm8150_firmware:-:*.*.*.*.*.*.*.*.*
cpe:2.3:h:qualcomm:sm8250:-:*.*.*.*.*.*.*.*.*
cpe:2.3:h:qualcomm:sm8250:-:*.*.*.*.*.*.*.*.*
cpe:2.3:o:qualcomm:sm8250_firmware:-:*.*.*.*.*.*.*.*.*
cpe:2.3:o:qualcomm:sm8250_firmware:-:*.*.*.*.*.*.*.*.*
cpe:2.3:h:qualcomm:sxr2130:-:*.*.*.*.*.*.*.*.*
cpe:2.3:h:qualcomm:sxr2130:-:*.*.*.*.*.*.*.*.*
cpe:2.3:o:qualcomm:sxr2130_firmware:-:*.*.*.*.*.*.*.*.*
cpe:2.3:o:qualcomm:sxr2130_firmware:-:*.*.*.*.*.*.*.*.*

No vendor comments have been submitted for this CVE

[← Previous ID](#)

Next ID→

© CVE.report 2023 |

Use of this information constitutes acceptance for use in an AS IS condition. There are NO warranties, implied or otherwise, with regard to this information or its use. Any use of this information is at the user's risk. It is the responsibility of user to evaluate the accuracy, completeness or usefulness of any information, opinion, advice or other content. EACH USER WILL BE SOLELY RESPONSIBLE FOR ANY consequences of his or her direct or indirect use of this web site. ALL WARRANTIES OF ANY KIND ARE EXPRESSLY DISCLAIMED. This site will NOT BE LIABLE FOR ANY DIRECT, INDIRECT or any other kind of loss.

CVE, CWE, and OVAL are registered trademarks of [The MITRE Corporation](#) and the authoritative source of CVE content is [MITRE's CVE web site](#). This site includes MITRE data granted under the following [license](#).

CVE.report and Source URL Uptime Status status.cve.report