



CVE-2019-14083

Published on: 03/05/2020 12:00:00 AM UTC

Last Modified on: 03/23/2021 11:27:58 PM UTC


CVE-2019-14083

[Source: Mitre](#)

[Source: NIST](#)

[CVE.ORG](#)

[Print: PDF](#)



Certain versions of [Apq8009](#) from [Qualcomm](#) contain the following vulnerability:

While parsing Service Descriptor Extended Attribute received as part of SDF frame, there is a possibility that incorrect length is specified in the attribute length field of extended SSI which can lead to integer underflow in Snapdragon Auto, Snapdragon Compute, Snapdragon Connectivity, Snapdragon Consumer Electronics Connectivity,

Snapdragon Consumer IOT, Snapdragon Industrial IOT, Snapdragon IoT, Snapdragon Mobile, Snapdragon Voice & Music, Snapdragon Wired Infrastructure and Networking in APQ8009, APQ8053, APQ8096, APQ8098, IPQ6018, IPQ8074, MSM8996AU, MSM8998, Nicobar, QCA6174A, QCA6390, QCA6574AU, QCA8081, QCA9377, QCA9379, QCN7605, QCS404, QCS405, QCS605, Rennell, SC8180X, SDA660, SDA845, SDM630, SDM636, SDM660, SDM670, SDM710, SDM845, SDM850, SDX20, SDX24, SM6150, SM7150, SM8150, SXR1130, SXR2130

CVE-2019-14083 has been assigned by [Q](#) product-security@qualcomm.com to track the vulnerability - currently rated as **CRITICAL** severity.

Affected Vendor/Software: [Q](#) **Qualcomm, Inc. - Snapdragon Auto, Snapdragon Compute, Snapdragon Connectivity, Snapdragon Consumer Electronics Connectivity, Snapdragon Consumer IOT, Snapdragon Industrial IOT, Snapdragon IoT, Snapdragon Mobile, Snapdragon Voice & Music, Snapdragon Wired Infrastructure and Networking** version **APQ8009, APQ8053, APQ8096, APQ8098, IPQ6018, IPQ8074, MSM8996AU, MSM8998, Nicobar, QCA6174A, QCA6390, QCA6574AU, QCA8081, QCA9377, QCA9379, QCN7605, QCS404, QCS405, QCS605, Rennell, SC8180X, SDA660, SDA845, SDM630, SDM636, SDM660, SDM670, SDM710, SDM845, SDM850, SDX20, SDX24, SM6150, SM7150, SM8150, SXR1130, SXR2130**

CVSS3 Score: **9.8 - CRITICAL**

Attack Vector	Attack Complexity	Privileges Required	User Interaction
NETWORK	LOW	NONE	NONE
Scope	Confidentiality Impact	Integrity Impact	Availability Impact
UNCHANGED	HIGH	HIGH	HIGH

CVSS2 Score: **10 - HIGH**

Access Vector	Access Complexity	Authentication
NETWORK	LOW	NONE
Confidentiality Impact	Integrity Impact	Availability Impact
COMPLETE	COMPLETE	COMPLETE

CVE References

Description	Tags	Link
March 2020 Security Bulletin Qualcomm	Vendor Advisory www.qualcomm.com text/html	Q CONFIRM www.qualcomm.com/company/product-security/bulletins/march-2020-bulletin
By selecting these links, you may be leaving CVEreport webspace. We have provided these links to other websites because they may have information that would be of interest to you. No inferences should be drawn on account of other sites being referenced, or not, from this page. There may be other websites that are more appropriate for your purpose. CVEreport does not necessarily endorse the views expressed, or concur with the facts presented on these sites. Further, CVEreport does not endorse any commercial products that may be mentioned on these sites. Please address comments about any linked pages to comment@cve.report.		

There are currently no QIDs associated with this CVE

Known Affected Configurations (CPE V2.3)

Type	Vendor	Product	Version	Update	Edition	Language
Hardware 	Qualcomm	Apq8009	-	All	All	All
Hardware 	Qualcomm	Apq8009	-	All	All	All
Operating System	Qualcomm	Apq8009 Firmware	-	All	All	All
Operating System	Qualcomm	Apq8009 Firmware	-	All	All	All
Hardware 	Qualcomm	Apq8053	-	All	All	All
Hardware 	Qualcomm	Apq8053	-	All	All	All
Operating System	Qualcomm	Apq8053 Firmware	-	All	All	All
Operating System	Qualcomm	Apq8053 Firmware	-	All	All	All
Hardware 	Qualcomm	Apq8096	-	All	All	All
Hardware 	Qualcomm	Apq8096	-	All	All	All
Operating System	Qualcomm	Apq8096 Firmware	-	All	All	All
Operating System	Qualcomm	Apq8096 Firmware	-	All	All	All
Hardware 	Qualcomm	Apq8098	-	All	All	All

Hardware  	Qualcomm	Apq8098	-	All	All	All
Operating System	Qualcomm	Apq8098 Firmware	-	All	All	All
Operating System	Qualcomm	Apq8098 Firmware	-	All	All	All
Hardware  	Qualcomm	Ipq6018	-	All	All	All
Hardware  	Qualcomm	Ipq6018	-	All	All	All
Operating System	Qualcomm	Ipq6018 Firmware	-	All	All	All
Operating System	Qualcomm	Ipq6018 Firmware	-	All	All	All
Hardware  	Qualcomm	Ipq8074	-	All	All	All
Hardware  	Qualcomm	Ipq8074	-	All	All	All
Operating System	Qualcomm	Ipq8074 Firmware	-	All	All	All
Operating System	Qualcomm	Ipq8074 Firmware	-	All	All	All
Hardware  	Qualcomm	Msm8996au	-	All	All	All
Hardware  	Qualcomm	Msm8996au	-	All	All	All
Operating System	Qualcomm	Msm8996au Firmware	-	All	All	All
Operating System	Qualcomm	Msm8996au Firmware	-	All	All	All
Hardware  	Qualcomm	Msm8998	-	All	All	All
Hardware  	Qualcomm	Msm8998	-	All	All	All
Operating System	Qualcomm	Msm8998 Firmware	-	All	All	All
Operating System	Qualcomm	Msm8998 Firmware	-	All	All	All
Hardware  	Qualcomm	Nicobar	-	All	All	All
Hardware  	Qualcomm	Nicobar	-	All	All	All
Operating System	Qualcomm	Nicobar Firmware	-	All	All	All
Operating System	Qualcomm	Nicobar Firmware	-	All	All	All
Hardware  	Qualcomm	Qca6174a	-	All	All	All
Hardware  	Qualcomm	Qca6174a	-	All	All	All
Operating System	Qualcomm	Qca6174a Firmware	-	All	All	All
Operating	Qualcomm	Qca6174a Firmware	-	All	All	All

System						
Hardware  	Qualcomm	Qca6390	-	All	All	All
Hardware  	Qualcomm	Qca6390	-	All	All	All
Operating System	Qualcomm	Qca6390 Firmware	-	All	All	All
Operating System	Qualcomm	Qca6390 Firmware	-	All	All	All
Hardware  	Qualcomm	Qca6574au	-	All	All	All
Hardware  	Qualcomm	Qca6574au	-	All	All	All
Operating System	Qualcomm	Qca6574au Firmware	-	All	All	All
Operating System	Qualcomm	Qca6574au Firmware	-	All	All	All
Hardware  	Qualcomm	Qca8081	-	All	All	All
Hardware  	Qualcomm	Qca8081	-	All	All	All
Operating System	Qualcomm	Qca8081 Firmware	-	All	All	All
Operating System	Qualcomm	Qca8081 Firmware	-	All	All	All
Hardware  	Qualcomm	Qca9377	-	All	All	All
Hardware  	Qualcomm	Qca9377	-	All	All	All
Operating System	Qualcomm	Qca9377 Firmware	-	All	All	All
Operating System	Qualcomm	Qca9377 Firmware	-	All	All	All
Hardware  	Qualcomm	Qca9379	-	All	All	All
Hardware  	Qualcomm	Qca9379	-	All	All	All
Operating System	Qualcomm	Qca9379 Firmware	-	All	All	All
Operating System	Qualcomm	Qca9379 Firmware	-	All	All	All
Hardware  	Qualcomm	Qcn7605	-	All	All	All
Hardware  	Qualcomm	Qcn7605	-	All	All	All
Operating System	Qualcomm	Qcn7605 Firmware	-	All	All	All
Operating System	Qualcomm	Qcn7605 Firmware	-	All	All	All
Hardware  	Qualcomm	Qcs404	-	All	All	All
Hardware  	Qualcomm	Qcs404	-	All	All	All

Operating System	Qualcomm	Qcs404 Firmware	-	All	All	All
Operating System	Qualcomm	Qcs404 Firmware	-	All	All	All
Hardware  	Qualcomm	Qcs405	-	All	All	All
Hardware  	Qualcomm	Qcs405	-	All	All	All
Operating System	Qualcomm	Qcs405 Firmware	-	All	All	All
Operating System	Qualcomm	Qcs405 Firmware	-	All	All	All
Hardware  	Qualcomm	Qcs605	-	All	All	All
Hardware  	Qualcomm	Qcs605	-	All	All	All
Operating System	Qualcomm	Qcs605 Firmware	-	All	All	All
Operating System	Qualcomm	Qcs605 Firmware	-	All	All	All
Hardware  	Qualcomm	Rennell	-	All	All	All
Hardware  	Qualcomm	Rennell	-	All	All	All
Operating System	Qualcomm	Rennell Firmware	-	All	All	All
Operating System	Qualcomm	Rennell Firmware	-	All	All	All
Hardware  	Qualcomm	Sc8180x	-	All	All	All
Hardware  	Qualcomm	Sc8180x	-	All	All	All
Operating System	Qualcomm	Sc8180x Firmware	-	All	All	All
Operating System	Qualcomm	Sc8180x Firmware	-	All	All	All
Hardware  	Qualcomm	Sda660	-	All	All	All
Hardware  	Qualcomm	Sda660	-	All	All	All
Operating System	Qualcomm	Sda660 Firmware	-	All	All	All
Operating System	Qualcomm	Sda660 Firmware	-	All	All	All
Hardware  	Qualcomm	Sda845	-	All	All	All
Hardware  	Qualcomm	Sda845	-	All	All	All
Operating System	Qualcomm	Sda845 Firmware	-	All	All	All
Operating System	Qualcomm	Sda845 Firmware	-	All	All	All

Hardware  	Qualcomm	Sdm630	-	All	All	All
Hardware  	Qualcomm	Sdm630	-	All	All	All
Operating System	Qualcomm	Sdm630 Firmware	-	All	All	All
Operating System	Qualcomm	Sdm630 Firmware	-	All	All	All
Hardware  	Qualcomm	Sdm636	-	All	All	All
Hardware  	Qualcomm	Sdm636	-	All	All	All
Operating System	Qualcomm	Sdm636 Firmware	-	All	All	All
Operating System	Qualcomm	Sdm636 Firmware	-	All	All	All
Hardware  	Qualcomm	Sdm660	-	All	All	All
Hardware  	Qualcomm	Sdm660	-	All	All	All
Operating System	Qualcomm	Sdm660 Firmware	-	All	All	All
Operating System	Qualcomm	Sdm660 Firmware	-	All	All	All
Hardware  	Qualcomm	Sdm670	-	All	All	All
Hardware  	Qualcomm	Sdm670	-	All	All	All
Operating System	Qualcomm	Sdm670 Firmware	-	All	All	All
Operating System	Qualcomm	Sdm670 Firmware	-	All	All	All
Hardware  	Qualcomm	Sdm710	-	All	All	All
Hardware  	Qualcomm	Sdm710	-	All	All	All
Operating System	Qualcomm	Sdm710 Firmware	-	All	All	All
Operating System	Qualcomm	Sdm710 Firmware	-	All	All	All
Hardware  	Qualcomm	Sdm845	-	All	All	All
Hardware  	Qualcomm	Sdm845	-	All	All	All
Operating System	Qualcomm	Sdm845 Firmware	-	All	All	All
Operating System	Qualcomm	Sdm845 Firmware	-	All	All	All
Hardware  	Qualcomm	Sdm850	-	All	All	All
Hardware  	Qualcomm	Sdm850	-	All	All	All
Operating System	Qualcomm	Sdm850 Firmware	-	All	All	All

Operating System	Qualcomm	Sdm850 Firmware	-	All	All	All
Hardware  	Qualcomm	Sdx20	-	All	All	All
Hardware  	Qualcomm	Sdx20	-	All	All	All
Operating System	Qualcomm	Sdx20 Firmware	-	All	All	All
Operating System	Qualcomm	Sdx20 Firmware	-	All	All	All
Hardware  	Qualcomm	Sdx24	-	All	All	All
Hardware  	Qualcomm	Sdx24	-	All	All	All
Operating System	Qualcomm	Sdx24 Firmware	-	All	All	All
Operating System	Qualcomm	Sdx24 Firmware	-	All	All	All
Hardware  	Qualcomm	Sm6150	-	All	All	All
Hardware  	Qualcomm	Sm6150	-	All	All	All
Operating System	Qualcomm	Sm6150 Firmware	-	All	All	All
Operating System	Qualcomm	Sm6150 Firmware	-	All	All	All
Hardware  	Qualcomm	Sm7150	-	All	All	All
Hardware  	Qualcomm	Sm7150	-	All	All	All
Operating System	Qualcomm	Sm7150 Firmware	-	All	All	All
Operating System	Qualcomm	Sm7150 Firmware	-	All	All	All
Hardware  	Qualcomm	Sm8150	-	All	All	All
Hardware  	Qualcomm	Sm8150	-	All	All	All
Operating System	Qualcomm	Sm8150 Firmware	-	All	All	All
Operating System	Qualcomm	Sm8150 Firmware	-	All	All	All
Hardware  	Qualcomm	Sxr1130	-	All	All	All
Hardware  	Qualcomm	Sxr1130	-	All	All	All
Operating System	Qualcomm	Sxr1130 Firmware	-	All	All	All
Operating System	Qualcomm	Sxr1130 Firmware	-	All	All	All
Hardware  	Qualcomm	Sxr2130	-	All	All	All

Hardware	Qualcomm	Sxr2130	-	All	All	All
Operating System	Qualcomm	Sxr2130 Firmware	-	All	All	All
Operating System	Qualcomm	Sxr2130 Firmware	-	All	All	All
cpe:2.3:h:qualcomm:apq8009:-:*~::~:						
cpe:2.3:h:qualcomm:apq8009:-:*~::~:						
cpe:2.3:o:qualcomm:apq8009_firmware:-:*~::~:						
cpe:2.3:o:qualcomm:apq8009_firmware:-:*~::~:						
cpe:2.3:h:qualcomm:apq8053:-:*~::~:						
cpe:2.3:h:qualcomm:apq8053:-:*~::~:						
cpe:2.3:o:qualcomm:apq8053_firmware:-:*~::~:						
cpe:2.3:o:qualcomm:apq8053_firmware:-:*~::~:						
cpe:2.3:h:qualcomm:apq8096:-:*~::~:						
cpe:2.3:h:qualcomm:apq8096:-:*~::~:						
cpe:2.3:o:qualcomm:apq8096_firmware:-:*~::~:						
cpe:2.3:o:qualcomm:apq8096_firmware:-:*~::~:						
cpe:2.3:h:qualcomm:apq8098:-:*~::~:						
cpe:2.3:h:qualcomm:apq8098:-:*~::~:						
cpe:2.3:o:qualcomm:apq8098_firmware:-:*~::~:						
cpe:2.3:o:qualcomm:apq8098_firmware:-:*~::~:						
cpe:2.3:h:qualcomm:ipq6018:-:*~::~:						
cpe:2.3:h:qualcomm:ipq6018:-:*~::~:						
cpe:2.3:o:qualcomm:ipq6018_firmware:-:*~::~:						
cpe:2.3:o:qualcomm:ipq6018_firmware:-:*~::~:						
cpe:2.3:h:qualcomm:ipq8074:-:*~::~:						
cpe:2.3:h:qualcomm:ipq8074:-:*~::~:						
cpe:2.3:o:qualcomm:ipq8074_firmware:-:*~::~:						
cpe:2.3:o:qualcomm:ipq8074_firmware:-:*~::~:						
cpe:2.3:h:qualcomm:msm8996au:-:*~::~:						

cpe:2.3:h:qualcomm:msm8996au:-:*:*:*:*:*:*:

```
cpe:2.3:o:qualcomm:msm8996au firmware:-.*:.*:.*:.*:.*:.*
```

```
cpe:2.3:o:qualcomm:msm8996au_firmware:-:*:*:*:*:*:
```

cpe:2.3:h:qualcomm:msm8998:-:*:*:*:*:*:*:

cpe:2.3:h:qualcomm:msm8998:-:*:*:*:*:*:*:

```
cpe:2.3:o:qualcomm:msm8998_firmware:-:*:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:msm8998_firmware:-:*:*:*:*:*:*:
```

cpe:2.3:h:qualcomm:nicobar:-:*:*:*:*:*:*:

cpe:2.3:h:qualcomm:nicobar:-:*:*:*:*:*:*:

```
cpe:2.3:o:qualcomm:nicobar firmware:-:*:*:*:*:*:*
```

```
cpe:2.3:o:qualcomm:nicobar_firmware:-:*:*:*:*:*:*:
```

cpe:2.3:h:qualcomm:qca6174a:-:*:*:*:*:*:*:

cpe:2.3:h:qualcomm:gca6174a:-:*:*:*:*:*:

```
cpe:2.3:o:qualcomm:qca6174a_firmware:-:*:*:*:*:*.*
```

```
cpe:2.3:o:qualcomm:qca6174a_firmware:-:*:*:*:*:*:*:
```

cpe:2.3:h:qualcomm:qca6390:-:*:*:*:*:*:

cpe:2.3:h:qualcomm:qca6390:-:*:*:*:*:*:

```
cpe:2.3:o:qualcomm:qca6390 firmware:-:*:*:*:*:*:*
```

```
cpe:2.3:o:qualcomm:qca6390 firmware:-:*:*:*:*:*.*
```

cpe:2.3:h:qualcomm:qca6574au:-:*:*:*:*:*:*:

cpe:2.3:h:qualcomm:qca6574au:-:*:*:*:*:*:*:

```
cpe:2.3:o:qualcomm:gca6574au firmware:-:*:*:*:*:*.*
```

```
cpe:2.3:o:qualcomm:qca6574au_firmware:-:*:*:*:*:*:
```

cpe:2.3:h:qualcomm:qca8081:-:*:*:*:*:*:

cpe:2.3:h:qualcomm:qca8081:-:*:*:*:*:*:

```
cpe:2.3:o:qualcomm:gca8081 firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:gca8081 firmware:-:*:*:*:*:*:
```

cpe:2.3:h:qualcomm:qca9377:-:*:*:*:*:*:

cpe:2.3:h:qualcomm:qca9377:-:*:*:*:*:*:

```
cpe:2.3:o:qualcomm:gca9377_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:gca9377_firmware:-:*:*:*:*:*.*
```

cpe:2.3:h:qualcomm:gca9379:-:*:*:*:*:*:*:

cpe:2.3:h:qualcomm:gca9379:-:*:*:*:*:*:*:

```
cpe:2.3:o:qualcomm:qca9379 firmware:-:*:*:*:*:*.*
```

```
cpe:2.3:o:qualcomm:qca9379 firmware:-:*:*:*:*:*:*
```

cpe:2.3:h:qualcomm:gcn7605:-:*:*:*:*:*:

cpe:2.3:h:qualcomm:gcn7605:-:*:*:*:*:*:

```
cpe:2.3:o:qualcomm:qcn7605_firmware:-:*:*:*:*:*:*
```

```
cpe:2.3:o:qualcomm:qcn7605 firmware:-:*:*:*:*:*:
```

cpe:2.3:h:qualcomm:qcs404:-:*:*:*:*:*:*:

cpe:2.3:h:qualcomm:qcs404:-:*:*:*:*:*:*:

```
cpe:2.3:o:qualcomm:qcs404_firmware:-:*:*:*:*:*:*
```

```
cpe:2.3:o:qualcomm:qcs404_firmware:-:*:*:*:*:*:*
```

cpe:2.3:h:qualcomm:qcs405:-:*:*:*:*:*:*:

cpe:2.3:h:qualcomm:qcs405:-:*:*:*:*:*:*:

```
cpe:2.3:o:qualcomm:qcs405_firmware:-:*:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:qcs405_firmware:-:*:*:*:*:*:
```

cpe:2.3:h:qualcomm:qcs605:-:*:*:*:*:*:*:

cpe:2.3:h:qualcomm:qcs605:-:*:*:*:*:*:*:

```
cpe:2.3:o:qualcomm:qcs605_firmware:-:*:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:qcs605_firmware:-:*:*:*:*:*:*:
```

cpe:2.3:h:qualcomm:rennell:-:*:*:*:*:*:*:

cpe:2.3:h:qualcomm:rennell:-:*:*:*:*:*:*:

```
cpe:2.3:o:qualcomm:rennell_firmware:-:*:*:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:rennell_firmware:-:*:*:*:*:*:
```

cpe:2.3:h:qualcomm:sc8180x:-:*:*:*:*:*:*:

cpe:2.3:h:qualcomm:sc8180x:-:*:*:*:*:*:*:

```
cpe:2.3:o:qualcomm:sc8180x_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:sc8180x_firmware:-:*:*:*:*:*:
```

cpe:2.3:h:qualcomm:sda660:-:*:*:*:*:*:*:

cpe:2.3:h:qualcomm:sda660:-:*:*:*:*:*:*:

```
cpe:2.3:o:qualcomm:sda660_firmware:-:*:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:sda660_firmware:-:*:*:*:*:*:*:
```

cpe:2.3:h:qualcomm:sda845:-:*:*:*:*:*:*:

cpe:2.3:h:qualcomm:sda845:-:*:*:*:*:*:*:

```
cpe:2.3:o:qualcomm:sda845_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:sda845_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:h:qualcomm:sdm630:-:*:*:*:*:*:*:
```

```
cpe:2.3:h:qualcomm:sdm630:-:*:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:sdm630_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:sdm630_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:h:qualcomm:sdm636:-:*:*:*:*:*:*:
```

```
cpe:2.3:h:qualcomm:sdm636:-:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:sdm636_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:sdm636_firmware:-:*:*:*:*:*:*
```

```
cpe:2.3:h:qualcomm:sdm660:-:*:*:*:*:*:*:
```

cpe:2.3:h:qualcomm:sdm660:-:*:*:*:*:*:*:

```
cpe:2.3:o:qualcomm:sdm660_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:sdm660_firmware:-:*:*:*:*:*:
```

```
cpe:2.3:h:qualcomm:sdm670:-:*:*:*:*:*:
```

cpe:2.3:h:qualcomm:sdm670:-:*:*:*:*:*:*:

```
cpe:2.3:o:qualcomm:sdm670 firmware:-:*:*:*:*:*:
```

```
cpe:2.3:o:qualcomm:sdm670 firmware:-:*:*:*:*:*:
```

cpe:2.3:h:qualcomm:sdm710:-:*:*:*:*:*:*:

cpe:2.3:h:qualcomm:sdm710:-:*:*:*:*:*:*:

```
cpe:2.3:o:qualcomm:sdm710 firmware:-:*:*:*:*:*:
```

cpe:2.3:o:qualcomm:sdm710_firmware:-:*****:
cpe:2.3:h:qualcomm:sdm710_firmware:-:*****:
cpe:2.3:o:qualcomm:sdm845:-:*****:
cpe:2.3:h:qualcomm:sdm845:-:*****:
cpe:2.3:o:qualcomm:sdm845_firmware:-:*****:
cpe:2.3:h:qualcomm:sdm845_firmware:-:*****:
cpe:2.3:o:qualcomm:sdm850:-:*****:
cpe:2.3:h:qualcomm:sdm850:-:*****:
cpe:2.3:o:qualcomm:sdm850_firmware:-:*****:
cpe:2.3:h:qualcomm:sdm850_firmware:-:*****:
cpe:2.3:o:qualcomm:sdx20:-:*****:
cpe:2.3:h:qualcomm:sdx20:-:*****:
cpe:2.3:o:qualcomm:sdx20_firmware:-:*****:
cpe:2.3:h:qualcomm:sdx20_firmware:-:*****:
cpe:2.3:o:qualcomm:sdx24:-:*****:
cpe:2.3:h:qualcomm:sdx24:-:*****:
cpe:2.3:o:qualcomm:sdx24_firmware:-:*****:
cpe:2.3:h:qualcomm:sdx24_firmware:-:*****:
cpe:2.3:o:qualcomm:sm6150:-:*****:
cpe:2.3:h:qualcomm:sm6150:-:*****:
cpe:2.3:o:qualcomm:sm6150_firmware:-:*****:
cpe:2.3:h:qualcomm:sm6150_firmware:-:*****:
cpe:2.3:o:qualcomm:sm7150:-:*****:
cpe:2.3:h:qualcomm:sm7150:-:*****:
cpe:2.3:o:qualcomm:sm7150_firmware:-:*****:
cpe:2.3:h:qualcomm:sm7150_firmware:-:*****:
cpe:2.3:o:qualcomm:sm8150:-:*****:
cpe:2.3:h:qualcomm:sm8150:-:*****:
cpe:2.3:o:qualcomm:sm8150_firmware:-:*****:

cpe:2.3:o:qualcomm:sm8150_firmware:-:*****:
cpe:2.3:h:qualcomm:sxr1130:-:*****:
cpe:2.3:h:qualcomm:sxr1130:-:*****:
cpe:2.3:o:qualcomm:sxr1130_firmware:-:*****:
cpe:2.3:o:qualcomm:sxr1130_firmware:-:*****:
cpe:2.3:h:qualcomm:sxr2130:-:*****:
cpe:2.3:h:qualcomm:sxr2130:-:*****:
cpe:2.3:o:qualcomm:sxr2130_firmware:-:*****:
cpe:2.3:o:qualcomm:sxr2130_firmware:-:*****:

No vendor comments have been submitted for this CVE

[← Previous ID](#)

[Next ID →](#)