



CVE-2019-17219


Published on: 10/06/2019 12:00:00 AM UTC

Last Modified on: 03/23/2021 11:27:38 PM UTC

CVE-2019-17219

[Source: Mitre](#)[Source: NIST](#)[CVE.ORG](#)[Print: PDF](#)

CVSS:31/AV:A/AC:L/PR:N/UI:N/S:U/C:H/I:H/A:H



Certain versions of [Combi-stream Mslq](#) from [Vzug](#) contain the following vulnerability:

An issue was discovered on V-Zug Combi-Steam MSLQ devices before Ethernet R07 and before WLAN R05. By default, the device does not enforce any authentication. An adjacent attacker is able to use the network interface without proper access control.

CVE-2019-17219 has been assigned by [M](#) cve@mitre.org to track the vulnerability - currently rated as **HIGH** severity.

CVSS3 Score: **8.8 - HIGH**

Attack Vector	Attack Complexity	Privileges Required	User Interaction
ADJACENT_NETWORK	LOW	NONE	NONE
Scope	Confidentiality Impact	Integrity Impact	Availability Impact
UNCHANGED	HIGH	HIGH	HIGH

CVSS2 Score: **5.8 - MEDIUM**

Access Vector	Access Complexity	Authentication
ADJACENT_NETWORK	LOW	NONE
Confidentiality Impact	Integrity Impact	Availability Impact
PARTIAL	PARTIAL	PARTIAL

CVE References

Description	Tags	Link
CVE-2019-17219 V-Zug Combi-Steam MSLQ improper authentication (ID 134115)	Permissions Required Third Party Advisory vuldb.com text/html	MISC vuldb.com/?id.134115

By selecting these links, you may be leaving CVEreport webspace. We have provided these links to other websites because they may have information that would be of interest to you. No inferences should be drawn on account of other sites being referenced, or not, from this page. There may be other websites that are more appropriate for your purpose. CVEreport does not necessarily endorse the views expressed, or concur with the facts presented on these sites. Further, CVEreport does not endorse any commercial products that may be mentioned on these sites. Please address comments about any linked pages to comment@cve.report.

There are currently no QIDs associated with this CVE

Known Affected Configurations (CPE V2.3)

Type	Vendor	Product	Version	Update	Edition	Language
Hardware 	Vzug	Combi-stream Mslq	-	All	All	All
Hardware 	Vzug	Combi-stream Mslq	-	All	All	All
Operating System	Vzug	Combi-stream Mslq Firmware	All	All	All	All
Operating System	Vzug	Combi-stream Mslq Firmware	All	All	All	All
cpe:2.3:h:vzug:combi-stream_mslq:-:~::~~::~~::~~::~~::~~::~~::						
cpe:2.3:h:vzug:combi-stream_mslq:-:~::~~::~~::~~::~~::~~::~~::						
cpe:2.3:o:vzug:combi-stream_mslq_firmware:~::~~::~~::~~::~~::~~::~~::						
cpe:2.3:o:vzug:combi-stream_mslq_firmware:~::~~::~~::~~::~~::~~::~~::						

No vendor comments have been submitted for this CVE

[← Previous ID](#)

[Next ID →](#)