




CVE-2019-19143

Published on: 01/27/2020 12:00:00 AM UTC

Last Modified on: 02/01/2023 03:19:00 PM UTC

CVE-2019-19143

[Source: Mitre](#)[Source: NIST](#)[CVE.ORG](#)[Print: PDF](#) 

Certain versions of [TL-wr849n](#) from [Tp-link](#) contain the following vulnerability:

TP-LINK TL-WR849N 0.9.1 4.16 devices do not require authentication to replace the firmware via a POST request to the cgi/softup URI.

CVE-2019-19143 has been assigned by [M](#) cve@mitre.org to track the vulnerability - currently rated as **MEDIUM** severity.

CVSS3 Score: **6.1 - MEDIUM**

Attack Vector	Attack Complexity	Privileges Required	User Interaction
ADJACENT_NETWORK	LOW	HIGH	NONE
Scope	Confidentiality Impact	Integrity Impact	Availability Impact
UNCHANGED	HIGH	HIGH	NONE

CVSS2 Score: **4.1 - MEDIUM**

Access Vector	Access Complexity	Authentication
ADJACENT_NETWORK	LOW	SINGLE
Confidentiality Impact	Integrity Impact	Availability Impact
PARTIAL	PARTIAL	NONE

CVE References

Description	Tags	Link
TP-Link TL-WR849N 0.9.1 4.16 Authentication Bypass ≈ Packet Storm	packetstormsecurity.com text/html	MISC packetstormsecurity.com/files/156586/TP-Link-TL-WR849N-0.9.1-4.16-Authentication-Bypass.html
Hack 'N' Routers - Vulnerabilidades comuns em roteadores	Exploit	MISC fireshellsecurity.team/hack-n-routers/

By selecting these links, you may be leaving CVEreport webspace. We have provided these links to other websites because they may have information that would be of interest to you. No inferences should be drawn on account of other sites being referenced, or not, from this page. There may be other websites that are more appropriate for your purpose. CVEreport does not necessarily endorse the views expressed, or concur with the facts presented on these sites. Further, CVEreport does not endorse any commercial products that may be mentioned on these sites. Please address comments about any linked pages to comment@cve.report.

There are currently no QIDs associated with this CVE

Known Affected Configurations (CPE V2.3)

Type	Vendor	Product	Version	Update	Edition	Language
Hardware  	Tp-link	TL-wr849n	-	All	All	All
Hardware  	Tp-link	TL-wr849n	-	All	All	All
Operating System	Tp-link	TL-wr849n Firmware	0.9.1_4.16	All	All	All
Operating System	Tp-link	TL-wr849n Firmware	0.9.1_4.16	All	All	All
cpe:2.3:h:tp-link:tl-wr849n:-:*:*:*:*:*:						
cpe:2.3:h:tp-link:tl-wr849n:-:*:*:*:*:*:						
cpe:2.3:o:tp-link:tl-wr849n_firmware:0.9.1_4.16:*:*:*:*:*:						
cpe:2.3:o:tp-link:tl-wr849n_firmware:0.9.1_4.16:*:*:*:*:*:						

No vendor comments have been submitted for this CVE

[← Previous ID](#)

[Next ID →](#)