



CVE-2019-3998

[MITRE](#)[NVD](#)[CVE.ORG](#)[Print: PDF](#)

Summary

CVE	CVE-2019-3998
State	PUBLIC
Assigner	vulnreport@tenable.com
Source Priority	CVE Program / NVD first with legacy fallback
Published	2020-02-13 21:15:00 UTC
Updated	2020-02-25 18:39:00 UTC
Description	Authentication bypass using an alternate path or channel in SimpliSafe SS3 firmware 1.4 allows a local, unauthenticated at

Risk And Classification

Problem Types: CWE-287

NVD Known Affected Configurations (CPE 2.3)

Type	Vendor	Product	Version	Update	Edition	Language
Hardware	Simplisafe	Simplisafe Ss3	-	All	All	All
Hardware	Simplisafe	Simplisafe Ss3	-	All	All	All
Operating System	Simplisafe	Simplisafe Ss3 Firmware	1.4	All	All	All
Operating System	Simplisafe	Simplisafe Ss3 Firmware	1.4	All	All	All

References

Reference	Source	Link	Tags
SimpliSafe SS3 Unauthenticated Wi-Fi Config Modification - Research Advisory Tenable®	MISC	www.tenable.com	Exploit, Third
CVE Program record	CVE.ORG	www.cve.org	canonical
NVD vulnerability detail	NVD	nvd.nist.gov	canonical, and

No vendor comments have been submitted for this CVE.

There are currently no legacy QID mappings associated with this CVE.

this information or its use. Any use of this information is at the user's risk. It is the responsibility of user to evaluate the accuracy, completeness or usefulness of any information, opinion, advice or other content. EACH USER WILL BE SOLELY RESPONSIBLE FOR ANY consequences of his or her direct or indirect use of this web site. ALL WARRANTIES OF ANY KIND ARE EXPRESSLY DISCLAIMED. This site will NOT BE LIABLE FOR ANY DIRECT, INDIRECT or any other kind of loss.

CVE, CWE, and OVAL are registered trademarks of [The MITRE Corporation](#) and the authoritative source of CVE content is [MITRE's CVE web site](#). This site includes MITRE data granted under the following [license](#).

CVE.report and Source URL Uptime Status [status.cve.report](#)