



CVE-2019-6327


Published on: 06/17/2019 12:00:00 AM UTC

Last Modified on: 03/23/2021 11:28:00 PM UTC

CVE-2019-6327

[Source: Mitre](#)[Source: NIST](#)[CVE.ORG](#)[Print: PDF](#)

CVSS:31/AV:N/AC:L/PR:N/UI:N/S:U/C:H/I:H/A:H



Certain versions of [Laserjet Pro M280-m281 T6b80a](#) from [Hp](#) contain the following vulnerability:

HP Color LaserJet Pro M280-M281 Multifunction Printer series (before v. 20190419), HP LaserJet Pro MFP M28-M31 Printer series (before v. 20190426) may have an IPP Parser potentially vulnerable to Buffer Overflow.

CVE-2019-6327 has been assigned by hp-security-alert@hp.com to track the vulnerability - currently rated as **CRITICAL** severity.

CVSS3 Score: **9.8 - CRITICAL**

Attack Vector	Attack Complexity	Privileges Required	User Interaction
NETWORK	LOW	NONE	NONE
Scope	Confidentiality Impact	Integrity Impact	Availability Impact
UNCHANGED	HIGH	HIGH	HIGH

CVSS2 Score: **7.5 - HIGH**

Access Vector	Access Complexity	Authentication
NETWORK	LOW	NONE
Confidentiality Impact	Integrity Impact	Availability Impact
PARTIAL	PARTIAL	PARTIAL

CVE References

Description	Tags	Link
HPSPBI03619 rev. 2 - Certain HP LaserJet Pro and MFP Printers, Multiple Potential Security Vulnerabilities HP® Customer Support	Vendor Advisory support.hp.com text/html	hp MISC support.hp.com/us-en/document/c06356322

By selecting these links, you may be leaving CVEreport webspace. We have provided these links to other websites because they may have information that

would be of interest to you. No inferences should be drawn on account of other sites being referenced, or not, from this page. There may be other websites that are more appropriate for your purpose. CVEreport does not necessarily endorse the views expressed, or concur with the facts presented on these sites. Further, CVEreport does not endorse any commercial products that may be mentioned on these sites. Please address comments about any linked pages to comment@cve.report.

There are currently no QIDs associated with this CVE

Known Affected Configurations (CPE V2.3)

Type	Vendor	Product	Version	Update	Edition	Language
Hardware 	Hp	Laserjet Pro M280-m281 T6b80a	-	All	All	All
Hardware 	Hp	Laserjet Pro M280-m281 T6b80a	-	All	All	All
Operating System	Hp	Laserjet Pro M280-m281 T6b80a Firmware	All	All	All	All
Operating System	Hp	Laserjet Pro M280-m281 T6b80a Firmware	All	All	All	All
Hardware 	Hp	Laserjet Pro M280-m281 T6b81a	-	All	All	All
Hardware 	Hp	Laserjet Pro M280-m281 T6b81a	-	All	All	All
Operating System	Hp	Laserjet Pro M280-m281 T6b81a Firmware	All	All	All	All
Operating System	Hp	Laserjet Pro M280-m281 T6b81a Firmware	All	All	All	All
Hardware 	Hp	Laserjet Pro M280-m281 T6b82a	-	All	All	All
Hardware 	Hp	Laserjet Pro M280-m281 T6b82a	-	All	All	All
Operating System	Hp	Laserjet Pro M280-m281 T6b82a Firmware	All	All	All	All
Operating System	Hp	Laserjet Pro M280-m281 T6b82a Firmware	All	All	All	All
Hardware 	Hp	Laserjet Pro M280-m281 T6b83a	-	All	All	All
Hardware 	Hp	Laserjet Pro M280-m281 T6b83a	-	All	All	All
Operating System	Hp	Laserjet Pro M280-m281 T6b83a Firmware	All	All	All	All
Operating System	Hp	Laserjet Pro M280-m281 T6b83a Firmware	All	All	All	All
Hardware 	Hp	Laserjet Pro Mfp M28-m31 W2g54a	-	All	All	All
Hardware 	Hp	Laserjet Pro Mfp M28-m31 W2g54a	-	All	All	All
Operating System	Hp	Laserjet Pro Mfp M28-m31 W2g54a Firmware	All	All	All	All
Operating System	Hp	Laserjet Pro Mfp M28-m31 W2g54a Firmware	All	All	All	All
Hardware 	Hp	Laserjet Pro Mfp M28-m31 W2g55a	-	All	All	All
Hardware 	Hp	Laserjet Pro Mfp M28-m31 W2g55a	-	All	All	All

Hardware		Hp	Laserjet Pro Mfp M28-m31 W2g55a	-	All	All	All
Operating System		Hp	Laserjet Pro Mfp M28-m31 W2g55a Firmware	All	All	All	All
Operating System		Hp	Laserjet Pro Mfp M28-m31 W2g55a Firmware	All	All	All	All
Hardware		Hp	Laserjet Pro Mfp M28-m31 Y5s50a	-	All	All	All
Hardware		Hp	Laserjet Pro Mfp M28-m31 Y5s50a	-	All	All	All
Operating System		Hp	Laserjet Pro Mfp M28-m31 Y5s50a Firmware	All	All	All	All
Operating System		Hp	Laserjet Pro Mfp M28-m31 Y5s50a Firmware	All	All	All	All
Hardware		Hp	Laserjet Pro Mfp M28-m31 Y5s53a	-	All	All	All
Hardware		Hp	Laserjet Pro Mfp M28-m31 Y5s53a	-	All	All	All
Operating System		Hp	Laserjet Pro Mfp M28-m31 Y5s53a Firmware	All	All	All	All
Operating System		Hp	Laserjet Pro Mfp M28-m31 Y5s53a Firmware	All	All	All	All
Hardware		Hp	Laserjet Pro Mfp M28-m31 Y5s54a	-	All	All	All
Hardware		Hp	Laserjet Pro Mfp M28-m31 Y5s54a	-	All	All	All
Operating System		Hp	Laserjet Pro Mfp M28-m31 Y5s54a Firmware	All	All	All	All
Operating System		Hp	Laserjet Pro Mfp M28-m31 Y5s54a Firmware	All	All	All	All
Hardware		Hp	Laserjet Pro Mfp M28-m31 Y5s55a	-	All	All	All
Hardware		Hp	Laserjet Pro Mfp M28-m31 Y5s55a	-	All	All	All
Operating System		Hp	Laserjet Pro Mfp M28-m31 Y5s55a Firmware	All	All	All	All
Operating System		Hp	Laserjet Pro Mfp M28-m31 Y5s55a Firmware	All	All	All	All
cpe:2.3:h:hp:laserjet_pro_m280-m281_t6b80a:-:~::~~::~~:::							
cpe:2.3:h:hp:laserjet_pro_m280-m281_t6b80a:-:~::~~::~~:::							
cpe:2.3:o:hp:laserjet_pro_m280-m281_t6b80a_firmware:~::~~::~~:::							
cpe:2.3:o:hp:laserjet_pro_m280-m281_t6b80a_firmware:~::~~::~~:::							
cpe:2.3:h:hp:laserjet_pro_m280-m281_t6b81a:-:~::~~::~~:::							
cpe:2.3:h:hp:laserjet_pro_m280-m281_t6b81a:-:~::~~::~~:::							
cpe:2.3:o:hp:laserjet_pro_m280-m281_t6b81a_firmware:~::~~::~~:::							
cpe:2.3:o:hp:laserjet_pro_m280-m281_t6b81a_firmware:~::~~::~~:::							

```
cpe:2.3:h:hp:laserjet_pro_m280-m281_t6b82a:-:*:*:*:*:*:
```

```
cpe:2.3:h:hp:laserjet_pro_m280-m281_t6b82a:-:*:*:*:*:*:
```

```
cpe:2.3:o:hp:laserjet_pro m280-m281 t6b82a firmware:*.*.*.*.*.*.*.*.*.*
```

```
cpe:2.3:o:hp:laserjet_pro_m280-m281_t6b82a_firmware:*.*.*.*.*.*.*.*.*.*
```

```
cpe:2.3:h:hp:laserjet_pro_m280-m281_t6b83a:-:::*:*:*:*:*:
```

cpe:2.3:h:hp:laserjet_pro_m280-m281_t6b83a:-:*:*:*:*:*:

```
cpe:2.3:o:hp:laserjet_pro_m280-m281_t6b83a_firmware:*.***.***.***.
```

```
cpe:2.3:o:hp:laserjet_pro_m280-m281_t6b83a_firmware:*.***.***.***.
```

cpe:2.3:h:hp:laserjet_pro_mfp_m28-m31_w2g54a:-:*:*:*:*:*:

cpe:2.3:h:hp:laserjet_pro_mfp_m28-m31_w2g54a:-:*:*:*:*:*:

```
cpe:2.3:o:hp:laserjet pro mfp m28-m31 w2q54a firmware:*.*.*.*.*.*.
```

```
cpe:2.3:o:hp:laserjet pro mfp m28-m31 w2q54a firmware:*.*.*.*.*.*.*.*.
```

cpe:2.3:h:hp:laserjet_pro_mfp_m28-m31_w2g55a:-:*:*:*:*:*:

cpe:2.3:h:hp:laserjet_pro_mfp_m28-m31_w2g55a:-:*:*:*:*:*:

```
cpe:2.3:o:hp:laserjet_pro_mfp_m28-m31_w2g55a_firmware:*:*:*:*:*:
```

```
cpe:2.3:o:hp:laserjet_pro_mfp_m28-m31_w2g55a_firmware:*.***.***.***:
```

cpe:2.3:h:hp:laserjet_pro_mfp_m28-m31_y5s50a:-.*:.*:.*:.*:.*:.*

```
cpe:2.3:h:hp:laserjet pro mfp m28-m31 y5s50a:-:*:*:*:*:*:
```

```
cpe:2.3:o:hp:laserjet_pro_mfp_m28-m31_y5s50a_firmware:.*:.*:.*:.*:.*:.*:.*
```

```
cpe:2.3:o:hp:laserjet_pro_mfp_m28-m31_y5s50a_firmware:*.***.***.***.
```

cpe:2.3:h:hp:laserjet_pro_mfp_m28-m31_y5s53a:-.*:.*:.*:.*:.*:.*

cpe:2.3:h:hp:laserjet_pro_mfp_m28-m31_y5s53a:-.*:.*:.*:.*:.*:.*

```
cpe:2.3:o:hp:laserjet_pro_mfp_m28-m31_y5s53a_firmware:.*:.*:.*:.*:.*:.*:.*
```

```
cpe:2.3:o:hp:laserjet_pro_mfp_m28-m31_y5s53a_firmware:*.*.*.*.*.*.*.*.*.*
```

cpe:2.3:h:hp:laserjet_pro_mfp_m28-m31_y5s54a:-.*:*:*:*:*:*:

cpe:2.3:h:hp:laserjet pro mfp m28-m31_y5s54a:-.*:.*:.*:.*:.*:.*:.*

```
cpe:2.3:o:hp:laserjet_pro_mfp_m28-m31_y5s54a_firmware:*.***.***.***.
```

```
cpe:2.3:o:hp:laserjet_pro_mfp_m28-m31_y5s54a_firmware:*.***.***.***.
```

cpe:2.3:h:hp:laserjet pro mfp m28-m31 v5s55a:-*:*:*:*:*:*:

cpe:2.3:h:hp:laserjet_pro_mfp_m28-m31_y5s55a:-:*:*:*:*:*:
cpe:2.3:o:hp:laserjet_pro_mfp_m28-m31_y5s55a_firmware:*:*:*:*:*:
cpe:2.3:o:hp:laserjet_pro_mfp_m28-m31_y5s55a_firmware:*:*:*:*:*:

No vendor comments have been submitted for this CVE

[← Previous ID](#)
[Next ID →](#)

© CVE.report 2023 |

Use of this information constitutes acceptance for use in an AS IS condition. There are NO warranties, implied or otherwise, with regard to this information or its use. Any use of this information is at the user's risk. It is the responsibility of user to evaluate the accuracy, completeness or usefulness of any information, opinion, advice or other content. EACH USER WILL BE SOLELY RESPONSIBLE FOR ANY consequences of his or her direct or indirect use of this web site. ALL WARRANTIES OF ANY KIND ARE EXPRESSLY DISCLAIMED. This site will NOT BE LIABLE FOR ANY DIRECT, INDIRECT or any other kind of loss.

CVE, CWE, and OVAL are registered trademarks of [The MITRE Corporation](#) and the authoritative source of CVE content is [MITRE's CVE web site](#). This site includes MITRE data granted under the following [license](#).

CVE.report and Source URL Uptime Status status.cve.report