



CVE-2019-6968

Published on: 08/02/2019 12:00:00 AM UTC

Last Modified on: 04/23/2021 06:09:00 PM UTC

CVE-2019-6968

Source: Mitre

Source: NIST

CVE.ORG

Print: PDF



Certain versions of [Dva-5592](#) from [Dlink](#) contain the following vulnerability:

The web interface of the D-Link DVA-5592 20180823 is vulnerable to XSS because HTML form parameters are directly reflected.

CVE-2019-6968 has been assigned by [M](#) cve@mitre.org to track the vulnerability - currently rated as **MEDIUM** severity.

CVSS3 Score: **6.1 - MEDIUM**

Attack Vector	Attack Complexity	Privileges Required	User Interaction
NETWORK	LOW	NONE	REQUIRED
Scope	Confidentiality Impact	Integrity Impact	Availability Impact
CHANGED	LOW	LOW	NONE

CVSS2 Score: **4.3 - MEDIUM**

Access Vector	Access Complexity	Authentication
NETWORK	MEDIUM	NONE
Confidentiality Impact	Integrity Impact	Availability Impact
NONE	PARTIAL	NONE

CVE References

Description	Tags	Link
D-Link DVA-5592 missing authentication check [CVE-2019-6969] D-Link DVA-5592 Self XSS [CVE-2019-6968] Alcatel LINKZONE no authentication control whatsoever [CVE-2019-7163]	Exploit Third Party Advisory rhaidiz.net text/html	MISC rhaidiz.net/2019/02/27/dribble-router-vulns-dlink-alcatel-cve-2019-6969-cve-2019-6968-cve-2019-7163/">rhaidiz.net/2019/02/27/dribble-router-vulns-dlink-alcatel-cve-2019-6969-cve-2019-6968-cve-2019-7163/

By selecting these links, you may be leaving CVEreport webspace. We have provided these links to other websites because they may have information that would be of interest to you. No inferences should be drawn on account of other sites being referenced, or not, from this page. There may be other websites that are more appropriate for your purpose. CVEreport does not necessarily endorse the views expressed, or concur with the facts presented on these sites. Further, CVEreport does not endorse any commercial products that may be mentioned on these sites. Please address comments about any linked pages to comment@cve.report.

There are currently no QIDs associated with this CVE

Known Affected Configurations (CPE V2.3)

Type	Vendor	Product	Version	Update	Edition	Language
Hardware 	Dlink	Dva-5592	-	All	All	All
Hardware 	Dlink	Dva-5592	-	All	All	All
Operating System	Dlink	Dva-5592 Firmware	20180823	All	All	All
Operating System	Dlink	Dva-5592 Firmware	20180823	All	All	All
<code>cpe:2.3:h:dlink:dva-5592:-:~::~~::~~::~~::~~::~~::~~:::</code>						
<code>cpe:2.3:h:dlink:dva-5592:-:~::~~::~~::~~::~~::~~::~~:::</code>						
<code>cpe:2.3:o:dlink:dva-5592_firmware:20180823:~::~~::~~::~~::~~::~~::~~:::</code>						
<code>cpe:2.3:o:dlink:dva-5592_firmware:20180823:~::~~::~~::~~::~~::~~::~~:::</code>						

No vendor comments have been submitted for this CVE

[← Previous ID](#)

[Next ID →](#)