



CVE-2020-11141

Published on: 11/02/2020 12:00:00 AM UTC

Last Modified on: 07/21/2021 11:39:00 AM UTC

CVE-2020-11141

[Source: Mitre](#)[Source: NIST](#)[CVE.ORG](#)[Print: PDF](#)

CVSS:31/AV:A/AC:L/PR:N/UI:N/S:U/C:H/I:N/A:H



Certain versions of [Apq8009](#) from [Qualcomm](#) contain the following vulnerability:

u'Buffer over-read issue in Bluetooth estack due to lack of check for invalid length of L2cap configuration request received from peer device.' in Snapdragon Auto, Snapdragon Compute, Snapdragon Connectivity, Snapdragon Consumer Electronics Connectivity, Snapdragon Consumer IOT, Snapdragon Industrial IOT, Snapdragon

Mobile, Snapdragon Voice & Music, Snapdragon Wired Infrastructure and Networking in APQ8009, APQ8053, QCA6390, QCN7605, SA415M, SA515M, SC8180X, SDX55, SM8250

CVE-2020-11141 has been assigned by [Q](#) product-security@qualcomm.com to track the vulnerability - currently rated as **HIGH** severity.

Affected Vendor/Software: [Q](#) **Qualcomm, Inc. - Snapdragon Auto, Snapdragon Compute, Snapdragon Connectivity, Snapdragon Consumer Electronics Connectivity, Snapdragon Consumer IOT, Snapdragon Industrial IOT, Snapdragon Mobile, Snapdragon Voice & Music, Snapdragon Wired Infrastructure and Networking** version **APQ8009, APQ8053, QCA6390, QCN7605, SA415M, SA515M, SC8180X, SDX55, SM8250**

CVSS3 Score: **8.1 - HIGH**

Attack Vector	Attack Complexity	Privileges Required	User Interaction
ADJACENT_NETWORK	LOW	NONE	NONE
Scope	Confidentiality Impact	Integrity Impact	Availability Impact
UNCHANGED	HIGH	NONE	HIGH

CVSS2 Score: **4.8 - MEDIUM**

Access Vector	Access Complexity	Authentication
ADJACENT_NETWORK	LOW	NONE
Confidentiality Impact	Integrity Impact	Availability Impact
PARTIAL	NONE	PARTIAL

CVE References

Description	Tags	Link
October 2020 Security Bulletin Qualcomm	Vendor Advisory www.qualcomm.com text/html	Q MISC www.qualcomm.com/company/product-security/bulletins/october-2020-security-bulletin
Page not found	Broken Link www.qualcomm.com text/html Inactive Link Not Archived	Q CONFIRM www.qualcomm.com/company/product-security/bulletins/october-2020-bulletin

By selecting these links, you may be leaving CVEreport webspace. We have provided these links to other websites because they may have information that would be of interest to you. No inferences should be drawn on account of other sites being referenced, or not, from this page. There may be other websites that are more appropriate for your purpose. CVEreport does not necessarily endorse the views expressed, or concur with the facts presented on these sites. Further, CVEreport does not endorse any commercial products that may be mentioned on these sites. Please address comments about any linked pages to comment@cve.report.

There are currently no QIDs associated with this CVE

Known Affected Configurations (CPE V2.3)

Type	Vendor	Product	Version	Update	Edition	Language
Hardware 	Qualcomm	Apq8009	-	All	All	All
Hardware 	Qualcomm	Apq8009	-	All	All	All
Operating System	Qualcomm	Apq8009 Firmware	-	All	All	All
Operating System	Qualcomm	Apq8009 Firmware	-	All	All	All
Hardware 	Qualcomm	Apq8053	-	All	All	All
Hardware 	Qualcomm	Apq8053	-	All	All	All
Operating System	Qualcomm	Apq8053 Firmware	-	All	All	All
Operating System	Qualcomm	Apq8053 Firmware	-	All	All	All
Hardware 	Qualcomm	Qca6390	-	All	All	All
Hardware 	Qualcomm	Qca6390	-	All	All	All
Operating System	Qualcomm	Qca6390 Firmware	-	All	All	All
Operating System	Qualcomm	Qca6390 Firmware	-	All	All	All
Hardware 	Qualcomm	Qcn7605	-	All	All	All
Hardware 	Qualcomm	Qcn7605	-	All	All	All
Operating System	Qualcomm	Qcn7605 Firmware	-	All	All	All

Operating System	Qualcomm	Qcn7605 Firmware	-	All	All	All
Hardware 🇹🇼 ↗️	Qualcomm	Sa415m	-	All	All	All
Hardware 🇹🇼 ↗️	Qualcomm	Sa415m	-	All	All	All
Operating System	Qualcomm	Sa415m Firmware	-	All	All	All
Operating System	Qualcomm	Sa415m Firmware	-	All	All	All
Hardware 🇹🇼 ↗️	Qualcomm	Sa515m	-	All	All	All
Hardware 🇹🇼 ↗️	Qualcomm	Sa515m	-	All	All	All
Operating System	Qualcomm	Sa515m Firmware	-	All	All	All
Operating System	Qualcomm	Sa515m Firmware	-	All	All	All
Hardware 🇹🇼 ↗️	Qualcomm	Sc8180x	-	All	All	All
Hardware 🇹🇼 ↗️	Qualcomm	Sc8180x	-	All	All	All
Operating System	Qualcomm	Sc8180x Firmware	-	All	All	All
Operating System	Qualcomm	Sc8180x Firmware	-	All	All	All
Hardware 🇹🇼 ↗️	Qualcomm	Sdx55	-	All	All	All
Hardware 🇹🇼 ↗️	Qualcomm	Sdx55	-	All	All	All
Operating System	Qualcomm	Sdx55 Firmware	-	All	All	All
Operating System	Qualcomm	Sdx55 Firmware	-	All	All	All
Hardware 🇹🇼 ↗️	Qualcomm	Sm8250	-	All	All	All
Hardware 🇹🇼 ↗️	Qualcomm	Sm8250	-	All	All	All
Operating System	Qualcomm	Sm8250 Firmware	-	All	All	All
Operating System	Qualcomm	Sm8250 Firmware	-	All	All	All
cpe:2.3:h:qualcomm:apq8009:-:*~::~:						
cpe:2.3:h:qualcomm:apq8009:-:*~::~:						
cpe:2.3:o:qualcomm:apq8009_firmware:-:*~::~:						
cpe:2.3:o:qualcomm:apq8009_firmware:-:*~::~:						
cpe:2.3:h:qualcomm:apq8053:-:*~::~:						
cpe:2.3:h:qualcomm:apq8053:-:*~::~:						

cpe:2.3:o:qualcomm:apq8053_firmware:-:*****:
cpe:2.3:o:qualcomm:apq8053_firmware:-:*****:
cpe:2.3:h:qualcomm:qca6390:-:*****:
cpe:2.3:h:qualcomm:qca6390:-:*****:
cpe:2.3:o:qualcomm:qca6390_firmware:-:*****:
cpe:2.3:o:qualcomm:qca6390_firmware:-:*****:
cpe:2.3:h:qualcomm:qcn7605:-:*****:
cpe:2.3:h:qualcomm:qcn7605:-:*****:
cpe:2.3:o:qualcomm:qcn7605_firmware:-:*****:
cpe:2.3:o:qualcomm:qcn7605_firmware:-:*****:
cpe:2.3:h:qualcomm:sa415m:-:*****:
cpe:2.3:h:qualcomm:sa415m:-:*****:
cpe:2.3:o:qualcomm:sa415m_firmware:-:*****:
cpe:2.3:o:qualcomm:sa415m_firmware:-:*****:
cpe:2.3:h:qualcomm:sa515m:-:*****:
cpe:2.3:h:qualcomm:sa515m:-:*****:
cpe:2.3:o:qualcomm:sa515m_firmware:-:*****:
cpe:2.3:o:qualcomm:sa515m_firmware:-:*****:
cpe:2.3:h:qualcomm:sc8180x:-:*****:
cpe:2.3:h:qualcomm:sc8180x:-:*****:
cpe:2.3:o:qualcomm:sc8180x_firmware:-:*****:
cpe:2.3:o:qualcomm:sc8180x_firmware:-:*****:
cpe:2.3:h:qualcomm:sdx55:-:*****:
cpe:2.3:h:qualcomm:sdx55:-:*****:
cpe:2.3:o:qualcomm:sdx55_firmware:-:*****:
cpe:2.3:o:qualcomm:sdx55_firmware:-:*****:
cpe:2.3:h:qualcomm:sm8250:-:*****:
cpe:2.3:h:qualcomm:sm8250:-:*****:

cpe:2.3:o:qualcomm:sm8250_firmware:-:*****:

cpe:2.3:o:qualcomm:sm8250_firmware:-:*****:

No vendor comments have been submitted for this CVE

Social Mentions

Source	Title	Posted (UTC)
 @Koolholio	CVE-2020-11141 @certbund @BSI_Bund	2022-01-15 20:14:18

← Previous ID

Next ID→