



CVE-2020-12319

Published on: 11/12/2020 12:00:00 AM UTC

Last Modified on: 03/23/2021 11:23:36 PM UTC

CVE-2020-12319


Source: Mitre

Source: NIST

CVE.ORG

Print: PDF

CVSS:31/AV:A/AC:L/PR:N/UI:N/S:U/C:N/I:N/A:H



Certain versions of [Dual Band Wireless-ac 3165](#) from [Intel](#) contain the following vulnerability:

Insufficient control flow management in some Intel(R) PROSet/Wireless WiFi products before version 21.110 may allow an unauthenticated user to potentially enable denial of service via adjacent access.

CVE-2020-12319 has been assigned by [intel](#) [secure@intel.com](#) to track the vulnerability - currently rated as **MEDIUM** severity.

CVSS3 Score: **6.5 - MEDIUM**

Attack Vector	Attack Complexity	Privileges Required	User Interaction
ADJACENT_NETWORK	LOW	NONE	NONE
Scope	Confidentiality Impact	Integrity Impact	Availability Impact
UNCHANGED	NONE	NONE	HIGH

CVSS2 Score: **3.3 - LOW**

Access Vector	Access Complexity	Authentication
ADJACENT_NETWORK	LOW	NONE
Confidentiality Impact	Integrity Impact	Availability Impact
NONE	NONE	PARTIAL

CVE References

Description	Tags	Link
INTEL-SA-00402	Patch Vendor Advisory www.intel.com text/html	intel MISC www.intel.com/content/www/us/en/security-center/advisory/intel-sa-00402

By selecting these links, you may be leaving CVEreport webspace. We have provided these links to other websites because they may have information that would be of interest to you. No inferences should be drawn on account of other sites being referenced, or not, from this page. There may be other websites that are more appropriate for your purpose. CVEreport does not necessarily endorse the views expressed, or concur with the facts presented on these sites. Further, CVEreport does not endorse any commercial products that may be mentioned on these sites. Please address comments about any linked pages to comment@cve.report.

There are currently no QIDs associated with this CVE

Known Affected Configurations (CPE V2.3)

Type	Vendor	Product	Version	Update	Edition	Language
Hardware  	Intel	Dual Band Wireless-ac 3165	-	All	All	All
Hardware  	Intel	Dual Band Wireless-ac 3165	-	All	All	All
Hardware  	Intel	Dual Band Wireless-ac 3168	-	All	All	All
Hardware  	Intel	Dual Band Wireless-ac 3168	-	All	All	All
Hardware  	Intel	Dual Band Wireless-ac 8260	-	All	All	All
Hardware  	Intel	Dual Band Wireless-ac 8260	-	All	All	All
Hardware  	Intel	Dual Band Wireless-ac 8265	-	All	All	All
Hardware  	Intel	Dual Band Wireless-ac 8265	-	All	All	All
Application	Intel	Proset/wireless Wifi	All	All	All	All
Application	Intel	Proset/wireless Wifi	All	All	All	All
Hardware  	Intel	Wi-fi 6 Ax200	-	All	All	All
Hardware  	Intel	Wi-fi 6 Ax200	-	All	All	All
Hardware  	Intel	Wi-fi 6 Ax201	-	All	All	All
Hardware  	Intel	Wi-fi 6 Ax201	-	All	All	All
Hardware  	Intel	Wireless-ac 9260	-	All	All	All
Hardware  	Intel	Wireless-ac 9260	-	All	All	All
Hardware  	Intel	Wireless-ac 9461	-	All	All	All
Hardware  	Intel	Wireless-ac 9461	-	All	All	All
Hardware  	Intel	Wireless-ac 9462	-	All	All	All
Hardware  	Intel	Wireless-ac 9462	-	All	All	All
Hardware  	Intel	Wireless-ac 9560	-	All	All	All
Hardware  	Intel	Wireless-ac 9560	-	All	All	All
Hardware  	Intel	Wireless 7265 Rev D	-	All	All	All
Hardware  	Intel	Wireless 7265 Rev D	-	All	All	All

cpe:2.3:h:intel:dual_band_wireless-ac_3165:-:*:*:*:*:*:

```
cpe:2.3:n:intel:wireless_7265_(rev_d):-:::~
```

Next ID→

completeness or usefulness of any information, opinion, advice or other content. EACH USER WILL BE SOLELY RESPONSIBLE FOR ANY consequences of his or her direct or indirect use of this web site. ALL WARRANTIES OF ANY KIND ARE EXPRESSLY DISCLAIMED. This site will NOT BE LIABLE FOR ANY DIRECT, INDIRECT or any other kind of loss.

CVE, CWE, and OVAL are registered trademarks of [The MITRE Corporation](#) and the authoritative source of CVE content is [MITRE's CVE web site](#). This site includes MITRE data granted under the following [license](#).

CVE.report and Source URL Uptime Status [status.cve.report](#)