



CVE-2020-26898

[MITRE](#)[NVD](#)[CVE.ORG](#)[Print: PDF](#)

Summary

CVE	CVE-2020-26898
State	PUBLIC
Assigner	cve@mitre.org
Source Priority	CVE Program / NVD first with legacy fallback
Published	2020-10-09 07:15:00 UTC
Updated	2020-10-19 17:34:00 UTC
Description	NETGEAR RAX40 devices before 1.0.3.80 are affected by incorrect configuration of security settings.

Risk And Classification

Problem Types: NVD-CWE-Other

NVD Known Affected Configurations (CPE 2.3)

Type	Vendor	Product	Version	Update	Edition	Language
Hardware	Netgear	Rax40	-	All	All	All
Hardware	Netgear	Rax40	-	All	All	All
Operating System	Netgear	Rax40 Firmware	All	All	All	All
Operating System	Netgear	Rax40 Firmware	All	All	All	All

References

Reference	Source	Link	T
Security Advisory for Security Misconfiguration on RAX40, PSV-2019-0267 Answer NETGEAR Support	MISC	kb.netgear.com	V
CVE Program record	CVE.ORG	www.cve.org	c
NVD vulnerability detail	NVD	nvd.nist.gov	c

No vendor comments have been submitted for this CVE.

There are currently no legacy QID mappings associated with this CVE.

completeness or usefulness of any information, opinion, advice or other content. EACH USER WILL BE SOLELY RESPONSIBLE FOR ANY consequences of his or her direct or indirect use of this web site. ALL WARRANTIES OF ANY KIND ARE EXPRESSLY DISCLAIMED. This site will NOT BE LIABLE FOR ANY DIRECT, INDIRECT or any other kind of loss.

CVE, CWE, and OVAL are registered trademarks of [The MITRE Corporation](#) and the authoritative source of CVE content is [MITRE's CVE web site](#). This site includes MITRE data granted under the following [license](#).

CVE.report and Source URL Uptime Status [status.cve.report](#)