



CVE-2020-35824


Published on: 12/29/2020 12:00:00 AM UTC

Last Modified on: 03/23/2021 11:23:47 PM UTC

CVE-2020-35824

[Source: Mitre](#)[Source: NIST](#)[CVE.ORG](#)[Print: PDF](#)

CVSS:31/AC:L/AV:A/A:N/C:H/I:H/PR:H/S:U/UI:N



Certain versions of **D7800** from **Netgear** contain the following vulnerability:

Certain NETGEAR devices are affected by stored XSS. This affects D7800 before 1.0.1.56, R7500v2 before 1.0.3.46, R7800 before 1.0.2.74, R8900 before 1.0.4.28, R9000 before 1.0.4.28, RAX120 before 1.0.0.78, RBK50 before 2.3.5.30, RBR50 before 2.3.5.30, RBS50 before 2.3.5.30, XR500 before 2.3.2.56, and XR700 before

1.0.1.10.

CVE-2020-35824 has been assigned by [M](#) cve@mitre.org to track the vulnerability - currently rated as **MEDIUM** severity.

CVSS3 Score: **4.8 - MEDIUM**

Attack Vector	Attack Complexity	Privileges Required	User Interaction
NETWORK	LOW	HIGH	REQUIRED
Scope	Confidentiality Impact	Integrity Impact	Availability Impact
CHANGED	LOW	LOW	NONE

CVSS2 Score: **3.5 - LOW**

Access Vector	Access Complexity	Authentication
NETWORK	MEDIUM	SINGLE
Confidentiality Impact	Integrity Impact	Availability Impact
NONE	PARTIAL	NONE

CVE References

Description	Tags	Link
Security Advisory for Stored Cross Site Scripting on Some Routers and WiFi Systems, PSV-2018-0501 Answer	Vendor Advisory kb.netgear.com	N MISC kb.netgear.com/00062673/Security-Advisory-for-Stored-Cross-Site-Scripting-on-Some-Routers-and-

By selecting these links, you may be leaving CVEreport webspace. We have provided these links to other websites because they may have information that would be of interest to you. No inferences should be drawn on account of other sites being referenced, or not, from this page. There may be other websites that are more appropriate for your purpose. CVEreport does not necessarily endorse the views expressed, or concur with the facts presented on these sites. Further, CVEreport does not endorse any commercial products that may be mentioned on these sites. Please address comments about any linked pages to comment@cve.report.

There are currently no QIDs associated with this CVE

Known Affected Configurations (CPE V2.3)

Type	Vendor	Product	Version	Update	Edition	Language
Hardware 	Netgear	D7800	-	All	All	All
Hardware 	Netgear	D7800	-	All	All	All
Operating System	Netgear	D7800 Firmware	All	All	All	All
Operating System	Netgear	D7800 Firmware	All	All	All	All
Hardware 	Netgear	R7500v2	-	All	All	All
Hardware 	Netgear	R7500v2	-	All	All	All
Operating System	Netgear	R7500v2 Firmware	All	All	All	All
Operating System	Netgear	R7500v2 Firmware	All	All	All	All
Hardware 	Netgear	R7800	-	All	All	All
Hardware 	Netgear	R7800	-	All	All	All
Operating System	Netgear	R7800 Firmware	All	All	All	All
Operating System	Netgear	R7800 Firmware	All	All	All	All
Hardware 	Netgear	R8900	-	All	All	All
Hardware 	Netgear	R8900	-	All	All	All
Operating System	Netgear	R8900 Firmware	All	All	All	All
Operating System	Netgear	R8900 Firmware	All	All	All	All
Hardware 	Netgear	R9000	-	All	All	All
Hardware 	Netgear	R9000	-	All	All	All
Operating System	Netgear	R9000 Firmware	All	All	All	All
Operating System	Netgear	R9000 Firmware	All	All	All	All


```

opv.2.0.0.mtgcar.07000_mimware. . . . .

```

```
cpe:2.3:o:netgear:d7800 firmware:*:*:*:*:*:*:*:
```

```
cpe:2.3:h:netgear:r7500v2:-:*:*:*:*:*:
```

```
cpe:2.3:h:netgear:r7500v2:-:*:*:*:*:*:*:
```

```
cpe:2.3:o:netgear:r7500v2 firmware:*.*.*.*.*.*.*.*
```

```
cpe:2.3:o:netgear:r7500v2 firmware:*.*.*.*.*.*.*.*
```

```
cpe:2.3:h:netgear:r7800:-:*:*:*:*:*:
```

```
cpe:2.3:h:netgear:r7800:-:*:*:*:*:*:*:
```

cpe:2.3:o:netgear:r7800_firmware:*.:.:.:.:.:.:.:

```
cpe:2.3:o:netgear:r7800_firmware:*.*.*.*.*.*.*.*
```

```
cpe:2.3:h:netgear:r8900:-:*:*:*:*:*:
```

```
cpe:2.3:h:netgear:r8900:-:*:*:*:*:*:
```

```
cpe:2.3:o:netgear:r8900_firmware:*:*:*:*:*:*:
```

cpe:2.3:o:netgear:r8900_firmware:*:*:*:*:*:*:*:*

```
cpe:2.3:h:netgear:r9000:-:*:*:*:*:*:*:
```

```
cpe:2.3:h:netgear:r9000:-:*:*:*:*:*:*:
```

```
cpe:2.3:o:netgear:r9000 firmware:*:*:*:*:*:*:*:
```

```
cpe:2.3:o:netgear:r9000_firmware:*:*:*:*:*:*:
```

```
cpe:2.3:h:netgear:rax120:-:*:*:*:*:*:*:
```

```
cpe:2.3:h:netgear:rax120:-:*:*:*:*:*:
```

```
cpe:2.3:o:netgear:rax120 firmware:*. *. *. *. *. *. *. *
```

cpe:2.3:o:netgear:rax120_firmware:*.:.:.:.:.:.:.:

```
cpe:2.3:h:netgear:rbk50:-:*:*:*:*:*:*:
```

```
cpe:2.3:h:netgear:rbk50:-:*:*:*:*:*:*:
```

```
cpe:2.3:o:netgear:rbk50 firmware:*.*.*.*.*.*.*.*
```

```
cpe:2.3:o:netgear:rbk50 firmware:*.*.*.*.*.*.*.*
```

```
cpe:2.3:h:netgear:rbr50:-:*:*:*:*:*:
```

```
cpe:2.3:h:netgear:rbr50:-:*:*:*:*:*:*:
```

cpe:2.3:o:netgear:rbr50_firmware:*:*:*:*:*:*:

cpe:2.3:o:netgear:rbr50_firmware:~::~::~:
cpe:2.3:h:netgear:rbs50:~::~::~:
cpe:2.3:h:netgear:rbs50:~::~::~:
cpe:2.3:o:netgear:rbs50_firmware:~::~::~:
cpe:2.3:o:netgear:rbs50_firmware:~::~::~:
cpe:2.3:h:netgear:xr500:~::~::~:
cpe:2.3:h:netgear:xr500:~::~::~:
cpe:2.3:o:netgear:xr500_firmware:~::~::~:
cpe:2.3:o:netgear:xr500_firmware:~::~::~:
cpe:2.3:h:netgear:xr700:~::~::~:
cpe:2.3:h:netgear:xr700:~::~::~:
cpe:2.3:o:netgear:xr700_firmware:~::~::~:
cpe:2.3:o:netgear:xr700_firmware:~::~::~:

No vendor comments have been submitted for this CVE