




CVE-2020-9070

Published on: 04/20/2020 12:00:00 AM UTC

Last Modified on: 07/21/2021 11:39:00 AM UTC

CVE-2020-9070

[Source: Mitre](#)[Source: NIST](#)[CVE.ORG](#)[Print: PDF](#) 

Certain versions of [Taurus-al00b](#) from [Huawei](#) contain the following vulnerability:

Huawei smartphones Taurus-AL00B with versions earlier than 10.0.0.205(C00E201R7P2) have an improper authentication vulnerability. The software insufficiently validate the user's identity when a user wants to do certain operation. An attacker can trick user into installing a malicious application to exploit this vulnerability.

Successful exploit may cause some information disclosure.

CVE-2020-9070 has been assigned by psirt@huawei.com to track the vulnerability - currently rated as **MEDIUM** severity.

Affected Vendor/Software: **Huawei** - **Taurus-AL00B** version **Versions earlier than 10.0.0.205(C00E201R7P2)**

CVSS3 Score: **5.5 - MEDIUM**

Attack Vector	Attack Complexity	Privileges Required	User Interaction
LOCAL	LOW	NONE	REQUIRED
Scope	Confidentiality Impact	Integrity Impact	Availability Impact
UNCHANGED	HIGH	NONE	NONE

CVSS2 Score: **4.3 - MEDIUM**

Access Vector	Access Complexity	Authentication
NETWORK	MEDIUM	NONE
Confidentiality Impact	Integrity Impact	Availability Impact
PARTIAL	NONE	NONE

CVE References

Description	Tags	Link
-------------	------	------

Security Advisory - Improper Authentication Vulnerability in Some Huawei Smartphones

Vendor Advisory

www.huawei.com

text/html

CONFIRM

www.huawei.com/en/psirt/security-advisories/huawei-sa-20200415-01-smartphone-en

Security Advisory - Improper Authentication Vulnerability in Some Huawei Smartphones

Vendor Advisory

www.huawei.com

text/html

CONFIRM

www.huawei.com/en/psirt/security-advisories/huawei-sa-20200415-01-smartphone-en

By selecting these links, you may be leaving CVEreport webspace. We have provided these links to other websites because they may have information that would be of interest to you. No inferences should be drawn on account of other sites being referenced, or not, from this page. There may be other websites that are more appropriate for your purpose. CVEreport does not necessarily endorse the views expressed, or concur with the facts presented on these sites. Further, CVEreport does not endorse any commercial products that may be mentioned on these sites. Please address comments about any linked pages to comment@cve.report.

There are currently no QIDs associated with this CVE

Known Affected Configurations (CPE V2.3)

Type	Vendor	Product	Version	Update	Edition	Language
Hardware 	Huawei	Taurus-al00b	-	All	All	All
Hardware 	Huawei	Taurus-al00b	-	All	All	All
Operating System	Huawei	Taurus-al00b Firmware	All	All	All	All
Operating System	Huawei	Taurus-al00b Firmware	All	All	All	All

cpe:2.3:h:huawei:taurus-al00b:-:~::~~::~~::~~::~~::~~::~~:::

cpe:2.3:h:huawei:taurus-al00b:-:~::~~::~~::~~::~~::~~::~~:::

cpe:2.3:o:huawei:taurus-al00b_firmware:~::~~::~~::~~::~~::~~::~~:::

cpe:2.3:o:huawei:taurus-al00b_firmware:~::~~::~~::~~::~~::~~::~~:::

No vendor comments have been submitted for this CVE

← Previous ID

Next ID →