



Published on: 02/05/2021 12:00:00 AM UTC


Last Modified on: 03/23/2021 11:24:13 PM UTC

CVE-2020-9118

Source: Mitre

Source: NIST

CVE.ORG

Print: PDF 

Certain versions of [Ais-bw80h-00](#) from [Huawei](#) contain the following vulnerability:

There is an insufficient integrity check vulnerability in Huawei Sound X Product. The system does not check certain software package's integrity sufficiently. Successful exploit could allow an attacker to load a crafted software package to the device. Affected product versions include: AIS-BW80H-00 versions

9.0.3.1(H100SP13C00),9.0.3.1(H100SP18C00),9.0.3.1(H100SP3C00),9.0.3.1(H100SP9C00),9

CVE-2020-9118 has been assigned by  psirt@huawei.com to track the vulnerability - currently rated as **MEDIUM** severity.

CVSS3 Score: 6.8 - MEDIUM

Attack Vector	Attack Complexity	Privileges Required	User Interaction
PHYSICAL	LOW	NONE	NONE
Scope	Confidentiality Impact	Integrity Impact	Availability Impact
UNCHANGED	HIGH	HIGH	HIGH

CVSS2 Score: 4.6 - MEDIUM

Access Vector	Access Complexity	Authentication
LOCAL	LOW	NONE
Confidentiality Impact	Integrity Impact	Availability Impact
PARTIAL	PARTIAL	PARTIAL

CVE References

Description	Tags	Link
Security Advisory - Insufficient Integrity Check Vulnerability	Vendor Advisory	 CONFIRM www.huawei.com/en/psirt/security-

By selecting these links, you may be leaving CVEreport webspace. We have provided these links to other websites because they may have information that would be of interest to you. No inferences should be drawn on account of other sites being referenced, or not, from this page. There may be other websites that are more appropriate for your purpose. CVEreport does not necessarily endorse the views expressed, or concur with the facts presented on these sites. Further, CVEreport does not endorse any commercial products that may be mentioned on these sites. Please address comments about any linked pages to comment@cve.report.

There are currently no QIDs associated with this CVE

Known Affected Configurations (CPE V2.3)

Type	Vendor	Product	Version	Update	Edition	Language
Hardware 	Huawei	Ais-bw80h-00	-	All	All	All
Hardware 	Huawei	Ais-bw80h-00	-	All	All	All
Operating System	Huawei	Ais-bw80h-00 Firmware	9.0.3.1\(\h100sp13c00\)	All	All	All
Operating System	Huawei	Ais-bw80h-00 Firmware	9.0.3.1\(\h100sp18c00\)	All	All	All
Operating System	Huawei	Ais-bw80h-00 Firmware	9.0.3.1\(\h100sp3c00\)	All	All	All
Operating System	Huawei	Ais-bw80h-00 Firmware	9.0.3.1\(\h100sp9c00\)	All	All	All
Operating System	Huawei	Ais-bw80h-00 Firmware	9.0.3.2\(\h100sp1c00\)	All	All	All
Operating System	Huawei	Ais-bw80h-00 Firmware	9.0.3.2\(\h100sp2c00\)	All	All	All
Operating System	Huawei	Ais-bw80h-00 Firmware	9.0.3.2\(\h100sp5c00\)	All	All	All
Operating System	Huawei	Ais-bw80h-00 Firmware	9.0.3.2\(\h100sp8c00\)	All	All	All
Operating System	Huawei	Ais-bw80h-00 Firmware	9.0.3.3\(\h100sp1c00\)	All	All	All
Operating System	Huawei	Ais-bw80h-00 Firmware	9.0.3.1\(\h100sp13c00\)	All	All	All
Operating System	Huawei	Ais-bw80h-00 Firmware	9.0.3.1\(\h100sp18c00\)	All	All	All
Operating System	Huawei	Ais-bw80h-00 Firmware	9.0.3.1\(\h100sp3c00\)	All	All	All
Operating System	Huawei	Ais-bw80h-00 Firmware	9.0.3.1\(\h100sp9c00\)	All	All	All
Operating System	Huawei	Ais-bw80h-00 Firmware	9.0.3.2\(\h100sp1c00\)	All	All	All
Operating System	Huawei	Ais-bw80h-00 Firmware	9.0.3.2\(\h100sp2c00\)	All	All	All
Operating System	Huawei	Ais-bw80h-00 Firmware	9.0.3.2\(\h100sp5c00\)	All	All	All

System						
Operating System	Huawei	Ais-bw80h-00 Firmware	9.0.3.2\(\h100sp8c00\)	All	All	All
Operating System	Huawei	Ais-bw80h-00 Firmware	9.0.3.3\(\h100sp1c00\)	All	All	All
cpe:2.3:h:huawei:ais-bw80h-00:-:*:*:*:*:*:*:						
cpe:2.3:h:huawei:ais-bw80h-00:-:*:*:*:*:*:*:						
cpe:2.3:o:huawei:ais-bw80h-00_firmware:9.0.3.1\(\h100sp13c00\):*:*:*:*:*:*:						
cpe:2.3:o:huawei:ais-bw80h-00_firmware:9.0.3.1\(\h100sp18c00\):*:*:*:*:*:*:						
cpe:2.3:o:huawei:ais-bw80h-00_firmware:9.0.3.1\(\h100sp3c00\):*:*:*:*:*:*:						
cpe:2.3:o:huawei:ais-bw80h-00_firmware:9.0.3.1\(\h100sp9c00\):*:*:*:*:*:*:						
cpe:2.3:o:huawei:ais-bw80h-00_firmware:9.0.3.2\(\h100sp1c00\):*:*:*:*:*:*:						
cpe:2.3:o:huawei:ais-bw80h-00_firmware:9.0.3.2\(\h100sp2c00\):*:*:*:*:*:*:						
cpe:2.3:o:huawei:ais-bw80h-00_firmware:9.0.3.2\(\h100sp5c00\):*:*:*:*:*:*:						
cpe:2.3:o:huawei:ais-bw80h-00_firmware:9.0.3.2\(\h100sp8c00\):*:*:*:*:*:*:						
cpe:2.3:o:huawei:ais-bw80h-00_firmware:9.0.3.3\(\h100sp1c00\):*:*:*:*:*:*:						
cpe:2.3:o:huawei:ais-bw80h-00_firmware:9.0.3.1\(\h100sp13c00\):*:*:*:*:*:*:						
cpe:2.3:o:huawei:ais-bw80h-00_firmware:9.0.3.1\(\h100sp18c00\):*:*:*:*:*:*:						
cpe:2.3:o:huawei:ais-bw80h-00_firmware:9.0.3.1\(\h100sp3c00\):*:*:*:*:*:*:						
cpe:2.3:o:huawei:ais-bw80h-00_firmware:9.0.3.1\(\h100sp9c00\):*:*:*:*:*:*:						
cpe:2.3:o:huawei:ais-bw80h-00_firmware:9.0.3.2\(\h100sp1c00\):*:*:*:*:*:*:						
cpe:2.3:o:huawei:ais-bw80h-00_firmware:9.0.3.2\(\h100sp2c00\):*:*:*:*:*:*:						
cpe:2.3:o:huawei:ais-bw80h-00_firmware:9.0.3.2\(\h100sp5c00\):*:*:*:*:*:*:						
cpe:2.3:o:huawei:ais-bw80h-00_firmware:9.0.3.2\(\h100sp8c00\):*:*:*:*:*:*:						
cpe:2.3:o:huawei:ais-bw80h-00_firmware:9.0.3.3\(\h100sp1c00\):*:*:*:*:*:*:						

No vendor comments have been submitted for this CVE

[← Previous ID](#)

[Next ID →](#)

completeness or usefulness of any information, opinion, advice or other content. EACH USER WILL BE SOLELY RESPONSIBLE FOR ANY consequences of his or her direct or indirect use of this web site. ALL WARRANTIES OF ANY KIND ARE EXPRESSLY DISCLAIMED. This site will NOT BE LIABLE FOR ANY DIRECT, INDIRECT or any other kind of loss.

CVE, CWE, and OVAL are registered trademarks of [The MITRE Corporation](#) and the authoritative source of CVE content is [MITRE's CVE web site](#). This site includes MITRE data granted under the following [license](#).

CVE.report and Source URL Uptime Status [status.cve.report](#)