



CVE-2021-0007

[MITRE](#)[NVD](#)[CVE.ORG](#)[JSON API](#)[Print: PDF !\[\]\(003082e50e3009141f59bd5df831749f_img.jpg\)](#)

Summary

CVE	CVE-2021-0007
State	PUBLIC
Assigner	secure@intel.com
Source Priority	CVE Program / NVD first with legacy fallback
Published	2021-08-11 13:15:00 UTC
Updated	2021-09-14 18:35:00 UTC
Description	Uncaught exception in firmware for Intel(R) Ethernet Adapters 800 Series Controllers and associated adapters before versi

Risk And Classification

Problem Types: CWE-755

NVD Known Affected Configurations (CPE 2.3)

Type	Vendor	Product	Version	Update	Edition	Language
Hardware	Intel	Ethernet Controller E810	-	All	All	All
Operating System	Intel	Ethernet Controller E810 Firmware	All	All	All	All

References

Reference	Source	Link	Tags
INTEL-SA-00479	MISC	www.intel.com	
Intel SA-00479 Ethernet Controller Vulnerabilities in NetApp Products NetApp Product Security	CONFIRM	security.netapp.com	
CVE Program record	CVE.ORG	www.cve.org	canoni
NVD vulnerability detail	NVD	nvd.nist.gov	canoni

No vendor comments have been submitted for this CVE.

There are currently no legacy QID mappings associated with this CVE.

consequences of his or her direct or indirect use of this web site. ALL WARRANTIES OF ANY KIND ARE EXPRESSLY DISCLAIMED. This site will NOT BE LIABLE FOR ANY DIRECT, INDIRECT or any other kind of loss.

CVE, CWE, and OVAL are registered trademarks of [The MITRE Corporation](#) and the authoritative source of CVE content is [MITRE's CVE web site](#). This site includes MITRE data granted under the following [license](#).

Free CVE JSON API cve.report/api

CVE.report and Source URL Uptime Status status.cve.report