



CVE-2021-20139

Published on: 12/09/2021 12:00:00 AM UTC

Last Modified on: 12/13/2021 06:06:00 PM UTC


CVE-2021-20139

Source: Mitre

Source: NIST

CVE.ORG

Print: PDF



Certain versions of [Gryphon Tower](#) from [Gryphonconnect](#) contain the following vulnerability:

An unauthenticated command injection vulnerability exists in the parameters of operation 3 in the controller_server service on Gryphon Tower routers. An unauthenticated remote attacker on the same network can execute commands as root on the device by sending a specially crafted malicious packet to the controller_server service on

port 9999.

CVE-2021-20139 has been assigned by vulnreport@tenable.com to track the vulnerability - currently rated as **HIGH** severity.

CVSS3 Score: **8.8 - HIGH**

Attack Vector	Attack Complexity	Privileges Required	User Interaction
ADJACENT_NETWORK	LOW	NONE	NONE
Scope	Confidentiality Impact	Integrity Impact	Availability Impact
UNCHANGED	HIGH	HIGH	HIGH

CVSS2 Score: **8.3 - HIGH**

Access Vector	Access Complexity	Authentication
ADJACENT_NETWORK	LOW	NONE
Confidentiality Impact	Integrity Impact	Availability Impact
COMPLETE	COMPLETE	COMPLETE

CVE References

Description	Tags	Link
Multiple Vulnerabilities in Gryphon Tower Router - Research Advisory Tenable®	www.tenable.com text/html	MISC www.tenable.com/security/research/tra-2021-

By selecting these links, you may be leaving CVEreport webspace. We have provided these links to other websites because they may have information that would be of interest to you. No inferences should be drawn on account of other sites being referenced, or not, from this page. There may be other websites that are more appropriate for your purpose. CVEreport does not necessarily endorse the views expressed, or concur with the facts presented on these sites. Further, CVEreport does not endorse any commercial products that may be mentioned on these sites. Please address comments about any linked pages to comment@cve.report.

There are currently no QIDs associated with this CVE

Known Affected Configurations (CPE V2.3)

Type	Vendor	Product	Version	Update	Edition	Language
Hardware 	Gryphonconnect	Gryphon Tower	-	All	All	All
Operating System	Gryphonconnect	Gryphon Tower Firmware	All	All	All	All
cpe:2.3:h:gryphonconnect:gryphon_tower:-:*:*:*:*:*:						
cpe:2.3:o:gryphonconnect:gryphon_tower_firmware:*:*:*:*:*:						

No vendor comments have been submitted for this CVE

Social Mentions

Source	Title	Posted (UTC)
 @CVEreport	CVE-2021-20139 : An unauthenticated command injection vulnerability exists in the parameters of operation 3 in the... twitter.com/i/web/status/1...	2021-12-09 16:07:12
 @workentin	New vulnerability on the NVD: CVE-2021-20139 ift.tt/3ICRhOX	2021-12-09 17:40:16
 @xanadulinux	CVE-2021-20139 ift.tt/3ICRhOX	2021-12-09 17:52:22
 /r/netcve	CVE-2021-20139	2021-12-09 17:38:41

[← Previous ID](#)

[Next ID →](#)

© CVE.report 2023   |

Use of this information constitutes acceptance for use in an AS IS condition. There are NO warranties, implied or otherwise, with regard to this information or its use. Any use of this information is at the user's risk. It is the responsibility of user to evaluate the accuracy, completeness or usefulness of any information, opinion, advice or other content. EACH USER WILL BE SOLELY RESPONSIBLE FOR ANY consequences of his or her direct or indirect use of this web site. ALL WARRANTIES OF ANY KIND ARE EXPRESSLY DISCLAIMED. This site will NOT BE LIABLE FOR ANY DIRECT, INDIRECT or any other kind of loss.

CVE, CWE, and OVAL are registered trademarks of [The MITRE Corporation](#) and the authoritative source of CVE content is [MITRE's CVE web site](#). This site includes MITRE data granted under the following [license](#).

CVE.report and Source URL Uptime Status [status.cve.report](#)