



# CVE-2021-20156

[MITRE](#)[NVD](#)[CVE.ORG](#)[Print: PDF !\[\]\(e3f8612927870f2e0f9f5989e6dd3064\_img.jpg\)](#)

## Summary

<b>CVE</b>	CVE-2021-20156
<b>State</b>	PUBLIC
<b>Assigner</b>	vulnreport@tenable.com
<b>Source Priority</b>	CVE Program / NVD first with legacy fallback
<b>Published</b>	2021-12-30 22:15:00 UTC
<b>Updated</b>	2022-01-07 17:33:00 UTC
<b>Description</b>	Trendnet AC2600 TEW-827DRU version 2.08B01 contains an improper access control configuration that could allow for a r

## Risk And Classification

**Problem Types:** CWE-347

## NVD Known Affected Configurations (CPE 2.3)

Type	Vendor	Product	Version	Update	Edition	Language
Hardware	<a href="#">Trendnet</a>	<a href="#">Tew-827dru</a>	2.0	All	All	All
Operating System	<a href="#">Trendnet</a>	<a href="#">Tew-827dru Firmware</a>	2.08b01	All	All	All

## References

Reference	Source	Link	Tags
Trendnet AC2600 TEW-827DRU Multiple Vulnerabilities - Research Advisory   Tenable®	MISC	<a href="http://www.tenable.com">www.tenable.com</a>	
CVE Program record	CVE.ORG	<a href="http://www.cve.org">www.cve.org</a>	canonical
NVD vulnerability detail	NVD	<a href="http://nvd.nist.gov">nvd.nist.gov</a>	canonical, analy

No vendor comments have been submitted for this CVE.

There are currently no legacy QID mappings associated with this CVE.

CVE, CWE, and OVAL are registered trademarks of [The MITRE Corporation](#) and the authoritative source of CVE content is [MITRE's CVE web site](#). This site includes MITRE data granted under the following [license](#).

**CVE.report and Source URL Uptime Status [status.cve.report](#)**