



CVE-2021-28150

[MITRE](#)[NVD](#)[CVE.ORG](#)[Print: PDF !\[\]\(e3f8612927870f2e0f9f5989e6dd3064_img.jpg\)](#)

Summary

CVE	CVE-2021-28150
State	PUBLIC
Assigner	cve@mitre.org
Source Priority	CVE Program / NVD first with legacy fallback
Published	2021-05-06 16:15:00 UTC
Updated	2022-07-12 17:42:00 UTC
Description	Hongdian H8922 3.0.5 devices allow the unprivileged guest user to read cli.conf (with the administrator password and other

Risk And Classification

Problem Types: CWE-425

NVD Known Affected Configurations (CPE 2.3)

Type	Vendor	Product	Version	Update	Edition	Language
Hardware	Hongdian	H8922	-	All	All	All
Operating System	Hongdian	H8922 Firmware	3.0.5	All	All	All

References

Reference	Source	Link	Tags
LTE industrial router	MISC	en.hongdian.com	
SSD Advisory – Hongdian H8922 Multiple Vulnerabilities - SSD Secure Disclosure	MISC	ssd-disclosure.com	
CVE Program record	CVE.ORG	www.cve.org	canonical
NVD vulnerability detail	NVD	nvd.nist.gov	canonical, analysis

No vendor comments have been submitted for this CVE.

There are currently no legacy QID mappings associated with this CVE.

site will NOT BE LIABLE FOR ANY DIRECT, INDIRECT or any other kind of loss.

CVE, CWE, and OVAL are registered trademarks of [The MITRE Corporation](#) and the authoritative source of CVE content is [MITRE's CVE web site](#). This site includes MITRE data granted under the following [license](#).

CVE.report and Source URL Uptime Status [status.cve.report](#)