



CVE-2021-28160

[MITRE](#)[NVD](#)[CVE.ORG](#)[JSON API](#)[Print: PDF](#)

Summary

CVE	CVE-2021-28160
State	PUBLIC
Assigner	cve@mitre.org
Source Priority	CVE Program / NVD first with legacy fallback
Published	2021-03-18 19:15:00 UTC
Updated	2021-03-25 02:56:00 UTC
Description	Wireless-N WiFi Repeater REV 1.0 (28.08.06.1) suffers from a reflected XSS vulnerability due to unsanitized SSID value w

Risk And Classification

Problem Types: CWE-79

NVD Known Affected Configurations (CPE 2.3)

Type	Vendor	Product	Version	Update	Edition	Language
Hardware	Acexy Wireless-n Wifi Repeater Project	Acexy Wireless-n Wifi Repeater	1.0	All	All	All
Operating System	Acexy Wireless-n Wifi Repeater Project	Acexy Wireless-n Wifi Repeater Firmware	28.08.06.1	All	All	All

References

Reference
Amazon.com: Super Boost WiFi WiFi Range Extender, 300Mbps Fast Speed WiFi Booster Wireless Repeater with High Gain Dual External Antennas
Hunting for vulnerabilities in low-cost WiFi Repeaters by ssh3ll Medium
CVE Program record
NVD vulnerability detail

No vendor comments have been submitted for this CVE.

There are currently no legacy QID mappings associated with this CVE.

completeness or usefulness of any information, opinion, advice or other content. EACH USER WILL BE SOLELY RESPONSIBLE FOR ANY consequences of his or her direct or indirect use of this web site. ALL WARRANTIES OF ANY KIND ARE EXPRESSLY DISCLAIMED. This site will NOT BE LIABLE FOR ANY DIRECT, INDIRECT or any other kind of loss.

CVE, CWE, and OVAL are registered trademarks of [The MITRE Corporation](#) and the authoritative source of CVE content is [MITRE's CVE web site](#). This site includes MITRE data granted under the following [license](#).

Free CVE JSON API cve.report/api

CVE.report and Source URL Uptime Status status.cve.report